TE CONNECTIVITY

PRODUCT CHANGE NOTIFICATION

CUSTOMER: HEILIND ELECTRONICSPRODUCLOCATION: WILMINGTONPCN DACUSTOMER NO: 167811AGREEITE CONNECTIVITY ENTITY: RMP (1082) - U.S. Operations on SAP

PRODUCT CHANGE NOTIFICATION NO: P-12-008571 PCN DATE: 20-NOV-12 AGREEMENT NO:

We would like to inform you about the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

GENERAL PRODUCT DESCRIPTION:

Amplimite, HD-20, Plug Assembly, Right-Angle, PCB Mount

DESCRIPTION OF CHANGE:

On solder-tail exit side of connector housing (opposite side of connector from mating face), add full length alignment rib between circuits for solder-tails on upper row of contacts. Current parts only have partial alignment ribs located on the upper end and low end of the solder-tails.

REASON FOR CHANGE:

Product improvement. The full length ribs between circuits will provide additional alignment support for the solder-tails when bent during the assembly process. This will prevent stubbing of the solder-tails on the lower alignment ribs during the bending operation.

ESTIMATE DATE:

LAST ORDER DATE:

(OBSOLETE PARTS ONLY)

LAST SHIP DATE:

(OBSOLETE PARTS ONLY)

FIRST DATE TO SHIP CHANGED PARTS: 02-JAN-2013

(CHANGED PARTS ONLY) LAST DATE FOR MIXED SHIPMENTS: 31-DEC-2013

(CHANGED PARTS ONLY)

TE CONNECTIVITY

PRODUCT CHANGE NOTIFICATION

CUSTOMER: HEILIND ELECTR	RONICS PRODUCT CHANGE NOTIFICATION NO: P-12-008571
LOCATION: WILMINGTON	PCN DATE: 20-NOV-12
CUSTOMER NO: 167811	AGREEMENT NO:
TE CONNECTIVITY ENTITY: R	RMP (1082) - U.S. Operations on SAP

PARTS BEING MODIFIED	CUSTOMER PART NBR
5747840-3	
5747840-4	
5747840-6	
5747841-6	
5747842-4	
5747843-4 (Alias Part Numbers: "CC2972-000", "AMP-0-5747843-4")	
5788792-1	
5788793-1	

TE CONNECTIVITY

PRODUCT CHANGE NOTIFICATION

CUSTOMER: MAVERICK ELECTRONICSPRODUCLOCATION: MCALLENPCN DACUSTOMER NO: 155785AGREEITE CONNECTIVITY ENTITY: RMP (1082) - U.S. Operations on SAP

PRODUCT CHANGE NOTIFICATION NO: P-12-008571 PCN DATE: 20-NOV-12 AGREEMENT NO:

We would like to inform you about the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

GENERAL PRODUCT DESCRIPTION:

Amplimite, HD-20, Plug Assembly, Right-Angle, PCB Mount

DESCRIPTION OF CHANGE:

On solder-tail exit side of connector housing (opposite side of connector from mating face), add full length alignment rib between circuits for solder-tails on upper row of contacts. Current parts only have partial alignment ribs located on the upper end and low end of the solder-tails.

REASON FOR CHANGE:

Product improvement. The full length ribs between circuits will provide additional alignment support for the solder-tails when bent during the assembly process. This will prevent stubbing of the solder-tails on the lower alignment ribs during the bending operation.

ESTIMATE DATE:

LAST ORDER DATE:

(OBSOLETE PARTS ONLY)

LAST SHIP DATE:

(OBSOLETE PARTS ONLY)

FIRST DATE TO SHIP CHANGED PARTS: 02-JAN-2013

(CHANGED PARTS ONLY) LAST DATE FOR MIXED SHIPMENTS: 31-DEC-2013

(CHANGED PARTS ONLY)

TE CONNECTIVITY

PRODUCT CHANGE NOTIFICATION

CUSTOMER: MAVERICK ELECTRONICSPRODUCT CHANGE NOTIFICATION NO: P-12-008571LOCATION: MCALLENPCN DATE: 20-NOV-12CUSTOMER NO: 155785AGREEMENT NO:TE CONNECTIVITY ENTITY: RMP (1082) - U.S. Operations on SAP

PARTS BEING MODIFIED CUSTOMER PART NBR

5747840-6

747840-6 (Alias Part Numbers: "1033351")