



# Product Change Notification

Current Date: 14-Apr-2020

## TE Connectivity

Product Change Notification: P-20-018898

PCN Date: 08-APR-20

Customer: Heilind Electronics  
Inc(0002135900)

Location: WORLDWIDE

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

### General Product Description:

Notification of Lead Time changes due to Corona Virus impact on tubing products.

### Description of Changes

This is a notification informing TE Connectivity customers that the Lead Times for tubing products are changing due the impact of Covid 19 Virus on Production.

#### Other attachments:

[PCN - Changes to Tubing lead times](#)

[Appliance Tubing - adjustment lead times 1](#)

[Appliance Tubing - adjustment lead times 2](#)

### Reason for Changes:

Document clarification. The Trutnov tubing plant remains open and producing as much heat Shrink tubing as it can however due to the closure of borders in the Czech Republic for reasons of Covid 19 virus protection we are not able to staff the factory at the required levels to keep up with required productivity outputs. This reduction has regrettably forced us to increase Lead Times for the tubing products.

### Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

13-APR-2020

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

No Mixed Shipments

### Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">034565-000</a>	NO			"5-1190267-6", "VERSAFIT-1/2-9-FSP"			
<a href="#">121397P015</a>	NO			"3-1190883-5", "ES2000-NO.3-B8-0-75MM"			
<a href="#">121397P018</a>	NO			"3-1190883-8", "ES2000-NO.3-B8-0-50MM"			
<a href="#">121397P023</a>	NO			"4-1190883-2", "ES2000-NO.3-B8-0-27MM"			
<a href="#">121397P024</a>	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
<a href="#">121397P043</a>	NO			"5-1190883-3", "ES2000-NO.3-B8-0-40MM"			
<a href="#">1547294005</a>	NO			"1191118-5", "VERSAFIT-1/8-2-SP"			
<a href="#">1616034001</a>	NO			"8-1191166-7", "VERSAFIT-3/16-0-BULK-SP"			
<a href="#">1766664003</a>	NO			"5-1191284-0", "VERSAFIT-3/8-2-SP"			
<a href="#">292801-000</a>	NO			"5-1192219-1", "RNF-100-1-BK-FSP"			
<a href="#">2951512003</a>	NO			"DWP-125-1/4-0-STK", "1448670-1", "16-0151"			
<a href="#">3371890001</a>	NO			"7-1192545-8", "ES-CAP-NO.1-C1-0-30MM"			
<a href="#">467625-000</a>	NO			"1193505-8", "RNF-100-1-YO-FSP"			
<a href="#">4903754007</a>	NO			"2-1193668-8", "RT-375-1/2-X-SP"			
<a href="#">5052932105</a>	NO			"1-1193826-7", "RNF-100-1/16-WH-STK"			
<a href="#">5052994173</a>	NO			"3-1193833-0", "RNF-100-1/8-BK-SP", "RNF-100-1/8-0"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">5053344102</a>	NO			"4-1193882-5", "RNF-100-1-1/2-BK-SP"			
<a href="#">5053444034</a>	NO			"6-1193887-4", "RNF-100-3-BK-SP"			
<a href="#">5058734012</a>	NO			"9-1193906-4", "VERSAFIT-3/16-9-SP"			
<a href="#">5058764004</a>	NO			"7-1193907-5", "VERSAFIT-3/8-0-SP"			
<a href="#">5069764008</a>	NO			"1193947-4", "CGPT-25.4/12.7-X-SP"			
<a href="#">5070014034</a>	NO			"RNF-100-3/64-CL-SP", "1642707-1"			
<a href="#">5070034072</a>	NO			"1-1193960-3", "RNF-100-3/32-CL-SP"			
<a href="#">5070114069</a>	NO			"8-1193968-0", "RNF-100-1-1/2-CL-SP"			
<a href="#">5076682002</a>	NO			"DWP-125-3/4-0-STK", "1448810-3"			
<a href="#">5200082006</a>	NO			"6-1194081-5", "CRN-1/2-0-STK"			
<a href="#">5302194002</a>	NO			"4-1194164-1", "RNF-150-1/4-0-SP"			
<a href="#">5501092019</a>	NO			"3-1194340-1", "SCL-1/4-0-STK", "SCL-1/4-0-STK"			
<a href="#">5504062129</a>	NO			"7-1194343-9", "ATUM-3/1-0-MS-STK"			
<a href="#">5509112040</a>	NO			"6-1194351-0", "ATUM-24/8-0-STK"			
<a href="#">5509122053</a>	NO			"8-1194352-9", "ATUM-40/13-0-STK", "ATUM-40/13-0-STK"			
<a href="#">556693-000</a>	NO			"4-1194391-0", "VERSAFIT-1/2-0-1.5IN-SM"			
<a href="#">6465212003</a>	NO			"114517-01", "1448193-1", "DWP-125-1/2-0-STK", "16-0149"			
<a href="#">829131P012</a>	NO			"7-1196474-1", "ES2000-NO.1-C1-0-50MM"			
<a href="#">829131P019</a>	NO			"7-1196474-7", "ES2000-NO.1-C1-0-27MM"			
<a href="#">829131P021</a>	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			
<a href="#">829131P079</a>	NO			"2-1196475-9", "ES2000-NO.1-C1-0-15MM"			
<a href="#">829131P081</a>	NO			"3-1196475-0", "ES2000-NO.1-C1-0-100MM"			
<a href="#">8726034006</a>	NO			"1-1196790-6", "RT-375-3/4-X-SP"			
<a href="#">9346692002</a>	NO			"2-1197242-1", "DWP-125-1-0-STK"			
<a href="#">956051-000</a>	NO			"9-1197401-5", "VERSAFIT-3/8-4-FSP"			
<a href="#">9668274002</a>	NO			"8-1197475-3", "VERSAFIT-1-1/2-0-SP"			
<a href="#">CA8791-000</a>	NO			"ES2000-NO.4-B7-0-203MM"			
<a href="#">CB5015-000</a>	NO			"1899279-5", "BSTS-07X4"			
<a href="#">CB5035-000</a>	NO			"BSTS-13X25FR/NM", "6-1899832-3"			
<a href="#">CB5330-000</a>	NO						
<a href="#">CB5349-000</a>	NO						
<a href="#">CR7724-000</a>	NO			"VERSAFIT-1/4-9-BULK-SP", "9-1899832-9"			
<a href="#">CS8789-000</a>	NO						
<a href="#">CV3299-000</a>	NO			"RW-175-3/64-X-STK"			
<a href="#">EL6596-000</a>	NO						
<a href="#">EL88702001</a>	NO			"PROV-VERSAFIT-1/2-0-STK", "1899841-2"			
<a href="#">NB10372001</a>	NO			"ATUM--24/8-0-STK"			
<a href="#">NB13034001</a>	NO						
<a href="#">NB13864001</a>	NO						
<a href="#">NB14124001</a>	NO						
<a href="#">NB14614001</a>	NO						
<a href="#">NB14922001</a>	NO						
<a href="#">NB15754001</a>	NO						
<a href="#">NB15964001</a>	NO						
<a href="#">NB16104001</a>	NO						
<a href="#">NB16412001</a>	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">NB16614001</a>	NO						
<a href="#">NB17002001</a>	NO						
<a href="#">NB17694001</a>	NO						
<a href="#">NB18742001</a>	NO						
<a href="#">NB19234001</a>	NO						
<a href="#">NB19444001</a>	NO						
<a href="#">NB20114001</a>	NO						
<a href="#">NB20224001</a>	NO						
<a href="#">NB20274001</a>	NO						
<a href="#">NB20394001</a>	NO						
<a href="#">NB25822001</a>	NO						

Customer: Heilind Asia Pacific (Hong Kong) ( 2980376 )

Location: Shatin, N.t.

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">5052994173</a>	NO			"3-1193833-0", "RNF-100-1/8-BK-SP", "RNF-100-1/8-0"			
<a href="#">5058764004</a>	NO			"7-1193907-5", "VERSAFIT-3/8-0-SP"			
<a href="#">5076682002</a>	NO			"DWP-125-3/4-0-STK", "1448810-3"			
<a href="#">5302194002</a>	NO		RYCRNF-150-1/4-0-SP	"4-1194164-1", "RNF-150-1/4-0-SP"			
<a href="#">956051-000</a>	NO			"9-1197401-5", "VERSAFIT-3/8-4-FSP"			

Customer: Heilind Asia Pacific ( 3133470 )

Location: Shanghai

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">121397P024</a>	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
<a href="#">5053344102</a>	NO			"4-1193882-5", "RNF-100-1-1/2-BK-SP"			
<a href="#">829131P021</a>	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			

Customer: Heilind Electronics ( 2873183 )

Location: Hudson

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">2951512003</a>	NO			"DWP-125-1/4-0-STK", "1448670-1", "16-0151"			
<a href="#">5058764004</a>	NO			"7-1193907-5", "VERSAFIT-3/8-0-SP"			
<a href="#">5302194002</a>	NO			"4-1194164-1", "RNF-150-1/4-0-SP"			

Customer: Heilind Electronics Brasil Ltda ( 3088064 )

Location: Sao Paulo

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">829131P012</a>	NO			"7-1196474-1", "ES2000-NO.1-C1-0-50MM"			

Customer: Heilind Asia Pacific (SG) Pte Ltd ( 3076161 )

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">2951512003</a>	NO			"DWP-125-1/4-0-STK", "1448670-1", "16-0151"			
<a href="#">5052994173</a>	NO			"3-1193833-0", "RNF-100-1/8-BK-SP", "RNF-100-1/8-0"			
<a href="#">829131P081</a>	NO			"3-1196475-0", "ES2000-NO.1-C1-0-100MM"			

Customer: Heilind Electronics Inc ( 1275266 )

Location: Visalia

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">034565-000</a>	NO			"5-1190267-6", "VERSAFIT-1/2-9-FSP"			
<a href="#">121397P015</a>	NO			"3-1190883-5", "ES2000-NO.3-B8-0-75MM"			
<a href="#">121397P018</a>	NO			"3-1190883-8", "ES2000-NO.3-B8-0-50MM"			
<a href="#">121397P023</a>	NO			"4-1190883-2", "ES2000-NO.3-B8-0-27MM"			
<a href="#">121397P024</a>	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
<a href="#">121397P043</a>	NO			"5-1190883-3", "ES2000-NO.3-B8-0-40MM"			
<a href="#">1616034001</a>	NO			"8-1191166-7", "VERSAFIT-3/16-0-BULK-SP"			
<a href="#">2951512003</a>	NO			"DWP-125-1/4-0-STK", "1448670-1", "16-0151"			
<a href="#">3371890001</a>	NO			"7-1192545-8", "ES-CAP-NO.1-C1-0-30MM"			
<a href="#">467625-000</a>	NO			"1193505-8", "RNF-100-1-YO-FSP"			
<a href="#">4903754007</a>	NO			"2-1193668-8", "RT-375-1/2-X-SP"			
<a href="#">5052932105</a>	NO			"1-1193826-7", "RNF-100-1/16-WH-STK"			
<a href="#">5052994173</a>	NO			"3-1193833-0", "RNF-100-1/8-BK-SP", "RNF-100-1/8-0"			
<a href="#">5053344102</a>	NO			"4-1193882-5", "RNF-100-1-1/2-BK-SP"			
<a href="#">5053444034</a>	NO			"6-1193887-4", "RNF-100-3-BK-SP"			
<a href="#">5058734012</a>	NO			"9-1193906-4", "VERSAFIT-3/16-9-SP"			
<a href="#">5058764004</a>	NO			"7-1193907-5", "VERSAFIT-3/8-0-SP"			
<a href="#">5076682002</a>	NO			"DWP-125-3/4-0-STK", "1448810-3"			
<a href="#">5200082006</a>	NO			"6-1194081-5", "CRN-1/2-0-STK"			
<a href="#">5302194002</a>	NO			"4-1194164-1", "RNF-150-1/4-0-SP"			
<a href="#">6465212003</a>	NO			"114517-01", "1448193-1", "DWP-125-1/2-0-STK", "16-0149"			
<a href="#">829131P012</a>	NO			"7-1196474-1", "ES2000-NO.1-C1-0-50MM"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">829131P021</a>	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			
<a href="#">9346692002</a>	NO			"2-1197242-1", "DWP-125-1-0-STK"			
<a href="#">9668274002</a>	NO			"8-1197475-3", "VERSAFIT-1-1/2-0-SP"			
<a href="#">CA8791-000</a>	NO			"ES2000-NO.4-B7-0-203MM"			
<a href="#">CB5015-000</a>	NO			"1899279-5", "BSTS-07X4"			
<a href="#">CB5035-000</a>	NO			"BSTS-13X25FR/NM", "6-1899832-3"			
<a href="#">CV3299-000</a>	NO			"RW-175-3/64-X-STK"			
<a href="#">NB14124001</a>	NO						
<a href="#">NB14614001</a>	NO						
<a href="#">NB16104001</a>	NO						
<a href="#">NB17002001</a>	NO						
<a href="#">NB18742001</a>	NO						
<a href="#">NB19234001</a>	NO						
<a href="#">NB19444001</a>	NO						
<a href="#">NB20114001</a>	NO						
<a href="#">NB20274001</a>	NO						
<a href="#">NB20394001</a>	NO						
<a href="#">NB25822001</a>	NO						

Customer: Heilind Electronics GmbH ( 113007 )

Location: Feldkirchen- Westerham

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">3371890001</a>	NO			"7-1192545-8", "ES-CAP-NO.1-C1-0-30MM"			
<a href="#">5069764008</a>	NO			"1193947-4", "CGPT-25.4/12.7-X-SP"			
<a href="#">829131P019</a>	NO			"7-1196474-7", "ES2000-NO.1-C1-0-27MM"			

Customer: Heilind Asia Pacific (HK) Ltd ( 3087523 )

Location: Dongguan

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">NB15754001</a>	NO						

Customer: Heilind Electronics Inc ( 1281082 )

Location: Highland Heights

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">121397P015</a>	NO			"3-1190883-5", "ES2000-NO.3-B8-0-75MM"			
<a href="#">121397P024</a>	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
<a href="#">1616034001</a>	NO			"8-1191166-7", "VERSAFIT-3/16-0-BULK-SP"			
<a href="#">292801-000</a>	NO			"5-1192219-1", "RNF-100-1-BK-FSP"			
<a href="#">2951512003</a>	NO			"DWP-125-1/4-0-STK", "1448670-1", "16-0151"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">5052994173</a>	NO			"3-1193833-0", "RNF-100-1/8-BK-SP", "RNF-100-1/8-0"			
<a href="#">5058734012</a>	NO			"9-1193906-4", "VERSAFIT-3/16-9-SP"			
<a href="#">5058764004</a>	NO			"7-1193907-5", "VERSAFIT-3/8-0-SP"			
<a href="#">5070034072</a>	NO			"1-1193960-3", "RNF-100-3/32-CL-SP"			
<a href="#">5070114069</a>	NO			"8-1193968-0", "RNF-100-1-1/2-CL-SP"			
<a href="#">5076682002</a>	NO			"DWP-125-3/4-0-STK", "1448810-3"			
<a href="#">5501092019</a>	NO			"3-1194340-1", "SCL-1/4-0-STK", "SCL-1/4-0-STK"			
<a href="#">556693-000</a>	NO			"4-1194391-0", "VERSAFIT-1/2-0-1.5IN-SM"			
<a href="#">6465212003</a>	NO			"114517-01", "1448193-1", "DWP-125-1/2-0-STK", "16-0149"			
<a href="#">829131P021</a>	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			
<a href="#">829131P079</a>	NO			"2-1196475-9", "ES2000-NO.1-C1-0-15MM"			
<a href="#">9346692002</a>	NO			"2-1197242-1", "DWP-125-1-0-STK"			
<a href="#">9668274002</a>	NO			"8-1197475-3", "VERSAFIT-1-1/2-0-SP"			
<a href="#">CB5330-000</a>	NO						
<a href="#">CB5349-000</a>	NO						
<a href="#">CR7724-000</a>	NO			"VERSAFIT-1/4-9-BULK-SP", "9-1899832-9"			
<a href="#">CS8789-000</a>	NO						
<a href="#">NB10372001</a>	NO			"ATUM--24/8-0-STK"			

Customer: Heilind Electronics Inc ( 264685 )

Location: Hudson

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">121397P023</a>	NO			"4-1190883-2", "ES2000-NO.3-B8-0-27MM"			
<a href="#">5052994173</a>	NO			"3-1193833-0", "RNF-100-1/8-BK-SP", "RNF-100-1/8-0"			
<a href="#">5302194002</a>	NO			"4-1194164-1", "RNF-150-1/4-0-SP"			
<a href="#">829131P021</a>	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			

Customer: Heilind Asia Pacific (Hong Kong) ( 2991513 )

Location: Hong Kong

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">5052994173</a>	NO			"3-1193833-0", "RNF-100-1/8-BK-SP", "RNF-100-1/8-0"			
<a href="#">5058764004</a>	NO			"7-1193907-5", "VERSAFIT-3/8-0-SP"			
<a href="#">5076682002</a>	NO			"DWP-125-3/4-0-STK", "1448810-3"			
<a href="#">5302194002</a>	NO		RYCRNF-150-1/4-0-SP	"4-1194164-1", "RNF-150-1/4-0-SP"			
<a href="#">956051-000</a>	NO			"9-1197401-5", "VERSAFIT-3/8-4-FSP"			

Customer: Heilind Asia Pacific (SG) Pte Ltd ( 2980456 )

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">2951512003</a>	NO			"DWP-125-1/4-0-STK", "1448670-1", "16-0151"			
<a href="#">5052994173</a>	NO			"3-1193833-0", "RNF-100-1/8-BK-SP", "RNF-100-1/8-0"			
<a href="#">829131P021</a>	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			
<a href="#">829131P081</a>	NO			"3-1196475-0", "ES2000-NO.1-C1-0-100MM"			

Customer: Heilind Electronics Inc ( 1276409 )

Location: Plano

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1766664003</a>	NO			"5-1191284-0", "VERSAFIT-3/8-2-SP"			

Customer: Maverick Electronics ( 155785 )

Location: Mcallen

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">9346692002</a>	NO			"2-1197242-1", "DWP-125-1-0-STK"			

Customer: Heilind Electronics GmbH ( 3050932 )

Location: Rosenheim

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">3371890001</a>	NO			"7-1192545-8", "ES-CAP-NO.1-C1-0-30MM"			
<a href="#">829131P019</a>	NO			"7-1196474-7", "ES2000-NO.1-C1-0-27MM"			

Customer: Heilind Electronics GmbH ( 3076131 )

Location: Feldkirchen-Westerham

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">5069764008</a>	NO			"1193947-4", "CGPT-25.4/12.7-X-SP"			

Customer: Heilind Electronics Inc ( 3181260 )

Location: Mentor

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">121397P024</a>	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
<a href="#">1616034001</a>	NO			"8-1191166-7", "VERSAFIT-3/16-0-BULK-SP"			
<a href="#">292801-000</a>	NO			"5-1192219-1", "RNF-100-1-BK-FSP"			
<a href="#">2951512003</a>	NO			"DWP-125-1/4-0-STK", "1448670-1", "16-0151"			
<a href="#">3371890001</a>	NO			"7-1192545-8", "ES-CAP-NO.1-C1-0-30MM"			
<a href="#">5052994173</a>	NO			"3-1193833-0", "RNF-100-1/8-BK-SP", "RNF-100-1/8-0"			
<a href="#">5058764004</a>	NO			"7-1193907-5", "VERSAFIT-3/8-0-SP"			
<a href="#">5070014034</a>	NO			"RNF-100-3/64-CL-SP", "1642707-1"			
<a href="#">5076682002</a>	NO			"DWP-125-3/4-0-STK", "1448810-3"			
<a href="#">5501092019</a>	NO			"3-1194340-1", "SCL-1/4-0-STK", "SCL-1/4-0-STK"			
<a href="#">5504062129</a>	NO			"7-1194343-9", "ATUM-3/1-0-MS-STK"			
<a href="#">556693-000</a>	NO			"4-1194391-0", "VERSAFIT-1/2-0-1.5IN-SM"			
<a href="#">829131P021</a>	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			
<a href="#">829131P079</a>	NO			"2-1196475-9", "ES2000-NO.1-C1-0-15MM"			
<a href="#">8726034006</a>	NO			"1-1196790-6", "RT-375-3/4-X-SP"			
<a href="#">9346692002</a>	NO			"2-1197242-1", "DWP-125-1-0-STK"			
<a href="#">CR7724-000</a>	NO			"VERSAFIT-1/4-9-BULK-SP", "9-1899832-9"			
<a href="#">EL6596-000</a>	NO						
<a href="#">NB10372001</a>	NO			"ATUM--24/8-0-STK"			
<a href="#">NB13034001</a>	NO						
<a href="#">NB13864001</a>	NO						
<a href="#">NB14922001</a>	NO						
<a href="#">NB15754001</a>	NO						
<a href="#">NB15964001</a>	NO						
<a href="#">NB16412001</a>	NO						
<a href="#">NB17002001</a>	NO						
<a href="#">NB17694001</a>	NO						
<a href="#">NB18742001</a>	NO						
<a href="#">NB20224001</a>	NO						
<a href="#">NB20274001</a>	NO						

Customer: Heilind Electronics Inc ( 3018732 )

Location: Stowe

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">2951512003</a>	NO			"DWP-125-1/4-0-STK", "1448670-1", "16-0151"			



Customer: Heilind Electronics Inc ( 206835 )

Location: Highland Heights

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">5052994173</a>	NO			"3-1193833-0", "RNF-100-1/8-BK-SP", "RNF-100-1/8-0"			

Customer: Heilind Electronics Inc ( 167811 )

Location: Wilmington

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">034565-000</a>	NO			"5-1190267-6", "VERSAFIT-1/2-9-FSP"			
<a href="#">121397P015</a>	NO			"3-1190883-5", "ES2000-NO.3-B8-0-75MM"			
<a href="#">121397P018</a>	NO			"3-1190883-8", "ES2000-NO.3-B8-0-50MM"			
<a href="#">121397P023</a>	NO			"4-1190883-2", "ES2000-NO.3-B8-0-27MM"			
<a href="#">121397P024</a>	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
<a href="#">121397P043</a>	NO			"5-1190883-3", "ES2000-NO.3-B8-0-40MM"			
<a href="#">1547294005</a>	NO			"1191118-5", "VERSAFIT-1/8-2-SP"			
<a href="#">1616034001</a>	NO			"8-1191166-7", "VERSAFIT-3/16-0-BULK-SP"			
<a href="#">1766664003</a>	NO			"5-1191284-0", "VERSAFIT-3/8-2-SP"			
<a href="#">292801-000</a>	NO			"5-1192219-1", "RNF-100-1-BK-FSP"			
<a href="#">2951512003</a>	NO			"DWP-125-1/4-0-STK", "1448670-1", "16-0151"			
<a href="#">3371890001</a>	NO			"7-1192545-8", "ES-CAP-NO.1-C1-0-30MM"			
<a href="#">467625-000</a>	NO			"1193505-8", "RNF-100-1-YO-FSP"			
<a href="#">4903754007</a>	NO			"2-1193668-8", "RT-375-1/2-X-SP"			
<a href="#">5052932105</a>	NO			"1-1193826-7", "RNF-100-1/16-WH-STK"			
<a href="#">5052994173</a>	NO			"3-1193833-0", "RNF-100-1/8-BK-SP", "RNF-100-1/8-0"			
<a href="#">5053344102</a>	NO			"4-1193882-5", "RNF-100-1-1/2-BK-SP"			
<a href="#">5053444034</a>	NO			"6-1193887-4", "RNF-100-3-BK-SP"			
<a href="#">5058734012</a>	NO			"9-1193906-4", "VERSAFIT-3/16-9-SP"			
<a href="#">5058764004</a>	NO			"7-1193907-5", "VERSAFIT-3/8-0-SP"			
<a href="#">5070014034</a>	NO			"RNF-100-3/64-CL-SP", "1642707-1"			
<a href="#">5070034072</a>	NO			"1-1193960-3", "RNF-100-3/32-CL-SP"			
<a href="#">5070114069</a>	NO			"8-1193968-0", "RNF-100-1-1/2-CL-SP"			
<a href="#">5076682002</a>	NO			"DWP-125-3/4-0-STK", "1448810-3"			
<a href="#">5200082006</a>	NO			"6-1194081-5", "CRN-1/2-0-STK"			
<a href="#">5302194002</a>	NO			"4-1194164-1", "RNF-150-1/4-0-SP"			
<a href="#">5501092019</a>	NO			"3-1194340-1", "SCL-1/4-0-STK", "SCL-1/4-0-STK"			
<a href="#">5504062129</a>	NO			"7-1194343-9", "ATUM-3/1-0-MS-STK"			
<a href="#">5509112040</a>	NO			"6-1194351-0", "ATUM-24/8-0-STK"			
<a href="#">5509122053</a>	NO			"8-1194352-9", "ATUM-40/13-0-STK", "ATUM-40/13-0-STK"			
<a href="#">556693-000</a>	NO			"4-1194391-0", "VERSAFIT-1/2-0-1.5IN-SM"			
<a href="#">6465212003</a>	NO			"114517-01", "1448193-1", "DWP-125-1/2-0-STK", "16-0149"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">829131P012</a>	NO			"7-1196474-1", "ES2000-NO.1-C1-0-50MM"			
<a href="#">829131P021</a>	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			
<a href="#">829131P079</a>	NO			"2-1196475-9", "ES2000-NO.1-C1-0-15MM"			
<a href="#">8726034006</a>	NO			"1-1196790-6", "RT-375-3/4-X-SP"			
<a href="#">9346692002</a>	NO			"2-1197242-1", "DWP-125-1-0-STK"			
<a href="#">9668274002</a>	NO			"8-1197475-3", "VERSAFIT-1-1/2-0-SP"			
<a href="#">CA8791-000</a>	NO			"ES2000-NO.4-B7-0-203MM"			
<a href="#">CB5015-000</a>	NO			"1899279-5", "BSTS-07X4"			
<a href="#">CB5035-000</a>	NO			"BSTS-13X25FR/NM", "6-1899832-3"			
<a href="#">CB5330-000</a>	NO						
<a href="#">CB5349-000</a>	NO						
<a href="#">CR7724-000</a>	NO			"VERSAFIT-1/4-9-BULK-SP", "9-1899832-9"			
<a href="#">CS8789-000</a>	NO						
<a href="#">CV3299-000</a>	NO			"RW-175-3/64-X-STK"			
<a href="#">EL6596-000</a>	NO						
<a href="#">EL88702001</a>	NO			"PROV-VERSAFIT-1/2-0-STK", "1899841-2"			
<a href="#">NB10372001</a>	NO			"ATUM--24/8-0-STK"			
<a href="#">NB13034001</a>	NO						
<a href="#">NB13864001</a>	NO						
<a href="#">NB14124001</a>	NO						
<a href="#">NB14614001</a>	NO						
<a href="#">NB14922001</a>	NO						
<a href="#">NB15754001</a>	NO						
<a href="#">NB15964001</a>	NO						
<a href="#">NB16104001</a>	NO						
<a href="#">NB16412001</a>	NO						
<a href="#">NB16614001</a>	NO						
<a href="#">NB17002001</a>	NO						
<a href="#">NB17694001</a>	NO						
<a href="#">NB18742001</a>	NO						
<a href="#">NB19234001</a>	NO						
<a href="#">NB19444001</a>	NO						
<a href="#">NB20114001</a>	NO						
<a href="#">NB20224001</a>	NO						
<a href="#">NB20274001</a>	NO						
<a href="#">NB20394001</a>	NO						
<a href="#">NB25822001</a>	NO						