PRODUCT CHANGE NOTIFICATION

E-Switch Series/ Part No affected: TL1275 series, all PNs. See list below.	Part /Series Description: Tact Switch

Affected Process

[X] Assembly [ ] Molding [ ] Stamping [ ] Plating

Change on:


[X] Drawing [X] Process [ ] Material [ ] Specification
[ ] Packaging [ ] Tooling Modification [ ] New Tooling [ ] Manufacturing Location
[ ] Others

Reason for change:

1. Improve tensile strength of wire to PCB connection. To prevent wires breaking during handling.
2.

Proposed change:

1. Add glue to the PCB to wrap the root of the conductor and the plastic outer covering together



BEFORE



AFTER

Proposed Transition/change over:
This will be a running change. Old inventory will be used up first. There may be mixed inventory in distribution.

[ ] Customer Notification

Action Item:

Part numbers affected:

TL1275CA2WA500QPR			
TL1275CA2WA500QPG			
TL1275CA2WA500QPB			
TL1275CA2WA500QPRG			
TL1275CB2WA500QPW			
TL1275CA2WA140QPG			