
JAE Electronics, Inc. · 142 Technology Drive #100 Irvine, CA 92618 · Ph. (949) 753-2600 · Fax (949) 753-2699 · www.jae.com

Material Change Notice:
DX4 Receptacle



Due to the discontinuance of the material currently being used, the insulator for the following DX4 receptacle parts will be changing per below:

	Part Number	SJ Drawing	Insulator Material Change
1	DX4R005JJ2R1800	**SJ110579**	**Current Material:** **35% GMF LCP TYPE IX SELCION KC173W** **New Material:** **35% GMF LCP TYPE UENO LCP UX101**
2	DX4R005HJ5R2000	**SJ111771**	
3	DX4R005JJER1800	**SJ114662**	

There is no change in connector performance or SJ drawings.

Effective: **March 2015**

For any questions regarding this matter, please contact your local JAE Sales Rep, Regional Sales Manager, or Marketing at marketing@jae.com.

Thank you for your cooperation.