PRODUCT CHANGE NOTIFICATION

PCN Date 10-20-23

E-Switch Series/ Part No affected: N634000	Part /Series Description: TL6340AF160Q

Affected Process

☐ Assembly ☐ Molding ☐ Stamping ☐ Plating

Change on:

☐ Drawing ☐ Process ☐ Material ☐ Specification

☐ Packaging ☒ Tooling Modification ☐ New Tooling ☐ Manufacturing Location

☐ Others

Reason for change:


1. The PCB hole was removed to improve the stability of the production process.
2. No change to form fit or function


Proposed change:

1.

Before — With PCB hole (Vents)

After — Remove the PCB hole(Vents)









Proposed Transition/change over:

This will be a running change. Old inventory will be used up first. There may be mixed inventory in distribution.

☐ Customer Notification

Action Item:
