PRODUCT CHANGE NOTIFICATION
PCN No: PCN-1047
Issue Date: 7/16/2024

Parts Affected		Old Rev.		New Rev.	
	FLP25-1.900		D		E
	FLP25-1.950		D		E
	FLP25-10.0		D		E
	FLP25-12.0		D		E
	FLP25-13.0		D		E
	FLP25-13.5		D		E
	FLP25-144.00		D		E
	FLP25-16.0		D		E
	FLP25-17.0		D		E
	FLP25-2.0		D		E
	FLP25-2.325		D		E
	FLP25-2.375		D		E
	FLP25-20.83		D		E
	FLP25-3.315		D		E
	FLP25-3.5		D		E
	FLP25-3.735		D		E
	FLP25-4.0		D		E
	FLP25-4.5		D		E
	FLP25-40.0		D		E
	FLP25-5.0		D		E
	FLP25-5.315		D		E
	FLP25-6.0		D		E
	FLP25-8.0		D		E
	PM7-C2031-10.00		B		C
	PM7-C2031-18.00		B		C
	PM7-C2031-2.00		B		C
	PM7-C2031-2.50		B		C
	PM7-C2031-20.00		B		C

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045
Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

PRODUCT CHANGE NOTIFICATION
PCN No: PCN-1047
Issue Date: 7/16/2024

Parts Affected	SMFLP25-1.00	Old Rev.	D	New Rev.	E
	SMFLP25-10.0		D		E
	SMFLP25-12.0		D		E
	SMFLP25-16.0		D		E
	SMFLP25-2.5		D		E
	SMFLP25-3.0		D		E
	SMFLP25-3.5		D		E
	SMFLP25-4.0		D		E
	SMFLP25-5.0		D		E
	SMFLP25-5.5		D		E
	SMFLP25-6.0		D		E
	SMFLP25-60.0		D		E
	SMFLP25-7.0		D		E
	SMFLP25-8.0		D		E
	SMFLP25-8.5		D		E
	FLP25-23.0		D		E

Change Will Affect:

The change will affect the product specifications.

Description of Change:

The drawings for FLP25-XX.X, PM7-C2031-XX.XX, and SMFLP25-X.X have been revised to remove incorrect and unnecessary dimensions.

Effective Date of Change: July 16, 2024

Reason for Change: Typographical errors on the datasheets.

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045
Please contact Bivar Inc. at www.bivar.com/contact or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.