Product Change Notification

Current Date: 04-Sep-2026

TE Connectivity

Product Change Notification: PCN-26-290299 **PCN Date:** 03-SEP-26

Customer: Heilind Electronics Inc(0002135900) **Location:** WORLDWIDE **Agreement:** Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

Product Description: (Text limited to 120 characters)
SR6/V23050 Force-Guided-Relays - reinstated CCC certification

General Description of Changes
Dear Customer, we are pleased to inform you that the CCC certification for our SR6/V23050 product family has been successfully reinstated for the most common coil voltages (only the 9Vdc 1200mW coil as well as the 6Vdc, 9Vdc & 36Vdc 800mW coils are not affected. They may be added in an upcoming CCC certificate update). As a result, all affected made-in-EU SR6/V23050 part numbers listed below that are manufactured going forward will once again carry the CCC mark on the relay cover. Thus, all relays manufactured with date code 2637 and later will definitively include the CCC marking. This certification reinstatement ensures continued compliance with CCC requirements. Should you have any questions, please do not hesitate to contact your TE Connectivity representative.

Reason for Changes:
Reinstated CCC certification.

PCN Attributes:	
Product Category:	**Kind of Change:**
Relays, Contactors & Switches	Revision Adjustment / Part Clarification
Change Feature:	**Potential Customer Impact:**
Clarification/Correction	
Remarks:	

Estimated Dates:	
Last Order Date (Obsolete Parts Only):	**First Ship Date of Changed Items** (Changed Parts Only):
	07-SEP-2026
Last Ship Date of Changed Items (Obsolete Parts Only):	**Last Date for Mixed Shipments:** (Changed Parts Only):
	No Mixed Shipments
Effectivity Date:	**Date of First Samples:**

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1393260-7	NO			"V23050-A1024-A542", "V23050A1024A542"			
8-1415537-0	NO			"SR6B6K24"			
9-1415018-1	NO			"V23050-A1110-A533", "V23050A1110A533"			

Customer: Heilind Electronics Brasil Ltda (3088064) **Location:** Sao Paulo **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1393260-7	NO			"V23050-A1024-A542", "V23050A1024A542"			

Customer: Heilind Asia Pacific (3229127) **Location:** Suzhou **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
8-1415537-0	NO			"SR6B6K24"			

Customer: Heilind Electronics sp z o o (3428049) **Location:** Myslowice **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
8-1415537-0	NO		AMP8-1415537-0	"SR6B6K24"			

Customer: Heilind Electronics Inc (167811) **Location:** Wilmington **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
9-1415018-1	NO			"V23050-A1110-A533", "V23050A1110A533"			