# Product Change Notification

Current Date: 17-Sep-2026

## TE Connectivity

**Product Change Notification:** PCN-26-290027 **PCN Date:** 15-SEP-26

**Customer:** Heilind Electronics Inc(0002135900) **Location:** WORLDWIDE **Agreement:** Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

| **Product Description:** (Text limited to 120 characters) |
|---|
| 13-AMPMODU Breakaway Headers 14-AMPMODU Shrouded Headers 283-AMPMODU MT (WtB Recpt) 296-AMPMODU MTE (WtB,WtW) |

| **General Description of Changes** |
|---|
| Dear Customer, TE Connectivity informs customers that the part numbers listed in this notification will be discontinued and transitioned to obsolete status. TE recognizes the potential impact of this change and is committed to supporting customers through this transition. Where applicable, last-time-buy opportunities may be offered, and alternative products may be available. Customers may reach out to consult available inventories at TE for first come first serve disposal. In this particularly case, please intensively review the LAST TIME ORDER date below and place any order or demands prior to the end of this date or in parallel shift any demands to the applicable replacement parts if necessary. Please reach out your TE sales representative for more detailed for further information on available replacement parts. Customers are advised that revised commercial conditions, including minimum order quantities and lead times, may apply. For additional information, including availability, timelines, and potential replacement solutions, please contact your local TE Connectivity sales representative |

| **Reason for Changes:** |
|---|
| Dear Customer, You are receiving this notice because TE Connectivity has record of you purchasing a part or multiple parts on the list below. According to our records in the last 2 years, no production or shipments of these parts have been performance to customer or our channels partners. Within our continued efforts to manage/ optimize our product portfolio throughout the lifecycle, we've made the decision to obsolete the parts stated thereafter. |

| **PCN Attributes:** | |
|---|---|
| **Product Category:** | **Kind of Change:** |
| Connectors | Status Change |
| **Change Feature:** | **Potential Customer Impact:** |
| Discontinuance | |
| **Remarks:** | |

| **Estimated Dates:** | |
|---|---|
| **Last Order Date** (Obsolete Parts Only): | **First Ship Date of Changed Items** (Changed Parts Only): |
| 08-DEC-2026 | |
| **Last Ship Date of Changed Items** (Obsolete Parts Only): | **Last Date for Mixed Shipments:** (Changed Parts Only): |
| 15-FEB-2027 | No Mixed Shipments |
| **Effectivity Date:** | **Date of First Samples:** |

**Part Number(s) being Modified:**

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|---|---|---|---|---|---|---|---|
| 1-103957-5 | YES | | | | | | |
| 2-103673-3 | YES | | | | | | |
| 3-103168-3 | YES | | | | | | |
| 1-103168-8 | YES | | | | 6-103168-8 | | RoHS compliant part |
| 103166-5 | YES | | | | 5-103166-5 | | RoHS compliant part |
| 103168-3 | YES | | | | 5-103168-3 | | RoHS compliant part |
| 103168-5 | YES | | | "406870055" | 5-103168-5 | | RoHS compliant part |
| 103168-9 | YES | | | | 5-103168-9 | | RoHS compliant part |
| 103638-5 | YES | | | "407161199" | 5-104363-5 | | RoHS compliant part |
| 103638-5 | YES | | | "407161199" | 5-104363-5 | | RoHS compliant part |
| 146869-1 | YES | | | | 5-146869-1 | | RoHS compliant part |
| 146870-1 | YES | | | | 5-146870-1 | | RoHS compliant part |
| 2-103168-8 | YES | | | | 7-103168-8 | | RoHS compliant part |

**Customer:** Heilind Asia Pacific (SG) Pte Ltd ( 3076161 ) **Location:** Singapore **Agreement Number:** Agreement Unknown

**Part Number(s) being Modified:**

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|---|---|---|---|---|---|---|---|
| 1-103957-5 | YES | | | | | | |

**Customer:** Heilind Asia Pacific ( 3133470 ) **Location:** Shanghai **Agreement Number:** Agreement Unknown

**Part Number(s) being Modified:**

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|---|---|---|---|---|---|---|---|
| 103638-5 | YES | | | "407161199" | 5-104363-5 | | RoHS compliant part |

**Customer:** Interstate Connecting ( 731279 ) **Location:** Lumberton **Agreement Number:** Agreement Unknown

**Part Number(s) being Modified:**

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|---|---|---|---|---|---|---|---|
| 1-103168-8 | YES | | | | 6-103168-8 | | RoHS compliant part |
| 103166-5 | YES | | | | 5-103166-5 | | RoHS compliant part |
| 103168-3 | YES | | | | 5-103168-3 | | RoHS compliant part |
| 103168-5 | YES | | | "406870055" | 5-103168-5 | | RoHS compliant part |
| 103168-9 | YES | | | | 5-103168-9 | | RoHS compliant part |
| 3-103168-3 | YES | | | | | | |

**Customer:** Trek Connect Inc ( 155622 ) **Location:** Lumberton **Agreement Number:** Agreement Unknown

**Part Number(s) being Modified:**

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|---|---|---|---|---|---|---|---|
| 2-103168-8 | YES | | | | 7-103168-8 | | RoHS compliant part |

**Customer:** Heilind Asia Pacific (SG) Pte Ltd ( 2980456 ) **Location:** Singapore **Agreement Number:** Agreement Unknown

**Part Number(s) being Modified:**

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|---|---|---|---|---|---|---|---|
| 1-103957-5 | YES | | | | | | |

**Customer:** Heilind Asia Pacific ( 3229127 ) **Location:** Suzhou **Agreement Number:** Agreement Unknown

**Part Number(s) being Modified:**

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|---|---|---|---|---|---|---|---|
| 103638-5 | YES | | | "407161199" | 5-104363-5 | | RoHS compliant part |

**Customer:** Heilind Electronics Inc ( 1276409 ) **Location:** Plano **Agreement Number:** Agreement Unknown

**Part Number(s) being Modified:**

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|---|---|---|---|---|---|---|---|
| 2-103673-3 | YES | | | | | | |

**Customer:** Heilind Electronics Inc ( 167811 ) **Location:** Wilmington **Agreement Number:** Agreement Unknown

**Part Number(s) being Modified:**

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|---|---|---|---|---|---|---|---|
| 146869-1 | YES | | | | 5-146869-1 | | RoHS compliant part |
| 146870-1 | YES | | | | 5-146870-1 | | RoHS compliant part |
| 2-103673-3 | YES | | | | | | |