Product Change Notification

Current Date: 16-Oct-2026

TE Connectivity

Product Change Notification: PCN-26-293753 **PCN Date:** 13-OCT-26

Customer: Heilind Electronics Inc(0002135900) **Location:** WORLDWIDE **Agreement:** Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

Product Description: (Text limited to 120 characters)
RNF-100 (Black and Colored Versions) VERSAFIT RP-4800

General Description of Changes
Reinstatement of Mil-Spec qualification for selected TE Connectivity heat-shrink tubing products specifically RNF-100 (Black and Colored), VERSAFIT, and RP-4800 following NAVAIR approval of a supplier-directed manufacturing location change. This PCN serves as an update to PCN-26-283716, which had communicated a temporary suspension of Mil-Spec approvals. There is no change to the form, fit, or function (FFF) of the affected products.Note: CRN (Black) and TAT-125 remain on hold under a separate restriction (PCN-26-283718) related to China-origin raw materials, which is addressed independently.

Reason for Changes:
The temporary Mil-Spec restriction was imposed due to a supplier-directed manufacturing location change that required formal regulatory review before Mil-Spec qualified production and shipments will resume. NAVAIR has reviewed and approved the manufacturing location change, enabling the reinstatement of Mil-Spec certification for the three affected product families.

PCN Attributes:	
Product Category:	**Kind of Change:**
Heat Shrink Tubing	Agency Approvals
Change Feature:	**Potential Customer Impact:**
No Feature Change	No Customer Impact
Remarks:	

Estimated Dates:	
Last Order Date (Obsolete Parts Only):	**First Ship Date of Changed Items** (Changed Parts Only):
	26-OCT-2026
Last Ship Date of Changed Items (Obsolete Parts Only):	**Last Date for Mixed Shipments:** (Changed Parts Only):
	No Mixed Shipments
Effectivity Date:	**Date of First Samples:**
14-OCT-2026	

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5052844058	NO			"RNF-100-3/64-BK-SP", "1642451-1"			
5052894108	NO			"RNF-100-1/16-BK-SP", "1642242-2"			
5052944219	NO			"RNF-100-3/32-BK-SP", "1642525-1"			
5052994173	NO			"3-1193833-0", "RNF-100-1/8-BK-SP", "RNF-100-1/8-0"			
5053044177	NO			"RNF-100-3/16-BK-SP", "RNF-100-3/16-0", "1832174-1"			
5053094268	NO			"4-1193845-5", "RNF-100-1/4-BK-SP"			
NB12724001	NO						
NB12744001	NO						
NB12762001	NO		M23053/5-108-0 (A)	"RNF-100-1/2-BK-STK"			
NB12904001	NO						
NB12924001	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
NB12944001	NO						
NB13044001	NO						
NB13052001	NO			"RNF-100-1-BK-STK"			
NB13282001	NO			"RNF-100-3/4-BK-STK"			
NB13444001	NO						
NB13504001	NO						
NB13524001	NO						
NB13542001	NO			"RNF-100-3/8-BK-STK"			
NB13674001	NO						
NB13714001	NO						
NB14124001	NO						
NB14134001	NO			"VERSAFIT-1/2-0-SP"			
NB14164001	NO						
NB14244001	NO						
NB14254001	NO						
NB14284001	NO			"VERSAFIT-1-0-SP."			
NB14354001	NO			"VERSAFIT-3/4-0-FSP"			
NB14374001	NO						
NB14474001	NO						
NB14494001	NO						
NB14614001	NO						
NB16924001	NO						
NB16934001	NO			"VERSAFIT-3/64-0-SP"			
NB17304001	NO						
NB17364001	NO			"9-1899847-8", "RP-4800-NO.2-0-SP"			
NB17434001	NO						
NB17694001	NO						
NB17754001	NO						
NB17914001	NO						
NB17932001	NO			"RNF-100-1-1/2-BK-STK"			
NB18044001	NO						
NB18144001	NO						
NB18442001	NO			"RNF-100-4-BK-STK"			
NB18742001	NO			"RNF-100-1/16-BK-STK"			
NB18844001	NO						
NB18902001	NO						
NB18964001	NO						
NB19014001	NO						
NB19044001	NO						
NB19084001	NO						
NB19144001	NO						
NB19162001	NO		M23053/5-104-0 (A)	"RNF-100-1/8-BK-STK"			
NB19202001	NO						
NB19284001	NO						
NB19304001	NO						
NB19312001	NO						
NB19324001	NO						
NB19334001	NO						
NB19352001	NO						
NB19414001	NO						
NB19534001	NO						
NB19564001	NO						
NB19642001	NO			"RNF-100-3/32-BK-STK"			
NB19914001	NO			"VERSAFIT-1/16-0-SP"			
NB19974001	NO						
NB19994001	NO						
NB20014001	NO						
NB20034001	NO						
NB20164001	NO			"VERSAFIT-1/8-0-SP"			
NB20234001	NO						
NB20274001	NO						
NB20344001	NO						
NB20364001	NO						
NB20374001	NO						
NB20384001	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
NB20394001	NO						
NB20424001	NO			"VERSAFIT-3/32-0-SP"			
NB20504001	NO						
NB21094001	NO			"RNF-100-1/4-VT-SP"			
NB23344001	NO						

Customer: Heilind Electronics Brasil Ltda (3088064) **Location:** Sao Paulo **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5052994173	NO			"3-1193833-0", "RNF-100-1/8-BK-SP", "RNF-100-1/8-0"			

Customer: Heilind Asia Pacific (SG) Pte Ltd (3076161) **Location:** Singapore **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5052844058	NO			"RNF-100-3/64-BK-SP", "1642451-1"			
5052894108	NO			"RNF-100-1/16-BK-SP", "1642242-2"			
5052994173	NO			"3-1193833-0", "RNF-100-1/8-BK-SP", "RNF-100-1/8-0"			
5053044177	NO			"RNF-100-3/16-BK-SP", "RNF-100-3/16-0", "1832174-1"			
5053094268	NO			"4-1193845-5", "RNF-100-1/4-BK-SP"			
NB19162001	NO			"RNF-100-1/8-BK-STK"			
NB19564001	NO						
NB20274001	NO						
NB20424001	NO			"VERSAFIT-3/32-0-SP"			
NB20424001	NO			"VERSAFIT-3/32-0-SP"			

Customer: Interstate Connecting (3196442) **Location:** Lumberton **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
NB19352001	NO						

Customer: Heilind Electronics sp z o o (3261330) **Location:** Krakow **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
NB13044001	NO						
NB19914001	NO			"VERSAFIT-1/16-0-SP"			

Customer: HEILIND ELECTRONICS BRASIL LTDA (3661258) **Location:** SAO PAULO **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5052994173	NO			"3-1193833-0", "RNF-100-1/8-BK-SP", "RNF-100-1/8-0"			

Customer: Heilind Electronics (2874919) **Location:** Visalia **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
NB19534001	NO						

Customer: Heilind Asia Pacific (SG) Pte Ltd (3076161) **Location:** Singapore **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5052844058	NO			"RNF-100-3/64-BK-SP", "1642451-1"			
5052894108	NO			"RNF-100-1/16-BK-SP", "1642242-2"			
5052994173	NO			"3-1193833-0", "RNF-100-1/8-BK-SP", "RNF-100-1/8-0"			
5053044177	NO			"RNF-100-3/16-BK-SP", "RNF-100-3/16-0", "1832174-1"			
5053094268	NO			"4-1193845-5", "RNF-100-1/4-BK-SP"			
NB19162001	NO			"RNF-100-1/8-BK-STK"			
NB19564001	NO						
NB20274001	NO						
NB20424001	NO			"VERSAFIT-3/32-0-SP"			
NB20424001	NO			"VERSAFIT-3/32-0-SP"			

Customer: Heilind Asia Pacific HK Ltd (3107423) **Location:** Shatin **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
NB13444001	NO						

Customer: Heilind Asia Pacific (3133470) **Location:** Shanghai **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
NB13504001	NO						
NB17694001	NO						
NB20164001	NO			"VERSAFIT-1/8-0-SP"			
NB20274001	NO						

Customer: Interstate Connecting (731279) **Location:** Lumberton **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
NB18144001	NO						
NB18902001	NO						
NB19352001	NO						

Customer: Heilind Asia Pacific (Hong Kong) (2980376) **Location:** Shatin, N.t. **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5052994173	NO			"3-1193833-0", "RNF-100-1/8-BK-SP", "RNF-100-1/8-0"			
5053094268	NO			"4-1193845-5", "RNF-100-1/4-BK-SP"			
NB13504001	NO						
NB19974001	NO						
NB20234001	NO						
NB20274001	NO						

Customer: Heilind Asia Pacific (SG) Pte Ltd (2980456) **Location:** Singapore **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5052844058	NO			"RNF-100-3/64-BK-SP", "1642451-1"			
5052894108	NO			"RNF-100-1/16-BK-SP", "1642242-2"			
5052994173	NO			"3-1193833-0", "RNF-100-1/8-BK-SP", "RNF-100-1/8-0"			
5053044177	NO			"RNF-100-3/16-BK-SP", "RNF-100-3/16-0", "1832174-1"			
5053094268	NO			"4-1193845-5", "RNF-100-1/4-BK-SP"			
NB19162001	NO		M23053/5-104-0(A)	"RNF-100-1/8-BK-STK"			
NB19564001	NO						
NB20274001	NO						
NB20424001	NO			"VERSAFIT-3/32-0-SP"			
NB20424001	NO			"VERSAFIT-3/32-0-SP"			

Customer: Heilind Asia Pacific (3229127) **Location:** Suzhou **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
NB13504001	NO						
NB17694001	NO						
NB20164001	NO			"VERSAFIT-1/8-0-SP"			
NB20274001	NO						

Customer: Heilind Electronics Inc (3181260) **Location:** Mentor **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5052894108	NO			"RNF-100-1/16-BK-SP", "1642242-2"			
5052944219	NO			"RNF-100-3/32-BK-SP", "1642525-1"			
5052994173	NO			"3-1193833-0", "RNF-100-1/8-BK-SP", "RNF-100-1/8-0"			
5053044177	NO			"RNF-100-3/16-BK-SP", "RNF-100-3/16-0", "1832174-1"			
5053094268	NO			"4-1193845-5", "RNF-100-1/4-BK-SP"			
NB12744001	NO						
NB12762001	NO			"RNF-100-1/2-BK-STK"			
NB12944001	NO						
NB13052001	NO			"RNF-100-1-BK-STK"			
NB13282001	NO			"RNF-100-3/4-BK-STK"			
NB13524001	NO						
NB13542001	NO			"RNF-100-3/8-BK-STK"			
NB13674001	NO						
NB13714001	NO						
NB14124001	NO						
NB14134001	NO			"VERSAFIT-1/2-0-SP"			
NB14164001	NO						
NB14254001	NO						
NB14284001	NO			"VERSAFIT-1-0-SP."			
NB14354001	NO			"VERSAFIT-3/4-0-FSP"			
NB14374001	NO						
NB14474001	NO						
NB14494001	NO						
NB16934001	NO			"VERSAFIT-3/64-0-SP"			
NB17694001	NO						
NB17754001	NO						
NB17914001	NO						
NB17932001	NO			"RNF-100-1-1/2-BK-STK"			
NB18902001	NO						
NB18964001	NO						
NB19014001	NO						
NB19044001	NO						
NB19084001	NO						
NB19144001	NO						
NB19162001	NO			"RNF-100-1/8-BK-STK"			
NB19334001	NO						
NB19414001	NO						
NB19914001	NO			"VERSAFIT-1/16-0-SP"			
NB19994001	NO						
NB20034001	NO						
NB20164001	NO			"VERSAFIT-1/8-0-SP"			
NB20274001	NO						
NB20364001	NO						
NB20384001	NO						
NB20394001	NO						
NB20424001	NO			"VERSAFIT-3/32-0-SP"			

Customer: Maverick Electronics (155785) **Location:** Mcallen **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5052844058	NO			"RNF-100-3/64-BK-SP", "1642451-1"			
NB16934001	NO			"VERSAFIT-3/64-0-SP"			
NB20344001	NO						

Customer: Heilind Electronics Inc (3274845) **Location:** Visalia **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5052894108	NO			"RNF-100-1/16-BK-SP", "1642242-2"			
NB12744001	NO						
NB14254001	NO						
NB17754001	NO						
NB20034001	NO						
NB20274001	NO						

Customer: Heilind Electronics GmbH (3497140) **Location:** Hanau **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
NB14494001	NO						
NB17304001	NO						
NB17364001	NO			"9-1899847-8", "RP-4800-NO.2-0-SP"			
NB20164001	NO			"VERSAFIT-1/8-0-SP"			

Customer: Heilind Electronics sp z o o (3428049) **Location:** Myslowice **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
NB19914001	NO			"VERSAFIT-1/16-0-SP"			

Customer: Heilind Electronics Inc (167811) **Location:** Wilmington **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5052844058	NO			"RNF-100-3/64-BK-SP", "1642451-1"			
5052894108	NO			"RNF-100-1/16-BK-SP", "1642242-2"			
5052944219	NO			"RNF-100-3/32-BK-SP", "1642525-1"			
5052994173	NO			"3-1193833-0", "RNF-100-1/8-BK-SP", "RNF-100-1/8-0"			
5053044177	NO			"RNF-100-3/16-BK-SP", "RNF-100-3/16-0", "1832174-1"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5053094268	NO			"4-1193845-5", "RNF-100-1/4-BK-SP"			
NB12724001	NO						
NB12744001	NO						
NB12762001	NO		M23053/5-108-0(A)	"RNF-100-1/2-BK-STK"			
NB12904001	NO						
NB12924001	NO						
NB12944001	NO						
NB13052001	NO			"RNF-100-1-BK-STK"			
NB13282001	NO			"RNF-100-3/4-BK-STK"			
NB13524001	NO						
NB13542001	NO			"RNF-100-3/8-BK-STK"			
NB13674001	NO						
NB13714001	NO						
NB14124001	NO						
NB14134001	NO			"VERSAFIT-1/2-0-SP"			
NB14164001	NO						
NB14244001	NO						
NB14254001	NO						
NB14284001	NO			"VERSAFIT-1-0-SP."			
NB14354001	NO			"VERSAFIT-3/4-0-FSP"			
NB14374001	NO						
NB14474001	NO						
NB14494001	NO						
NB14614001	NO						
NB16924001	NO						
NB16934001	NO			"VERSAFIT-3/64-0-SP"			
NB17434001	NO						
NB17694001	NO						
NB17754001	NO						
NB17914001	NO						
NB17932001	NO			"RNF-100-1-1/2-BK-STK"			
NB18044001	NO						
NB18442001	NO			"RNF-100-4-BK-STK"			
NB18742001	NO			"RNF-100-1/16-BK-STK"			
NB18844001	NO						
NB18902001	NO						
NB18964001	NO						
NB19014001	NO						
NB19044001	NO						
NB19084001	NO						
NB19144001	NO						
NB19162001	NO		M23053/5-104-0(A)	"RNF-100-1/8-BK-STK"			
NB19202001	NO						
NB19284001	NO						
NB19304001	NO						
NB19312001	NO						
NB19324001	NO						
NB19334001	NO						
NB19414001	NO						
NB19564001	NO						
NB19642001	NO			"RNF-100-3/32-BK-STK"			
NB19914001	NO			"VERSAFIT-1/16-0-SP"			
NB19994001	NO						
NB20014001	NO						
NB20034001	NO						
NB20164001	NO			"VERSAFIT-1/8-0-SP"			
NB20274001	NO						
NB20364001	NO						
NB20374001	NO						
NB20384001	NO						
NB20394001	NO						
NB20424001	NO			"VERSAFIT-3/32-0-SP"			
NB20504001	NO						
NB21094001	NO			"RNF-100-1/4-VT-SP"			
NB23344001	NO						

Customer: Heilind Asia Pacific (Hong Kong) (2991513) **Location:** Hong Kong **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5052994173	NO			"3-1193833-0", "RNF-100-1/8-BK-SP", "RNF-100-1/8-0"			
5053094268	NO			"4-1193845-5", "RNF-100-1/4-BK-SP"			
NB13504001	NO						
NB19974001	NO						
NB20234001	NO						
NB20274001	NO						

Customer: Heilind Asia Pacific (SG) Pte Ltd (2980456) **Location:** Singapore **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5052844058	NO			"RNF-100-3/64-BK-SP", "1642451-1"			
5052894108	NO			"RNF-100-1/16-BK-SP", "1642242-2"			
5052994173	NO			"3-1193833-0", "RNF-100-1/8-BK-SP", "RNF-100-1/8-0"			
5053044177	NO			"RNF-100-3/16-BK-SP", "RNF-100-3/16-0", "1832174-1"			
5053094268	NO			"4-1193845-5", "RNF-100-1/4-BK-SP"			
NB19162001	NO		M23053/5-104-0(A)	"RNF-100-1/8-BK-STK"			
NB19564001	NO						
NB20274001	NO						
NB20424001	NO			"VERSAFIT-3/32-0-SP"			
NB20424001	NO			"VERSAFIT-3/32-0-SP"			