# Product Change Notification

Current Date: 19-Oct-2026

## TE Connectivity

**Product Change Notification:** PCN-26-293771 **PCN Date:** 13-OCT-26

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

| **Product Description:** (Text limited to 120 characters) |
|---|
| RNF-100 (Black and Colored Versions) VERSAFIT RP-4800 |

| **General Description of Changes** |
|---|
| Reinstatement of Mil-Spec qualification for selected TE Connectivity heat-shrink tubing products specifically RNF-100 (Black and Colored), VERSAFIT, and RP-4800 following NAVAIR approval of a supplier-directed manufacturing location change. This PCN serves as an update to PCN-26-283716, which had communicated a temporary suspension of Mil-Spec approvals. There is no change to the form, fit, or function (FFF) of the affected products.Note: CRN (Black) and TAT-125 remain on hold under a separate restriction (PCN-26-283718) related to China-origin raw materials, which is addressed independently.<br>**Other attachments:**<br>Cross reference sheet<br>PCN wording file |

| **Reason for Changes:** |
|---|
| The temporary Mil-Spec restriction was imposed due to a supplier-directed manufacturing location change that required formal regulatory review before Mil-Spec qualified production and shipments will resume. NAVAIR has reviewed and approved the manufacturing location change, enabling the reinstatement of Mil-Spec certification for the three affected product families. |

| **PCN Attributes:** | |
|---|---|
| **Product Category:** | **Kind of Change:** |
| Heat Shrink Tubing | Agency Approvals |
| **Change Feature:** | **Potential Customer Impact:** |
| No Feature Change | No Customer Impact |
| **Remarks:** | |

| **Estimated Dates:** | |
|---|---|
| **Last Order Date** (Obsolete Parts Only): | **First Ship Date of Changed Items** (Changed Parts Only): |
| | 26-OCT-2026 |
| **Last Ship Date of Changed Items** (Obsolete Parts Only): | **Last Date for Mixed Shipments:** (Changed Parts Only): |
| | No Mixed Shipments |
| **Effectivity Date:** | **Date of First Samples:** |
| 14-OCT-2026 | |

**Part Number(s) being Modified:**

| Part Number | Part Discontinued per PCN | Customer Drawing | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference | Distributed PCN(s) |
|---|---|---|---|---|---|---|---|
| 5052844058 | NO | | 1642451-1, **RNF-100-3/64-BK-SP** | | | | No Data Found |
| 5052894108 | NO | | 1642242-2, **RNF-100-1/16-BK-SP** | | | | No Data Found |
| 5052944219 | NO | | 1642525-1, **RNF-100-3/32-BK-SP** | | | | No Data Found |
| 5052994173 | NO | | 3-1193833-0,,RNF-100-1/8-0, **RNF-100-1/8-BK-SP** | | | | No Data Found |
| 5053044177 | NO | | RNF-100-3/16-0,1832174-1, **RNF-100-3/16-BK-SP** | | | | No Data Found |
| 5053094268 | NO | | 4-1193845-5, **RNF-100-1/4-BK-SP** | | | | No Data Found |
| EL88662001 | NO | | 1899841-1, **PROV-VERSAFIT-1/16-0-STK** | | | | No Data Found |
| EL88702001 | NO | | 1899841-2, **PROV-VERSAFIT-1/2-0-STK** | | | | No Data Found |

| Part Number | Part Discontinued per PCN | Customer Drawing | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference | Distributed PCN(s) |
|---|---|---|---|---|---|---|---|
| EL88812001 | NO | | 1899841-3, **PROV-VERSAFIT-3/4-0-STK** | | | | No Data Found |
| EL88842001 | NO | | "1899841-4" | | | | No Data Found |
| EL88852001 | NO | | 1899841-5, **PROV-VERSAFIT-1/8-0-STK** | | | | No Data Found |
| EL89012001 | NO | | 1899841-6, **PROV-VERSAFIT-1-0-STK** | | | | No Data Found |
| EL89072001 | NO | | 1899841-7, **PROV-VERSAFIT-1-1/2-0-STK** | | | | No Data Found |
| EL91042001 | NO | | "1-1899841-5" | | | | No Data Found |
| EL91192001 | NO | | 1-1899841-6, **VERSAFIT-3/32-0-STK** | | | | No Data Found |
| EL91232001 | NO | | 1-1899841-8, **PROV-VERSAFIT-3/64-0-STK** | | | | No Data Found |
| EL91262001 | NO | | 1-1899841-9, **VERSAFIT-3/8-0-STK** | | | | No Data Found |
| EL93092001 | NO | | 2-1899841-6, **PROV-VERSAFIT-1/16-9-STK** | | | | No Data Found |
| EL93192001 | NO | | 2-1899841-7, **PROV-VERSAFIT-3/32-9-STK** | | | | No Data Found |
| EL93212001 | NO | | 2-1899841-8, **PROV-VERSAFIT-1/8-9-STK** | | | | No Data Found |
| EL93382001 | NO | | 3-1899841-0, **PROV-VERSAFIT-3/16-9-STK** | | | | No Data Found |
| EL93462001 | NO | | 3-1899841-1, **PROV-VERSAFIT-1/4-9-STK** | | | | No Data Found |
| EL93502001 | NO | | 3-1899841-2, **PROV-VERSAFIT-1/2-9-STK** | | | | No Data Found |
| EL93562001 | NO | | 3-1899841-3, **PROV-VERSAFIT-3/4-9-STK** | | | | No Data Found |
| EL93762001 | NO | | 3-1899841-7, **PROV-VERSAFIT-1/2-2-STK** | | | | No Data Found |
| EL93772001 | NO | | 3-1899841-8, **VERSAFIT-1/4-2-STK** | | | | No Data Found |
| EL93902001 | NO | | 4-1899841-0, **PROV-VERSAFIT-1/8-2-STK** | | | | No Data Found |
| EL93922001 | NO | | 4-1899841-1, **PROV-VERSAFIT-1/8-6-STK** | | | | No Data Found |
| EL93932001 | NO | | 4-1899841-2, **PROV-VERSAFIT-3/16-2-STK** | | | | No Data Found |
| EL93942001 | NO | | **PROV-VERSAFIT-3/16-6-STK** | | | | No Data Found |
| EL94712001 | NO | | 4-1899841-4, **PROV-VERSAFIT-3/32-2-STK** | | | | No Data Found |
| EL94782001 | NO | | 4-1899841-5, **PROV-VERSAFIT-3/4-2-STK** | | | | No Data Found |
| EL95122001 | NO | | 4-1899841-8, **PROV-VERSAFIT-1/2-4-STK** | | | | No Data Found |
| EL95132001 | NO | | 4-1899841-9, **PROV-VERSAFIT-1/8-4-STK** | | | | No Data Found |
| EL95182001 | NO | | 5-1899841-0, **PROV-VERSAFIT-3/16-4-STK** | | | | No Data Found |
| EL95202001 | NO | | 5-1899841-2, **PROV-VERSAFIT-3/8-4-STK** | | | | No Data Found |
| EL97494001 | NO | | 6-1899841-1, **VERSAFIT-3/64-1-SP** | | | | No Data Found |
| EM69614001 | NO | | 7-1899845-7, **VERSAFIT-3/16-7-SP** | | | | No Data Found |
| EP43874001 | NO | | | | | | No Data Found |
| EP62634001 | NO | | | | | | No Data Found |
| EP63242001 | NO | | **VERSAFIT-2-4-STK** | | | | No Data Found |
| EP83974001 | NO | | **RP-4800-NO.4-3-SP** | | | | No Data Found |
| EP87694001 | NO | | | | | | No Data Found |
| ER54184001 | NO | | | | | | No Data Found |
| ER62274001 | NO | | | | | | No Data Found |
| ES10092001 | NO | | **RP-4800-NO.7-4-STK** | | | | No Data Found |
| ES10932001 | NO | | **RP-4800-NO.7-9-STK** | | | | No Data Found |

| Part Number | Part Discontinued per PCN | Customer Drawing | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference | Distributed PCN(s) |
|---|---|---|---|---|---|---|---|
| ES10942001 | NO | | | | | | No Data Found |
| ES88634001 | NO | | | | | | No Data Found |
| NB12724001 | NO | | | | | | No Data Found |
| NB12744001 | NO | | | | | | No Data Found |
| NB12762001 | NO | | **RNF-100-1/2-BK-STK** | | | | No Data Found |
| NB12784001 | NO | | | | | | No Data Found |
| NB12794001 | NO | | | | | | No Data Found |
| NB12802001 | NO | | **RNF-100-1/2-BU-STK** | | | | No Data Found |
| NB12854001 | NO | | | | | | No Data Found |
| NB12864001 | NO | | | | | | No Data Found |
| NB12872001 | NO | | | | | | No Data Found |
| NB12884001 | NO | | | | | | No Data Found |
| NB12892001 | NO | | | | | | No Data Found |
| NB12904001 | NO | | | | | | No Data Found |
| NB12924001 | NO | | | | | | No Data Found |
| NB12932001 | NO | | **RNF-100-1/2-RD-STK** | | | | No Data Found |
| NB12944001 | NO | | | | | | No Data Found |
| NB12964001 | NO | | | | | | No Data Found |
| NB12982001 | NO | | | | | | No Data Found |
| NB12994001 | NO | | | | | | No Data Found |
| NB13004001 | NO | | | | | | No Data Found |
| NB13012001 | NO | | **RNF-100-1/2-YO-STK** | | | | No Data Found |
| NB13034001 | NO | | | | | | No Data Found |
| NB13044001 | NO | | | | | | No Data Found |
| NB13052001 | NO | | **RNF-100-1-BK-STK** | | | | No Data Found |
| NB13084001 | NO | | | | | | No Data Found |
| NB13094001 | NO | | | | | | No Data Found |
| NB13102001 | NO | | **RNF-100-1-BU-STK** | | | | No Data Found |
| NB13144001 | NO | | | | | | No Data Found |
| NB13152001 | NO | | | | | | No Data Found |
| NB13162001 | NO | | | | | | No Data Found |
| NB13174001 | NO | | | | | | No Data Found |
| NB13184001 | NO | | | | | | No Data Found |
| NB13192001 | NO | | | | | | No Data Found |
| NB13204001 | NO | | | | | | No Data Found |
| NB13214001 | NO | | | | | | No Data Found |
| NB13222001 | NO | | | | | | No Data Found |
| NB13234001 | NO | | | | | | No Data Found |
| NB13244001 | NO | | | | | | No Data Found |
| NB13252001 | NO | | | | | | No Data Found |
| NB13264001 | NO | | | | | | No Data Found |
| NB13274001 | NO | | | | | | No Data Found |
| NB13282001 | NO | | **RNF-100-3/4-BK-STK** | | | | No Data Found |
| NB13304001 | NO | | | | | | No Data Found |
| NB13314001 | NO | | | | | | No Data Found |
| NB13322001 | NO | | | | | | No Data Found |
| NB13374001 | NO | | | | | | No Data Found |
| NB13382001 | NO | | | | | | No Data Found |
| NB13392001 | NO | | | | | | No Data Found |
| NB13404001 | NO | | | | | | No Data Found |
| NB13414001 | NO | | | | | | No Data Found |
| NB13422001 | NO | | **RNF-100-3/4-RD-STK** | | | | No Data Found |
| NB13434001 | NO | | | | | | No Data Found |
| NB13444001 | NO | | | | | | No Data Found |
| NB13462001 | NO | | **RNF-100-3/4-WH-STK** | | | | No Data Found |
| NB13484001 | NO | | | | | | No Data Found |
| NB13492001 | NO | | | | | | No Data Found |
| NB13504001 | NO | | | | | | No Data Found |
| NB13524001 | NO | | | | | | No Data Found |
| NB13542001 | NO | | **RNF-100-3/8-BK-STK** | | | | No Data Found |
| NB13564001 | NO | | | | | | No Data Found |
| NB13574001 | NO | | | | | | No Data Found |
| NB13582001 | NO | | | | | | No Data Found |
| NB13624001 | NO | | | | | | No Data Found |
| NB13634001 | NO | | | | | | No Data Found |

| Part Number | Part Discontinued per PCN | Customer Drawing | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference | Distributed PCN(s) |
|---|---|---|---|---|---|---|---|
| NB13642001 | NO | | | | | | No Data Found |
| NB13654001 | NO | | | | | | No Data Found |
| NB13664001 | NO | | | | | | No Data Found |
| NB13674001 | NO | | | | | | No Data Found |
| NB13684001 | NO | | | | | | No Data Found |
| NB13692001 | NO | | **RNF-100-3/8-RD-STK** | | | | No Data Found |
| NB13704001 | NO | | | | | | No Data Found |
| NB13714001 | NO | | | | | | No Data Found |
| NB13724001 | NO | | | | | | No Data Found |
| NB13742001 | NO | | | | | | No Data Found |
| NB13754001 | NO | | | | | | No Data Found |
| NB13764001 | NO | | | | | | No Data Found |
| NB13772001 | NO | | | | | | No Data Found |
| NB14124001 | NO | | | | | | No Data Found |
| NB14134001 | NO | | "VERSAFIT-1/2-0-SP" | | | | No Data Found |
| NB14154001 | NO | | | | | | No Data Found |
| NB14164001 | NO | | | | | | No Data Found |
| NB14174001 | NO | | | | | | No Data Found |
| NB14184001 | NO | | | | | | No Data Found |
| NB14194001 | NO | | | | | | No Data Found |
| NB14204001 | NO | | | | | | No Data Found |
| NB14214001 | NO | | | | | | No Data Found |
| NB14224001 | NO | | | | | | No Data Found |
| NB14234001 | NO | | | | | | No Data Found |
| NB14244001 | NO | | | | | | No Data Found |
| NB14254001 | NO | | | | | | No Data Found |
| NB14284001 | NO | | **VERSAFIT-1-0-SP.** | | | | No Data Found |
| NB14304001 | NO | | | | | | No Data Found |
| NB14314001 | NO | | | | | | No Data Found |
| NB14324001 | NO | | | | | | No Data Found |
| NB14344001 | NO | | | | | | No Data Found |
| NB14354001 | NO | | **VERSAFIT-3/4-0-FSP** | | | | No Data Found |
| NB14374001 | NO | | | | | | No Data Found |
| NB14394001 | NO | | | | | | No Data Found |
| NB14404001 | NO | | | | | | No Data Found |
| NB14414001 | NO | | | | | | No Data Found |
| NB14424001 | NO | | | | | | No Data Found |
| NB14434001 | NO | | | | | | No Data Found |
| NB14444001 | NO | | | | | | No Data Found |
| NB14454001 | NO | | | | | | No Data Found |
| NB14474001 | NO | | | | | | No Data Found |
| NB14494001 | NO | | | | | | No Data Found |
| NB14514001 | NO | | | | | | No Data Found |
| NB14524001 | NO | | | | | | No Data Found |
| NB14534001 | NO | | | | | | No Data Found |
| NB14544001 | NO | | | | | | No Data Found |
| NB14554001 | NO | | | | | | No Data Found |
| NB14564001 | NO | | | | | | No Data Found |
| NB14584001 | NO | | | | | | No Data Found |
| NB14594001 | NO | | | | | | No Data Found |
| NB14604001 | NO | | | | | | No Data Found |
| NB14614001 | NO | | | | | | No Data Found |
| NB14622001 | NO | | | | | | No Data Found |
| NB15004001 | NO | | | | | | No Data Found |
| NB15014001 | NO | | | | | | No Data Found |
| NB15224001 | NO | | | | | | No Data Found |
| NB15492001 | NO | | **RNF-100-3/64-BK-STK** | | | | No Data Found |
| NB15504001 | NO | | | | | | No Data Found |
| NB15512001 | NO | | | | | | No Data Found |
| NB15542001 | NO | | | | | | No Data Found |
| NB15554001 | NO | | | | | | No Data Found |
| NB15562001 | NO | | | | | | No Data Found |
| NB15574001 | NO | | | | | | No Data Found |
| NB15592001 | NO | | **RNF-100-3/64-WH-STK** | | | | No Data Found |
| NB15604001 | NO | | | | | | No Data Found |

| Part Number | Part Discontinued per PCN | Customer Drawing | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference | Distributed PCN(s) |
|---|---|---|---|---|---|---|---|
| NB15612001 | NO | | | | | | No Data Found |
| NB16924001 | NO | | | | | | No Data Found |
| NB16934001 | NO | | **VERSAFIT-3/64-0-SP** | | | | No Data Found |
| NB16964001 | NO | | | | | | No Data Found |
| NB16974001 | NO | | | | | | No Data Found |
| NB16984001 | NO | | | | | | No Data Found |
| NB16994001 | NO | | | | | | No Data Found |
| NB17304001 | NO | | | | | | No Data Found |
| NB17312001 | NO | | **RP-4800-NO.1-0-STK** | | | | No Data Found |
| NB17364001 | NO | | 9-1899847-8**, RP-4800-NO.2-0-SP** | | | | No Data Found |
| NB17372001 | NO | | **RP-4800-NO.2-0-STK** | | | | No Data Found |
| NB17384001 | NO | | | | | | No Data Found |
| NB17394001 | NO | | **RP-4800-NO.3-0-SP** | | | | No Data Found |
| NB17402001 | NO | | **RP-4800-NO.3-0-STK** | | | | No Data Found |
| NB17414001 | NO | | **RP-4800-NO.4-0-SP** | | | | No Data Found |
| NB17422001 | NO | | **RP-4800-NO.4-0-STK** | | | | No Data Found |
| NB17434001 | NO | | | | | | No Data Found |
| NB17444001 | NO | | | | | | No Data Found |
| NB17452001 | NO | | | | | | No Data Found |
| NB17464001 | NO | | | | | | No Data Found |
| NB17474001 | NO | | | | | | No Data Found |
| NB17482001 | NO | | | | | | No Data Found |
| NB17494001 | NO | | | | | | No Data Found |
| NB17504001 | NO | | | | | | No Data Found |
| NB17512001 | NO | | | | | | No Data Found |
| NB17524001 | NO | | **RP-4800-NO.9-9-SP** | | | | No Data Found |
| NB17694001 | NO | | | | | | No Data Found |
| NB17704001 | NO | | | | | | No Data Found |
| NB17714001 | NO | | | | | | No Data Found |
| NB17724001 | NO | | | | | | No Data Found |
| NB17734001 | NO | | | | | | No Data Found |
| NB17754001 | NO | | | | | | No Data Found |
| NB17774001 | NO | | | | | | No Data Found |
| NB17784001 | NO | | | | | | No Data Found |
| NB17794001 | NO | | | | | | No Data Found |
| NB17804001 | NO | | | | | | No Data Found |
| NB17814001 | NO | | | | | | No Data Found |
| NB17824001 | NO | | | | | | No Data Found |
| NB17914001 | NO | | | | | | No Data Found |
| NB17924001 | NO | | | | | | No Data Found |
| NB17932001 | NO | | **RNF-100-1-1/2-BK-STK** | | | | No Data Found |
| NB17942001 | NO | | | | | | No Data Found |
| NB17954001 | NO | | | | | | No Data Found |
| NB17962001 | NO | | **RNF-100-1-1/2-BU-STK** | | | | No Data Found |
| NB17994001 | NO | | | | | | No Data Found |
| NB18002001 | NO | | | | | | No Data Found |
| NB18014001 | NO | | | | | | No Data Found |
| NB18022001 | NO | | | | | | No Data Found |
| NB18034001 | NO | | | | | | No Data Found |
| NB18044001 | NO | | | | | | No Data Found |
| NB18052001 | NO | | | | | | No Data Found |
| NB18064001 | NO | | | | | | No Data Found |
| NB18072001 | NO | | **RNF-100-1-1/2-YO-STK** | | | | No Data Found |
| NB18144001 | NO | | | | | | No Data Found |
| NB18162001 | NO | | **RNF-100-2-BK-STK** | | | | No Data Found |
| NB18174001 | NO | | | | | | No Data Found |
| NB18182001 | NO | | | | | | No Data Found |
| NB18204001 | NO | | | | | | No Data Found |
| NB18214001 | NO | | | | | | No Data Found |
| NB18222001 | NO | | | | | | No Data Found |
| NB18234001 | NO | | | | | | No Data Found |
| NB18242001 | NO | | | | | | No Data Found |
| NB18254001 | NO | | | | | | No Data Found |
| NB18262001 | NO | | | | | | No Data Found |

| Part Number | Part Discontinued per PCN | Customer Drawing | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference | Distributed PCN(s) |
|---|---|---|---|---|---|---|---|
| NB18274001 | NO | | | | | | No Data Found |
| NB18284001 | NO | | | | | | No Data Found |
| NB18302001 | NO | | | | | | No Data Found |
| NB18334001 | NO | | | | | | No Data Found |
| NB18342001 | NO | | | | | | No Data Found |
| NB18372001 | NO | | | | | | No Data Found |
| NB18384001 | NO | | | | | | No Data Found |
| NB18392001 | NO | | | | | | No Data Found |
| NB18404001 | NO | | | | | | No Data Found |
| NB18412001 | NO | | | | | | No Data Found |
| NB18424001 | NO | | | | | | No Data Found |
| NB18434001 | NO | | | | | | No Data Found |
| NB18442001 | NO | | **RNF-100-4-BK-STK** | | | | No Data Found |
| NB18462001 | NO | | | | | | No Data Found |
| NB18742001 | NO | | **RNF-100-1/16-BK-STK** | | | | No Data Found |
| NB18752001 | NO | | | | | | No Data Found |
| NB18764001 | NO | | | | | | No Data Found |
| NB18772001 | NO | | | | | | No Data Found |
| NB18804001 | NO | | | | | | No Data Found |
| NB18812001 | NO | | | | | | No Data Found |
| NB18824001 | NO | | | | | | No Data Found |
| NB18832001 | NO | | | | | | No Data Found |
| NB18844001 | NO | | | | | | No Data Found |
| NB18852001 | NO | | **RNF-100-1/16-RD-STK** | | | | No Data Found |
| NB18864001 | NO | | | | | | No Data Found |
| NB18872001 | NO | | | | | | No Data Found |
| NB18884001 | NO | | | | | | No Data Found |
| NB18902001 | NO | | | | | | No Data Found |
| NB18914001 | NO | | | | | | No Data Found |
| NB18922001 | NO | | | | | | No Data Found |
| NB18932001 | NO | | **RNF-100-1/4-BK-STK** | | | | No Data Found |
| NB18954001 | NO | | | | | | No Data Found |
| NB18964001 | NO | | | | | | No Data Found |
| NB18972001 | NO | | | | | | No Data Found |
| NB19014001 | NO | | | | | | No Data Found |
| NB19022001 | NO | | | | | | No Data Found |
| NB19044001 | NO | | | | | | No Data Found |
| NB19062001 | NO | | | | | | No Data Found |
| NB19084001 | NO | | | | | | No Data Found |
| NB19112001 | NO | | | | | | No Data Found |
| NB19144001 | NO | | | | | | No Data Found |
| NB19152001 | NO | | **RNF-100-1/4-YO-STK** | | | | No Data Found |
| NB19162001 | NO | | **RNF-100-1/8-BK-STK** | | | | No Data Found |
| NB19174001 | NO | | | | | | No Data Found |
| NB19182001 | NO | | | | | | No Data Found |
| NB19194001 | NO | | | | | | No Data Found |
| NB19202001 | NO | | | | | | No Data Found |
| NB19254001 | NO | | | | | | No Data Found |
| NB19262001 | NO | | | | | | No Data Found |
| NB19274001 | NO | | | | | | No Data Found |
| NB19284001 | NO | | | | | | No Data Found |
| NB19292001 | NO | | | | | | No Data Found |
| NB19304001 | NO | | | | | | No Data Found |
| NB19312001 | NO | | | | | | No Data Found |
| NB19324001 | NO | | | | | | No Data Found |
| NB19334001 | NO | | | | | | No Data Found |
| NB19352001 | NO | | | | | | No Data Found |
| NB19374001 | NO | | | | | | No Data Found |
| NB19382001 | NO | | | | | | No Data Found |
| NB19392001 | NO | | **RNF-100-3/16-BK-STK** | | | | No Data Found |
| NB19402001 | NO | | | | | | No Data Found |
| NB19414001 | NO | | | | | | No Data Found |
| NB19432001 | NO | | **RNF-100-3/16-BU-STK** | | | | No Data Found |
| NB19484001 | NO | | | | | | No Data Found |
| NB19492001 | NO | | | | | | No Data Found |

| Part Number | Part Discontinued per PCN | Customer Drawing | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference | Distributed PCN(s) |
|---|---|---|---|---|---|---|---|
| NB19504001 | NO | | | | | | No Data Found |
| NB19512001 | NO | | | | | | No Data Found |
| NB19524001 | NO | | | | | | No Data Found |
| NB19534001 | NO | | | | | | No Data Found |
| NB19542001 | NO | | | | | | No Data Found |
| NB19554001 | NO | | | | | | No Data Found |
| NB19564001 | NO | | | | | | No Data Found |
| NB19592001 | NO | | | | | | No Data Found |
| NB19604001 | NO | | | | | | No Data Found |
| NB19612001 | NO | | | | | | No Data Found |
| NB19642001 | NO | | **RNF-100-3/32-BK-STK** | | | | No Data Found |
| NB19652001 | NO | | | | | | No Data Found |
| NB19664001 | NO | | | | | | No Data Found |
| NB19672001 | NO | | | | | | No Data Found |
| NB19714001 | NO | | | | | | No Data Found |
| NB19722001 | NO | | | | | | No Data Found |
| NB19732001 | NO | | | | | | No Data Found |
| NB19744001 | NO | | | | | | No Data Found |
| NB19752001 | NO | | | | | | No Data Found |
| NB19762001 | NO | | | | | | No Data Found |
| NB19774001 | NO | | | | | | No Data Found |
| NB19792001 | NO | | | | | | No Data Found |
| NB19814001 | NO | | | | | | No Data Found |
| NB19832001 | NO | | | | | | No Data Found |
| NB19914001 | NO | | **VERSAFIT-1/16-0-SP** | | | | No Data Found |
| NB19954001 | NO | | | | | | No Data Found |
| NB19964001 | NO | | | | | | No Data Found |
| NB19974001 | NO | | | | | | No Data Found |
| NB19984001 | NO | | | | | | No Data Found |
| NB19994001 | NO | | | | | | No Data Found |
| NB20004001 | NO | | | | | | No Data Found |
| NB20014001 | NO | | | | | | No Data Found |
| NB20034001 | NO | | | | | | No Data Found |
| NB20074001 | NO | | | | | | No Data Found |
| NB20084001 | NO | | | | | | No Data Found |
| NB20094001 | NO | | | | | | No Data Found |
| NB20114001 | NO | | | | | | No Data Found |
| NB20124001 | NO | | | | | | No Data Found |
| NB20144001 | NO | | | | | | No Data Found |
| NB20164001 | NO | | **VERSAFIT-1/8-0-SP** | | | | No Data Found |
| NB20204001 | NO | | | | | | No Data Found |
| NB20214001 | NO | | | | | | No Data Found |
| NB20224001 | NO | | | | | | No Data Found |
| NB20234001 | NO | | | | | | No Data Found |
| NB20244001 | NO | | | | | | No Data Found |
| NB20274001 | NO | | | | | | No Data Found |
| NB20334001 | NO | | | | | | No Data Found |
| NB20344001 | NO | | | | | | No Data Found |
| NB20354001 | NO | | | | | | No Data Found |
| NB20364001 | NO | | | | | | No Data Found |
| NB20374001 | NO | | | | | | No Data Found |
| NB20384001 | NO | | | | | | No Data Found |
| NB20394001 | NO | | | | | | No Data Found |
| NB20424001 | NO | | **VERSAFIT-3/32-0-SP** | | | | No Data Found |
| NB20464001 | NO | | | | | | No Data Found |
| NB20474001 | NO | | | | | | No Data Found |
| NB20484001 | NO | | | | | | No Data Found |
| NB20494001 | NO | | | | | | No Data Found |
| NB20504001 | NO | | | | | | No Data Found |
| NB20554001 | NO | | | | | | No Data Found |
| NB20594001 | NO | | | | | | No Data Found |
| NB20774001 | NO | | | | | | No Data Found |
| NB20782001 | NO | | | | | | No Data Found |
| NB20844001 | NO | | | | | | No Data Found |
| NB20952001 | NO | | | | | | No Data Found |

| Part Number | Part Discontinued per PCN | Customer Drawing | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference | Distributed PCN(s) |
|---|---|---|---|---|---|---|---|
| NB21024001 | NO | | | | | | No Data Found |
| NB21032001 | NO | | | | | | No Data Found |
| NB21044001 | NO | | | | | | No Data Found |
| NB21052001 | NO | | | | | | No Data Found |
| NB21094001 | NO | | **RNF-100-1/4-VT-SP** | | | | No Data Found |
| NB21112001 | NO | | | | | | No Data Found |
| NB21302001 | NO | | | | | | No Data Found |
| NB21342001 | NO | | | | | | No Data Found |
| NB21454001 | NO | | | | | | No Data Found |
| NB21484001 | NO | | | | | | No Data Found |
| NB21622001 | NO | | | | | | No Data Found |
| NB21704001 | NO | | | | | | No Data Found |
| NB21852001 | NO | | | | | | No Data Found |
| NB21874001 | NO | | | | | | No Data Found |
| NB21924001 | NO | | | | | | No Data Found |
| NB21972001 | NO | | | | | | No Data Found |
| NB22032001 | NO | | | | | | No Data Found |
| NB22134001 | NO | | | | | | No Data Found |
| NB22204001 | NO | | | | | | No Data Found |
| NB22214001 | NO | | | | | | No Data Found |
| NB22232001 | NO | | | | | | No Data Found |
| NB22254001 | NO | | | | | | No Data Found |
| NB22404001 | NO | | | | | | No Data Found |
| NB22412001 | NO | | | | | | No Data Found |
| NB22474001 | NO | | | | | | No Data Found |
| NB22524001 | NO | | | | | | No Data Found |
| NB22532001 | NO | | | | | | No Data Found |
| NB22574001 | NO | | | | | | No Data Found |
| NB22582001 | NO | | | | | | No Data Found |
| NB22594001 | NO | | | | | | No Data Found |
| NB22614001 | NO | | | | | | No Data Found |
| NB22622001 | NO | | | | | | No Data Found |
| NB22764001 | NO | | | | | | No Data Found |
| NB23054001 | NO | | | | | | No Data Found |
| NB23062001 | NO | | | | | | No Data Found |
| NB23114001 | NO | | | | | | No Data Found |
| NB23144001 | NO | | | | | | No Data Found |
| NB23152001 | NO | | | | | | No Data Found |
| NB23164001 | NO | | | | | | No Data Found |
| NB23174001 | NO | | **VERSAFIT-1/16-1-SP** | | | | No Data Found |
| NB23244001 | NO | | | | | | No Data Found |
| NB23274001 | NO | | | | | | No Data Found |
| NB23284001 | NO | | | | | | No Data Found |
| NB23334001 | NO | | | | | | No Data Found |
| NB23344001 | NO | | | | | | No Data Found |
| NB23354001 | NO | | | | | | No Data Found |
| NB23474001 | NO | | | | | | No Data Found |
| NB23484001 | NO | | | | | | No Data Found |
| NB23494001 | NO | | | | | | No Data Found |
| NB23504001 | NO | | | | | | No Data Found |
| NB23554001 | NO | | | | | | No Data Found |
| NB23564001 | NO | | | | | | No Data Found |
| NB23574001 | NO | | | | | | No Data Found |
| NB23584001 | NO | | | | | | No Data Found |
| NB23614001 | NO | | | | | | No Data Found |
| NB23674001 | NO | | | | | | No Data Found |
| NB23744001 | NO | | | | | | No Data Found |
| NB23794001 | NO | | | | | | No Data Found |
| NB23804001 | NO | | | | | | No Data Found |
| NB23814001 | NO | | | | | | No Data Found |
| NB23834001 | NO | | | | | | No Data Found |
| NB23844001 | NO | | | | | | No Data Found |
| NB24764001 | NO | | | | | | No Data Found |
| NB24782001 | NO | | | | | | No Data Found |
| NB24802001 | NO | | | | | | No Data Found |

| Part Number | Part Discontinued per PCN | Customer Drawing | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference | Distributed PCN(s) |
|---|---|---|---|---|---|---|---|
| NB24814001 | NO | | | | | | No Data Found |
| NB24822001 | NO | | | | | | No Data Found |
| NB24884001 | NO | | | | | | No Data Found |
| NB24894001 | NO | | | | | | No Data Found |
| NB24904001 | NO | | | | | | No Data Found |
| NB24962001 | NO | | | | | | No Data Found |
| NB24972001 | NO | | | | | | No Data Found |
| NB24992001 | NO | | | | | | No Data Found |
| NB25004001 | NO | | | | | | No Data Found |
| NB25012001 | NO | | | | | | No Data Found |
| NB25054001 | NO | | | | | | No Data Found |
| NB25064001 | NO | | | | | | No Data Found |
| NB25074001 | NO | | | | | | No Data Found |
| NB25084001 | NO | | | | | | No Data Found |
| NB25094001 | NO | | | | | | No Data Found |
| NB25124001 | NO | | | | | | No Data Found |
| NB25132001 | NO | | | | | | No Data Found |
| NB29104001 | NO | | | | | | No Data Found |
| NB38762001 | NO | | **VERSAFIT-1-1/2-4-STK** | | | | No Data Found |