Product Change Notification

Current Date: 13-Nov-2026

TE Connectivity

Product Change Notification: P-26-031935 **PCN Date:** 12-NOV-26

Customer: Heilind Electronics Inc(0002135900) **Location:** WORLDWIDE **Agreement:** Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
All System 6 Heat shrink Identification sleeves

Description of Changes
Additional assembly manufacturing machines are being added to the TE Trutnov site. There is no change to fit, form, or function of the product. Manufacturing drawing and BOM is unchanged.

Reason for Changes:	
Product improvement.The additional machines are being added to increase capacity and improve customer service.	
Estimated Dates:	
Last Order Date (Obsolete Parts Only):	**First Date To Ship** (Changed Parts Only):
Last Ship Date (Obsolete Parts Only):	**Last Date for Mixed Shipments:** (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
0120930001	NO		4-1190095-9, TMS-SCE-1K-3/8-2.0-9	"4-1190095-9", "TMS-SCE-1K-3/8-2.0-9"			
0211910001	NO			"8-1190164-6", "TMS-SCE-5K-1/8-2.0-9"			
0253350001	NO			"6-1190196-0", "TMS-SCE-1K-1-2.0-9"			
0561490001	NO			"8-1190427-4", "RPS-18-12/2.0-9"			
0567590001	NO			"9-1190431-3", "TMS-SCE-3/4-2.0-9"			
1056030001	NO			"8-1190771-5", "D-SCE-1K-3.2-50-S1-4"			
1806950001	NO			"6-1191313-5", "RPS-2.5K-16-10/2.0-9"			
1845630001	NO			"1191340-2", "RPS-6-250/2.0-9"			
2866050001	NO			"7-1192170-8", "RPS-22-18/2.0-4"			
3340610001	NO			"9-1192523-5", "D-SCE-1K-9.5-50-S1-4"			
3593590001	NO			"9-1192695-7", "TMS-SCE-1/4-2.0-S1-9"			
3906690001	NO			"1-1192933-4", "TMS-SCE-1/4-2.0-4"			
4377070001	NO			"9-1193289-4", "TMS-SCE-1K-1/4-2.0-S1-9"			
4407170001	NO			"7-1193313-4", "TMS-SCE-3/32-2.0-4"			
4554650001	NO			"9-1193418-3", "TMS-SCE-1K-1/8-2.0-9"			
5101310001	NO			"1194010-2", "RPS-2.5K-18-12/2.0-S3-9"			
5134530001	NO			"1-1194034-6", "TMS-SCE-1-2.0-S1-9"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5502830001	NO			"5-1194342-6", "RPS-1K-16-10/2.0-9"			
5883010001	NO			"1194655-9", "TMS-SCE-3/16-2.0-S1-4"			
6134370001	NO			"4-1194849-3", "RPS-22-18/2.0-9"			
631354-000	NO			"4-1199205-9", "TMS-SCE-2.5K-1/4-2.0-S1-4"			
6418370001	NO			"6-1195072-6", "TMS-SCE-1/8-2.0-4"			
707112-000	NO			"8-1199190-0", "D-SCE-1K-6.4-50-S1-9"			
7278870001	NO			"1-1195688-7", "RPS-1K-18-12/2.0-9"			
7385170001	NO			"2-1195765-1", "TMS-SCE-1K-1/2-2.0-9"			
7674850001	NO			"9-1195980-4", "RPS-1K-8-4/2.0-9"			
772259-000	NO			"4-1196015-2", "D-SCE-2.5K-4.8-50-S1-4"			
8296870003	NO			"1-1196479-8", "RPS-10-2/2.0-9"			
846169-000	NO			"6-1196600-1", "TMS-SCE-1K-3/8-2.0-S1-9"			
8737350001	NO			"5-1196798-2", "RPS-1K-22-18/2.0-4"			
9262950001	NO			"1197184-4", "TMS-SCE-2.5K-1/4-2.0-S1-9"			
9422810001	NO			"5-1197295-7", "TMS-SCE-3/8-2.0-9"			
9463210001	NO			"2-1197323-9", "TMS-SCE-1K-3/4-2.0-4"			
9934510001	NO			"6-1197684-9", "HT-SCE-1K-1/8-2.0-9"			
A18003-000	NO			"9-1201131-2", "HX-SCE-1K-12.7-50-S1-4"			
A19408-000	NO			"9-1201131-6", "HX-SCE-1K-3.2-50-S1-4"			
A98991-000	NO			"7-1201132-4", "HX-SCE-1K-9.5-50-9"			
C04635-000	NO			"7-1201132-6", "HX-SCE-1K-4.8-50-S1-9"			
C32003-000	NO			"1201133-7", "HX-SCE-1K-6.4-50-S1-9"			
C50936-000	NO			"2-1201133-8", "HX-SCE-1K-25.4-50-9"			
CC0117-000	NO			"TMS-SCE-1K-3/32-2.0-6", "3-1899111-4"			
E09585-000	NO			"2-1201715-9", "TMS-SCE-1K-2-1/4-2.0-4"			
E82341-000	NO			"4-1201135-8", "HX-SCE-1K-9.5-50-SS1-9"			
E85771-000	NO			"1199984-3", "TMS-SCE-1K-1/4-2.0-6"			
EC9855-000	NO			"6-1899791-6", "ZHD-SCE-1K-6.4-50-S1-4"			
ED8414-000	NO			"2-1899632-4", "HX-SCE-0.5K-38.1-50-9"			
ET0960-000	NO						
F26167-000	NO			"9-1201135-4", "HX-SCE-1K-6.4-50-S1-4"			

Customer: Heilind Asia Pacific (SG) Pte Ltd (3076161) **Location:** Singapore **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
3906690001	NO			"1-1192933-4", "TMS-SCE-1/4-2.0-4"			
9422810001	NO			"5-1197295-7", "TMS-SCE-3/8-2.0-9"			

Customer: Interstate Connecting (3196442) **Location:** Lumberton **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
0211910001	NO			"8-1190164-6", "TMS-SCE-5K-1/8-2.0-9"			

Customer: Heilind Electronics sp z o o (3261330) **Location:** Krakow **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
0561490001	NO			"8-1190427-4", "RPS-18-12/2.0-9"			
5502830001	NO			"5-1194342-6", "RPS-1K-16-10/2.0-9"			

Customer: Heilind Asia Pacific (SG) Pte Ltd (3076161) **Location:** Singapore **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
3906690001	NO			"1-1192933-4", "TMS-SCE-1/4-2.0-4"			
9422810001	NO			"5-1197295-7", "TMS-SCE-3/8-2.0-9"			

Customer: Heilind Asia Pacific (3133470) **Location:** Shanghai **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1056030001	NO			"8-1190771-5", "D-SCE-1K-3.2-50-S1-4"			
772259-000	NO			"4-1196015-2", "D-SCE-2.5K-4.8-50-S1-4"			

Customer: Interstate Connecting (731279) **Location:** Lumberton **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
0211910001	NO			"8-1190164-6", "TMS-SCE-5K-1/8-2.0-9"			
3906690001	NO			"1-1192933-4", "TMS-SCE-1/4-2.0-4"			

Customer: Trek Connect Inc (155622) **Location:** Lumberton **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
3906690001	NO			"1-1192933-4", "TMS-SCE-1/4-2.0-4"			
4407170001	NO			"7-1193313-4", "TMS-SCE-3/32-2.0-4"			

Customer: Heilind Asia Pacific (Hong Kong) (2980376) **Location:** Shatin, N.t. **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
9422810001	NO			"5-1197295-7", "TMS-SCE-3/8-2.0-9"			
A98991-000	NO			"7-1201132-4", "HX-SCE-1K-9.5-50-9"			

Customer: Heilind Asia Pacific (3229127) **Location:** Suzhou **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1056030001	NO			"8-1190771-5", "D-SCE-1K-3.2-50-S1-4"			
772259-000	NO			"4-1196015-2", "D-SCE-2.5K-4.8-50-S1-4"			

Customer: Heilind Electronics GmbH (113007) **Location:** Bruckmühl **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
3593590001	NO			"9-1192695-7", "TMS-SCE-1/4-2.0-S1-9"			
4407170001	NO			"7-1193313-4", "TMS-SCE-3/32-2.0-4"			
6418370001	NO			"6-1195072-6", "TMS-SCE-1/8-2.0-4"			
8737350001	NO			"5-1196798-2", "RPS-1K-22-18/2.0-4"			
EC9855-000	NO			"6-1899791-6", "ZHD-SCE-1K-6.4-50-S1-4"			

Customer: Heilind Electronics GmbH (3497140) **Location:** Hanau **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
3593590001	NO			"9-1192695-7", "TMS-SCE-1/4-2.0-S1-9"			
4407170001	NO			"7-1193313-4", "TMS-SCE-3/32-2.0-4"			
6418370001	NO			"6-1195072-6", "TMS-SCE-1/8-2.0-4"			
8737350001	NO			"5-1196798-2", "RPS-1K-22-18/2.0-4"			
EC9855-000	NO			"6-1899791-6", "ZHD-SCE-1K-6.4-50-S1-4"			

Customer: Heilind Electronics sp z o o (3428049) **Location:** Myslowice **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5502830001	NO			"5-1194342-6", "RPS-1K-16-10/2.0-9"			

Customer: Heilind Electronics Inc (167811) **Location:** Wilmington **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
0120930001	NO		4-1190095-9, TMS-SCE-1K-3/8-2.0-9	"4-1190095-9", "TMS-SCE-1K-3/8-2.0-9"			
0253350001	NO			"6-1190196-0", "TMS-SCE-1K-1-2.0-9"			
0561490001	NO			"8-1190427-4", "RPS-18-12/2.0-9"			
0567590001	NO			"9-1190431-3", "TMS-SCE-3/4-2.0-9"			
1056030001	NO			"8-1190771-5", "D-SCE-1K-3.2-50-S1-4"			
1806950001	NO			"6-1191313-5", "RPS-2.5K-16-10/2.0-9"			
1845630001	NO			"1191340-2", "RPS-6-250/2.0-9"			
2866050001	NO			"7-1192170-8", "RPS-22-18/2.0-4"			
3340610001	NO			"9-1192523-5", "D-SCE-1K-9.5-50-S1-4"			
3906690001	NO			"1-1192933-4", "TMS-SCE-1/4-2.0-4"			
4377070001	NO			"9-1193289-4", "TMS-SCE-1K-1/4-2.0-S1-9"			
4407170001	NO			"7-1193313-4", "TMS-SCE-3/32-2.0-4"			
4554650001	NO			"9-1193418-3", "TMS-SCE-1K-1/8-2.0-9"			
5101310001	NO			"1194010-2", "RPS-2.5K-18-12/2.0-S3-9"			
5134530001	NO			"1-1194034-6", "TMS-SCE-1-2.0-S1-9"			
5502830001	NO			"5-1194342-6", "RPS-1K-16-10/2.0-9"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5883010001	NO			"1194655-9", "TMS-SCE-3/16-2.0-S1-4"			
6134370001	NO			"4-1194849-3", "RPS-22-18/2.0-9"			
631354-000	NO			"4-1199205-9", "TMS-SCE-2.5K-1/4-2.0-S1-4"			
6418370001	NO			"6-1195072-6", "TMS-SCE-1/8-2.0-4"			
707112-000	NO			"8-1199190-0", "D-SCE-1K-6.4-50-S1-9"			
7278870001	NO			"1-1195688-7", "RPS-1K-18-12/2.0-9"			
7385170001	NO			"2-1195765-1", "TMS-SCE-1K-1/2-2.0-9"			
7674850001	NO			"9-1195980-4", "RPS-1K-8-4/2.0-9"			
8296870003	NO			"1-1196479-8", "RPS-10-2/2.0-9"			
846169-000	NO			"6-1196600-1", "TMS-SCE-1K-3/8-2.0-S1-9"			
8737350001	NO			"5-1196798-2", "RPS-1K-22-18/2.0-4"			
9262950001	NO			"1197184-4", "TMS-SCE-2.5K-1/4-2.0-S1-9"			
9422810001	NO			"5-1197295-7", "TMS-SCE-3/8-2.0-9"			
9463210001	NO			"2-1197323-9", "TMS-SCE-1K-3/4-2.0-4"			
9934510001	NO			"6-1197684-9", "HT-SCE-1K-1/8-2.0-9"			
A18003-000	NO			"9-1201131-2", "HX-SCE-1K-12.7-50-S1-4"			
A19408-000	NO			"9-1201131-6", "HX-SCE-1K-3.2-50-S1-4"			
C04635-000	NO			"7-1201132-6", "HX-SCE-1K-4.8-50-S1-9"			
C32003-000	NO			"1201133-7", "HX-SCE-1K-6.4-50-S1-9"			
C50936-000	NO			"2-1201133-8", "HX-SCE-1K-25.4-50-9"			
CC0117-000	NO			"TMS-SCE-1K-3/32-2.0-6", "3-1899111-4"			
E09585-000	NO			"2-1201715-9", "TMS-SCE-1K-2-1/4-2.0-4"			
E82341-000	NO			"4-1201135-8", "HX-SCE-1K-9.5-50-SS1-9"			
E85771-000	NO			"1199984-3", "TMS-SCE-1K-1/4-2.0-6"			
ED8414-000	NO			"2-1899632-4", "HX-SCE-0.5K-38.1-50-9"			
ET0960-000	NO						
F26167-000	NO			"9-1201135-4", "HX-SCE-1K-6.4-50-S1-4"			

Customer: Heilind Asia Pacific (Hong Kong) (2991513) **Location:** Hong Kong **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
9422810001	NO			"5-1197295-7", "TMS-SCE-3/8-2.0-9"			
A98991-000	NO			"7-1201132-4", "HX-SCE-1K-9.5-50-9"			