Product Change Notification

Current Date: 13-Nov-2026

TE Connectivity

Product Change Notification: P-26-031936 **PCN Date:** 12-NOV-26

Customer: Heilind Electronics Inc(0002135900) **Location:** WORLDWIDE **Agreement:** Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
All System 6 Heat shrink Identification sleeves

Description of Changes
Additional assembly manufacturing machines are being added to the TE Trutnov site. There is no change to fit, form, or function of the product. Manufacturing drawing and BOM is unchanged.

Reason for Changes:	
Product improvement.The additional machines are being added to increase capacity and improve customer service.	
Estimated Dates:	
Last Order Date (Obsolete Parts Only):	**First Date To Ship** (Changed Parts Only):
Last Ship Date (Obsolete Parts Only):	**Last Date for Mixed Shipments:** (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
0173830001	NO			"6-1190135-6", "TMS-SCE-1K-1/8-2.0-S2-4"			
0313730001	NO			"5-1190243-4", "TMS-SCE-3/8-2.0-S1-4"			
073937-000	NO			"5-1190553-2", "D-SCE-2.5K-6.4-50-S1-4"			
0969750001	NO			"1190711-2", "TMS-SCE-1K-3/32-2.0-9"			
0981630001	NO			"6-1190718-9", "TMS-SCE-3/8-2.0-1"			
1099510001	NO			"1-1190803-1", "TMS-SCE-1K-3/16-2.0-9"			
1130910001	NO			"1-1190825-3", "TMS-SCE-1-2.0-S1-4"			
1139070001	NO			"7-1190830-7", "TMS-SCE-3/16-2.0-S2-4"			
121727-000	NO			"1190886-5", "HT-SCE-1K-3/8-2.0-9"			
1229590001	NO			"5-1190894-1", "RPS-16-10/2.0-9"			
1289310001	NO			"5-1190936-3", "TMS-SCE-1K-3/32-2.0-4"			
1505370001	NO			"3-1191088-8", "TMS-SCE-1K-1-1/2-2.0-9"			
1506550001	NO			"1-1191089-4", "TMS-SCE-3/32-2.0-S1-9"			
2290750001	NO			"6-1191684-9", "TMS-SCE-1K-1-2.0-4"			
2439450001	NO			"6-1191789-1", "RPS-1K-22-18/2.0-9"			
2861530001	NO		TMS-SCE-5K-1/8-2.0-S1-4	"5-1192167-2", "TMS-SCE-5K-1/8-2.0-S1-4"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
330433-000	NO			"7-1192496-7", "TMS-SCE-2X-1K-3/16-9"			
335781-000	NO			"2-1192536-1", "TMS-SCE-2.5K-3/16-2.0S1-4"			
3549610001	NO			"3-1192665-7", "TMS-SCE-1K-3/16-2.0-S1-9"			
397277-000	NO			"6-1192979-1", "HT-SCE-1K-3/16-2.0-9"			
3979470001	NO			"4-1192984-3", "RPS-8-4/2.0-9"			
4397130001	NO			"3-1193304-2", "TMS-SCE-1-2.0-9"			
4575670001	NO			"5-1193433-5", "TMS-SCE-1K-3/4-2.0-9"			
4589050001	NO			"6-1193442-2", "RPS-1K-8-4/2.0-S1-9"			
4785230001	NO			"1193583-3", "TMS-SCE-1/4-2.0-S1-4"			
5061850001	NO			"4-1193927-0", "TMS-SCE-1/2-2.0-9"			
5273550001	NO			"5-1194143-3", "TMS-SCE-3/16-2.0-9"			
5294130001	NO			"7-1194157-4", "TMS-SCE-3/8-2.0-4"			
5332610001	NO			"6-1194186-0", "TMS-SCE-3/16-2.0-4"			
5363690001	NO			"4-1194210-5", "TMS-SCE-2.5K-1/4-2.0-9"			
5414710001	NO			"3-1194246-8", "TMS-SCE-1-1/2-2.0-9"			
588371-000	NO			"7-1194655-7", "D-SCE-5K-3.2-50-S1-4"			
6176350001	NO			"8-1194880-6", "TMS-SCE-3/4-2.0-S1-4"			
6315830001	NO			"5-1194997-7", "TMS-SCE-3/4-2.0-4"			
6325250001	NO			"4-1195004-1", "TMS-SCE-1/2-2.0-4"			
6632750001	NO			"7-1195227-1", "TMS-SCE-3/32-2.0-9"			
6641710001	NO			"2-1195234-2", "TMS-SCE-1/4-2.0-9"			
6694470001	NO			"1195271-5", "TMS-SCE-1K-3/8-2.0-S1-4"			
6706090001	NO			"4-1195278-6", "TMS-SCE-1-1/2-2.0-4"			
7223870001	NO			"1195648-8", "TMS-SCE-1/8-2.0-S1-4"			
7474490001	NO			"8-1195830-1", "TMS-SCE-1K-1/4-2.0-9"			
8264810001	NO			"8-1196455-8", "TMS-SCE-2.5K-3/16-2.0-9"			
8350110001	NO			"8-1196518-2", "TMS-SCE-1/8-2.0-9"			
872083-000	NO			"6-1196786-9", "D-SCE-1K-25-50-4"			
8810490001	NO			"9-1196858-0", "TMS-SCE-3/8-2.0-7"			
9353250001	NO			"2-1197247-2", "RPS-16-10/2.0-4"			
9435730001	NO			"8-1197304-1", "TMS-SCE-1K-1/8-2.0-S1-9"			
9809850001	NO			"4-1197580-3", "D-SCE-1K-25-50-S1-4"			
A18880-000	NO			"9-1201131-4", "HX-SCE-1K-6.4-50-SS1-9"			
A69169-000	NO			"4-1201132-1", "HX-SCE-1K-19.0-50-4"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
C09972-000	NO			"7-1201132-8", "HX-SCE-1K-19.0-50-S1-9"			
C13218-000	NO			"8-1201132-1", "HX-SCE-1K-9.5-50-S1-4"			
C92297-000	NO			"6-1201133-1", "HX-SCE-12.7-50-4"			
D98423-000	NO		HX-SCE-5K-2.4-50-SS1-4	"6-1201134-1", "HX-SCE-5K-2.4-50-SS1-4"			
E21108-000	NO			"7-1201134-8", "HX-SCE-1K-3.2-50-9"			
E24938-000	NO			"8-1201134-5", "HX-SCE-1K-12.7-50-S1-9"			
E50792-000	NO			"1-1201135-6", "HX-SCE-38.1-50-S1-9"			
EM7620-000	NO						
F04160-000	NO			"9-1201444-0", "TMS-SCE-2X-1K-3/4-9"			
F21848-000	NO			"D-SCE-1K-2.4-50-9", "9-1200397-9"			
F42151-000	NO			"1-1201136-6", "HX-SCE-1K-4.8-50-SS1-4"			

Customer: Heilind Asia Pacific (SG) Pte Ltd (3076161) **Location:** Singapore **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5273550001	NO			"5-1194143-3", "TMS-SCE-3/16-2.0-9"			

Customer: Interstate Connecting (3196442) **Location:** Lumberton **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1099510001	NO			"1-1190803-1", "TMS-SCE-1K-3/16-2.0-9"			
5363690001	NO			"4-1194210-5", "TMS-SCE-2.5K-1/4-2.0-9"			
EM7620-000	NO						

Customer: Heilind Electronics sp z o o (3261330) **Location:** Krakow **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2439450001	NO			"6-1191789-1", "RPS-1K-22-18/2.0-9"			
6176350001	NO			"8-1194880-6", "TMS-SCE-3/4-2.0-S1-4"			
9809850001	NO			"4-1197580-3", "D-SCE-1K-25-50-S1-4"			

Customer: Interstate Connecting (731279) **Location:** Lumberton **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1099510001	NO			"1-1190803-1", "TMS-SCE-1K-3/16-2.0-9"			
5363690001	NO			"4-1194210-5", "TMS-SCE-2.5K-1/4-2.0-9"			
6315830001	NO			"5-1194997-7", "TMS-SCE-3/4-2.0-4"			
6325250001	NO			"4-1195004-1", "TMS-SCE-1/2-2.0-4"			
6632750001	NO			"7-1195227-1", "TMS-SCE-3/32-2.0-9"			
8264810001	NO			"8-1196455-8", "TMS-SCE-2.5K-3/16-2.0-9"			
EM7620-000	NO						

Customer: Trek Connect Inc (155622) **Location:** Lumberton **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5061850001	NO			"4-1193927-0", "TMS-SCE-1/2-2.0-9"			
5414710001	NO			"3-1194246-8", "TMS-SCE-1-1/2-2.0-9"			
6632750001	NO			"7-1195227-1", "TMS-SCE-3/32-2.0-9"			
6641710001	NO			"2-1195234-2", "TMS-SCE-1/4-2.0-9"			
8350110001	NO			"8-1196518-2", "TMS-SCE-1/8-2.0-9"			

Customer: Heilind Asia Pacific (Hong Kong) (2980376) **Location:** Shatin, N.t. **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5061850001	NO			"4-1193927-0", "TMS-SCE-1/2-2.0-9"			
E21108-000	NO			"7-1201134-8", "HX-SCE-1K-3.2-50-9"			

Customer: Heilind Asia Pacific (SG) Pte Ltd (2980456) **Location:** Singapore **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5273550001	NO			"5-1194143-3", "TMS-SCE-3/16-2.0-9"			

Customer: Heilind Electronics GmbH (3147483) **Location:** Rosenheim **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
6706090001	NO			"4-1195278-6", "TMS-SCE-1-1/2-2.0-4"			

Customer: Heilind Electronics GmbH (113007) **Location:** Bruckmühl **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
0313730001	NO			"5-1190243-4", "TMS-SCE-3/8-2.0-S1-4"			
1130910001	NO			"1-1190825-3", "TMS-SCE-1-2.0-S1-4"			
1139070001	NO			"7-1190830-7", "TMS-SCE-3/16-2.0-S2-4"			
1506550001	NO			"1-1191089-4", "TMS-SCE-3/32-2.0-S1-9"			
2439450001	NO			"6-1191789-1", "RPS-1K-22-18/2.0-9"			
5332610001	NO			"6-1194186-0", "TMS-SCE-3/16-2.0-4"			
6176350001	NO			"8-1194880-6", "TMS-SCE-3/4-2.0-S1-4"			
6706090001	NO			"4-1195278-6", "TMS-SCE-1-1/2-2.0-4"			
9435730001	NO			"8-1197304-1", "TMS-SCE-1K-1/8-2.0-S1-9"			

Customer: Heilind Electronics GmbH (3497140) **Location:** Hanau **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
0313730001	NO			"5-1190243-4", "TMS-SCE-3/8-2.0-S1-4"			
1130910001	NO			"1-1190825-3", "TMS-SCE-1-2.0-S1-4"			
1139070001	NO			"7-1190830-7", "TMS-SCE-3/16-2.0-S2-4"			
1506550001	NO			"1-1191089-4", "TMS-SCE-3/32-2.0-S1-9"			
2439450001	NO			"6-1191789-1", "RPS-1K-22-18/2.0-9"			
5332610001	NO			"6-1194186-0", "TMS-SCE-3/16-2.0-4"			
6176350001	NO			"8-1194880-6", "TMS-SCE-3/4-2.0-S1-4"			
9435730001	NO			"8-1197304-1", "TMS-SCE-1K-1/8-2.0-S1-9"			

Customer: Heilind Electronics sp z o o (3428049) **Location:** Myslowice **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2439450001	NO			"6-1191789-1", "RPS-1K-22-18/2.0-9"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
6176350001	NO			"8-1194880-6", "TMS-SCE-3/4-2.0-S1-4"			
9809850001	NO			"4-1197580-3", "D-SCE-1K-25-50-S1-4"			

Customer: Heilind Electronics Inc (167811) **Location:** Wilmington **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
0173830001	NO			"6-1190135-6", "TMS-SCE-1K-1/8-2.0-S2-4"			
073937-000	NO			"5-1190553-2", "D-SCE-2.5K-6.4-50-S1-4"			
0969750001	NO			"1190711-2", "TMS-SCE-1K-3/32-2.0-9"			
0981630001	NO			"6-1190718-9", "TMS-SCE-3/8-2.0-1"			
121727-000	NO			"1190886-5", "HT-SCE-1K-3/8-2.0-9"			
1229590001	NO			"5-1190894-1", "RPS-16-10/2.0-9"			
1289310001	NO			"5-1190936-3", "TMS-SCE-1K-3/32-2.0-4"			
1505370001	NO			"3-1191088-8", "TMS-SCE-1K-1-1/2-2.0-9"			
2290750001	NO			"6-1191684-9", "TMS-SCE-1K-1-2.0-4"			
2439450001	NO			"6-1191789-1", "RPS-1K-22-18/2.0-9"			
2861530001	NO		TMS-SCE-5K-1/8-2.0-S1-4	"5-1192167-2", "TMS-SCE-5K-1/8-2.0-S1-4"			
330433-000	NO			"7-1192496-7", "TMS-SCE-2X-1K-3/16-9"			
335781-000	NO			"2-1192536-1", "TMS-SCE-2.5K-3/16-2.0S1-4"			
3549610001	NO			"3-1192665-7", "TMS-SCE-1K-3/16-2.0-S1-9"			
397277-000	NO			"6-1192979-1", "HT-SCE-1K-3/16-2.0-9"			
3979470001	NO			"4-1192984-3", "RPS-8-4/2.0-9"			
4397130001	NO			"3-1193304-2", "TMS-SCE-1-2.0-9"			
4575670001	NO			"5-1193433-5", "TMS-SCE-1K-3/4-2.0-9"			
4589050001	NO			"6-1193442-2", "RPS-1K-8-4/2.0-S1-9"			
4785230001	NO			"1193583-3", "TMS-SCE-1/4-2.0-S1-4"			
5061850001	NO			"4-1193927-0", "TMS-SCE-1/2-2.0-9"			
5273550001	NO			"5-1194143-3", "TMS-SCE-3/16-2.0-9"			
5294130001	NO			"7-1194157-4", "TMS-SCE-3/8-2.0-4"			
5332610001	NO			"6-1194186-0", "TMS-SCE-3/16-2.0-4"			
588371-000	NO			"7-1194655-7", "D-SCE-5K-3.2-50-S1-4"			
6325250001	NO			"4-1195004-1", "TMS-SCE-1/2-2.0-4"			
6632750001	NO			"7-1195227-1", "TMS-SCE-3/32-2.0-9"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
6641710001	NO			"2-1195234-2", "TMS-SCE-1/4-2.0-9"			
6694470001	NO			"1195271-5", "TMS-SCE-1K-3/8-2.0-S1-4"			
6706090001	NO			"4-1195278-6", "TMS-SCE-1-1/2-2.0-4"			
7223870001	NO			"1195648-8", "TMS-SCE-1/8-2.0-S1-4"			
7474490001	NO			"8-1195830-1", "TMS-SCE-1K-1/4-2.0-9"			
8350110001	NO			"8-1196518-2", "TMS-SCE-1/8-2.0-9"			
872083-000	NO			"6-1196786-9", "D-SCE-1K-25-50-4"			
8810490001	NO			"9-1196858-0", "TMS-SCE-3/8-2.0-7"			
9353250001	NO			"2-1197247-2", "RPS-16-10/2.0-4"			
9435730001	NO			"8-1197304-1", "TMS-SCE-1K-1/8-2.0-S1-9"			
A18880-000	NO			"9-1201131-4", "HX-SCE-1K-6.4-50-SS1-9"			
A69169-000	NO			"4-1201132-1", "HX-SCE-1K-19.0-50-4"			
C09972-000	NO			"7-1201132-8", "HX-SCE-1K-19.0-50-S1-9"			
C13218-000	NO			"8-1201132-1", "HX-SCE-1K-9.5-50-S1-4"			
C92297-000	NO			"6-1201133-1", "HX-SCE-12.7-50-4"			
D98423-000	NO		HX-SCE-5K-2.4-50-SS1-4	"6-1201134-1", "HX-SCE-5K-2.4-50-SS1-4"			
E24938-000	NO			"8-1201134-5", "HX-SCE-1K-12.7-50-S1-9"			
E50792-000	NO			"1-1201135-6", "HX-SCE-38.1-50-S1-9"			
EM7620-000	NO						
F04160-000	NO			"9-1201444-0", "TMS-SCE-2X-1K-3/4-9"			
F21848-000	NO			"D-SCE-1K-2.4-50-9", "9-1200397-9"			
F42151-000	NO			"1-1201136-6", "HX-SCE-1K-4.8-50-SS1-4"			

Customer: Heilind Asia Pacific (Hong Kong) (2991513) **Location:** Hong Kong **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5061850001	NO			"4-1193927-0", "TMS-SCE-1/2-2.0-9"			
E21108-000	NO			"7-1201134-8", "HX-SCE-1K-3.2-50-9"			