Get Email Version

PRODUCT CHANGE NOTIFICATION

TE CONNECTIVITY

CUSTOMER: HEILIND ELECTRONICS PRODUCT CHANGE NOTIFICATION NO: E-13-006938

LOCATION: WILMINGTON **PCN DATE:** 24-APR-13

CUSTOMER NO: 167811 AGREEMENT NO: TE CONNECTIVITY ENTITY: RMP (1082) - U.S. Operations on SAP

We would like to inform you about the following change(s) to the listed TE Connectivity Product. In case of any

further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

GENERAL PRODUCT DESCRIPTION:

SDE PRO-CRIMPER III Hand Tool

DESCRIPTION OF CHANGE:

Change terminal locator back to 58515-1 until new locator is approved.

REASON FOR CHANGE:

Product improvement.

ESTIMATE DATE:

LAST ORDER DATE:

(OBSOLETE PARTS ONLY)

LAST SHIP DATE:

(OBSOLETE PARTS ONLY)

FIRST DATE TO SHIP CHANGED

PARTS: 26-APR-2013 (CHANGED PARTS ONLY)

LAST DATE FOR MIXED

SHIPMENTS: NO MIXED SHIPMENTS

(CHANGED PARTS ONLY)

TE CONNECTIVITY

PRODUCT CHANGE NOTIFICATION

CUSTOMER: HEILIND ELECTRONICS **PRODUCT CHANGE NOTIFICATION NO:** E-13-006938

LOCATION: WILMINGTON **PCN DATE:** 24-APR-13

CUSTOMER NO: 167811 AGREEMENT NO:

TE CONNECTIVITY ENTITY: RMP (1082) - U.S. Operations on SAP

PARTS BEING MODIFIED CUSTOMER PART NBR

58514-1

58514-2

Get Email Version

PRODUCT CHANGE NOTIFICATION

TE CONNECTIVITY

CUSTOMER: HEILIND ELECTRONICS PRODUCT CHANGE NOTIFICATION NO: E-13-006938

LOCATION: HIGHLAND HEIGHTS **PCN DATE:** 24-APR-13

CUSTOMER NO: 415410 AGREEMENT NO: TE CONNECTIVITY ENTITY: RMP (1082) - U.S. Operations on SAP

We would like to inform you about the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

GENERAL PRODUCT DESCRIPTION:

SDE PRO-CRIMPER III Hand Tool

DESCRIPTION OF CHANGE:

Change terminal locator back to 58515-1 until new locator is approved.

REASON FOR CHANGE:

Product improvement.

ESTIMATE DATE:

LAST ORDER DATE:

(OBSOLETE PARTS ONLY)

LAST SHIP DATE:

(OBSOLETE PARTS ONLY)

FIRST DATE TO SHIP CHANGED

PARTS: 26-APR-2013
(CHANGED PARTS ONLY)
LAST DATE FOR MIXED

SHIPMENTS: NO MIXED SHIPMENTS

(CHANGED PARTS ONLY)

TE CONNECTIVITY

PRODUCT CHANGE NOTIFICATION

CUSTOMER: HEILIND ELECTRONICS PRODUCT CHANGE NOTIFICATION NO: E-13-006938

LOCATION: HIGHLAND HEIGHTS **PCN DATE**: 24-APR-13

CUSTOMER NO: 415410 AGREEMENT NO:

TE CONNECTIVITY ENTITY: RMP (1082) - U.S. Operations on SAP

PARTS BEING MODIFIED CUSTOMER PART NBR

58606-2

Get Email Version

PRODUCT CHANGE NOTIFICATION

TE CONNECTIVITY

CUSTOMER: MAVERICK ELECTRONICS PRODUCT CHANGE NOTIFICATION NO: E-13-006938

LOCATION: MCALLEN **PCN DATE**: 24-APR-13

CUSTOMER NO: 155785 AGREEMENT NO:

TE CONNECTIVITY ENTITY: RMP (1082) - U.S. Operations on SAP

We would like to inform you about the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

GENERAL PRODUCT DESCRIPTION:

SDE PRO-CRIMPER III Hand Tool

DESCRIPTION OF CHANGE:

Change terminal locator back to 58515-1 until new locator is approved.

REASON FOR CHANGE:

Product improvement.

ESTIMATE DATE:

LAST ORDER DATE:

(OBSOLETE PARTS ONLY)

LAST SHIP DATE:

(OBSOLETE PARTS ONLY)

FIRST DATE TO SHIP CHANGED

PARTS: 26-APR-2013 (CHANGED PARTS ONLY)

LAST DATE FOR MIXED

SHIPMENTS: NO MIXED SHIPMENTS

(CHANGED PARTS ONLY)

TE CONNECTIVITY

PRODUCT CHANGE **NOTIFICATION**

CUSTOMER: MAVERICK ELECTRONICS **PRODUCT CHANGE NOTIFICATION NO:** E-13-006938

LOCATION: MCALLEN PCN DATE: 24-APR-13

CUSTOMER NO: 155785 **AGREEMENT NO:**

TE CONNECTIVITY ENTITY: RMP (1082) - U.S. Operations on SAP

PARTS BEING MODIFIED CUSTOMER PART NBR

58583-1