

CURRENT DATE: 9-MAY-2013

TE CONNECTIVITY

PRODUCT CHANGE NOTIFICATION

CUSTOMER: HEILIND ELECTRONICS

LOCATION: WILMINGTON

CUSTOMER NO: 167811

TE CONNECTIVITY ENTITY: RMP (1082) - U.S. Operations on SAP

PRODUCT CHANGE NOTIFICATION NO: P-12-008122

PCN DATE: 20-JUN-12

AGREEMENT NO:

We would like to inform you about the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

GENERAL PRODUCT DESCRIPTION:

USB2.0 and USB3.0 connector

DESCRIPTION OF CHANGE:

Transfer manufacturing location from TE Zhuhai to TE GD

REASON FOR CHANGE:

manufacturing location change

ESTIMATE DATE:

LAST ORDER DATE:

(OBSOLETE PARTS ONLY)

LAST SHIP DATE:

(OBSOLETE PARTS ONLY)

FIRST DATE TO SHIP CHANGED PARTS:

24-SEP-2012

(CHANGED PARTS ONLY)

LAST DATE FOR MIXED

SHIPMENTS: 24-OCT-2012

(CHANGED PARTS ONLY)

CURRENT DATE: 9-MAY-2013**TE CONNECTIVITY****PRODUCT CHANGE
NOTIFICATION****CUSTOMER:** HEILIND ELECTRONICS**PRODUCT CHANGE NOTIFICATION NO:** P-12-008122**LOCATION:** WILMINGTON**PCN DATE:** 20-JUN-12**CUSTOMER NO:** 167811**AGREEMENT NO:****TE CONNECTIVITY ENTITY:** RMP (1082) - U.S. Operations on SAP**Parts being Discontinued or available with Alternates**

PARTS AFFECTED	CUSTOMER PART NBR	SUBSTITUTE PART NBR	DESCRIPTION OF DIFFERENCES
292303-1 (Alias Part Numbers: "CU5879-000", "PER-292303-1")			
292303-4			
292304-1 (Alias Part Numbers: "C73502-000", "PER-292304-1")			
292304-2			
5787745-2			
5787834-1			

5788336-1