

CURRENT DATE: 8-NOVEMBER-2013

[Get Email Version](#)

TE CONNECTIVITY

PRODUCT CHANGE NOTIFICATION

CUSTOMER: HEILIND ELECTRONICS

PRODUCT CHANGE NOTIFICATION NO: P-13-009087

LOCATION: WILMINGTON

PCN DATE: 30-APR-13

CUSTOMER NO: 167811

AGREEMENT NO: 081213180007

TE CONNECTIVITY ENTITY: RMP (1082) - U.S. Operations on SAP

We would like to inform you about the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

GENERAL PRODUCT DESCRIPTION:

Change of marking

DESCRIPTION OF CHANGE:

The circuit diagram will not be molded in at the side anymore, but laser marked on the top side of the cover. Furthermore the Tyco logo will be replaced by the new TE logo.

REASON FOR CHANGE:

Product improvement.

ESTIMATE DATE:

LAST ORDER DATE:

(OBSOLETE PARTS ONLY)

LAST SHIP DATE:

(OBSOLETE PARTS ONLY)

FIRST DATE TO SHIP CHANGED PARTS:

30-JUL-2013

(CHANGED PARTS ONLY)

LAST DATE FOR MIXED

SHIPMENTS: 30-OCT-2013

(CHANGED PARTS ONLY)

CURRENT DATE: 8-NOVEMBER-2013

TE CONNECTIVITY

PRODUCT CHANGE NOTIFICATION

CUSTOMER: HEILIND ELECTRONICS

PRODUCT CHANGE NOTIFICATION NO: P-13-009087

LOCATION: WILMINGTON

PCN DATE: 30-APR-13

CUSTOMER NO: 167811

AGREEMENT NO: 081213180007

TE CONNECTIVITY ENTITY: RMP (1082) - U.S. Operations on SAP

PARTS BEING MODIFIED

CUSTOMER PART NBR

1-1904022-1

(Alias Part Numbers:

"0 332 209 138")

2-1904022-4

(Alias Part Numbers:

"0 332 209 161")