



Product Change Notification

Current Date: 04-Jun-2014

TE Connectivity

Product Change Notification: E-14-007798

PCN Date: 02-JUN-14

Customer: Heilind Electronics (167811)

Location: Wilmington

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
PRO-CRIMPER III Hand Tool and Die Sets

Description of Changes
Change all tools and die sets to new design locator assembly. 58515-1 assembly changes to 2063771-1.

Reason for Changes:
Product Improvement. The old and new locator have similar components and perform the same. The new locator is positioned with slightly longer die pins and does not use the tool frame for alignment. This make for a more versatile and study locator.

Estimated Dates:	
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	27-JUN-2014
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	30-JUN-2014

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
58495-1	NO					
90548-2	NO					
90574-1	NO					
90574-2	NO					



Product Change Notification

Current Date: 04-Jun-2014

TE Connectivity

Product Change Notification: E-14-007798

PCN Date: 02-JUN-14

Customer: Maverick Electronics (155784)

Location: Mayfield Village

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
PRO-CRIMPER III Hand Tool and Die Sets

Description of Changes
Change all tools and die sets to new design locator assembly. 58515-1 assembly changes to 2063771-1.

Reason for Changes:
Product Improvement. The old and new locator have similar components and perform the same. The new locator is positioned with slightly longer die pins and does not use the tool frame for alignment. This make for a more versatile and study locator.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	27-JUN-2014
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	30-JUN-2014

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
90546-1	NO					