

## Global Change Notification (GCN)

Product Family	Mini Fit	10641456
		GCN Number
Series	Various	July 03, 2014
		Date Issued
Reason For Change	New, Modified, Or Replacement Tooling	
Change Description	Molex is building another mold to make housings 5569-054 and 5569-055.	
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.	
Reason For Short Notice Exception	Force Majeure	
Assessment Of Change (How Product Will Be Qualified & Validated)	The new mold will be fully qualified by Molex before it is put into production.	
Internal Molex Qualification Date (Planned Date Information Available)	July 02, 2014	
Sample Availability Date (Changed Part)	July 02, 2014	
Date of Implementation	July 09, 2014	
Method of Identifying Change	Parts made after July 9, 2014	
Recommended Replacement Parts	Not Applicable	
Last Time Buy Date for Obsolete Parts		
Last Time Ship Date for Obsolete Parts		

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	QuiNann Lim	QuiNann.Lim@molex.com	+31-40-295-8472
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

**Molex, Inc.**  
 2222 Wellington Court  
 Lisle, IL 60532  
 TEL: 630-969-4747  
[www.molex.com](http://www.molex.com)

Material

15041501  
15241501  
15271501  
15271505  
15271507  
39303055  
39303056  
39303057  
39303058  
39307051  
39307052  
50304436  
50304437  
50304439  
50304442  
50361747  
50361748  
98268053  
98268054  
432320001  
432320002  
432320003  
432320004  
432320005  
432320006  
432320011  
432320012  
432320016  
432320019  
432320021  
469990098  
469990100  
469990289