

Global Change Notification (GCN)

Product Family	MX123	10664193	
		GCN Number	
Series	34566 & 34576	January 19, 2015	
		Date Issued	
Reason For Change	New, Modified, Or Replacement Tooling		
Change Description	The purpose of this letter is to inform you that Molex will be adding new capacity tooling to our grommet seal supplier for the MX123 – 80-Way and 56-Way Female Harness Connector Assemblies. This additional tooling is needed in order to keep up with current and future demands of this product. The grommet seal supplier will remain unchanged, and there are no changes to fit, form or function. As a result of the new capacity tooling, the grommet seal color will change. The color of the existing/old 80-way grommet seal was green. The color of the new 80-way grommet seal will be rust red. The color of the existing/old 56-way grommet seal was light blue. The color of the existing/old 56-way grommet seal was light blue. The color of the new 56-way grommet seal will be rust red. This change is similar to one previously administered for the 73way. All current and future 80-way and 56-way female harness connector assemblies will be impacted by this change. This includes, but is not limited to, the attached list of part numbers. Please note that if you have recently requested custom void patterns for the 56-way and 80-way female harness connector assembly part numbers will remain the same. Only the subcomponent part number for the grommet seal itself will be changed. Product previously ordered should be FIFO'ed and consumed. No changes will be tracked via revision control on the drawings. Molex will submit PPAP documentation upon requests after Dec. 15th, 2014. Molex will begin shipment of the 56-way female harness connector assemblies with the new grommet seals beginning March 2015. Alt that time only rust red grommet seals will be shipped, as the green and light blue grommet seals will no longer be available. Marnies context Product Manager 2025 Taylor Road Auburn Hills, Michigan 48326 (248) 371-9700 marnie.fender@molex.com		
NEW 80-WAY GROMMET SEAL	ROMMET SEAL	**************************************	
ULD OV WAT O	NEW 56-WAY GROMMET SI	EAL OLD 56-WAY GROMMET SEAL	
Part Numbers Affected	Please refer to CustomerPartList.csv attache	ed to e-mail message.	
Reason For Short Notice Exception	New Capacity		
Assessment Of Change (How Product Will Be Qualified & Validated)	validation testing		
Internal Molex Qualification Date	December 15, 2014		

(Planned Date Information Available) Sample Availability Date (Changed Part)

December 15, 2014

February 20, 2015

new seal color

Method of Identifying Change

Recommended Replacement Parts NA

Last Time Buy Date for Obsolete Parts

Last Time Ship Date for Obsolete Parts

INA			

Contact	Name	E-mail	Phone Number	
Sales Engineer	Please refer to e-mail message for your local sales engineer.			
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416	
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751	
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271	
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352	

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com Molex Part Number