

Global Change Notification (GCN)

Product Family	Multiple	10671572
		GCN Number
Series	Multiple	May 13, 2015
		Date Issued
Reason For Change	Supplier Change	
Change Description	This is to inform you that our supplier and the material for all rivets is changing in order to improve delivery performance and material properties. The material previously used for rivets was SUS-430 and it is being standardized to SUS-302 which is more durable to Salt Spray requirements. The old supplier had long and inconsistent lead time while the new supplier will increase our ability to meet customer demand. There will be no change to fit, form and function. This is going to be a running change that will impact multiple product families and series.	
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.	
Reason For Short Notice Exception	Force Majeure	
Assessment Of Change (How Product Will Be Qualified & Validated)	FAI, salt spray testing, visual inspection, and strength test have been performed. Report is being prepared.	
Internal Molex Qualification Date (Planned Date Information Available)	February 06, 2015	
Sample Availability Date (Changed Part)	February 06, 2015	
Date of Implementation	May 18, 2015	
Method of Identifying Change	Tracked by serial code and date located on final assemblies.	
Recommended Replacement Parts	N/A	
Last Time Buy Date for Obsolete Parts		
Last Time Ship Date for Obsolete Parts		

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc.
 2222 Wellington Court
 Lisle, IL 60532
 TEL: 630-969-4747
www.molex.com