

Global Change Notification (GCN)

Product Family	zSFP+	10730399
		GCN Number
Series	171224 and 172501	November 11, 2015
		Date Issued
Reason For Change	Manufacturing Process Change	
Change Description	Molex is adding spot welds to our metal EMI spring finger gasket to secure the corners of the gasket to the cage body. This is being done to make the product easier to handle during the assembly process at the customer. This change does not affect form, fit, or function of the product. This is a notification only and will be a running change.	
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.	
Reason For Short Notice Exception	8D Corrective Action Changes	
Assessment Of Change (How Product Will Be Qualified & Validated)	Molex internal qualification	
Internal Molex Qualification Date (Planned Date Information Available)	September 30, 2015	
Sample Availability Date (Changed Part)	September 30, 2015	
Date of Implementation	November 13, 2015	
Method of Identifying Change	N.A.	
Recommended Replacement Parts	N.A.	
Last Time Buy Date for Obsolete Parts		
Last Time Ship Date for Obsolete Parts		

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc.
 2222 Wellington Court
 Lisle, IL 60532
 TEL: 630-969-4747
www.molex.com