



# Product Change Notification

Current Date: 19-Jan-2016

## TE Connectivity

Product Change Notification: P-16-012527

PCN Date: 14-JAN-16

Customer: (0002135900)

Location: WORLDWIDE

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

**General Product Description:**

AFFECTS CUSTOMER SHIPMENTS WITHIN NORTH AMERICA ONLY - Distribution Center change from Santa Teresa, NM to El Paso, TX

**Description of Changes**

THERE IS NO CHANGE TO MANUFACTURING LOCATION OR TO PARTS! TE has established a new Distribution Center in El Paso, TX to support our South-West Customers. The transition to El Paso will take place during the weekend of February 13th - 14th. All products you currently receive from our Santa Teresa, NM location will be transitioned to the new Distribution Center by Monday, February 15, 2016. In preparation of the February 15th go-live, TE will be shipping February 15th requirements on Friday February 12th. Your TE Customer Care Representative will contact you to review any special arrangements required for pick-up on Friday and to make any appropriate adjustments to your DUNS/Vendor Codes/Supplier Codes for the new Distribution Center. Current DC address: 101 Lindbergh, Santa Teresa, NM 88008 Current DUNS Code: 036967748 New DC address: 32 Celerity Wagon, El Paso, TX 79906 New DUNS Code: 080037706 See attached Customer letter.

**Reason for Changes:**

Customer Request. As of the end of August 2015, our current distribution center located in Santa Teresa, New Mexico was divested to Commscope. As a result, TE has established a new Distribution Center in El Paso, TX to support our South-West Customers. In conjunction with the relocation, our new El Paso Distribution Center will be operating on SAP Warehouse Management. The transition will be transparent with the exception of the SAP Packing List. Currently with the use of MOVE in our Santa Teresa DC, Packing Lists can only be printed by carton or by pallet. With the use of SAP Warehouse Management in our El Paso DC, the Packing Lists will be printed by shipment and/or by pallet.

**Estimated Dates:**

<b>Last Order Date</b> (Obsolete Parts Only):	<b>First Date To Ship</b> (Changed Parts Only):
	15-FEB-2016
<b>Last Ship Date</b> (Obsolete Parts Only):	<b>Last Date for Mixed Shipments:</b> (Changed Parts Only):
	No Mixed Shipments

**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-104479-0</a>	NO						
<a href="#">1-104479-3</a>	NO						
<a href="#">1-104480-7</a>	NO						
<a href="#">1-1123722-5</a>	NO						
<a href="#">1-1123723-3</a>	NO						
<a href="#">1-160759-1</a>	NO						
<a href="#">1-170823-3</a>	NO						
<a href="#">1-176497-1</a>	NO						
<a href="#">1-324227-0</a>	NO						
<a href="#">1-33220-2</a>	NO						
<a href="#">1-35115-0</a>	NO						
<a href="#">1-480270-0</a>	NO			"1-0480270-0"			
<a href="#">1-480271-0</a>	NO						
<a href="#">1-480283-0</a>	NO						
<a href="#">1-480284-0</a>	NO						
<a href="#">1-480318-0</a>	NO			"A77825-000", "AMP-1-0480318-0"			
<a href="#">1-480319-0</a>	NO						
<a href="#">1-480319-9</a>	NO						
<a href="#">1-480350-0</a>	NO						
<a href="#">1-480388-0</a>	NO						
<a href="#">1-480416-0</a>	NO						
<a href="#">1-480416-1</a>	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-480698-0</a>	NO			"834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341"			
<a href="#">1-480699-0</a>	NO			"402376412", "1-0480699-0", "500-060-1982", "4-27202-1755"			
<a href="#">1-480700-0</a>	NO			"AMPS-1-0480700-0", "F47049-000", "1-0480700-0", "2-42932-9342"			
<a href="#">1-480701-0</a>	NO						
<a href="#">1-480705-0</a>	NO			"1-0480705-0"			
<a href="#">1-480706-0</a>	NO			"873818-000", "AMPS-1-0480706-0", "2-42934-0301"			
<a href="#">1-66105-8</a>	NO						
<a href="#">1-770904-0</a>	NO						
<a href="#">1-770968-1</a>	NO						
<a href="#">1-794606-2</a>	NO						
<a href="#">1-794608-0</a>	NO						
<a href="#">1-794617-2</a>	NO						
<a href="#">1-794617-6</a>	NO						
<a href="#">103653-1</a>	NO			"010-0961-00"			
<a href="#">103653-2</a>	NO			"010-0962-00"			
<a href="#">103653-4</a>	NO						
<a href="#">104257-1</a>	NO						
<a href="#">104257-2</a>	NO			"AMP-0-0104257-2", "C75259-000", "030-0095-00"			
<a href="#">104257-3</a>	NO						
<a href="#">104257-5</a>	NO			"030-0096-00"			
<a href="#">104479-2</a>	NO						
<a href="#">104479-9</a>	NO						
<a href="#">104480-2</a>	NO						
<a href="#">106455-3</a>	NO						
<a href="#">106455-4</a>	NO						
<a href="#">1123721-2</a>	NO						
<a href="#">1217138-1</a>	NO						
<a href="#">1375819-3</a>	NO						
<a href="#">142685-3</a>	NO						
<a href="#">1445049-4</a>	NO						
<a href="#">1445389-3</a>	NO						
<a href="#">154717-3</a>	NO						
<a href="#">154717-7</a>	NO						
<a href="#">154718-3</a>	NO						
<a href="#">154719</a>	NO			"154719-0"			
<a href="#">154719-1</a>	NO			"0-0154719-1"			
<a href="#">1601063-2</a>	NO			"131-129-021"			
<a href="#">1601117-1</a>	NO			"150-003-000"			
<a href="#">1601140-1</a>	NO			"153-001-000"			
<a href="#">1601623-1</a>	NO			"L061D16TB"			
<a href="#">160173-2</a>	NO						
<a href="#">160467-2</a>	NO						
<a href="#">160859-2</a>	NO						
<a href="#">163300-6</a>	NO						
<a href="#">170003-4</a>	NO						
<a href="#">170360-3</a>	NO						
<a href="#">170362-3</a>	NO						
<a href="#">171637-1</a>	NO						
<a href="#">172159-1</a>	NO						
<a href="#">1744144-1</a>	NO						
<a href="#">177898-1</a>	NO						
<a href="#">177914-1</a>	NO						
<a href="#">177915-1</a>	NO						
<a href="#">177916-1</a>	NO						
<a href="#">2-1601140-1</a>	NO			"153-004-000"			
<a href="#">2-31819-1</a>	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">2-31894-2</a>	NO			"405223587"			
<a href="#">2-31895-1</a>	NO						
<a href="#">2-31897-2</a>	NO			"F55945-000", "RAYVOSS-22-16/22-18-R3/8"			
<a href="#">2-320563-2</a>	NO						
<a href="#">2-320568-1</a>	NO			"403802838"			
<a href="#">2-32952-1</a>	NO						
<a href="#">2-33457-2</a>	NO			"401771357"			
<a href="#">2-33458-3</a>	NO						
<a href="#">2-34112-2</a>	NO						
<a href="#">2-34113-2</a>	NO						
<a href="#">2-34123-1</a>	NO			"405109166"			
<a href="#">2-34144-1</a>	NO						
<a href="#">2-34161-1</a>	NO						
<a href="#">2-34162-1</a>	NO						
<a href="#">2-34163-1</a>	NO						
<a href="#">2-34164-2</a>	NO						
<a href="#">2-35109-1</a>	NO			"1140297", "1139542"			
<a href="#">2-36153-2</a>	NO						
<a href="#">2-36160-1</a>	NO						
<a href="#">2-36161-2</a>	NO			"402624795"			
<a href="#">2-794617-4</a>	NO						
<a href="#">201692-4</a>	NO						
<a href="#">2029154002</a>	NO			"1-1191471-8", "RNF-150-1/2-0-SP"			
<a href="#">206036-2</a>	NO						
<a href="#">206037-1</a>	NO			"A33294-000", "AMPS-0-0206037-1"			
<a href="#">206037-2</a>	NO						
<a href="#">206070-8</a>	NO		118408-3				
<a href="#">206150-1</a>	NO						
<a href="#">206151-2</a>	NO						
<a href="#">206322-9</a>	NO						
<a href="#">206708-1</a>	NO						
<a href="#">206966-9</a>	NO						
<a href="#">208652-1</a>	NO						
<a href="#">2132781-3</a>	NO						
<a href="#">2132813-2</a>	NO						
<a href="#">2201778-1</a>	NO						
<a href="#">3-640252-1</a>	NO						
<a href="#">3-640311-1</a>	NO						
<a href="#">3-640401-1</a>	NO						
<a href="#">3-641190-5</a>	NO						
<a href="#">3-770060-1</a>	NO						
<a href="#">3-794121-1</a>	NO						
<a href="#">316086-1</a>	NO						
<a href="#">31818</a>	NO			"768360-000", "AMPS-0-0031818-0"			
<a href="#">320619</a>	NO			"AMPS-0-0320619-0", "C41604-000", "4-00520-1990"			
<a href="#">320764</a>	NO						
<a href="#">321201</a>	NO						
<a href="#">321253</a>	NO						
<a href="#">321576</a>	NO						
<a href="#">324047</a>	NO			"A42815-000", "AMP-0-0324047-0"			
<a href="#">33220</a>	NO						
<a href="#">33460</a>	NO			"CS4742-000", "AMPS-0-0033460-0"			
<a href="#">33465</a>	NO			"AMP-0-0033465-0", "F07864-000"			
<a href="#">3371890001</a>	NO			"7-1192545-8", "ES-CAP-NO.1-C1-0-30MM"			
<a href="#">34070</a>	NO			"268412-000", "AMPS-0-0034070-0"			
<a href="#">34072</a>	NO			"611528-000", "AMPS-0-0034072-0"			
<a href="#">34125</a>	NO			"AMP-0-0034125-0", "F03616-000"			
<a href="#">34130</a>	NO		5M392-1				
<a href="#">34137</a>	NO		5M392-2	"F21569-000", "AMPS-0-0034137-0"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">34138</a>	NO		5M392-3	"CM8395-000", "AMP-0-0034138-0"			
<a href="#">34318</a>	NO		5M392-4	"AMPS-0-0034318-0", "C05587-000"			
<a href="#">350210-1</a>	NO			"407072693"			
<a href="#">350218-1</a>	NO						
<a href="#">350536-1</a>	NO			"403429822"			
<a href="#">350537-3</a>	NO						
<a href="#">350558-1</a>	NO						
<a href="#">350561-1</a>	NO			"0-0350561-1", "CU3085-000", "AMPS-0-0350561-1"			
<a href="#">350570-1</a>	NO						
<a href="#">350767-1</a>	NO			"AMP-0-0350767-1", "F84278-000"			
<a href="#">350778-1</a>	NO			"403738545", "AMPS-0-0350778-1", "E83488-000", "500-020-2698", "500-020-0104"			
<a href="#">350851-1</a>	NO			"0-0350851-1", "2021755", "CU3086-000", "AMPS-0-0350851-1"			
<a href="#">350923-3</a>	NO			"403980899"			
<a href="#">35109</a>	NO			"AMPS-0-0035109-0", "F67095-000"			
<a href="#">35110</a>	NO			"AMPS-0-0035110-0", "E36230-000", "2-14492-3100"			
<a href="#">35669</a>	NO						
<a href="#">36946</a>	NO		5M392-8	"CN3419-000", "AMPS-0-0036946-0"			
<a href="#">36951</a>	NO		5M392-11				
<a href="#">36958</a>	NO						
<a href="#">4-794636-2</a>	NO						
<a href="#">41765</a>	NO						
<a href="#">41770</a>	NO						
<a href="#">42776-1</a>	NO						
<a href="#">4367790003</a>	NO			"1-1193283-5", "ES-CAP-NO.2-B9-0-35MM"			
<a href="#">5053094268</a>	NO			"4-1193845-5", "RNF-100-1/4-BK-SP"			
<a href="#">5053194267</a>	NO			"3-1193862-4", "RNF-100-1/2-BK-SP", "RNF-100-1/2-0"			
<a href="#">5053344102</a>	NO			"4-1193882-5", "RNF-100-1-1/2-BK-SP"			
<a href="#">5058724002</a>	NO			"5-1193906-0", "VERSAFIT-3/16-0-SP"			
<a href="#">5058744001</a>	NO			"1193907-8", "VERSAFIT-1/4-0-SP"			
<a href="#">5070064069</a>	NO			"2-1193963-6", "RNF-100-1/4-CL-SP"			
<a href="#">51863</a>	NO			"4-16211-9784"			
<a href="#">51863-1</a>	NO						
<a href="#">51864-3</a>	NO						
<a href="#">52041</a>	NO						
<a href="#">52943-1</a>	NO			"401771464"			
<a href="#">53128-1</a>	NO						
<a href="#">53831-1</a>	NO						
<a href="#">5510320002</a>	NO			"3-1194355-8", "PD-CAP-1/8-0"			
<a href="#">55785-1</a>	NO			"AMP-0-0055785-1", "D10979-000"			
<a href="#">61085-1</a>	NO						
<a href="#">61117-1</a>	NO			"403631302"			
<a href="#">61118-1</a>	NO			"0-0061118-1"			
<a href="#">61314-1</a>	NO			"403334121", "0-0061314-1", "14629", "1101201"			
<a href="#">61622-1</a>	NO						
<a href="#">62000-2</a>	NO						
<a href="#">62001-1</a>	NO						
<a href="#">62001-2</a>	NO						
<a href="#">62002-2</a>	NO						
<a href="#">62305-2</a>	NO						
<a href="#">62306-2</a>	NO						
<a href="#">62310-2</a>	NO						
<a href="#">62311-2</a>	NO						
<a href="#">62429-1</a>	NO						
<a href="#">62935-1</a>	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">640251-7</a>	NO						
<a href="#">640388-2</a>	NO						
<a href="#">640388-3</a>	NO						
<a href="#">640456-2</a>	NO			"403612641", "2-42934-0583"			
<a href="#">640456-5</a>	NO						
<a href="#">640903-2</a>	NO						
<a href="#">640923-2</a>	NO			"1181513"			
<a href="#">647402-2</a>	NO						
<a href="#">647402-3</a>	NO						
<a href="#">66098-8</a>	NO						
<a href="#">66100-8</a>	NO						
<a href="#">66102-8</a>	NO						
<a href="#">66104-8</a>	NO						
<a href="#">66358-9</a>	NO						
<a href="#">66359-9</a>	NO						
<a href="#">7-1393114-8</a>	NO			"KUHP-11D51-24"			
<a href="#">770007-1</a>	NO						
<a href="#">770008-3</a>	NO						
<a href="#">770476-1</a>	NO						
<a href="#">770476-2</a>	NO						
<a href="#">770579-1</a>	NO			"0-0770579-1"			
<a href="#">770580-1</a>	NO			"0-0770580-1"			
<a href="#">770849-4</a>	NO						
<a href="#">770903-1</a>	NO			"E25278-000", "DUL-PIN-22-18AW-S/M-UMNL"			
<a href="#">770904-1</a>	NO			"2-42939-6041"			
<a href="#">794219-1</a>	NO						
<a href="#">794221-1</a>	NO						
<a href="#">794223-1</a>	NO						
<a href="#">794272-1</a>	NO						
<a href="#">794412-1</a>	NO						
<a href="#">794606-1</a>	NO			"AMPS-0-0794606-1", "F30642-000"			
<a href="#">794616-4</a>	NO						
<a href="#">794616-6</a>	NO						
<a href="#">794617-8</a>	NO						
<a href="#">794758-1</a>	NO						
<a href="#">794781-1</a>	NO						
<a href="#">796075-1</a>	NO						
<a href="#">796286-1</a>	NO						
<a href="#">796288-1</a>	NO						
<a href="#">87631-2</a>	NO						
<a href="#">917686-1</a>	NO						
<a href="#">926291-1</a>	NO						

Customer: Heilind Electronic( 1341448 )

Location: Markham

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">106455-3</a>	NO						
<a href="#">106455-4</a>	NO						
<a href="#">177915-1</a>	NO						
<a href="#">206070-8</a>	NO		118408-3				
<a href="#">34072</a>	NO			"611528-000", "AMPS-0-0034072-0"			
<a href="#">34318</a>	NO		5M392-4	"AMPS-0-0034318-0", "C05587-000"			
<a href="#">5058724002</a>	NO			"5-1193906-0", "VERSAFIT-3/16-0-SP"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">5058744001</a>	NO			"1193907-8", "VERSAFIT-1/4-0-SP"			

Customer: Heilind Electronics Inc( 2914593 )

Location: Camarillo

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">104257-3</a>	NO						
<a href="#">177915-1</a>	NO						
<a href="#">177916-1</a>	NO						

Customer: Maverick Electronics( 155785 )

Location: McAllen

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-104479-0</a>	NO						
<a href="#">1-104479-3</a>	NO						
<a href="#">1-480416-1</a>	NO						
<a href="#">1-480698-0</a>	NO			"834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341"			
<a href="#">1-480700-0</a>	NO			"AMPS-1-0480700-0", "F47049-000", "1-0480700-0", "2-42932-9342"			
<a href="#">1-480701-0</a>	NO						
<a href="#">1-480706-0</a>	NO			"873818-000", "AMPS-1-0480706-0", "2-42934-0301"			
<a href="#">1-794606-2</a>	NO						
<a href="#">1-794617-2</a>	NO						
<a href="#">1-794617-6</a>	NO						
<a href="#">103653-1</a>	NO			"010-0961-00"			
<a href="#">103653-2</a>	NO			"010-0962-00"			
<a href="#">103653-4</a>	NO						
<a href="#">104257-1</a>	NO						
<a href="#">104257-2</a>	NO			"AMP-0-0104257-2", "C75259-000", "030-0095-00"			
<a href="#">104257-3</a>	NO						
<a href="#">104257-5</a>	NO			"030-0096-00"			
<a href="#">1445049-4</a>	NO						
<a href="#">170360-3</a>	NO						
<a href="#">170362-3</a>	NO						
<a href="#">171637-1</a>	NO						
<a href="#">172159-1</a>	NO						
<a href="#">2-34161-1</a>	NO						
<a href="#">2-35109-1</a>	NO			"1140297", "1139542"			
<a href="#">2-36161-2</a>	NO			"402624795"			
<a href="#">2-794617-4</a>	NO						
<a href="#">3-770060-1</a>	NO						
<a href="#">34070</a>	NO			"268412-000", "AMPS-0-0034070-0"			
<a href="#">34137</a>	NO		5M392-2	"F21569-000", "AMPS-0-0034137-0"			
<a href="#">350218-1</a>	NO						
<a href="#">350536-1</a>	NO			"403429822"			
<a href="#">350767-1</a>	NO			"AMP-0-0350767-1", "F84278-000"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">350778-1</a>	NO			"403738545", "AMPS-0-0350778-1", "E83488-000", "500-020-2698", "500-020-0104"			
<a href="#">5053194267</a>	NO			"3-1193862-4", "RNF-100-1/2-BK-SP", "RNF-100-1/2-0"			
<a href="#">5058724002</a>	NO			"5-1193906-0", "VERSAFIT-3/16-0-SP"			
<a href="#">5058744001</a>	NO			"1193907-8", "VERSAFIT-1/4-0-SP"			
<a href="#">52943-1</a>	NO			"401771464"			
<a href="#">647402-3</a>	NO						
<a href="#">770580-1</a>	NO			"0-0770580-1"			
<a href="#">770903-1</a>	NO			"E25278-000", "DUL-PIN-22-18AW-S/M-UMNL"			
<a href="#">770904-1</a>	NO			"2-42939-6041"			
<a href="#">794617-8</a>	NO						
<a href="#">794758-1</a>	NO						

Customer: Heilind Electronics( 1281082 )

Location: Highland Heights

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-104479-0</a>	NO						
<a href="#">1-104479-3</a>	NO						
<a href="#">1-104480-7</a>	NO						
<a href="#">1-1123722-5</a>	NO						
<a href="#">1-1123723-3</a>	NO						
<a href="#">1-160759-1</a>	NO						
<a href="#">1-324227-0</a>	NO						
<a href="#">1-35115-0</a>	NO						
<a href="#">1-480270-0</a>	NO			"1-0480270-0"			
<a href="#">1-480271-0</a>	NO						
<a href="#">1-480283-0</a>	NO						
<a href="#">1-480284-0</a>	NO						
<a href="#">1-480318-0</a>	NO			"A77825-000", "AMP-1-0480318-0"			
<a href="#">1-480319-0</a>	NO						
<a href="#">1-480319-9</a>	NO						
<a href="#">1-480350-0</a>	NO						
<a href="#">1-480388-0</a>	NO						
<a href="#">1-480416-0</a>	NO						
<a href="#">1-480698-0</a>	NO			"834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341"			
<a href="#">1-480699-0</a>	NO			"402376412", "1-0480699-0", "500-060-1982", "4-27202-1755"			
<a href="#">1-480700-0</a>	NO			"AMPS-1-0480700-0", "F47049-000", "1-0480700-0", "2-42932-9342"			
<a href="#">1-480701-0</a>	NO						
<a href="#">1-480705-0</a>	NO			"1-0480705-0"			
<a href="#">1-480706-0</a>	NO			"873818-000", "AMPS-1-0480706-0", "2-42934-0301"			
<a href="#">1-66105-8</a>	NO						
<a href="#">1-770904-0</a>	NO						
<a href="#">1-770968-1</a>	NO						
<a href="#">1-794606-2</a>	NO						
<a href="#">1-794608-0</a>	NO						
<a href="#">1-794617-2</a>	NO						
<a href="#">1-794617-6</a>	NO						
<a href="#">103653-1</a>	NO			"010-0961-00"			
<a href="#">103653-2</a>	NO			"010-0962-00"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">103653-4</a>	NO						
<a href="#">104257-1</a>	NO						
<a href="#">104257-2</a>	NO			"AMP-0-0104257-2", "C75259-000", "030-0095-00"			
<a href="#">104257-3</a>	NO						
<a href="#">104257-5</a>	NO			"030-0096-00"			
<a href="#">104479-9</a>	NO						
<a href="#">104480-2</a>	NO						
<a href="#">106455-3</a>	NO						
<a href="#">1123721-2</a>	NO						
<a href="#">1217138-1</a>	NO						
<a href="#">1375819-3</a>	NO						
<a href="#">142685-3</a>	NO						
<a href="#">1445049-4</a>	NO						
<a href="#">1445389-3</a>	NO						
<a href="#">154718-3</a>	NO						
<a href="#">154719</a>	NO			"154719-0"			
<a href="#">154719-1</a>	NO			"0-0154719-1"			
<a href="#">1601117-1</a>	NO			"150-003-000"			
<a href="#">1601140-1</a>	NO			"153-001-000"			
<a href="#">1601623-1</a>	NO			"L061D16TB"			
<a href="#">170003-4</a>	NO						
<a href="#">170360-3</a>	NO						
<a href="#">170362-3</a>	NO						
<a href="#">171637-1</a>	NO						
<a href="#">172159-1</a>	NO						
<a href="#">1744144-1</a>	NO						
<a href="#">177898-1</a>	NO						
<a href="#">177915-1</a>	NO						
<a href="#">177916-1</a>	NO						
<a href="#">2-1601140-1</a>	NO			"153-004-000"			
<a href="#">2-31819-1</a>	NO						
<a href="#">2-31894-2</a>	NO			"405223587"			
<a href="#">2-31895-1</a>	NO						
<a href="#">2-31897-2</a>	NO			"F55945-000", "RAYVOSS-22-16/22-18-R3/8"			
<a href="#">2-320563-2</a>	NO						
<a href="#">2-320568-1</a>	NO			"403802838"			
<a href="#">2-32952-1</a>	NO						
<a href="#">2-33457-2</a>	NO			"401771357"			
<a href="#">2-33458-3</a>	NO						
<a href="#">2-34112-2</a>	NO						
<a href="#">2-34113-2</a>	NO						
<a href="#">2-34123-1</a>	NO			"405109166"			
<a href="#">2-34144-1</a>	NO						
<a href="#">2-34161-1</a>	NO						
<a href="#">2-34162-1</a>	NO						
<a href="#">2-34163-1</a>	NO						
<a href="#">2-34164-2</a>	NO						
<a href="#">2-35109-1</a>	NO			"1140297", "1139542"			
<a href="#">2-36153-2</a>	NO						
<a href="#">2-36160-1</a>	NO						
<a href="#">2-36161-2</a>	NO			"402624795"			
<a href="#">2-794617-4</a>	NO						
<a href="#">201692-4</a>	NO						
<a href="#">206036-2</a>	NO						
<a href="#">206037-1</a>	NO			"A33294-000", "AMPS-0-0206037-1"			
<a href="#">206037-2</a>	NO						
<a href="#">206070-8</a>	NO						
<a href="#">206150-1</a>	NO						
<a href="#">206151-2</a>	NO						
<a href="#">206322-9</a>	NO						



Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">206708-1</a>	NO						
<a href="#">206966-9</a>	NO						
<a href="#">2132781-3</a>	NO						
<a href="#">2132813-2</a>	NO						
<a href="#">3-640252-1</a>	NO						
<a href="#">3-640311-1</a>	NO						
<a href="#">3-640401-1</a>	NO						
<a href="#">3-641190-5</a>	NO						
<a href="#">3-770060-1</a>	NO						
<a href="#">3-794121-1</a>	NO						
<a href="#">31818</a>	NO			"768360-000", "AMPS-0-0031818-0"			
<a href="#">320619</a>	NO			"AMPS-0-0320619-0", "C41604-000", "4-00520-1990"			
<a href="#">320764</a>	NO						
<a href="#">321253</a>	NO						
<a href="#">324047</a>	NO			"A42815-000", "AMP-0-0324047-0"			
<a href="#">33220</a>	NO						
<a href="#">33460</a>	NO			"CS4742-000", "AMPS-0-0033460-0"			
<a href="#">33465</a>	NO			"AMP-0-0033465-0", "F07864-000"			
<a href="#">34070</a>	NO			"268412-000", "AMPS-0-0034070-0"			
<a href="#">34072</a>	NO			"611528-000", "AMPS-0-0034072-0"			
<a href="#">34125</a>	NO			"AMP-0-0034125-0", "F03616-000"			
<a href="#">34130</a>	NO						
<a href="#">34137</a>	NO			"F21569-000", "AMPS-0-0034137-0"			
<a href="#">34138</a>	NO			"CM8395-000", "AMP-0-0034138-0"			
<a href="#">34318</a>	NO			"AMPS-0-0034318-0", "C05587-000"			
<a href="#">350210-1</a>	NO			"407072693"			
<a href="#">350218-1</a>	NO						
<a href="#">350536-1</a>	NO			"403429822"			
<a href="#">350537-3</a>	NO						
<a href="#">350558-1</a>	NO						
<a href="#">350561-1</a>	NO			"0-0350561-1", "CU3085-000", "AMPS-0-0350561-1"			
<a href="#">350570-1</a>	NO						
<a href="#">350767-1</a>	NO			"AMP-0-0350767-1", "F84278-000"			
<a href="#">350778-1</a>	NO			"403738545", "AMPS-0-0350778-1", "E83488-000", "500-020-2698", "500-020-0104"			
<a href="#">350851-1</a>	NO			"0-0350851-1", "2021755", "CU3086-000", "AMPS-0-0350851-1"			
<a href="#">350923-3</a>	NO			"403980899"			
<a href="#">35109</a>	NO			"AMPS-0-0035109-0", "F67095-000"			
<a href="#">35110</a>	NO			"AMPS-0-0035110-0", "E36230-000", "2-14492-3100"			
<a href="#">35669</a>	NO						
<a href="#">36946</a>	NO			"CN3419-000", "AMPS-0-0036946-0"			
<a href="#">36951</a>	NO						
<a href="#">36958</a>	NO						
<a href="#">41770</a>	NO						
<a href="#">4367790003</a>	NO			"1-1193283-5", "ES-CAP-NO.2-B9-0-35MM"			
<a href="#">5053094268</a>	NO			"4-1193845-5", "RNF-100-1/4-BK-SP"			
<a href="#">5053344102</a>	NO			"4-1193882-5", "RNF-100-1-1/2-BK-SP"			
<a href="#">5058724002</a>	NO			"5-1193906-0", "VERSAFIT-3/16-0-SP"			
<a href="#">5058744001</a>	NO			"1193907-8", "VERSAFIT-1/4-0-SP"			
<a href="#">5070064069</a>	NO			"2-1193963-6", "RNF-100-1/4-CL-SP"			
<a href="#">51863</a>	NO			"4-16211-9784"			
<a href="#">51863-1</a>	NO						
<a href="#">51864-3</a>	NO						
<a href="#">52943-1</a>	NO			"401771464"			
<a href="#">5510320002</a>	NO			"3-1194355-8", "PD-CAP-1/8-0"			
<a href="#">55785-1</a>	NO			"AMP-0-0055785-1", "D10979-000"			
<a href="#">61085-1</a>	NO						
<a href="#">61117-1</a>	NO			"403631302"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">61118-1</a>	NO			"0-0061118-1"			
<a href="#">61314-1</a>	NO			"403334121", "0-0061314-1", "14629", "1101201"			
<a href="#">61622-1</a>	NO						
<a href="#">62305-2</a>	NO						
<a href="#">62310-2</a>	NO						
<a href="#">62311-2</a>	NO						
<a href="#">640251-7</a>	NO						
<a href="#">640388-2</a>	NO						
<a href="#">640388-3</a>	NO						
<a href="#">640456-2</a>	NO			"403612641", "2-42934-0583"			
<a href="#">640456-5</a>	NO						
<a href="#">640903-2</a>	NO						
<a href="#">640923-2</a>	NO			"1181513"			
<a href="#">647402-2</a>	NO						
<a href="#">647402-3</a>	NO						
<a href="#">66098-8</a>	NO						
<a href="#">66100-8</a>	NO						
<a href="#">66102-8</a>	NO						
<a href="#">66104-8</a>	NO						
<a href="#">66358-9</a>	NO						
<a href="#">66359-9</a>	NO						
<a href="#">770007-1</a>	NO						
<a href="#">770008-3</a>	NO						
<a href="#">770476-1</a>	NO						
<a href="#">770476-2</a>	NO						
<a href="#">770579-1</a>	NO			"0-0770579-1"			
<a href="#">770580-1</a>	NO			"0-0770580-1"			
<a href="#">770849-4</a>	NO						
<a href="#">770903-1</a>	NO			"E25278-000", "DUL-PIN-22-18AW-S/M-UMNL"			
<a href="#">770904-1</a>	NO			"2-42939-6041"			
<a href="#">794219-1</a>	NO						
<a href="#">794221-1</a>	NO						
<a href="#">794223-1</a>	NO						
<a href="#">794272-1</a>	NO						
<a href="#">794412-1</a>	NO						
<a href="#">794606-1</a>	NO			"AMPS-0-0794606-1", "F30642-000"			
<a href="#">794616-4</a>	NO						
<a href="#">794616-6</a>	NO						
<a href="#">794617-8</a>	NO						
<a href="#">794758-1</a>	NO						
<a href="#">794781-1</a>	NO						
<a href="#">87631-2</a>	NO						

Customer: Heilind Electronics( 264685 )

Location: Hudson

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-104480-7</a>	NO						
<a href="#">104479-9</a>	NO						
<a href="#">2-34161-1</a>	NO						
<a href="#">2-36153-2</a>	NO						
<a href="#">5058724002</a>	NO			"5-1193906-0", "VERSAFIT-3/16-0-SP"			
<a href="#">5058744001</a>	NO			"1193907-8", "VERSAFIT-1/4-0-SP"			
<a href="#">66098-8</a>	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">66102-8</a>	NO						
<a href="#">66104-8</a>	NO						
<a href="#">66358-9</a>	NO						
<a href="#">770904-1</a>	NO			"2-42939-6041"			

Customer: Heilind Asia Pacific (Hong Kong)( 2991513 )

Location: Hong Kong

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-104479-0</a>	NO						
<a href="#">1-104480-7</a>	NO						
<a href="#">1-160759-1</a>	NO						
<a href="#">1-480270-0</a>	NO			"1-0480270-0"			
<a href="#">1-480318-0</a>	NO			"A77825-000", "AMP-1-0480318-0"			
<a href="#">1-480319-0</a>	NO						
<a href="#">1-480350-0</a>	NO						
<a href="#">1-480416-0</a>	NO						
<a href="#">1-480698-0</a>	NO			"834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341"			
<a href="#">1-480700-0</a>	NO			"AMPS-1-0480700-0", "F47049-000", "1-0480700-0", "2-42932-9342"			
<a href="#">1-480701-0</a>	NO						
<a href="#">1-480705-0</a>	NO			"1-0480705-0"			
<a href="#">1-480706-0</a>	NO			"873818-000", "AMPS-1-0480706-0", "2-42934-0301"			
<a href="#">1-770904-0</a>	NO						
<a href="#">1-770968-1</a>	NO						
<a href="#">1-794606-2</a>	NO						
<a href="#">1-794608-0</a>	NO						
<a href="#">1-794617-2</a>	NO						
<a href="#">1-794617-6</a>	NO						
<a href="#">103653-1</a>	NO			"010-0961-00"			
<a href="#">103653-2</a>	NO			"010-0962-00"			
<a href="#">103653-4</a>	NO						
<a href="#">104257-1</a>	NO						
<a href="#">104257-2</a>	NO			"AMP-0-0104257-2", "C75259-000", "030-0095-00"			
<a href="#">104257-3</a>	NO						
<a href="#">104257-5</a>	NO			"030-0096-00"			
<a href="#">104479-9</a>	NO						
<a href="#">104480-2</a>	NO						
<a href="#">1375819-3</a>	NO						
<a href="#">154717-7</a>	NO						
<a href="#">154719-1</a>	NO			"0-0154719-1"			
<a href="#">160173-2</a>	NO						
<a href="#">163300-6</a>	NO						
<a href="#">170360-3</a>	NO						
<a href="#">170362-3</a>	NO						
<a href="#">171637-1</a>	NO						
<a href="#">172159-1</a>	NO						
<a href="#">2-36160-1</a>	NO						
<a href="#">206036-2</a>	NO						
<a href="#">206037-1</a>	NO			"A33294-000", "AMPS-0-0206037-1"			
<a href="#">206037-2</a>	NO						
<a href="#">206070-8</a>	NO						
<a href="#">206322-9</a>	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">206708-1</a>	NO						
<a href="#">3-640252-1</a>	NO						
<a href="#">3-640311-1</a>	NO						
<a href="#">3-640401-1</a>	NO						
<a href="#">3-770060-1</a>	NO						
<a href="#">320619</a>	NO			"AMPS-0-0320619-0", "C41604-000", "4-00520-1990"			
<a href="#">321253</a>	NO						
<a href="#">321576</a>	NO						
<a href="#">324047</a>	NO			"A42815-000", "AMP-0-0324047-0"			
<a href="#">33460</a>	NO			"CS4742-000", "AMPS-0-0033460-0"			
<a href="#">33465</a>	NO			"AMP-0-0033465-0", "F07864-000"			
<a href="#">34138</a>	NO			"CM8395-000", "AMP-0-0034138-0"			
<a href="#">350210-1</a>	NO			"407072693"			
<a href="#">350218-1</a>	NO						
<a href="#">350536-1</a>	NO			"403429822"			
<a href="#">350558-1</a>	NO						
<a href="#">350561-1</a>	NO			"0-0350561-1", "CU3085-000", "AMPS-0-0350561-1"			
<a href="#">350570-1</a>	NO						
<a href="#">350767-1</a>	NO			"AMP-0-0350767-1", "F84278-000"			
<a href="#">350778-1</a>	NO			"403738545", "AMPS-0-0350778-1", "E83488-000", "500-020-2698", "500-020-0104"			
<a href="#">350851-1</a>	NO			"0-0350851-1", "2021755", "CU3086-000", "AMPS-0-0350851-1"			
<a href="#">350923-3</a>	NO			"403980899"			
<a href="#">35109</a>	NO			"AMPS-0-0035109-0", "F67095-000"			
<a href="#">35110</a>	NO			"AMPS-0-0035110-0", "E36230-000", "2-14492-3100"			
<a href="#">5053094268</a>	NO			"4-1193845-5", "RNF-100-1/4-BK-SP"			
<a href="#">5058724002</a>	NO			"5-1193906-0", "VERSAFIT-3/16-0-SP"			
<a href="#">5058744001</a>	NO			"1193907-8", "VERSAFIT-1/4-0-SP"			
<a href="#">51863</a>	NO			"4-16211-9784"			
<a href="#">51864-3</a>	NO						
<a href="#">61117-1</a>	NO			"403631302"			
<a href="#">61118-1</a>	NO			"0-0061118-1"			
<a href="#">61314-1</a>	NO			"403334121", "0-0061314-1", "14629", "1101201"			
<a href="#">640456-5</a>	NO						
<a href="#">66098-8</a>	NO						
<a href="#">66100-8</a>	NO						
<a href="#">66102-8</a>	NO						
<a href="#">66104-8</a>	NO						
<a href="#">66358-9</a>	NO						
<a href="#">66359-9</a>	NO						
<a href="#">770007-1</a>	NO						
<a href="#">770008-3</a>	NO						
<a href="#">770476-2</a>	NO						
<a href="#">770579-1</a>	NO			"0-0770579-1"			
<a href="#">770580-1</a>	NO			"0-0770580-1"			
<a href="#">770849-4</a>	NO						
<a href="#">770903-1</a>	NO			"E25278-000", "DUL-PIN-22-18AW-S/M-UMNL"			
<a href="#">770904-1</a>	NO			"2-42939-6041"			
<a href="#">794219-1</a>	NO						
<a href="#">794221-1</a>	NO						
<a href="#">794223-1</a>	NO						
<a href="#">794606-1</a>	NO			"AMPS-0-0794606-1", "F30642-000"			
<a href="#">794617-8</a>	NO						
<a href="#">794758-1</a>	NO						
<a href="#">796075-1</a>	NO						
<a href="#">926291-1</a>	NO						

Customer: Heilind Electronics( 206835 )

Location: Highland Heights

Agreement Number: Agreement Unknown

## Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">5058724002</a>	NO			"5-1193906-0", "VERSAFIT-3/16-0-SP"			

Customer: Heilind Electronics( 2873183 )

Location: Hudson

Agreement Number: Agreement Unknown

## Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-104479-0</a>	NO						
<a href="#">1-104480-7</a>	NO						
<a href="#">1-480318-0</a>	NO			"A77825-000", "AMP-1-0480318-0"			
<a href="#">1-480319-0</a>	NO						
<a href="#">1-480698-0</a>	NO			"834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341"			
<a href="#">1-480699-0</a>	NO			"402376412", "1-0480699-0", "500-060-1982", "4-27202-1755"			
<a href="#">1-480700-0</a>	NO			"AMPS-1-0480700-0", "F47049-000", "1-0480700-0", "2-42932-9342"			
<a href="#">1-480701-0</a>	NO						
<a href="#">1-480706-0</a>	NO			"873818-000", "AMPS-1-0480706-0", "2-42934-0301"			
<a href="#">1-770904-0</a>	NO						
<a href="#">1-794606-2</a>	NO						
<a href="#">1-794608-0</a>	NO						
<a href="#">104257-2</a>	NO			"AMP-0-0104257-2", "C75259-000", "030-0095-00"			
<a href="#">104479-9</a>	NO						
<a href="#">104480-2</a>	NO						
<a href="#">1123721-2</a>	NO						
<a href="#">1375819-3</a>	NO						
<a href="#">170360-3</a>	NO						
<a href="#">170362-3</a>	NO						
<a href="#">171637-1</a>	NO						
<a href="#">172159-1</a>	NO						
<a href="#">2-31894-2</a>	NO			"405223587"			
<a href="#">2-320568-1</a>	NO			"403802838"			
<a href="#">2-33457-2</a>	NO			"401771357"			
<a href="#">2-34144-1</a>	NO						
<a href="#">2-34161-1</a>	NO						
<a href="#">2-36153-2</a>	NO						
<a href="#">2-36160-1</a>	NO						
<a href="#">2-36161-2</a>	NO			"402624795"			
<a href="#">3-640252-1</a>	NO						
<a href="#">3-640311-1</a>	NO						
<a href="#">3-770060-1</a>	NO						
<a href="#">350218-1</a>	NO						
<a href="#">350536-1</a>	NO			"403429822"			
<a href="#">350537-3</a>	NO						
<a href="#">350558-1</a>	NO						
<a href="#">350561-1</a>	NO			"0-0350561-1", "CU3085-000", "AMPS-0-0350561-1"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">350570-1</a>	NO						
<a href="#">350767-1</a>	NO			"AMP-0-0350767-1", "F84278-000"			
<a href="#">350851-1</a>	NO			"0-0350851-1", "2021755", "CU3086-000", "AMPS-0-0350851-1"			
<a href="#">350923-3</a>	NO			"403980899"			
<a href="#">5053194267</a>	NO			"3-1193862-4", "RNF-100-1/2-BK-SP", "RNF-100-1/2-0"			
<a href="#">5053344102</a>	NO			"4-1193882-5", "RNF-100-1-1/2-BK-SP"			
<a href="#">5058724002</a>	NO			"5-1193906-0", "VERSAFIT-3/16-0-SP"			
<a href="#">5058744001</a>	NO			"1193907-8", "VERSAFIT-1/4-0-SP"			
<a href="#">61117-1</a>	NO			"403631302"			
<a href="#">61118-1</a>	NO			"0-0061118-1"			
<a href="#">61314-1</a>	NO			"403334121", "0-0061314-1", "14629", "1101201"			
<a href="#">640251-7</a>	NO						
<a href="#">640456-5</a>	NO						
<a href="#">640903-2</a>	NO						
<a href="#">640923-2</a>	NO			"1181513"			
<a href="#">66098-8</a>	NO						
<a href="#">66100-8</a>	NO						
<a href="#">66102-8</a>	NO						
<a href="#">66104-8</a>	NO						
<a href="#">66358-9</a>	NO						
<a href="#">66359-9</a>	NO						
<a href="#">770007-1</a>	NO						
<a href="#">770008-3</a>	NO						
<a href="#">770476-1</a>	NO						
<a href="#">770476-2</a>	NO						
<a href="#">770849-4</a>	NO						
<a href="#">770903-1</a>	NO			"E25278-000", "DUL-PIN-22-18AWS/M-UMNL"			
<a href="#">770904-1</a>	NO			"2-42939-6041"			
<a href="#">794219-1</a>	NO						
<a href="#">794223-1</a>	NO						
<a href="#">794606-1</a>	NO			"AMPS-0-0794606-1", "F30642-000"			
<a href="#">794617-8</a>	NO						

Customer: Heilind Asia Pacific (Hong Kong)( 2980376 )

Location: Hong Kong

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-104479-0</a>	NO						
<a href="#">1-104480-7</a>	NO						
<a href="#">1-160759-1</a>	NO						
<a href="#">1-480270-0</a>	NO			"1-0480270-0"			
<a href="#">1-480318-0</a>	NO			"A77825-000", "AMP-1-0480318-0"			
<a href="#">1-480319-0</a>	NO						
<a href="#">1-480350-0</a>	NO						
<a href="#">1-480416-0</a>	NO						
<a href="#">1-480698-0</a>	NO			"834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341"			
<a href="#">1-480700-0</a>	NO			"AMPS-1-0480700-0", "F47049-000", "1-0480700-0", "2-42932-9342"			
<a href="#">1-480701-0</a>	NO						
<a href="#">1-480705-0</a>	NO			"1-0480705-0"			
<a href="#">1-480706-0</a>	NO			"873818-000", "AMPS-1-0480706-0", "2-42934-0301"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-770904-0</a>	NO						
<a href="#">1-770968-1</a>	NO						
<a href="#">1-794606-2</a>	NO						
<a href="#">1-794608-0</a>	NO						
<a href="#">1-794617-2</a>	NO						
<a href="#">1-794617-6</a>	NO						
<a href="#">103653-1</a>	NO			"010-0961-00"			
<a href="#">103653-2</a>	NO			"010-0962-00"			
<a href="#">103653-4</a>	NO						
<a href="#">104257-1</a>	NO						
<a href="#">104257-2</a>	NO			"AMP-0-0104257-2", "C75259-000", "030-0095-00"			
<a href="#">104257-3</a>	NO						
<a href="#">104257-5</a>	NO			"030-0096-00"			
<a href="#">104479-9</a>	NO						
<a href="#">104480-2</a>	NO						
<a href="#">1375819-3</a>	NO						
<a href="#">154717-7</a>	NO						
<a href="#">154719-1</a>	NO			"0-0154719-1"			
<a href="#">160173-2</a>	NO						
<a href="#">163300-6</a>	NO						
<a href="#">170360-3</a>	NO						
<a href="#">170362-3</a>	NO						
<a href="#">171637-1</a>	NO						
<a href="#">172159-1</a>	NO						
<a href="#">177915-1</a>	NO						
<a href="#">2-36160-1</a>	NO						
<a href="#">206036-2</a>	NO						
<a href="#">206037-1</a>	NO			"A33294-000", "AMPS-0-0206037-1"			
<a href="#">206037-2</a>	NO						
<a href="#">206070-8</a>	NO		118408-3				
<a href="#">206322-9</a>	NO						
<a href="#">206708-1</a>	NO						
<a href="#">3-640252-1</a>	NO						
<a href="#">3-640311-1</a>	NO						
<a href="#">3-640401-1</a>	NO						
<a href="#">3-770060-1</a>	NO						
<a href="#">320619</a>	NO			"AMPS-0-0320619-0", "C41604-000", "4-00520-1990"			
<a href="#">321253</a>	NO						
<a href="#">321576</a>	NO						
<a href="#">324047</a>	NO			"A42815-000", "AMP-0-0324047-0"			
<a href="#">33460</a>	NO			"CS4742-000", "AMPS-0-0033460-0"			
<a href="#">33465</a>	NO			"AMP-0-0033465-0", "F07864-000"			
<a href="#">34138</a>	NO		5M392-3	"CM8395-000", "AMP-0-0034138-0"			
<a href="#">350210-1</a>	NO			"407072693"			
<a href="#">350218-1</a>	NO						
<a href="#">350536-1</a>	NO			"403429822"			
<a href="#">350558-1</a>	NO						
<a href="#">350561-1</a>	NO			"0-0350561-1", "CU3085-000", "AMPS-0-0350561-1"			
<a href="#">350570-1</a>	NO						
<a href="#">350767-1</a>	NO			"AMP-0-0350767-1", "F84278-000"			
<a href="#">350778-1</a>	NO			"403738545", "AMPS-0-0350778-1", "E83488-000", "500-020-2698", "500-020-0104"			
<a href="#">350851-1</a>	NO			"0-0350851-1", "2021755", "CU3086-000", "AMPS-0-0350851-1"			
<a href="#">350923-3</a>	NO			"403980899"			
<a href="#">35109</a>	NO			"AMPS-0-0035109-0", "F67095-000"			
<a href="#">35110</a>	NO			"AMPS-0-0035110-0", "E36230-000", "2-14492-3100"			
<a href="#">5053094268</a>	NO			"4-1193845-5", "RNF-100-1/4-BK-SP"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">5058724002</a>	NO			"5-1193906-0", "VERSAFIT-3/16-0-SP"			
<a href="#">5058744001</a>	NO			"1193907-8", "VERSAFIT-1/4-0-SP"			
<a href="#">51863</a>	NO			"4-16211-9784"			
<a href="#">51863-1</a>	NO						
<a href="#">51864-3</a>	NO						
<a href="#">61117-1</a>	NO			"403631302"			
<a href="#">61118-1</a>	NO			"0-0061118-1"			
<a href="#">61314-1</a>	NO			"403334121", "0-0061314-1", "14629", "1101201"			
<a href="#">640456-5</a>	NO						
<a href="#">66098-8</a>	NO						
<a href="#">66100-8</a>	NO						
<a href="#">66102-8</a>	NO						
<a href="#">66104-8</a>	NO						
<a href="#">66358-9</a>	NO						
<a href="#">66359-9</a>	NO						
<a href="#">770007-1</a>	NO						
<a href="#">770008-3</a>	NO						
<a href="#">770476-2</a>	NO						
<a href="#">770579-1</a>	NO			"0-0770579-1"			
<a href="#">770580-1</a>	NO			"0-0770580-1"			
<a href="#">770849-4</a>	NO						
<a href="#">770903-1</a>	NO			"E25278-000", "DUL-PIN-22-18AW-S/M-UMNL"			
<a href="#">770904-1</a>	NO			"2-42939-6041"			
<a href="#">794219-1</a>	NO						
<a href="#">794221-1</a>	NO						
<a href="#">794223-1</a>	NO						
<a href="#">794606-1</a>	NO			"AMPS-0-0794606-1", "F30642-000"			
<a href="#">794617-8</a>	NO						
<a href="#">794758-1</a>	NO						
<a href="#">796075-1</a>	NO						
<a href="#">926291-1</a>	NO						

Customer: Heilind Asia Pacific (SG) Pte Ltd( 2980456 )

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-170823-3</a>	NO						
<a href="#">1-480270-0</a>	NO			"1-0480270-0"			
<a href="#">1-480416-0</a>	NO						
<a href="#">1-480698-0</a>	NO			"834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341"			
<a href="#">1-480700-0</a>	NO			"AMPS-1-0480700-0", "F47049-000", "1-0480700-0", "2-42932-9342"			
<a href="#">1-794606-2</a>	NO						
<a href="#">104257-2</a>	NO			"AMP-0-0104257-2", "C75259-000", "030-0095-00"			
<a href="#">104257-5</a>	NO			"030-0096-00"			
<a href="#">1375819-3</a>	NO						
<a href="#">154717-7</a>	NO						
<a href="#">170360-3</a>	NO						
<a href="#">171637-1</a>	NO						
<a href="#">177914-1</a>	NO						
<a href="#">206037-1</a>	NO			"A33294-000", "AMPS-0-0206037-1"			
<a href="#">206070-8</a>	NO		118408-3				
<a href="#">206322-9</a>	NO						



Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">2201778-1</a>	NO						
<a href="#">3-640252-1</a>	NO						
<a href="#">3-770060-1</a>	NO						
<a href="#">321253</a>	NO						
<a href="#">350218-1</a>	NO						
<a href="#">350561-1</a>	NO			"0-0350561-1", "CU3085-000", "AMPS-0-0350561-1"			
<a href="#">350767-1</a>	NO			"AMP-0-0350767-1", "F84278-000"			
<a href="#">350778-1</a>	NO			"403738545", "AMPS-0-0350778-1", "E83488-000", "500-020-2698", "500-020-0104"			
<a href="#">350851-1</a>	NO			"0-0350851-1", "2021755", "CU3086-000", "AMPS-0-0350851-1"			
<a href="#">35110</a>	NO			"AMPS-0-0035110-0", "E36230-000", "2-14492-3100"			
<a href="#">4-794636-2</a>	NO						
<a href="#">51863</a>	NO			"4-16211-9784"			
<a href="#">61117-1</a>	NO			"403631302"			
<a href="#">61314-1</a>	NO			"403334121", "0-0061314-1", "14629", "1101201"			
<a href="#">640456-2</a>	NO			"403612641", "2-42934-0583"			
<a href="#">66102-8</a>	NO						
<a href="#">770008-3</a>	NO						
<a href="#">770579-1</a>	NO			"0-0770579-1"			
<a href="#">794272-1</a>	NO						
<a href="#">794606-1</a>	NO			"AMPS-0-0794606-1", "F30642-000"			
<a href="#">926291-1</a>	NO						

Customer: Heilind Asia Pacific (HK) Ltd( 3087523 )

Location: Dongguan

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-794606-2</a>	NO						
<a href="#">3-794121-1</a>	NO						
<a href="#">796075-1</a>	NO						

Customer: Heilind Electronics( 1276409 )

Location: Plano

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-480699-0</a>	NO			"402376412", "1-0480699-0", "500-060-1982", "4-27202-1755"			
<a href="#">1-480700-0</a>	NO			"AMPS-1-0480700-0", "F47049-000", "1-0480700-0", "2-42932-9342"			
<a href="#">1-480701-0</a>	NO						
<a href="#">177915-1</a>	NO						
<a href="#">2-33457-2</a>	NO			"401771357"			
<a href="#">2-33458-3</a>	NO						
<a href="#">2-34161-1</a>	NO						
<a href="#">2-34162-1</a>	NO						
<a href="#">2-34164-2</a>	NO						
<a href="#">2-35109-1</a>	NO			"1140297", "1139542"			
<a href="#">316086-1</a>	NO						
<a href="#">350218-1</a>	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">350536-1</a>	NO			"403429822"			
<a href="#">350767-1</a>	NO			"AMP-0-0350767-1", "F84278-000"			
<a href="#">770007-1</a>	NO						
<a href="#">794616-6</a>	NO						

Customer: Heilind Electronics Inc( 2914597 )

Location: Brookfield

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1445389-3</a>	NO						
<a href="#">34070</a>	NO			"268412-000", "AMPS-0-0034070-0"			
<a href="#">794781-1</a>	NO						

Customer: Heilind Electronics( 2932930 )

Location: McAllen

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-794617-6</a>	NO						
<a href="#">350778-1</a>	NO			"403738545", "AMPS-0-0350778-1", "E83488-000", "500-020-2698", "500-020-0104"			
<a href="#">61118-1</a>	NO			"0-0061118-1"			

Customer: Kotek Eletro Eletronica Ltda( 2786372 )

Location: Sao Paulo

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-480700-0</a>	NO			"AMPS-1-0480700-0", "F47049-000", "1-0480700-0", "2-42932-9342"			
<a href="#">1-480705-0</a>	NO			"1-0480705-0"			
<a href="#">160467-2</a>	NO						
<a href="#">170362-3</a>	NO						
<a href="#">172159-1</a>	NO						
<a href="#">177914-1</a>	NO						
<a href="#">177915-1</a>	NO						
<a href="#">2-36160-1</a>	NO						
<a href="#">206037-2</a>	NO						
<a href="#">61118-1</a>	NO			"0-0061118-1"			
<a href="#">770476-1</a>	NO						
<a href="#">794272-1</a>	NO						

Customer: Heilind Electronics Inc( 2914594 )

Location: San Jose

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
-------------	---------------------------	------------------	----------------------	----------------------	------------------------	---------------------------------	---------------------------

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">2-35109-1</a>	NO			"1140297", "1139542"			

Customer: Heilind Asia Pacific (SG) Pte Ltd( 2980456 )

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-170823-3</a>	NO						
<a href="#">1-480270-0</a>	NO			"1-0480270-0"			
<a href="#">1-480416-0</a>	NO						
<a href="#">1-480698-0</a>	NO			"834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341"			
<a href="#">1-480700-0</a>	NO			"AMPS-1-0480700-0", "F47049-000", "1-0480700-0", "2-42932-9342"			
<a href="#">1-794606-2</a>	NO						
<a href="#">104257-2</a>	NO			"AMP-0-0104257-2", "C75259-000", "030-0095-00"			
<a href="#">104257-5</a>	NO			"030-0096-00"			
<a href="#">1375819-3</a>	NO						
<a href="#">154717-7</a>	NO						
<a href="#">170360-3</a>	NO						
<a href="#">171637-1</a>	NO						
<a href="#">177914-1</a>	NO						
<a href="#">206037-1</a>	NO			"A33294-000", "AMPS-0-0206037-1"			
<a href="#">206070-8</a>	NO		118408-3				
<a href="#">206322-9</a>	NO						
<a href="#">2201778-1</a>	NO						
<a href="#">3-640252-1</a>	NO						
<a href="#">3-770060-1</a>	NO						
<a href="#">321253</a>	NO						
<a href="#">350218-1</a>	NO						
<a href="#">350561-1</a>	NO			"0-0350561-1", "CU3085-000", "AMPS- 0-0350561-1"			
<a href="#">350767-1</a>	NO			"AMP-0-0350767-1", "F84278-000"			
<a href="#">350778-1</a>	NO			"403738545", "AMPS-0-0350778-1", "E83488-000", "500-020-2698", "500-020-0104"			
<a href="#">350851-1</a>	NO			"0-0350851-1", "2021755", "CU3086-000", "AMPS-0-0350851-1"			
<a href="#">35110</a>	NO			"AMPS-0-0035110-0", "E36230-000", "2-14492-3100"			
<a href="#">4-794636-2</a>	NO						
<a href="#">51863</a>	NO			"4-16211-9784"			
<a href="#">61117-1</a>	NO			"403631302"			
<a href="#">61314-1</a>	NO			"403334121", "0-0061314-1", "14629", "1101201"			
<a href="#">640456-2</a>	NO			"403612641", "2-42934-0583"			
<a href="#">66102-8</a>	NO						
<a href="#">770008-3</a>	NO						
<a href="#">770579-1</a>	NO			"0-0770579-1"			
<a href="#">794272-1</a>	NO						
<a href="#">794606-1</a>	NO			"AMPS-0-0794606-1", "F30642-000"			
<a href="#">926291-1</a>	NO						

Customer: Heilind Asia Pacific (SG) Pte Ltd( 2980456 )

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-170823-3</a>	NO						
<a href="#">1-480270-0</a>	NO			"1-0480270-0"			
<a href="#">1-480416-0</a>	NO						
<a href="#">1-480698-0</a>	NO			"834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341"			
<a href="#">1-480700-0</a>	NO			"AMPS-1-0480700-0", "F47049-000", "1-0480700-0", "2-42932-9342"			
<a href="#">1-794606-2</a>	NO						
<a href="#">104257-2</a>	NO			"AMP-0-0104257-2", "C75259-000", "030-0095-00"			
<a href="#">104257-5</a>	NO			"030-0096-00"			
<a href="#">1375819-3</a>	NO						
<a href="#">154717-7</a>	NO						
<a href="#">170360-3</a>	NO						
<a href="#">171637-1</a>	NO						
<a href="#">177914-1</a>	NO						
<a href="#">206037-1</a>	NO			"A33294-000", "AMPS-0-0206037-1"			
<a href="#">206070-8</a>	NO		118408-3				
<a href="#">206322-9</a>	NO						
<a href="#">2201778-1</a>	NO						
<a href="#">3-640252-1</a>	NO						
<a href="#">3-770060-1</a>	NO						
<a href="#">321253</a>	NO						
<a href="#">350218-1</a>	NO						
<a href="#">350561-1</a>	NO			"0-0350561-1", "CU3085-000", "AMPS- 0-0350561-1"			
<a href="#">350767-1</a>	NO			"AMP-0-0350767-1", "F84278-000"			
<a href="#">350778-1</a>	NO			"403738545", "AMPS-0-0350778-1", "E83488-000", "500-020-2698", "500-020-0104"			
<a href="#">350851-1</a>	NO			"0-0350851-1", "2021755", "CU3086-000", "AMPS-0-0350851-1"			
<a href="#">35110</a>	NO			"AMPS-0-0035110-0", "E36230-000", "2-14492-3100"			
<a href="#">4-794636-2</a>	NO						
<a href="#">51863</a>	NO			"4-16211-9784"			
<a href="#">61117-1</a>	NO			"403631302"			
<a href="#">61314-1</a>	NO			"403334121", "0-0061314-1", "14629", "1101201"			
<a href="#">640456-2</a>	NO			"403612641", "2-42934-0583"			
<a href="#">66102-8</a>	NO						
<a href="#">770008-3</a>	NO						
<a href="#">770579-1</a>	NO			"0-0770579-1"			
<a href="#">794272-1</a>	NO						
<a href="#">794606-1</a>	NO			"AMPS-0-0794606-1", "F30642-000"			
<a href="#">926291-1</a>	NO						

Customer: Heilind Asia Pacific (SG) Pte Ltd( 3076161 )

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-480698-0</a>	NO			"834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341"			
<a href="#">1-480700-0</a>	NO			"AMPS-1-0480700-0", "F47049-000", "1-0480700-0", "2-42932-9342"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">170360-3</a>	NO						
<a href="#">171637-1</a>	NO						
<a href="#">206037-1</a>	NO			"A33294-000", "AMPS-0-0206037-1"			
<a href="#">350561-1</a>	NO			"0-0350561-1", "CU3085-000", "AMPS-0-0350561-1"			
<a href="#">794272-1</a>	NO						

Customer: Heilind Electronics( 1275266 )

Location: Visalia

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-104479-3</a>	NO						
<a href="#">1-104480-7</a>	NO						
<a href="#">1-160759-1</a>	NO						
<a href="#">1-176497-1</a>	NO						
<a href="#">1-33220-2</a>	NO						
<a href="#">1-35115-0</a>	NO						
<a href="#">1-480270-0</a>	NO			"1-0480270-0"			
<a href="#">1-480283-0</a>	NO						
<a href="#">1-480318-0</a>	NO			"A77825-000", "AMP-1-0480318-0"			
<a href="#">1-480319-0</a>	NO						
<a href="#">1-480319-9</a>	NO						
<a href="#">1-480350-0</a>	NO						
<a href="#">1-480416-1</a>	NO						
<a href="#">1-480698-0</a>	NO			"834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341"			
<a href="#">1-480699-0</a>	NO			"402376412", "1-0480699-0", "500-060-1982", "4-27202-1755"			
<a href="#">1-480700-0</a>	NO			"AMPS-1-0480700-0", "F47049-000", "1-0480700-0", "2-42932-9342"			
<a href="#">1-480701-0</a>	NO						
<a href="#">1-480705-0</a>	NO			"1-0480705-0"			
<a href="#">1-480706-0</a>	NO			"873818-000", "AMPS-1-0480706-0", "2-42934-0301"			
<a href="#">1-770904-0</a>	NO						
<a href="#">1-794606-2</a>	NO						
<a href="#">1-794608-0</a>	NO						
<a href="#">1-794617-2</a>	NO						
<a href="#">1-794617-6</a>	NO						
<a href="#">103653-1</a>	NO			"010-0961-00"			
<a href="#">103653-2</a>	NO			"010-0962-00"			
<a href="#">103653-4</a>	NO						
<a href="#">104257-1</a>	NO						
<a href="#">104257-2</a>	NO			"AMP-0-0104257-2", "C75259-000", "030-0095-00"			
<a href="#">104257-3</a>	NO						
<a href="#">104257-5</a>	NO			"030-0096-00"			
<a href="#">104479-2</a>	NO						
<a href="#">104479-9</a>	NO						
<a href="#">106455-4</a>	NO						
<a href="#">1123721-2</a>	NO						
<a href="#">1375819-3</a>	NO						
<a href="#">1445049-4</a>	NO						
<a href="#">1445389-3</a>	NO						
<a href="#">154717-3</a>	NO						
<a href="#">154718-3</a>	NO						
<a href="#">154719</a>	NO			"154719-0"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">154719-1</a>	NO			"0-0154719-1"			
<a href="#">1601063-2</a>	NO			"131-129-021"			
<a href="#">171637-1</a>	NO						
<a href="#">172159-1</a>	NO						
<a href="#">177898-1</a>	NO						
<a href="#">177914-1</a>	NO						
<a href="#">177915-1</a>	NO						
<a href="#">2-31895-1</a>	NO						
<a href="#">2-320563-2</a>	NO						
<a href="#">2-320568-1</a>	NO			"403802838"			
<a href="#">2-32952-1</a>	NO						
<a href="#">2-33457-2</a>	NO			"401771357"			
<a href="#">2-33458-3</a>	NO						
<a href="#">2-34112-2</a>	NO						
<a href="#">2-34113-2</a>	NO						
<a href="#">2-34123-1</a>	NO			"405109166"			
<a href="#">2-34144-1</a>	NO						
<a href="#">2-34161-1</a>	NO						
<a href="#">2-34162-1</a>	NO						
<a href="#">2-34164-2</a>	NO						
<a href="#">2-35109-1</a>	NO			"1140297", "1139542"			
<a href="#">2-36153-2</a>	NO						
<a href="#">2-36160-1</a>	NO						
<a href="#">2-36161-2</a>	NO			"402624795"			
<a href="#">2-794617-4</a>	NO						
<a href="#">201692-4</a>	NO						
<a href="#">2029154002</a>	NO			"1-1191471-8", "RNF-150-1/2-0-SP"			
<a href="#">206036-2</a>	NO						
<a href="#">206037-1</a>	NO			"A33294-000", "AMPS-0-0206037-1"			
<a href="#">206037-2</a>	NO						
<a href="#">206070-8</a>	NO						
<a href="#">206150-1</a>	NO						
<a href="#">206151-2</a>	NO						
<a href="#">206322-9</a>	NO						
<a href="#">206708-1</a>	NO						
<a href="#">208652-1</a>	NO						
<a href="#">3-640252-1</a>	NO						
<a href="#">3-640311-1</a>	NO						
<a href="#">3-770060-1</a>	NO						
<a href="#">3-794121-1</a>	NO						
<a href="#">316086-1</a>	NO						
<a href="#">31818</a>	NO			"768360-000", "AMPS-0-0031818-0"			
<a href="#">320619</a>	NO			"AMPS-0-0320619-0", "C41604-000", "4-00520-1990"			
<a href="#">321253</a>	NO						
<a href="#">321576</a>	NO						
<a href="#">33460</a>	NO			"CS4742-000", "AMPS-0-0033460-0"			
<a href="#">33465</a>	NO			"AMP-0-0033465-0", "F07864-000"			
<a href="#">34070</a>	NO			"268412-000", "AMPS-0-0034070-0"			
<a href="#">34130</a>	NO						
<a href="#">34137</a>	NO			"F21569-000", "AMPS-0-0034137-0"			
<a href="#">34138</a>	NO			"CM8395-000", "AMP-0-0034138-0"			
<a href="#">34318</a>	NO			"AMPS-0-0034318-0", "C05587-000"			
<a href="#">350218-1</a>	NO						
<a href="#">350536-1</a>	NO			"403429822"			
<a href="#">350537-3</a>	NO						
<a href="#">350561-1</a>	NO			"0-0350561-1", "CU3085-000", "AMPS-0-0350561-1"			
<a href="#">350570-1</a>	NO						
<a href="#">350851-1</a>	NO			"0-0350851-1", "2021755", "CU3086-000", "AMPS-0-0350851-1"			
<a href="#">350923-3</a>	NO			"403980899"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">35109</a>	NO			"AMPS-0-0035109-0", "F67095-000"			
<a href="#">35110</a>	NO			"AMPS-0-0035110-0", "E36230-000", "2-14492-3100"			
<a href="#">36946</a>	NO			"CN3419-000", "AMPS-0-0036946-0"			
<a href="#">41765</a>	NO						
<a href="#">42776-1</a>	NO						
<a href="#">5053094268</a>	NO			"4-1193845-5", "RNF-100-1/4-BK-SP"			
<a href="#">5053194267</a>	NO			"3-1193862-4", "RNF-100-1/2-BK-SP", "RNF-100-1/2-0"			
<a href="#">5053344102</a>	NO			"4-1193882-5", "RNF-100-1-1/2-BK-SP"			
<a href="#">5058724002</a>	NO			"5-1193906-0", "VERSAFIT-3/16-0-SP"			
<a href="#">5058744001</a>	NO			"1193907-8", "VERSAFIT-1/4-0-SP"			
<a href="#">5070064069</a>	NO			"2-1193963-6", "RNF-100-1/4-CL-SP"			
<a href="#">51863</a>	NO			"4-16211-9784"			
<a href="#">51863-1</a>	NO						
<a href="#">52041</a>	NO						
<a href="#">53128-1</a>	NO						
<a href="#">53831-1</a>	NO						
<a href="#">5510320002</a>	NO			"3-1194355-8", "PD-CAP-1/8-0"			
<a href="#">61085-1</a>	NO						
<a href="#">61117-1</a>	NO			"403631302"			
<a href="#">61118-1</a>	NO			"0-0061118-1"			
<a href="#">61314-1</a>	NO			"403334121", "0-0061314-1", "14629", "1101201"			
<a href="#">62000-2</a>	NO						
<a href="#">62001-1</a>	NO						
<a href="#">62001-2</a>	NO						
<a href="#">62002-2</a>	NO						
<a href="#">62306-2</a>	NO						
<a href="#">62311-2</a>	NO						
<a href="#">62429-1</a>	NO						
<a href="#">62935-1</a>	NO						
<a href="#">640388-2</a>	NO						
<a href="#">640456-2</a>	NO			"403612641", "2-42934-0583"			
<a href="#">640456-5</a>	NO						
<a href="#">640903-2</a>	NO						
<a href="#">66098-8</a>	NO						
<a href="#">66100-8</a>	NO						
<a href="#">66102-8</a>	NO						
<a href="#">66104-8</a>	NO						
<a href="#">7-1393114-8</a>	NO			"KUHP-11D51-24"			
<a href="#">770007-1</a>	NO						
<a href="#">770008-3</a>	NO						
<a href="#">770476-2</a>	NO						
<a href="#">770579-1</a>	NO			"0-0770579-1"			
<a href="#">770580-1</a>	NO			"0-0770580-1"			
<a href="#">770849-4</a>	NO						
<a href="#">770903-1</a>	NO			"E25278-000", "DUL-PIN-22-18AWS/M-UMNL"			
<a href="#">770904-1</a>	NO			"2-42939-6041"			
<a href="#">794412-1</a>	NO						
<a href="#">794606-1</a>	NO			"AMPS-0-0794606-1", "F30642-000"			
<a href="#">794616-4</a>	NO						
<a href="#">794616-6</a>	NO						
<a href="#">794617-8</a>	NO						
<a href="#">794758-1</a>	NO						
<a href="#">796075-1</a>	NO						
<a href="#">796286-1</a>	NO						
<a href="#">87631-2</a>	NO						
<a href="#">917686-1</a>	NO						

Customer: Heilind Electronics( 167811 )

Location: Wilmington

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-104479-0</a>	NO						
<a href="#">1-104479-3</a>	NO						
<a href="#">1-104480-7</a>	NO						
<a href="#">1-1123722-5</a>	NO						
<a href="#">1-1123723-3</a>	NO						
<a href="#">1-160759-1</a>	NO						
<a href="#">1-176497-1</a>	NO						
<a href="#">1-324227-0</a>	NO						
<a href="#">1-33220-2</a>	NO						
<a href="#">1-35115-0</a>	NO						
<a href="#">1-480270-0</a>	NO			"1-0480270-0"			
<a href="#">1-480271-0</a>	NO						
<a href="#">1-480283-0</a>	NO						
<a href="#">1-480284-0</a>	NO						
<a href="#">1-480318-0</a>	NO			"A77825-000", "AMP-1-0480318-0"			
<a href="#">1-480319-0</a>	NO						
<a href="#">1-480319-9</a>	NO						
<a href="#">1-480350-0</a>	NO						
<a href="#">1-480388-0</a>	NO						
<a href="#">1-480416-0</a>	NO						
<a href="#">1-480416-1</a>	NO						
<a href="#">1-480698-0</a>	NO			"834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341"			
<a href="#">1-480699-0</a>	NO			"402376412", "1-0480699-0", "500-060-1982", "4-27202-1755"			
<a href="#">1-480700-0</a>	NO			"AMPS-1-0480700-0", "F47049-000", "1-0480700-0", "2-42932-9342"			
<a href="#">1-480701-0</a>	NO						
<a href="#">1-480705-0</a>	NO			"1-0480705-0"			
<a href="#">1-480706-0</a>	NO			"873818-000", "AMPS-1-0480706-0", "2-42934-0301"			
<a href="#">1-66105-8</a>	NO						
<a href="#">1-770904-0</a>	NO						
<a href="#">1-770968-1</a>	NO						
<a href="#">1-794606-2</a>	NO						
<a href="#">1-794608-0</a>	NO						
<a href="#">1-794617-2</a>	NO						
<a href="#">1-794617-6</a>	NO						
<a href="#">103653-1</a>	NO			"010-0961-00"			
<a href="#">103653-2</a>	NO			"010-0962-00"			
<a href="#">103653-4</a>	NO						
<a href="#">104257-1</a>	NO						
<a href="#">104257-2</a>	NO			"AMP-0-0104257-2", "C75259-000", "030-0095-00"			
<a href="#">104257-3</a>	NO						
<a href="#">104257-5</a>	NO			"030-0096-00"			
<a href="#">104479-2</a>	NO						
<a href="#">104479-9</a>	NO						
<a href="#">104480-2</a>	NO						
<a href="#">106455-3</a>	NO						
<a href="#">106455-4</a>	NO						
<a href="#">1123721-2</a>	NO						
<a href="#">1217138-1</a>	NO						
<a href="#">1375819-3</a>	NO						
<a href="#">142685-3</a>	NO						
<a href="#">1445049-4</a>	NO						



Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1445389-3</a>	NO						
<a href="#">154717-3</a>	NO						
<a href="#">154718-3</a>	NO						
<a href="#">154719</a>	NO			"154719-0"			
<a href="#">154719-1</a>	NO			"0-0154719-1"			
<a href="#">1601063-2</a>	NO			"131-129-021"			
<a href="#">1601117-1</a>	NO			"150-003-000"			
<a href="#">1601140-1</a>	NO			"153-001-000"			
<a href="#">1601623-1</a>	NO			"L061D16TB"			
<a href="#">160859-2</a>	NO						
<a href="#">163306-2</a>	NO						
<a href="#">170003-4</a>	NO						
<a href="#">170360-3</a>	NO						
<a href="#">170362-3</a>	NO						
<a href="#">171637-1</a>	NO						
<a href="#">172159-1</a>	NO						
<a href="#">1744144-1</a>	NO						
<a href="#">177898-1</a>	NO						
<a href="#">177914-1</a>	NO						
<a href="#">177915-1</a>	NO						
<a href="#">177916-1</a>	NO						
<a href="#">2-1601140-1</a>	NO			"153-004-000"			
<a href="#">2-31819-1</a>	NO						
<a href="#">2-31894-2</a>	NO			"405223587"			
<a href="#">2-31895-1</a>	NO						
<a href="#">2-31897-2</a>	NO			"F55945-000", "RAYVOSS-22-16/22-18-R3/8"			
<a href="#">2-320563-2</a>	NO						
<a href="#">2-320568-1</a>	NO			"403802838"			
<a href="#">2-32952-1</a>	NO						
<a href="#">2-33457-2</a>	NO			"401771357"			
<a href="#">2-33458-3</a>	NO						
<a href="#">2-34112-2</a>	NO						
<a href="#">2-34113-2</a>	NO						
<a href="#">2-34123-1</a>	NO			"405109166"			
<a href="#">2-34144-1</a>	NO						
<a href="#">2-34161-1</a>	NO						
<a href="#">2-34162-1</a>	NO						
<a href="#">2-34163-1</a>	NO						
<a href="#">2-34164-2</a>	NO						
<a href="#">2-35109-1</a>	NO			"1140297", "1139542"			
<a href="#">2-36153-2</a>	NO						
<a href="#">2-36160-1</a>	NO						
<a href="#">2-36161-2</a>	NO			"402624795"			
<a href="#">2-794617-4</a>	NO						
<a href="#">201692-4</a>	NO						
<a href="#">2029154002</a>	NO			"1-1191471-8", "RNF-150-1/2-0-SP"			
<a href="#">206036-2</a>	NO						
<a href="#">206037-1</a>	NO			"A33294-000", "AMPS-0-0206037-1"			
<a href="#">206037-2</a>	NO						
<a href="#">206070-8</a>	NO		118408-3				
<a href="#">206150-1</a>	NO						
<a href="#">206151-2</a>	NO						
<a href="#">206322-9</a>	NO						
<a href="#">206708-1</a>	NO						
<a href="#">206966-9</a>	NO						
<a href="#">208652-1</a>	NO						
<a href="#">2132781-3</a>	NO						
<a href="#">2132813-2</a>	NO						
<a href="#">3-640252-1</a>	NO						
<a href="#">3-640311-1</a>	NO						
<a href="#">3-640401-1</a>	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">3-641190-5</a>	NO						
<a href="#">3-770060-1</a>	NO						
<a href="#">3-794121-1</a>	NO						
<a href="#">316086-1</a>	NO						
<a href="#">31818</a>	NO			"768360-000", "AMPS-0-0031818-0"			
<a href="#">320619</a>	NO			"AMPS-0-0320619-0", "C41604-000", "4-00520-1990"			
<a href="#">320764</a>	NO						
<a href="#">321201</a>	NO						
<a href="#">321253</a>	NO						
<a href="#">321576</a>	NO						
<a href="#">324047</a>	NO			"A42815-000", "AMP-0-0324047-0"			
<a href="#">33220</a>	NO						
<a href="#">33460</a>	NO			"CS4742-000", "AMPS-0-0033460-0"			
<a href="#">33465</a>	NO			"AMP-0-0033465-0", "F07864-000"			
<a href="#">34070</a>	NO			"268412-000", "AMPS-0-0034070-0"			
<a href="#">34072</a>	NO			"611528-000", "AMPS-0-0034072-0"			
<a href="#">34125</a>	NO			"AMP-0-0034125-0", "F03616-000"			
<a href="#">34130</a>	NO		5M392-1				
<a href="#">34137</a>	NO		5M392-2	"F21569-000", "AMPS-0-0034137-0"			
<a href="#">34138</a>	NO		5M392-3	"CM8395-000", "AMP-0-0034138-0"			
<a href="#">34318</a>	NO		5M392-4	"AMPS-0-0034318-0", "C05587-000"			
<a href="#">350210-1</a>	NO			"407072693"			
<a href="#">350218-1</a>	NO						
<a href="#">350390-2</a>	NO						
<a href="#">350536-1</a>	NO			"403429822"			
<a href="#">350537-3</a>	NO						
<a href="#">350558-1</a>	NO						
<a href="#">350561-1</a>	NO			"0-0350561-1", "CU3085-000", "AMPS-0-0350561-1"			
<a href="#">350570-1</a>	NO						
<a href="#">350767-1</a>	NO			"AMP-0-0350767-1", "F84278-000"			
<a href="#">350778-1</a>	NO			"403738545", "AMPS-0-0350778-1", "E83488-000", "500-020-2698", "500-020-0104"			
<a href="#">350851-1</a>	NO			"0-0350851-1", "2021755", "CU3086-000", "AMPS-0-0350851-1"			
<a href="#">350923-3</a>	NO			"403980899"			
<a href="#">35109</a>	NO			"AMPS-0-0035109-0", "F67095-000"			
<a href="#">35110</a>	NO			"AMPS-0-0035110-0", "E36230-000", "2-14492-3100"			
<a href="#">35669</a>	NO						
<a href="#">36946</a>	NO		5M392-8	"CN3419-000", "AMPS-0-0036946-0"			
<a href="#">36951</a>	NO		5M392-11				
<a href="#">36958</a>	NO						
<a href="#">41765</a>	NO						
<a href="#">41770</a>	NO						
<a href="#">41904</a>	NO						
<a href="#">42776-1</a>	NO						
<a href="#">4367790003</a>	NO			"1-1193283-5", "ES-CAP-NO.2-B9-0-35MM"			
<a href="#">5053094268</a>	NO			"4-1193845-5", "RNF-100-1/4-BK-SP"			
<a href="#">5053194267</a>	NO			"3-1193862-4", "RNF-100-1/2-BK-SP", "RNF-100-1/2-0"			
<a href="#">5053344102</a>	NO			"4-1193882-5", "RNF-100-1-1/2-BK-SP"			
<a href="#">5058724002</a>	NO			"5-1193906-0", "VERSAFIT-3/16-0-SP"			
<a href="#">5058744001</a>	NO			"1193907-8", "VERSAFIT-1/4-0-SP"			
<a href="#">5070064069</a>	NO			"2-1193963-6", "RNF-100-1/4-CL-SP"			
<a href="#">51863</a>	NO			"4-16211-9784"			
<a href="#">51863-1</a>	NO						
<a href="#">51864-3</a>	NO						
<a href="#">52041</a>	NO						
<a href="#">52943-1</a>	NO			"401771464"			
<a href="#">53128-1</a>	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">53831-1</a>	NO						
<a href="#">5510320002</a>	NO			"3-1194355-8", "PD-CAP-1/8-0"			
<a href="#">55785-1</a>	NO			"AMP-0-0055785-1", "D10979-000"			
<a href="#">61085-1</a>	NO						
<a href="#">61117-1</a>	NO			"403631302"			
<a href="#">61118-1</a>	NO			"0-0061118-1"			
<a href="#">61314-1</a>	NO			"403334121", "0-0061314-1", "14629", "1101201"			
<a href="#">61366-1</a>	NO						
<a href="#">61622-1</a>	NO						
<a href="#">62000-2</a>	NO						
<a href="#">62001-1</a>	NO						
<a href="#">62001-2</a>	NO						
<a href="#">62002-2</a>	NO						
<a href="#">62305-2</a>	NO						
<a href="#">62306-2</a>	NO						
<a href="#">62310-2</a>	NO						
<a href="#">62311-2</a>	NO						
<a href="#">62429-1</a>	NO						
<a href="#">62935-1</a>	NO						
<a href="#">640251-7</a>	NO						
<a href="#">640388-2</a>	NO						
<a href="#">640388-3</a>	NO						
<a href="#">640456-2</a>	NO			"403612641", "2-42934-0583"			
<a href="#">640456-5</a>	NO						
<a href="#">640903-2</a>	NO						
<a href="#">640923-2</a>	NO			"1181513"			
<a href="#">647402-2</a>	NO						
<a href="#">647402-3</a>	NO						
<a href="#">66098-8</a>	NO						
<a href="#">66100-8</a>	NO						
<a href="#">66102-8</a>	NO						
<a href="#">66104-8</a>	NO						
<a href="#">66358-9</a>	NO						
<a href="#">66359-9</a>	NO						
<a href="#">7-1393114-8</a>	NO			"KUHP-11D51-24"			
<a href="#">770007-1</a>	NO						
<a href="#">770008-3</a>	NO						
<a href="#">770476-1</a>	NO						
<a href="#">770476-2</a>	NO						
<a href="#">770579-1</a>	NO			"0-0770579-1"			
<a href="#">770580-1</a>	NO			"0-0770580-1"			
<a href="#">770849-4</a>	NO						
<a href="#">770903-1</a>	NO			"E25278-000", "DUL-PIN-22-18AW-S/M-UMNL"			
<a href="#">770904-1</a>	NO			"2-42939-6041"			
<a href="#">794219-1</a>	NO						
<a href="#">794221-1</a>	NO						
<a href="#">794223-1</a>	NO						
<a href="#">794272-1</a>	NO						
<a href="#">794412-1</a>	NO						
<a href="#">794606-1</a>	NO			"AMPS-0-0794606-1", "F30642-000"			
<a href="#">794616-4</a>	NO						
<a href="#">794616-6</a>	NO						
<a href="#">794617-8</a>	NO						
<a href="#">794758-1</a>	NO						
<a href="#">794781-1</a>	NO						
<a href="#">796075-1</a>	NO						
<a href="#">796286-1</a>	NO						
<a href="#">796288-1</a>	NO						
<a href="#">87631-2</a>	NO						
<a href="#">917686-1</a>	NO						

Customer: Heilind Electronics( 415410 )

Location: Highland Heights

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-480705-0</a>	NO			"1-0480705-0"			
<a href="#">3371890001</a>	NO			"7-1192545-8", "ES-CAP-NO.1-C1-0-30MM"			
<a href="#">5058724002</a>	NO			"5-1193906-0", "VERSAFIT-3/16-0-SP"			

Customer: Heilind Electronics( 2873181 )

Location: Raleigh

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-480700-0</a>	NO			"AMPS-1-0480700-0", "F47049-000", "1-0480700-0", "2-42932-9342"			

Customer: Heilind Electronics( 2880698 )

Location: Itasca

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-480699-0</a>	NO			"402376412", "1-0480699-0", "500-060-1982", "4-27202-1755"			
<a href="#">1-480705-0</a>	NO			"1-0480705-0"			
<a href="#">206037-1</a>	NO			"A33294-000", "AMPS-0-0206037-1"			
<a href="#">206708-1</a>	NO						

Customer: Heilind Electronics( 1331779 )

Location: Peachtree City

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-35115-0</a>	NO						

Customer: Heilind Electronics Inc( 2873182 )

Location: Plano

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">3-640401-1</a>	NO						
<a href="#">350767-1</a>	NO			"AMP-0-0350767-1", "F84278-000"			
<a href="#">53831-1</a>	NO						

Customer: Maverick Electronics( 155785 )

Location: McAllen

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-104479-0</a>	NO						
<a href="#">1-104479-3</a>	NO						
<a href="#">1-480416-1</a>	NO						
<a href="#">1-480698-0</a>	NO			"834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341"			
<a href="#">1-480700-0</a>	NO			"AMPS-1-0480700-0", "F47049-000", "1-0480700-0", "2-42932-9342"			
<a href="#">1-480701-0</a>	NO						
<a href="#">1-480706-0</a>	NO			"873818-000", "AMPS-1-0480706-0", "2-42934-0301"			
<a href="#">1-794606-2</a>	NO						
<a href="#">1-794617-2</a>	NO						
<a href="#">1-794617-6</a>	NO						
<a href="#">103653-1</a>	NO			"010-0961-00"			
<a href="#">103653-2</a>	NO			"010-0962-00"			
<a href="#">103653-4</a>	NO						
<a href="#">104257-1</a>	NO						
<a href="#">104257-2</a>	NO			"AMP-0-0104257-2", "C75259-000", "030-0095-00"			
<a href="#">104257-3</a>	NO						
<a href="#">104257-5</a>	NO			"030-0096-00"			
<a href="#">1445049-4</a>	NO						
<a href="#">170360-3</a>	NO						
<a href="#">170362-3</a>	NO						
<a href="#">171637-1</a>	NO						
<a href="#">172159-1</a>	NO						
<a href="#">2-34161-1</a>	NO						
<a href="#">2-35109-1</a>	NO			"1140297", "1139542"			
<a href="#">2-36161-2</a>	NO			"402624795"			
<a href="#">2-794617-4</a>	NO						
<a href="#">3-770060-1</a>	NO						
<a href="#">34070</a>	NO			"268412-000", "AMPS-0-0034070-0"			
<a href="#">34137</a>	NO		5M392-2	"F21569-000", "AMPS-0-0034137-0"			
<a href="#">350218-1</a>	NO						
<a href="#">350536-1</a>	NO			"403429822"			
<a href="#">350767-1</a>	NO			"AMP-0-0350767-1", "F84278-000"			
<a href="#">350778-1</a>	NO			"403738545", "AMPS-0-0350778-1", "E83488-000", "500-020-2698", "500-020-0104"			
<a href="#">5053194267</a>	NO			"3-1193862-4", "RNF-100-1/2-BK-SP", "RNF-100-1/2-0"			
<a href="#">5058724002</a>	NO			"5-1193906-0", "VERSAFIT-3/16-0-SP"			
<a href="#">5058744001</a>	NO			"1193907-8", "VERSAFIT-1/4-0-SP"			
<a href="#">52943-1</a>	NO			"401771464"			
<a href="#">647402-3</a>	NO						
<a href="#">770580-1</a>	NO			"0-0770580-1"			
<a href="#">770903-1</a>	NO			"E25278-000", "DUL-PIN-22-18AW- S/M-UMNL"			
<a href="#">770904-1</a>	NO			"2-42939-6041"			
<a href="#">794617-8</a>	NO						
<a href="#">794758-1</a>	NO						