



Product Change Notification

Current Date: 23-Aug-2016

TE Connectivity

Product Change Notification: P-16-013455

PCN Date: 18-AUG-16

Customer: Heilind Electronics
Inc(0002135900)

Location: WORLDWIDE

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Amplimite socket contact

Description of Changes

Rescind Product Change Notification E-15-014884. This change will not take place. If this change is enacted in the future another PCN will be issued. The original PCN specified that a spherical radius would be acceptable in the socket hood. This change is not taking place at this time per the PCN. If the change is adopted in the future a new PCN will be issued.

Reason for Changes:

Document clarification.No change to product.

Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

18-AUG-2016

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
205090-1	NO			"033-0012-00", "CC5846-000", "HD 20 SOCKET CONTACT", "4-16211-7507"			
205090-2	NO						

Customer: Maverick Electronics(155785)

Location: Mcallen

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
205090-1	NO			"033-0012-00", "CC5846-000", "HD 20 SOCKET CONTACT", "4-16211-7507"			

Customer: Heilind Asia Pacific (Hong Kong)(2991513)

Location: Hong Kong

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
205090-1	NO			"033-0012-00", "CC5846-000", "HD 20 SOCKET CONTACT", "4-16211-7507"			

Customer: Heilind Asia Pacific (Hong Kong)(2980376)

Location: Hong Kong

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
205090-1	NO			"033-0012-00", "CC5846-000", "HD 20 SOCKET CONTACT", "4-16211-7507"			

Customer: Heilind Asia Pacific (HK) Ltd(3087523)

Location: Dongguan

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
205090-2	NO						

Customer: Heilind Electronics(167811)

Location: Wilmington

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
205090-1	NO			"033-0012-00", "CC5846-000", "HD 20 SOCKET CONTACT", "4-16211-7507"			
205090-2	NO						

Customer: Maverick Electronics(155785)

Location: Mcallen

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
205090-1	NO			"033-0012-00", "CC5846-000", "HD 20 SOCKET CONTACT", "4-16211-7507"			