



Product Change Notification

Current Date: 08-Apr-2020

TE Connectivity

Product Change Notification: P-20-018876

PCN Date: 03-APR-20

Customer: Heilind Electronics
Inc(0002135900)

Location: WORLDWIDE

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Notification of packaging changes for -STK tubing products

Description of Changes

This is a notification informing TE Connectivity customers that the packaging boxes used for the tubing -STK products will be changing.

Other attachments:
[New Stick Boxes](#)
[PCN - Changes to Stick boxes](#)
[Stick parts for box changes](#)
Reason for Changes:

Product improvement.We are moving to a more robust design that will give better protection to the tubing products during transportation.The boxes are moving from a square profile to a rectangular one with different cardboard and latching method.We will be transitioning boxes as existing packaging is consumed so not all product will change at the same time.

Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

06-APR-2020

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

31-OCT-2020

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
035377P004	NO			"4-1190273-8", "ES1000-NO.3-B8-X-STK"			
063725P022	NO			"6-1190481-1", "ES2000-NO.2-B9-0-STK", "ES2000-2-4FOOT"			
085193P003	NO			"9-1190628-5", "ES1000-NO.4-B7-X-STK"			
1118012001	NO			"1190816-1", "DWP-125-3/4-2-STK"			
121397P024	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
130599P006	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			
193197P004	NO			"4-1191401-7", "ES1000-NO.1-C1-X-STK"			
206247P038	NO			"2-1191495-7", "SCT-NO.4-E2-0-STK"			
2951512003	NO			"DWP-125-1/4-0-STK", "1448670-1", "16-0151"			
4429522003	NO			"6-1193329-8", "DWP-125-1/8-0-STK"			
5052842057	NO			"3-1193821-9", "RNF-100-3/64-BK-STK"			
5052852029	NO			"1-1193822-4", "RNF-100-3/64-RD-STK"			
5052892107	NO			"5-1193823-3", "RNF-100-1/16-BK-STK", "16-0112"			
5052932105	NO			"1-1193826-7", "RNF-100-1/16-WH-STK"			
5052942218	NO			"1-1193827-7", "RNF-100-3/32-BK-STK"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5052992172	NO			"1-1193833-7", "RNF-100-1/8-BK-STK"			
5053042176	NO			"8-1193838-6", "RNF-100-3/16-BK-STK"			
5053092267	NO			"2-1193845-2", "RNF-100-1/4-BK-STK"			
5053142385	NO			"2-1193853-6", "RNF-100-3/8-BK-STK"			
5053172050	NO			"1-1193860-9", "RNF-100-3/8-BU-STK"			
5053192266	NO			"1-1193862-2", "RNF-100-1/2-BK-STK"			
5053212154	NO			"8-1193865-9", "RNF-100-1/2-YO-STK"			
5053222056	NO			"4-1193867-3", "RNF-100-1/2-BU-STK"			
5053242179	NO			"1-1193869-9", "RNF-100-3/4-BK-STK"			
5053282198	NO			"1193875-3", "RNF-100-3/4-WH-STK"			
5053292160	NO			"3-1193876-7", "RNF-100-1-BK-STK"			
5053332136	NO			"9-1193880-0", "RNF-100-1-WH-STK"			
5053342101	NO			"2-1193882-6", "RNF-100-1-1/2-BK-STK"			
5053392064	NO			"7-1193885-6", "RNF-100-2-BK-STK"			
5053442033	NO			"5-1193887-7", "RNF-100-3-BK-STK"			
5070022040	NO			"2-1193959-4", "RNF-100-1/16-CL-STK"			
5070032071	NO			"1193960-3", "RNF-100-3/32-CL-STK"			
5070042082	NO			"RNF-100-1/8-CL-STK", "1642972-1"			
5070052056	NO			"1-1193962-3", "RNF-100-3/16-CL-STK"			
5070062068	NO			"1-1193963-3", "RNF-100-1/4-CL-STK", "RNF-100-1/4-CL-STK"			
5070072080	NO			"1-1193964-8", "RNF-100-3/8-CL-STK", "RNF-100-3/8-CL-STK"			
5070102070	NO			"7-1193967-7", "RNF-100-1-CL-STK"			
5076682002	NO			"DWP-125-3/4-0-STK", "1448810-3"			
537637P041	NO			"8-1194219-5", "SCT-NO.3-E3-0-STK"			
543633P064	NO			"5-1194264-0", "SCT-NO.1-E6-0-STK"			
5500102028	NO			"2-1194329-8", "SCL-1/8-0-STK", "SCL-1/8-0-STK"			
5500192011	NO			"5-1194330-0", "SCL-3/8-0-STK", "SCL-3/8-0-STK"			
5500282020	NO			"6-1194331-8", "SCL-3/16-0-STK", "SCL-3/16-0-STK"			
5500312016	NO			"8-1194332-3", "SCL-1/2-0-STK", "SCL-1/2-0-STK"			
5500692005	NO			"TAT-125-1/4-0-STK", "1324239-2"			
5500702004	NO			"7-1194335-4", "TAT-125-3/8-0-STK"			
5500712011	NO			"1194336-2", "TAT-125-1/2-0-STK"			
5500722008	NO			"4-1194336-1", "TAT-125-3/4-0-STK", "1406806"			
5500732014	NO			"7-1194336-1", "TAT-125-1-0-STK"			
5500742015	NO			"1194337-3", "TAT-125-1-1/2-0-STK"			
5500962003	NO			"3-1194338-0", "TAT-125-1/8-0-STK"			
5500982001	NO			"3-1194338-9", "TAT-125-3/16-0-STK"			
5501052008	NO			"1-1194339-0", "SCL-3/4-0-STK", "SCL-3/4-0-STK"			
5501092019	NO			"3-1194340-1", "SCL-1/4-0-STK", "SCL-1/4-0-STK"			
576105P004	NO			"7-1194570-9", "ES1000-NO.2-B9-X-STK"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5978892002	NO			"4-1194727-5", "DWP-125-1-1/2-0-STK"			
6009112002	NO			"7-1194754-0", "DWP-125-3/16-0-STK"			
6465212003	NO			"114517-01", "1448193-1", "DWP-125-1/2-0-STK", "16-0149"			
7580142002	NO			"DWP-125-3/8-0-STK", "1448852-3", "16-0150"			
771113P007	NO			"4-1196007-4", "FL2500-NO.2-I9-0-101MM"			
774185P009	NO			"8-1196028-7", "QS1500-NO.1-F5-0-STK"			
829131P021	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			
9346692002	NO			"2-1197242-1", "DWP-125-1-0-STK"			
CP6582-000	NO						
CR3231-000	NO			"TAT-125-1/4-2-STK"			
CZ0181-000	NO			"SCT-NO.5-Z4-0-STK"			
EH2292-000	NO			"DWFR-19/6-0-STK"			
EH2294-000	NO			"DWFR-40/13-0-STK"			
EH2296-000	NO			"DWFR-8/2-0-STK"			
EH2298-000	NO			"DWFR-16/4-0-STK"			

Customer: Heilind Asia Pacific (Hong Kong) (2980376)

Location: Shatin, N.t.

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
035377P004	NO			"4-1190273-8", "ES1000-NO.3-B8-X-STK"			
206247P038	NO			"2-1191495-7", "SCT-NO.4-E2-0-STK"			
5053142385	NO			"2-1193853-6", "RNF-100-3/8-BK-STK"			
5053292160	NO			"3-1193876-7", "RNF-100-1-BK-STK"			
5070022040	NO			"2-1193959-4", "RNF-100-1/16-CL-STK"			
5076682002	NO			"DWP-125-3/4-0-STK", "1448810-3"			
5500312016	NO			"8-1194332-3", "SCL-1/2-0-STK", "SCL-1/2-0-STK"			
5500692005	NO			"TAT-125-1/4-0-STK", "1324239-2"			
5500702004	NO			"7-1194335-4", "TAT-125-3/8-0-STK"			
5500712011	NO			"1194336-2", "TAT-125-1/2-0-STK"			
5500732014	NO			"7-1194336-1", "TAT-125-1-0-STK"			
5500962003	NO			"3-1194338-0", "TAT-125-1/8-0-STK"			
5500982001	NO			"3-1194338-9", "TAT-125-3/16-0-STK"			

Customer: Heilind Asia Pacific (3133470)

Location: Shanghai

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
063725P022	NO			"6-1190481-1", "ES2000-NO.2-B9-0-STK", "ES2000-2-4FOOT"			
121397P024	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
130599P006	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			
829131P021	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			

Customer: Heilind Electronics (2873183)

Location: Hudson

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1118012001	NO			"1190816-1", "DWP-125-3/4-2-STK"			
193197P004	NO			"4-1191401-7", "ES1000-NO.1-C1-X-STK"			
206247P038	NO			"2-1191495-7", "SCT-NO.4-E2-0-STK"			
2951512003	NO			"DWP-125-1/4-0-STK", "1448670-1", "16-0151"			
4429522003	NO			"6-1193329-8", "DWP-125-1/8-0-STK"			
5052892107	NO			"5-1193823-3", "RNF-100-1/16-BK-STK", "16-0112"			
5070022040	NO			"2-1193959-4", "RNF-100-1/16-CL-STK"			
5070042082	NO			"RNF-100-1/8-CL-STK", "1642972-1"			
537637P041	NO			"8-1194219-5", "SCT-NO.3-E3-0-STK"			
5500712011	NO			"1194336-2", "TAT-125-1/2-0-STK"			
5500962003	NO			"3-1194338-0", "TAT-125-1/8-0-STK"			
CR3231-000	NO			"TAT-125-1/4-2-STK"			

Customer: Heilind Electronics Brasil Ltda (3088064)

Location: Sao Paulo

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
035377P004	NO			"4-1190273-8", "ES1000-NO.3-B8-X-STK"			
EH2292-000	NO			"DWFR-19/6-0-STK"			

Customer: Heilind Asia Pacific (3146614)

Location: Dongguan

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
193197P004	NO			"4-1191401-7", "ES1000-NO.1-C1-X-STK"			

Customer: Heilind Asia Pacific (SG) Pte Ltd (3076161)

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2951512003	NO			"DWP-125-1/4-0-STK", "1448670-1", "16-0151"			
5052942218	NO			"1-1193827-7", "RNF-100-3/32-BK-STK"			
5053342101	NO			"2-1193882-6", "RNF-100-1-1/2-BK-STK"			

Customer: Heilind Electronics Inc (1275266)

Location: Visalia

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
035377P004	NO			"4-1190273-8", "ES1000-NO.3-B8-X-STK"			
063725P022	NO			"6-1190481-1", "ES2000-NO.2-B9-0-STK", "ES2000-2-4FOOT"			
085193P003	NO			"9-1190628-5", "ES1000-NO.4-B7-X-STK"			
121397P024	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
130599P006	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			
193197P004	NO			"4-1191401-7", "ES1000-NO.1-C1-X-STK"			
2951512003	NO			"DWP-125-1/4-0-STK", "1448670-1", "16-0151"			
4429522003	NO			"6-1193329-8", "DWP-125-1/8-0-STK"			
5052842057	NO			"3-1193821-9", "RNF-100-3/64-BK-STK"			
5052892107	NO			"5-1193823-3", "RNF-100-1/16-BK-STK", "16-0112"			
5052932105	NO			"1-1193826-7", "RNF-100-1/16-WH-STK"			
5052942218	NO			"1-1193827-7", "RNF-100-3/32-BK-STK"			
5053192266	NO			"1-1193862-2", "RNF-100-1/2-BK-STK"			
5053242179	NO			"1-1193869-9", "RNF-100-3/4-BK-STK"			
5053282198	NO			"1193875-3", "RNF-100-3/4-WH-STK"			
5053292160	NO			"3-1193876-7", "RNF-100-1-BK-STK"			
5070022040	NO			"2-1193959-4", "RNF-100-1/16-CL-STK"			
5070042082	NO			"RNF-100-1/8-CL-STK", "1642972-1"			
5070052056	NO			"1-1193962-3", "RNF-100-3/16-CL-STK"			
5070062068	NO			"1-1193963-3", "RNF-100-1/4-CL-STK", "RNF-100-1/4-CL-STK"			
5070102070	NO			"7-1193967-7", "RNF-100-1-CL-STK"			
5076682002	NO			"DWP-125-3/4-0-STK", "1448810-3"			
5500312016	NO			"8-1194332-3", "SCL-1/2-0-STK", "SCL-1/2-0-STK"			
5500692005	NO			"TAT-125-1/4-0-STK", "1324239-2"			
5500702004	NO			"7-1194335-4", "TAT-125-3/8-0-STK"			
5500712011	NO			"1194336-2", "TAT-125-1/2-0-STK"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5500722008	NO			"4-1194336-1", "TAT-125-3/4-0-STK", "1406806"			
5500732014	NO			"7-1194336-1", "TAT-125-1-0-STK"			
5500742015	NO			"1194337-3", "TAT-125-1-1/2-0-STK"			
5500962003	NO			"3-1194338-0", "TAT-125-1/8-0-STK"			
5500982001	NO			"3-1194338-9", "TAT-125-3/16-0-STK"			
5501052008	NO			"1-1194339-0", "SCL-3/4-0-STK", "SCL-3/4-0-STK"			
576105P004	NO			"7-1194570-9", "ES1000-NO.2-B9-X-STK"			
6009112002	NO			"7-1194754-0", "DWP-125-3/16-0-STK"			
6465212003	NO			"114517-01", "1448193-1", "DWP-125-1/2-0-STK", "16-0149"			
7580142002	NO			"DWP-125-3/8-0-STK", "1448852-3", "16-0150"			
771113P007	NO			"4-1196007-4", "FL2500-NO.2-I9-0-101MM"			
774185P009	NO			"8-1196028-7", "QS1500-NO.1-F5-0-STK"			
829131P021	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			
9346692002	NO			"2-1197242-1", "DWP-125-1-0-STK"			
EH2298-000	NO			"DWFR-16/4-0-STK"			

Customer: Heilind Electronics GmbH (113007)

Location: Feldkirchen- Westerham

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
085193P003	NO			"9-1190628-5", "ES1000-NO.4-B7-X-STK"			
5500102028	NO			"2-1194329-8", "SCL-1/8-0-STK", "SCL-1/8-0-STK"			
5500282020	NO			"6-1194331-8", "SCL-3/16-0-STK", "SCL-3/16-0-STK"			

Customer: Heilind Electronics Inc (3152148)

Location: Phoenix

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
537637P041	NO			"8-1194219-5", "SCT-NO.3-E3-0-STK"			

Customer: Heilind Electronics Inc (1281082)

Location: Highland Heights

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
063725P022	NO			"6-1190481-1", "ES2000-NO.2-B9-0-STK", "ES2000-2-4FOOT"			
121397P024	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
130599P006	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			
193197P004	NO			"4-1191401-7", "ES1000-NO.1-C1-X-STK"			
2951512003	NO			"DWP-125-1/4-0-STK", "1448670-1", "16-0151"			
4429522003	NO			"6-1193329-8", "DWP-125-1/8-0-STK"			
5052852029	NO			"1-1193822-4", "RNF-100-3/64-RD-STK"			
5052892107	NO			"5-1193823-3", "RNF-100-1/16-BK-STK", "16-0112"			
5052992172	NO			"1-1193833-7", "RNF-100-1/8-BK-STK"			
5053042176	NO			"8-1193838-6", "RNF-100-3/16-BK-STK"			
5053192266	NO			"1-1193862-2", "RNF-100-1/2-BK-STK"			
5053212154	NO			"8-1193865-9", "RNF-100-1/2-YO-STK"			
5053222056	NO			"4-1193867-3", "RNF-100-1/2-BU-STK"			
5053342101	NO			"2-1193882-6", "RNF-100-1-1/2-BK-STK"			
5053392064	NO			"7-1193885-6", "RNF-100-2-BK-STK"			
5053442033	NO			"5-1193887-7", "RNF-100-3-BK-STK"			
5070042082	NO			"RNF-100-1/8-CL-STK", "1642972-1"			
5070072080	NO			"1-1193964-8", "RNF-100-3/8-CL-STK", "RNF-100-3/8-CL-STK"			
5076682002	NO			"DWP-125-3/4-0-STK", "1448810-3"			
543633P064	NO			"5-1194264-0", "SCT-NO.1-E6-0-STK"			
5500102028	NO			"2-1194329-8", "SCL-1/8-0-STK", "SCL-1/8-0-STK"			
5500192011	NO			"5-1194330-0", "SCL-3/8-0-STK", "SCL-3/8-0-STK"			
5500692005	NO			"TAT-125-1/4-0-STK", "1324239-2"			
5500702004	NO			"7-1194335-4", "TAT-125-3/8-0-STK"			
5500712011	NO			"1194336-2", "TAT-125-1/2-0-STK"			
5500732014	NO			"7-1194336-1", "TAT-125-1-0-STK"			
5500962003	NO			"3-1194338-0", "TAT-125-1/8-0-STK"			
5500982001	NO			"3-1194338-9", "TAT-125-3/16-0-STK"			
5501092019	NO			"3-1194340-1", "SCL-1/4-0-STK", "SCL-1/4-0-STK"			
5978892002	NO			"4-1194727-5", "DWP-125-1-1/2-0-STK"			
6465212003	NO			"114517-01", "1448193-1", "DWP-125-1/2-0-STK", "16-0149"			
7580142002	NO			"DWP-125-3/8-0-STK", "1448852-3", "16-0150"			
829131P021	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			
9346692002	NO			"2-1197242-1", "DWP-125-1-0-STK"			

Customer: Heilind Electronics Inc (264685)

Location: Hudson

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
206247P038	NO			"2-1191495-7", "SCT-NO.4-E2-0-STK"			
537637P041	NO			"8-1194219-5", "SCT-NO.3-E3-0-STK"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
543633P064	NO			"5-1194264-0", "SCT-NO.1-E6-0-STK"			
829131P021	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			
CP6582-000	NO						

Customer: Heilind Asia Pacific (Hong Kong) (2991513)

Location: Hong Kong

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
035377P004	NO			"4-1190273-8", "ES1000-NO.3-B8-X-STK"			
206247P038	NO			"2-1191495-7", "SCT-NO.4-E2-0-STK"			
5053142385	NO			"2-1193853-6", "RNF-100-3/8-BK-STK"			
5053292160	NO			"3-1193876-7", "RNF-100-1-BK-STK"			
5070022040	NO			"2-1193959-4", "RNF-100-1/16-CL-STK"			
5076682002	NO			"DWP-125-3/4-0-STK", "1448810-3"			
5500312016	NO			"8-1194332-3", "SCL-1/2-0-STK", "SCL-1/2-0-STK"			
5500692005	NO			"TAT-125-1/4-0-STK", "1324239-2"			
5500702004	NO			"7-1194335-4", "TAT-125-3/8-0-STK"			
5500712011	NO			"1194336-2", "TAT-125-1/2-0-STK"			
5500732014	NO			"7-1194336-1", "TAT-125-1-0-STK"			
5500962003	NO			"3-1194338-0", "TAT-125-1/8-0-STK"			
5500982001	NO			"3-1194338-9", "TAT-125-3/16-0-STK"			

Customer: Heilind Asia Pacific (SG) Pte Ltd (2980456)

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2951512003	NO			"DWP-125-1/4-0-STK", "1448670-1", "16-0151"			
5052942218	NO			"1-1193827-7", "RNF-100-3/32-BK-STK"			
5053332136	NO			"9-1193880-0", "RNF-100-1-WH-STK"			
5053342101	NO			"2-1193882-6", "RNF-100-1-1/2-BK-STK"			
543633P064	NO			"5-1194264-0", "SCT-NO.1-E6-0-STK"			
829131P021	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			

Customer: Heilind Electronics Inc (1276409)

Location: Plano

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
035377P004	NO			"4-1190273-8", "ES1000-NO.3-B8-X-STK"			

Customer: Maverick Electronics (155785)

Location: Mcallen

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
193197P004	NO			"4-1191401-7", "ES1000-NO.1-C1-X-STK"			
9346692002	NO			"2-1197242-1", "DWP-125-1-0-STK"			

Customer: Heilind Electronics GmbH (3050932)

Location: Rosenheim

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5500102028	NO			"2-1194329-8", "SCL-1/8-0-STK", "SCL-1/8-0-STK"			
5500282020	NO			"6-1194331-8", "SCL-3/16-0-STK", "SCL-3/16-0-STK"			

Customer: Heilind Electronics Inc (3181260)

Location: Mentor

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
085193P003	NO			"9-1190628-5", "ES1000-NO.4-B7-X-STK"			
121397P024	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
130599P006	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			
193197P004	NO			"4-1191401-7", "ES1000-NO.1-C1-X-STK"			
206247P038	NO			"2-1191495-7", "SCT-NO.4-E2-0-STK"			
2951512003	NO			"DWP-125-1/4-0-STK", "1448670-1", "16-0151"			
4429522003	NO			"6-1193329-8", "DWP-125-1/8-0-STK"			
5053042176	NO			"8-1193838-6", "RNF-100-3/16-BK-STK"			
5053092267	NO			"2-1193845-2", "RNF-100-1/4-BK-STK"			
5053172050	NO			"1-1193860-9", "RNF-100-3/8-BU-STK"			
5070032071	NO			"1193960-3", "RNF-100-3/32-CL-STK"			
5070042082	NO			"RNF-100-1/8-CL-STK", "1642972-1"			
5076682002	NO			"DWP-125-3/4-0-STK", "1448810-3"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
537637P041	NO			"8-1194219-5", "SCT-NO.3-E3-0-STK"			
543633P064	NO			"5-1194264-0", "SCT-NO.1-E6-0-STK"			
5500192011	NO			"5-1194330-0", "SCL-3/8-0-STK", "SCL-3/8-0-STK"			
5500692005	NO			"TAT-125-1/4-0-STK", "1324239-2"			
5500732014	NO			"7-1194336-1", "TAT-125-1-0-STK"			
5500962003	NO			"3-1194338-0", "TAT-125-1/8-0-STK"			
5500982001	NO			"3-1194338-9", "TAT-125-3/16-0-STK"			
5501092019	NO			"3-1194340-1", "SCL-1/4-0-STK", "SCL-1/4-0-STK"			
576105P004	NO			"7-1194570-9", "ES1000-NO.2-B9-X-STK"			
5978892002	NO			"4-1194727-5", "DWP-125-1-1/2-0-STK"			
6009112002	NO			"7-1194754-0", "DWP-125-3/16-0-STK"			
829131P021	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			
9346692002	NO			"2-1197242-1", "DWP-125-1-0-STK"			
CZ0181-000	NO			"SCT-NO.5-Z4-0-STK"			
EH2296-000	NO			"DWFR-8/2-0-STK"			

Customer: Heilind Electronics Inc (3018732)

Location: Stowe

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2951512003	NO			"DWP-125-1/4-0-STK", "1448670-1", "16-0151"			

Customer: Heilind Electronic (1341448)

Location: Markham

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
EH2294-000	NO			"DWFR-40/13-0-STK"			

Customer: Heilind Electronics Inc (167811)

Location: Wilmington

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
035377P004	NO			"4-1190273-8", "ES1000-NO.3-B8-X-STK"			
063725P022	NO			"6-1190481-1", "ES2000-NO.2-B9-0-STK", "ES2000-2-4FOOT"			
085193P003	NO			"9-1190628-5", "ES1000-NO.4-B7-X-STK"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
121397P024	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
130599P006	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			
193197P004	NO			"4-1191401-7", "ES1000-NO.1-C1-X-STK"			
206247P038	NO			"2-1191495-7", "SCT-NO.4-E2-0-STK"			
2951512003	NO			"DWP-125-1/4-0-STK", "1448670-1", "16-0151"			
4429522003	NO			"6-1193329-8", "DWP-125-1/8-0-STK"			
5052842057	NO			"3-1193821-9", "RNF-100-3/64-BK-STK"			
5052852029	NO			"1-1193822-4", "RNF-100-3/64-RD-STK"			
5052892107	NO			"5-1193823-3", "RNF-100-1/16-BK-STK", "16-0112"			
5052932105	NO			"1-1193826-7", "RNF-100-1/16-WH-STK"			
5052942218	NO			"1-1193827-7", "RNF-100-3/32-BK-STK"			
5052992172	NO			"1-1193833-7", "RNF-100-1/8-BK-STK"			
5053042176	NO			"8-1193838-6", "RNF-100-3/16-BK-STK"			
5053092267	NO			"2-1193845-2", "RNF-100-1/4-BK-STK"			
5053172050	NO			"1-1193860-9", "RNF-100-3/8-BU-STK"			
5053192266	NO			"1-1193862-2", "RNF-100-1/2-BK-STK"			
5053212154	NO			"8-1193865-9", "RNF-100-1/2-YO-STK"			
5053222056	NO			"4-1193867-3", "RNF-100-1/2-BU-STK"			
5053242179	NO			"1-1193869-9", "RNF-100-3/4-BK-STK"			
5053282198	NO			"1193875-3", "RNF-100-3/4-WH-STK"			
5053292160	NO			"3-1193876-7", "RNF-100-1-BK-STK"			
5053342101	NO			"2-1193882-6", "RNF-100-1-1/2-BK-STK"			
5053392064	NO			"7-1193885-6", "RNF-100-2-BK-STK"			
5053442033	NO			"5-1193887-7", "RNF-100-3-BK-STK"			
5070022040	NO			"2-1193959-4", "RNF-100-1/16-CL-STK"			
5070032071	NO			"1193960-3", "RNF-100-3/32-CL-STK"			
5070042082	NO			"RNF-100-1/8-CL-STK", "1642972-1"			
5070052056	NO			"1-1193962-3", "RNF-100-3/16-CL-STK"			
5070062068	NO			"1-1193963-3", "RNF-100-1/4-CL-STK", "RNF-100-1/4-CL-STK"			
5070072080	NO			"1-1193964-8", "RNF-100-3/8-CL-STK", "RNF-100-3/8-CL-STK"			
5070102070	NO			"7-1193967-7", "RNF-100-1-CL-STK"			
5076682002	NO			"DWP-125-3/4-0-STK", "1448810-3"			
537637P041	NO			"8-1194219-5", "SCT-NO.3-E3-0-STK"			
543633P064	NO			"5-1194264-0", "SCT-NO.1-E6-0-STK"			
5500102028	NO			"2-1194329-8", "SCL-1/8-0-STK", "SCL-1/8-0-STK"			
5500192011	NO			"5-1194330-0", "SCL-3/8-0-STK", "SCL-3/8-0-STK"			
5500312016	NO			"8-1194332-3", "SCL-1/2-0-STK", "SCL-1/2-0-STK"			
5500692005	NO			"TAT-125-1/4-0-STK", "1324239-2"			
5500702004	NO			"7-1194335-4", "TAT-125-3/8-0-STK"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5500712011	NO			"1194336-2", "TAT-125-1/2-0-STK"			
5500722008	NO			"4-1194336-1", "TAT-125-3/4-0-STK", "1406806"			
5500732014	NO			"7-1194336-1", "TAT-125-1-0-STK"			
5500742015	NO			"1194337-3", "TAT-125-1-1/2-0-STK"			
5500962003	NO			"3-1194338-0", "TAT-125-1/8-0-STK"			
5500982001	NO			"3-1194338-9", "TAT-125-3/16-0-STK"			
5501052008	NO			"1-1194339-0", "SCL-3/4-0-STK", "SCL-3/4-0-STK"			
5501092019	NO			"3-1194340-1", "SCL-1/4-0-STK", "SCL-1/4-0-STK"			
576105P004	NO			"7-1194570-9", "ES1000-NO.2-B9-X-STK"			
5978892002	NO			"4-1194727-5", "DWP-125-1-1/2-0-STK"			
6009112002	NO			"7-1194754-0", "DWP-125-3/16-0-STK"			
6465212003	NO			"114517-01", "1448193-1", "DWP-125-1/2-0-STK", "16-0149"			
7580142002	NO			"DWP-125-3/8-0-STK", "1448852-3", "16-0150"			
771113P007	NO			"4-1196007-4", "FL2500-NO.2-I9-0-101MM"			
774185P009	NO			"8-1196028-7", "QS1500-NO.1-F5-0-STK"			
829131P021	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			
9346692002	NO			"2-1197242-1", "DWP-125-1-0-STK"			
CP6582-000	NO						
CZ0181-000	NO			"SCT-NO.5-Z4-0-STK"			
EH2296-000	NO			"DWFR-8/2-0-STK"			
EH2298-000	NO			"DWFR-16/4-0-STK"			

Customer: Heilind Electronics (2972714)

Location: Cypress

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5052992172	NO			"1-1193833-7", "RNF-100-1/8-BK-STK"			