



Product Change Notification

Current Date: 14-Apr-2020

TE Connectivity

Product Change Notification: P-20-018897

PCN Date: 08-APR-20

Customer: Heilind Electronics
Inc(0002135900)

Location: WORLDWIDE

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Notification of Lead Time changes due to Corona Virus impact on tubing products.

Description of Changes

This is a notification informing TE Connectivity customers that the Lead Times for tubing products are changing due the impact of Covid 19 Virus on Production.

Other attachments:
[PCN - Changes to Tubing lead times](#)
[Appliance Tubing - adjustment lead times 1](#)
[Appliance Tubing - adjustment lead times 2](#)
Reason for Changes:

Document clarification.The Trutnov tubing plant remains open and producing as much heat Shrink tubing as it can however due to the closure of borders in the Czech Republic for reasons of Covid 19 virus protection we are not able to staff the factory at the required levels to keep up with required productivity outputs. This reduction has regrettably forced us to increase Lead Times for the tubing products.

Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

13-APR-2020

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
010083-000	NO			"7-1190078-5", "VERSAFIT-3/4-2-FSP"			
1118012001	NO			"1190816-1", "DWP-125-3/4-2-STK"			
1484614018	NO			"9-1191072-9", "VERSAFIT-1-0-SP"			
1615034002	NO			"1-1191166-7", "RNF-150-3/64-0-SP"			
2509914004	NO			"6-1191839-5", "RNF-150-3/16-0-SP"			
4429522003	NO			"6-1193329-8", "DWP-125-1/8-0-STK"			
5025074002	NO			"1193775-1", "RNF-150-3/8-0-SP"			
5025812002	NO			"6-1193777-8", "TAK-SLEEVE-1/8-X-STK"			
5052942218	NO			"1-1193827-7", "RNF-100-3/32-BK-STK"			
5053054039	NO			"3-1193841-7", "RNF-100-3/16-RD-SP"			
5053092267	NO			"2-1193845-2", "RNF-100-1/4-BK-STK"			
5053254051	NO			"9-1193871-3", "RNF-100-3/4-RD-SP"			
5053332136	NO			"9-1193880-0", "RNF-100-1-WH-STK"			
505344M031	NO			"1193888-4", "RNF-100-3-BK-SP-CS5529"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5058684016	NO			"5-1193905-6", "VERSAFIT-3/32-0-SP", "16-0162"			
5058704033	NO			"1193906-3", "VERSAFIT-1/8-0-SP", "16-0184"			
5058744001	NO			"1193907-8", "VERSAFIT-1/4-0-SP"			
5058754003	NO			"5-1193907-9", "VERSAFIT-1/4-9-SP"			
5058784018	NO			"2-1193908-7", "VERSAFIT-1/2-0-SP"			
5058804002	NO			"6-1193908-4", "VERSAFIT-3/4-0-SP"			
5067452035	NO			"9-1193932-6", "ATUM-19/6-0-STK"			
5072014003	NO			"1193972-1", "RNF-100-1-1/4-CL-SP"			
5200172005	NO			"1-1194082-2", "CRN-1/4-0-STK"			
537637P035	NO			"7-1194219-9", "SCT-NO.3-E3-0-65MM"			
537637P036	NO			"8-1194219-0", "SCT-NO.3-E3-0-75MM"			
537637P041	NO			"8-1194219-5", "SCT-NO.3-E3-0-STK"			
5500102028	NO			"2-1194329-8", "SCL-1/8-0-STK", "SCL-1/8-0-STK"			
5500192011	NO			"5-1194330-0", "SCL-3/8-0-STK", "SCL-3/8-0-STK"			
5509102149	NO			"1194350-8", "ATUM-12/4-0-MS-STK"			
5509112121	NO			"7-1194351-0", "ATUM-24/8-0-MS-STK"			
5765956019	NO			"4-1194574-9", "RT-375-3/8-X-65MM"			
584485-000	NO			"5-1194628-5", "VERSAFIT-1/4-0-1.5IN-SM"			
6756114001	NO			"1-1195313-3", "VERSAFIT-1/4-6-SP"			
705721-001	NO			"4-1195534-5", "RBK-85-KIT-2110-A0"			
729987-000	NO			"1195703-2", "VERSAFIT-3/8-6-FSP"			
7523674005	NO			"1-1195866-1", "RNF-150-3/32-0-SP"			
939259-000	NO			"6-1197274-7", "VERSAFIT-3/4-9-FSP"			
CL0859-000	NO			"SST-48-04/FR/97"			
CS8672-000	NO			"HRHF-175FR-10/97/NM"			
CV3300-000	NO			"RW-175-1/16-X-STK", "16-0113"			
CV4362-000	NO			"HT-200-3/4-X-SP"			
EH2296-000	NO			"DWFR-8/2-0-STK"			
NB07744001	NO						
NB10132001	NO						
NB10784001	NO						
NB10802001	NO						
NB11242001	NO			"ATUM--40/13-0-STK"			
NB13114001	NO						
NB14374001	NO						
NB14474001	NO						
NB14734001	NO						
NB15524001	NO						
NB15714001	NO						
NB15994001	NO						
NB16252001	NO						
NB16404001	NO						
NB16744001	NO						
NB16754001	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
NB17744001	NO						
NB19162001	NO						
NB19462001	NO						
NB19684001	NO						
NB20264001	NO						

Customer: Heilind Asia Pacific (Hong Kong) (2980376)

Location: Shatin, N.t.

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5058684016	NO			"5-1193905-6", "VERSAFIT-3/32-0-SP", "16-0162"			
5058704033	NO			"1193906-3", "VERSAFIT-1/8-0-SP", "16-0184"			
5058744001	NO			"1193907-8", "VERSAFIT-1/4-0-SP"			
5058784018	NO			"2-1193908-7", "VERSAFIT-1/2-0-SP"			
705721-001	NO			"4-1195534-5", "RBK-85-KIT-2110-A0"			
NB15714001	NO		RYCRNF-150-1/4-0-SP.M				

Customer: Heilind Electronics (2873183)

Location: Hudson

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1118012001	NO			"1190816-1", "DWP-125-3/4-2-STK"			
4429522003	NO			"6-1193329-8", "DWP-125-1/8-0-STK"			
5058704033	NO			"1193906-3", "VERSAFIT-1/8-0-SP", "16-0184"			
5058804002	NO			"6-1193908-4", "VERSAFIT-3/4-0-SP"			
537637P041	NO			"8-1194219-5", "SCT-NO.3-E3-0-STK"			

Customer: Heilind Asia Pacific (3068918)

Location: Kwai Chung

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
CV4362-000	NO			"HT-200-3/4-X-SP"			

Customer: Heilind Electronics Brasil Ltda (3088064)

Location: Sao Paulo

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
NB11242001	NO			"ATUM--40/13-0-STK"			

Customer: Heilind Asia Pacific (Hong Kong) (3133488)

Location: Hong Kong

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
NB17744001	NO						

Customer: Heilind Asia Pacific (SG) Pte Ltd (3076161)

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2509914004	NO			"6-1191839-5", "RNF-150-3/16-0-SP"			
5052942218	NO			"1-1193827-7", "RNF-100-3/32-BK-STK"			
5058684016	NO			"5-1193905-6", "VERSAFIT-3/32-0-SP", "16-0162"			
5058684016	NO			"5-1193905-6", "VERSAFIT-3/32-0-SP", "16-0162"			
NB10132001	NO						
NB10802001	NO						

Customer: Heilind Electronics Inc (1275266)

Location: Visalia

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1484614018	NO			"9-1191072-9", "VERSAFIT-1-0-SP"			
1615034002	NO			"1-1191166-7", "RNF-150-3/64-0-SP"			
2509914004	NO			"6-1191839-5", "RNF-150-3/16-0-SP"			
4429522003	NO			"6-1193329-8", "DWP-125-1/8-0-STK"			
5025812002	NO			"6-1193777-8", "TAK-SLEEVE-1/8-X-STK"			
5052942218	NO			"1-1193827-7", "RNF-100-3/32-BK-STK"			
5053054039	NO			"3-1193841-7", "RNF-100-3/16-RD-SP"			
5053254051	NO			"9-1193871-3", "RNF-100-3/4-RD-SP"			
505344M031	NO			"1193888-4", "RNF-100-3-BK-SP-CS5529"			
5058684016	NO			"5-1193905-6", "VERSAFIT-3/32-0-SP", "16-0162"			
5058704033	NO			"1193906-3", "VERSAFIT-1/8-0-SP", "16-0184"			
5058744001	NO			"1193907-8", "VERSAFIT-1/4-0-SP"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5058754003	NO			"5-1193907-9", "VERSAFIT-1/4-9-SP"			
5058784018	NO			"2-1193908-7", "VERSAFIT-1/2-0-SP"			
5058804002	NO			"6-1193908-4", "VERSAFIT-3/4-0-SP"			
5200172005	NO			"1-1194082-2", "CRN-1/4-0-STK"			
537637P035	NO			"7-1194219-9", "SCT-NO.3-E3-0-65MM"			
NB10132001	NO						
NB10802001	NO						
NB11242001	NO			"ATUM--40/13-0-STK"			
NB14374001	NO						
NB14474001	NO						
NB15714001	NO						
NB16404001	NO						
NB16744001	NO						
NB16754001	NO						
NB19462001	NO						

Customer: Heilind Electronics GmbH (113007)

Location: Feldkirchen- Westerham

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5500102028	NO			"2-1194329-8", "SCL-1/8-0-STK", "SCL-1/8-0-STK"			
5765956019	NO			"4-1194574-9", "RT-375-3/8-X-65MM"			
NB07744001	NO						

Customer: Heilind Electronics Inc (3152148)

Location: Phoenix

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
537637P041	NO			"8-1194219-5", "SCT-NO.3-E3-0-STK"			

Customer: Heilind Electronics GmbH (3183976)

Location: Rosenheim

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5509112121	NO			"7-1194351-0", "ATUM-24/8-0-MS-STK"			

Customer: Heilind Electronics Inc (1281082)

Location: Highland Heights

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
-------------	---------------------------	------------------	----------------------	----------------------	------------------------	---------------------------------	---------------------------

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1484614018	NO			"9-1191072-9", "VERSAFIT-1-0-SP"			
4429522003	NO			"6-1193329-8", "DWP-125-1/8-0-STK"			
5025074002	NO			"1193775-1", "RNF-150-3/8-0-SP"			
5058684016	NO			"5-1193905-6", "VERSAFIT-3/32-0-SP", "16-0162"			
5058704033	NO			"1193906-3", "VERSAFIT-1/8-0-SP", "16-0184"			
5058744001	NO			"1193907-8", "VERSAFIT-1/4-0-SP"			
5058784018	NO			"2-1193908-7", "VERSAFIT-1/2-0-SP"			
5058804002	NO			"6-1193908-4", "VERSAFIT-3/4-0-SP"			
537637P036	NO			"8-1194219-0", "SCT-NO.3-E3-0-75MM"			
5500102028	NO			"2-1194329-8", "SCL-1/8-0-STK", "SCL-1/8-0-STK"			
5500192011	NO			"5-1194330-0", "SCL-3/8-0-STK", "SCL-3/8-0-STK"			
584485-000	NO			"5-1194628-5", "VERSAFIT-1/4-0-1.5IN-SM"			
7523674005	NO			"1-1195866-1", "RNF-150-3/32-0-SP"			
CL0859-000	NO			"SST-48-04/FR/97"			
CV3300-000	NO			"RW-175-1/16-X-STK", "16-0113"			
NB10132001	NO						
NB10802001	NO						
NB11242001	NO			"ATUM--40/13-0-STK"			

Customer: Heilind Electronics Inc (264685)

Location: Hudson

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
010083-000	NO			"7-1190078-5", "VERSAFIT-3/4-2-FSP"			
5025074002	NO			"1193775-1", "RNF-150-3/8-0-SP"			
5058744001	NO			"1193907-8", "VERSAFIT-1/4-0-SP"			
537637P041	NO			"8-1194219-5", "SCT-NO.3-E3-0-STK"			
939259-000	NO			"6-1197274-7", "VERSAFIT-3/4-9-FSP"			

Customer: Heilind Asia Pacific (Hong Kong) (2991513)

Location: Hong Kong

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5058684016	NO			"5-1193905-6", "VERSAFIT-3/32-0-SP", "16-0162"			
5058704033	NO			"1193906-3", "VERSAFIT-1/8-0-SP", "16-0184"			
5058744001	NO			"1193907-8", "VERSAFIT-1/4-0-SP"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5058784018	NO			"2-1193908-7", "VERSAFIT-1/2-0-SP"			
705721-001	NO			"4-1195534-5", "RBK-85-KIT-2110-A0"			
NB15714001	NO		RYCRNF-150-1/4-0-SP.M				

Customer: Heilind Asia Pacific (SG) Pte Ltd (2980456)

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2509914004	NO			"6-1191839-5", "RNF-150-3/16-0-SP"			
5052942218	NO			"1-1193827-7", "RNF-100-3/32-BK-STK"			
5053332136	NO			"9-1193880-0", "RNF-100-1-WH-STK"			
5058684016	NO			"5-1193905-6", "VERSAFIT-3/32-0-SP", "16-0162"			
5058684016	NO			"5-1193905-6", "VERSAFIT-3/32-0-SP", "16-0162"			
NB10132001	NO						
NB10784001	NO						
NB10802001	NO						

Customer: Heilind Electronics GmbH (1205662)

Location: Feldkirchen-Westerham

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
NB07744001	NO						

Customer: Maverick Electronics (155785)

Location: Mcallen

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5058704033	NO			"1193906-3", "VERSAFIT-1/8-0-SP", "16-0184"			
5058784018	NO			"2-1193908-7", "VERSAFIT-1/2-0-SP"			

Customer: Heilind Electronics GmbH (3050932)

Location: Rosenheim

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5500102028	NO			"2-1194329-8", "SCL-1/8-0-STK", "SCL-1/8-0-STK"			

Customer: Heilind Electronics GmbH (3076131)

Location: Feldkirchen-Westerham

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
NB07744001	NO						

Customer: Heilind Asia Pacific (SG) Pte Ltd (3076161)

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2509914004	NO			"6-1191839-5", "RNF-150-3/16-0-SP"			
5052942218	NO			"1-1193827-7", "RNF-100-3/32-BK-STK"			
5058684016	NO			"5-1193905-6", "VERSAFIT-3/32-0-SP", "16-0162"			
5058684016	NO			"5-1193905-6", "VERSAFIT-3/32-0-SP", "16-0162"			
NB10132001	NO						
NB10802001	NO						

Customer: Heilind Electronics Inc (3181260)

Location: Mentor

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1615034002	NO			"1-1191166-7", "RNF-150-3/64-0-SP"			
4429522003	NO			"6-1193329-8", "DWP-125-1/8-0-STK"			
5053054039	NO			"3-1193841-7", "RNF-100-3/16-RD-SP"			
5053092267	NO			"2-1193845-2", "RNF-100-1/4-BK-STK"			
5058684016	NO			"5-1193905-6", "VERSAFIT-3/32-0-SP", "16-0162"			
5058704033	NO			"1193906-3", "VERSAFIT-1/8-0-SP", "16-0184"			
5058744001	NO			"1193907-8", "VERSAFIT-1/4-0-SP"			
5058784018	NO			"2-1193908-7", "VERSAFIT-1/2-0-SP"			
5058804002	NO			"6-1193908-4", "VERSAFIT-3/4-0-SP"			
537637P036	NO			"8-1194219-0", "SCT-NO.3-E3-0-75MM"			
537637P041	NO			"8-1194219-5", "SCT-NO.3-E3-0-STK"			
5500192011	NO			"5-1194330-0", "SCL-3/8-0-STK", "SCL-3/8-0-STK"			
5509102149	NO			"1194350-8", "ATUM-12/4-0-MS-STK"			
705721-001	NO			"4-1195534-5", "RBK-85-KIT-2110-A0"			
CL0859-000	NO			"SST-48-04/FR/97"			
CS8672-000	NO			"HRHF-175FR-10/97/NM"			
EH2296-000	NO			"DWFR-8/2-0-STK"			
NB10132001	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
NB10802001	NO						
NB13114001	NO						
NB14374001	NO						
NB14474001	NO						
NB14734001	NO						
NB15524001	NO						
NB15714001	NO						
NB15994001	NO						
NB16252001	NO						
NB17744001	NO						
NB19162001	NO						
NB19684001	NO						
NB20264001	NO						

Customer: Heilind Electronics Inc (167811)

Location: Wilmington

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
010083-000	NO			"7-1190078-5", "VERSAFIT-3/4-2-FSP"			
1484614018	NO			"9-1191072-9", "VERSAFIT-1-0-SP"			
1615034002	NO			"1-1191166-7", "RNF-150-3/64-0-SP"			
2509914004	NO			"6-1191839-5", "RNF-150-3/16-0-SP"			
4429522003	NO			"6-1193329-8", "DWP-125-1/8-0-STK"			
5025074002	NO			"1193775-1", "RNF-150-3/8-0-SP"			
5025812002	NO			"6-1193777-8", "TAK-SLEEVE-1/8-X-STK"			
5052942218	NO			"1-1193827-7", "RNF-100-3/32-BK-STK"			
5053054039	NO			"3-1193841-7", "RNF-100-3/16-RD-SP"			
5053092267	NO			"2-1193845-2", "RNF-100-1/4-BK-STK"			
5053254051	NO			"9-1193871-3", "RNF-100-3/4-RD-SP"			
505344M031	NO			"1193888-4", "RNF-100-3-BK-SP-CS5529"			
5058684016	NO			"5-1193905-6", "VERSAFIT-3/32-0-SP", "16-0162"			
5058704033	NO			"1193906-3", "VERSAFIT-1/8-0-SP", "16-0184"			
5058744001	NO			"1193907-8", "VERSAFIT-1/4-0-SP"			
5058754003	NO			"5-1193907-9", "VERSAFIT-1/4-9-SP"			
5058784018	NO			"2-1193908-7", "VERSAFIT-1/2-0-SP"			
5058804002	NO			"6-1193908-4", "VERSAFIT-3/4-0-SP"			
5067452035	NO			"9-1193932-6", "ATUM-19/6-0-STK"			
5072014003	NO			"1193972-1", "RNF-100-1-1/4-CL-SP"			
5200172005	NO			"1-1194082-2", "CRN-1/4-0-STK"			
537637P035	NO			"7-1194219-9", "SCT-NO.3-E3-0-65MM"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
537637P036	NO			"8-1194219-0", "SCT-NO.3-E3-0-75MM"			
537637P041	NO			"8-1194219-5", "SCT-NO.3-E3-0-STK"			
5500102028	NO			"2-1194329-8", "SCL-1/8-0-STK", "SCL-1/8-0-STK"			
5500192011	NO			"5-1194330-0", "SCL-3/8-0-STK", "SCL-3/8-0-STK"			
5509102149	NO			"1194350-8", "ATUM-12/4-0-MS-STK"			
584485-000	NO			"5-1194628-5", "VERSAFIT-1/4-0-1.5IN-SM"			
6756114001	NO			"1-1195313-3", "VERSAFIT-1/4-6-SP"			
705721-001	NO			"4-1195534-5", "RBK-85-KIT-2110-A0"			
7523674005	NO			"1-1195866-1", "RNF-150-3/32-0-SP"			
939259-000	NO			"6-1197274-7", "VERSAFIT-3/4-9-FSP"			
CL0859-000	NO			"SST-48-04/FR/97"			
CS8672-000	NO			"HRHF-175FR-10/97/NM"			
CV3300-000	NO			"RW-175-1/16-X-STK", "16-0113"			
EH2296-000	NO			"DWFR-8/2-0-STK"			
NB10132001	NO						
NB10802001	NO						
NB11242001	NO			"ATUM--40/13-0-STK"			
NB13114001	NO						
NB14374001	NO						
NB14474001	NO						
NB14734001	NO						
NB15524001	NO						
NB15714001	NO						
NB15994001	NO						
NB16252001	NO						
NB16404001	NO						
NB16744001	NO						
NB16754001	NO						
NB17744001	NO						
NB19162001	NO						
NB19462001	NO						
NB19684001	NO						
NB20264001	NO						

Customer: Heilind Electronics (2972714)

Location: Cypress

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
729987-000	NO			"1195703-2", "VERSAFIT-3/8-6-FSP"			

Customer: Heilind Asia Pacific (SG) Pte Ltd (2980456)

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2509914004	NO			"6-1191839-5", "RNF-150-3/16-0-SP"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5052942218	NO			"1-1193827-7", "RNF-100-3/32-BK-STK"			
5053332136	NO			"9-1193880-0", "RNF-100-1-WH-STK"			
5058684016	NO			"5-1193905-6", "VERSAFIT-3/32-0-SP", "16-0162"			
5058684016	NO			"5-1193905-6", "VERSAFIT-3/32-0-SP", "16-0162"			
NB10132001	NO						
NB10784001	NO						
NB10802001	NO						