



Product Change Notification

Current Date: 14-Apr-2020

TE Connectivity

Product Change Notification: P-20-018900

PCN Date: 08-APR-20

Customer: Heilind Electronics
Inc(0002135900)

Location: WORLDWIDE

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Notification of Lead Time changes due to Corona Virus impact on tubing products.

Description of Changes

This is a notification informing TE Connectivity customers that the Lead Times for tubing products are changing due the impact of Covid 19 Virus on Production.

Other attachments:

[PCN - Changes to Tubing lead times](#)

[Appliance Tubing - adjustment lead times 1](#)

[Appliance Tubing - adjustment lead times 2](#)

Reason for Changes:

Document clarification. The Trutnov tubing plant remains open and producing as much heat Shrink tubing as it can however due to the closure of borders in the Czech Republic for reasons of Covid 19 virus protection we are not able to staff the factory at the required levels to keep up with required productivity outputs. This reduction has regrettably forced us to increase Lead Times for the tubing products.

Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

13-APR-2020

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
085193P003	NO			"9-1190628-5", "ES1000-NO.4-B7-X-STK"			
130599P002	NO			"6-1190948-0", "ES2000-NO.4-B7-0-27MM"			
130599P003	NO			"6-1190948-1", "ES2000-NO.4-B7-0-75MM"			
130599P006	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			
130599P010	NO			"6-1190948-7", "ES2000-NO.4-B7-0-40MM"			
130599P011	NO			"6-1190948-8", "ES2000-NO.4-B7-0-50MM"			
130599P014	NO			"7-1190948-1", "ES2000-NO.4-B7-0-100MM"			
3075774001	NO			"6-1192329-0", "HTAT-16/4-0-SP"			
3137794006	NO			"4-1192373-4", "RT-375-1-X-SP"			
3530654001	NO			"1192652-1", "VERSAFIT-5/8-0-SP"			
4951524017	NO			"7-1193702-5", "ATUM-32/8-0-SP"			
5053044177	NO			"RNF-100-3/16-BK-SP", "RNF-100-3/16-0", "1832174-1"			
5053064084	NO			"9-1193841-6", "RNF-100-3/16-YO-SP"			
5053282198	NO			"1193875-3", "RNF-100-3/4-WH-STK"			
5053384055	NO			"3-1193885-3", "RNF-100-1-1/2-WH-SP"			
5053392024	NO			"7-1193885-5", "RNF-100-2-0-STK"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5053392064	NO			"7-1193885-6", "RNF-100-2-BK-STK"			
5053442033	NO			"5-1193887-7", "RNF-100-3-BK-STK"			
5053494030	NO			"1-1193889-6", "RNF-100-4-BK-SP"			
5070024041	NO			"3-1193959-4", "RNF-100-1/16-CL-SP"			
5070042082	NO			"RNF-100-1/8-CL-STK", "1642972-1"			
5200252015	NO			"1194083-1", "CRN-3/16-0-STK"			
5500282020	NO			"6-1194331-8", "SCL-3/16-0-STK", "SCL-3/16-0-STK"			
5509092132	NO			"5-1194348-8", "ATUM-6/2-0-MS-STK"			
5509104074	NO			"1-1194350-1", "ATUM-12/4-0-SP"			
5510040002	NO			"4-1194354-6", "PD-CAP-1/4-0"			
5664172001	NO			"1194473-5", "HTAT-48/13-0-STK"			
5677964005	NO			"2-1194511-3", "RNF-3000-39/13-X-SP"			
6009112002	NO			"7-1194754-0", "DWP-125-3/16-0-STK"			
603324-1	NO			"377135P008", "VFP-21-1/8-0-STK-SM"			
7145794002	NO			"8-1195592-7", "VERSAFIT-3X-1-0-SP"			
9026664002	NO			"1197015-7", "VERSAFIT-1/4-5-SP"			
9202774002	NO			"1197141-3", "VERSAFIT-3X-3/4-0-SP"			
9578674002	NO			"1197415-9", "VERSAFIT-3X-1/4-0-SP"			
9617634002	NO			"6-1197440-1", "VERSAFIT-3X-3/8-0-SP", "VERSAFIT 3X"			
CB5286-000	NO						
CB5429-000	NO			"XFFR-03X25", "2-1899833-8"			
CF3967-000	NO			"SST-48-11/226-CS8747"			
CV25342001	NO			"RW-175-E-1/4-X-STK", "5-1899810-4"			
EH2294-000	NO			"DWFR-40/13-0-STK"			
NB08082001	NO						
NB09944001	NO						
NB09952001	NO			"ATUM--19/6-0-STK"			
NB10114001	NO						
NB11382001	NO						
NB13132001	NO						
NB13264001	NO						
NB14534001	NO						
NB14634001	NO						
NB14932001	NO						
NB15794001	NO						
NB15944001	NO						
NB16352001	NO						
NB16502001	NO						
NB18784001	NO						
NB18792001	NO						
NB18932001	NO						
NB19144001	NO						
NB19242001	NO						
NB20024001	NO						
NB20134001	NO						
NB20164001	NO						
NB20384001	NO						
NB20424001	NO						
NB25842001	NO						

Customer: Heilind Electronics, Inc., D.B. (1202905)

Location: Feldkirchen-Westerham

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
3075774001	NO			"6-1192329-0", "HTAT-16/4-0-SP"			

Customer: Heilind Asia Pacific (Hong Kong) (2980376)

Location: Shatin, N.t.

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
3137794006	NO			"4-1192373-4", "RT-375-1-X-SP"			
5053044177	NO			"RNF-100-3/16-BK-SP", "RNF-100-3/16-0", "1832174-1"			
NB09952001	NO			"ATUM--19/6-0-STK"			
NB11382001	NO		RYCATUM-52/13-0-STK				
NB15794001	NO						
NB18792001	NO						
NB19242001	NO						
NB20164001	NO						

Customer: Heilind Asia Pacific (3133470)

Location: Shanghai

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
130599P006	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			
5053392024	NO			"7-1193885-5", "RNF-100-2-0-STK"			
7145794002	NO			"8-1195592-7", "VERSAFIT-3X-1-0-SP"			

Customer: Heilind Electronics (2873183)

Location: Hudson

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5070042082	NO			"RNF-100-1/8-CL-STK", "1642972-1"			

Customer: Heilind Electronics Brasil Ltda (3088064)

Location: Sao Paulo

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5509104074	NO			"1-1194350-1", "ATUM-12/4-0-SP"			

Customer: Heilind Asia Pacific (SG) Pte Ltd (3076161)

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5053044177	NO			"RNF-100-3/16-BK-SP", "RNF-100-3/16-0", "1832174-1"			
NB08082001	NO						
NB20424001	NO						
NB20424001	NO						

Customer: Heilind Electronics Inc (1275266)

Location: Visalia

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
085193P003	NO			"9-1190628-5", "ES1000-NO.4-B7-X-STK"			
130599P003	NO			"6-1190948-1", "ES2000-NO.4-B7-0-75MM"			
130599P006	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			
130599P011	NO			"6-1190948-8", "ES2000-NO.4-B7-0-50MM"			
3530654001	NO			"1192652-1", "VERSAFIT-5/8-0-SP"			
5053044177	NO			"RNF-100-3/16-BK-SP", "RNF-100-3/16-0", "1832174-1"			
5053064084	NO			"9-1193841-6", "RNF-100-3/16-YO-SP"			
5053282198	NO			"1193875-3", "RNF-100-3/4-WH-STK"			
5053384055	NO			"3-1193885-3", "RNF-100-1-1/2-WH-SP"			
5053494030	NO			"1-1193889-6", "RNF-100-4-BK-SP"			
5070042082	NO			"RNF-100-1/8-CL-STK", "1642972-1"			
5200252015	NO			"1194083-1", "CRN-3/16-0-STK"			
5510040002	NO			"4-1194354-6", "PD-CAP-1/4-0"			
6009112002	NO			"7-1194754-0", "DWP-125-3/16-0-STK"			
603324-1	NO			"377135P008", "VFP-21-1/8-0-STK-SM"			
7145794002	NO			"8-1195592-7", "VERSAFIT-3X-1-0-SP"			
9578674002	NO			"1197415-9", "VERSAFIT-3X-1/4-0-SP"			
NB13132001	NO						
NB13264001	NO						
NB14932001	NO						
NB15944001	NO						
NB16352001	NO						
NB16502001	NO						
NB18792001	NO						
NB19144001	NO						
NB20164001	NO						
NB20384001	NO						
NB20424001	NO						

Customer: Heilind Electronics GmbH (113007)

Location: Feldkirchen- Westerham

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
085193P003	NO			"9-1190628-5", "ES1000-NO.4-B7-X-STK"			
3075774001	NO			"6-1192329-0", "HTAT-16/4-0-SP"			
4951524017	NO			"7-1193702-5", "ATUM-32/8-0-SP"			
5500282020	NO			"6-1194331-8", "SCL-3/16-0-STK", "SCL-3/16-0-STK"			
CV25342001	NO			"RW-175-E-1/4-X-STK", "5-1899810-4"			
NB09952001	NO			"ATUM--19/6-0-STK"			

Customer: Heilind Electronics GmbH (3183976)

Location: Rosenheim

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
NB10114001	NO						

Customer: Heilind Electronics Inc (1281082)

Location: Highland Heights

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
130599P003	NO			"6-1190948-1", "ES2000-NO.4-B7-0-75MM"			
130599P006	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			
3530654001	NO			"1192652-1", "VERSAFIT-5/8-0-SP"			
5053392064	NO			"7-1193885-6", "RNF-100-2-BK-STK"			
5053442033	NO			"5-1193887-7", "RNF-100-3-BK-STK"			
5070042082	NO			"RNF-100-1/8-CL-STK", "1642972-1"			
5510040002	NO			"4-1194354-6", "PD-CAP-1/4-0"			
CB5286-000	NO						
CF3967-000	NO			"SST-48-11/226-CS8747"			
NB11382001	NO						

Customer: Heilind Electronics Inc (2873182)

Location: Plano

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
9202774002	NO			"1197141-3", "VERSAFIT-3X-3/4-0-SP"			

Customer: Heilind Electronics Inc (264685)

Location: Hudson

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
7145794002	NO			"8-1195592-7", "VERSAFIT-3X-1-0-SP"			
9026664002	NO			"1197015-7", "VERSAFIT-1/4-5-SP"			
NB16502001	NO						

Customer: Heilind Asia Pacific (Hong Kong) (2991513)

Location: Hong Kong

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
3137794006	NO			"4-1192373-4", "RT-375-1-X-SP"			
5053044177	NO			"RNF-100-3/16-BK-SP", "RNF-100-3/16-0", "1832174-1"			
NB09952001	NO			"ATUM--19/6-0-STK"			
NB11382001	NO		RYCATUM-52/13-0-STK				
NB15794001	NO						
NB18792001	NO						
NB19242001	NO						
NB20164001	NO						

Customer: Heilind Asia Pacific (SG) Pte Ltd (2980456)

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5053044177	NO			"RNF-100-3/16-BK-SP", "RNF-100-3/16-0", "1832174-1"			
5664172001	NO			"1194473-5", "HTAT-48/13-0-STK"			
5677964005	NO			"2-1194511-3", "RNF-3000-39/13-X-SP"			
NB08082001	NO						
NB20424001	NO						
NB20424001	NO						

Customer: Heilind Electronics Inc (3152180)

Location: Westminster

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
9578674002	NO			"1197415-9", "VERSAFIT-3X-1/4-0-SP"			
9617634002	NO			"6-1197440-1", "VERSAFIT-3X-3/8-0-SP", "VERSAFIT 3X"			

Customer: Heilind Electronics Inc (1276409)

Location: Plano

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
130599P014	NO			"7-1190948-1", "ES2000-NO.4-B7-0-100MM"			
NB14534001	NO						

Customer: Maverick Electronics (155785)

Location: Mcallen

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
130599P002	NO			"6-1190948-0", "ES2000-NO.4-B7-0-27MM"			
5053044177	NO			"RNF-100-3/16-BK-SP", "RNF-100-3/16-0", "1832174-1"			
9026664002	NO			"1197015-7", "VERSAFIT-1/4-5-SP"			

Customer: Heilind Electronics GmbH (3050932)

Location: Rosenheim

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5500282020	NO			"6-1194331-8", "SCL-3/16-0-STK", "SCL-3/16-0-STK"			
NB09952001	NO			"ATUM--19/6-0-STK"			

Customer: Heilind Electronics GmbH (3076131)

Location: Feldkirchen-Westerham

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
3075774001	NO			"6-1192329-0", "HTAT-16/4-0-SP"			

Customer: Heilind Asia Pacific (SG) Pte Ltd (3076161)

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5053044177	NO			"RNF-100-3/16-BK-SP", "RNF-100-3/16-0", "1832174-1"			
NB08082001	NO						
NB20424001	NO						
NB20424001	NO						

Customer: Heilind Electronics Inc (3181260)

Location: Mentor

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
085193P003	NO			"9-1190628-5", "ES1000-NO.4-B7-			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
				X-STK"			
130599P006	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			
3530654001	NO			"1192652-1", "VERSAFIT-5/8-0-SP"			
5053044177	NO			"RNF-100-3/16-BK-SP", "RNF-100-3/16-0", "1832174-1"			
5070024041	NO			"3-1193959-4", "RNF-100-1/16-CL-SP"			
5070042082	NO			"RNF-100-1/8-CL-STK", "1642972-1"			
6009112002	NO			"7-1194754-0", "DWP-125-3/16-0-STK"			
CB5286-000	NO						
CB5429-000	NO			"XFFR-03X25", "2-1899833-8"			
CF3967-000	NO			"SST-48-11/226-CS8747"			
NB08082001	NO						
NB09944001	NO						
NB09952001	NO			"ATUM--19/6-0-STK"			
NB11382001	NO						
NB14634001	NO						
NB14932001	NO						
NB18784001	NO						
NB18932001	NO						
NB19242001	NO						
NB20024001	NO						
NB20134001	NO						
NB20164001	NO						
NB20424001	NO						
NB25842001	NO						

Customer: Maverick Electronics (155785)

Location: Mcallen

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
130599P002	NO			"6-1190948-0", "ES2000-NO.4-B7-0-27MM"			
5053044177	NO			"RNF-100-3/16-BK-SP", "RNF-100-3/16-0", "1832174-1"			
9026664002	NO			"1197015-7", "VERSAFIT-1/4-5-SP"			

Customer: Heilind Electronic (1341448)

Location: Markham

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
EH2294-000	NO			"DWFR-40/13-0-STK"			
NB14932001	NO						

Customer: Heilind Electronics Inc (167811)

Location: Wilmington

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
085193P003	NO			"9-1190628-5", "ES1000-NO.4-B7-			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
				X-STK"			
130599P003	NO			"6-1190948-1", "ES2000-NO.4-B7-0-75MM"			
130599P006	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			
130599P010	NO			"6-1190948-7", "ES2000-NO.4-B7-0-40MM"			
130599P011	NO			"6-1190948-8", "ES2000-NO.4-B7-0-50MM"			
130599P014	NO			"7-1190948-1", "ES2000-NO.4-B7-0-100MM"			
3530654001	NO			"1192652-1", "VERSAFIT-5/8-0-SP"			
5053044177	NO			"RNF-100-3/16-BK-SP", "RNF-100-3/16-0", "1832174-1"			
5053064084	NO			"9-1193841-6", "RNF-100-3/16-YO-SP"			
5053282198	NO			"1193875-3", "RNF-100-3/4-WH-STK"			
5053384055	NO			"3-1193885-3", "RNF-100-1-1/2-WH-SP"			
5053392064	NO			"7-1193885-6", "RNF-100-2-BK-STK"			
5053442033	NO			"5-1193887-7", "RNF-100-3-BK-STK"			
5053494030	NO			"1-1193889-6", "RNF-100-4-BK-SP"			
5070024041	NO			"3-1193959-4", "RNF-100-1/16-CL-SP"			
5070042082	NO			"RNF-100-1/8-CL-STK", "1642972-1"			
5200252015	NO			"1194083-1", "CRN-3/16-0-STK"			
5509092132	NO			"5-1194348-8", "ATUM-6/2-0-MS-STK"			
5510040002	NO			"4-1194354-6", "PD-CAP-1/4-0"			
6009112002	NO			"7-1194754-0", "DWP-125-3/16-0-STK"			
603324-1	NO			"377135P008", "VFP-21-1/8-0-STK-SM"			
7145794002	NO			"8-1195592-7", "VERSAFIT-3X-1-0-SP"			
9026664002	NO			"1197015-7", "VERSAFIT-1/4-5-SP"			
9578674002	NO			"1197415-9", "VERSAFIT-3X-1/4-0-SP"			
CB5286-000	NO						
CB5429-000	NO			"XFFR-03X25", "2-1899833-8"			
CF3967-000	NO			"SST-48-11/226-CS8747"			
NB08082001	NO						
NB09944001	NO						
NB09952001	NO			"ATUM--19/6-0-STK"			
NB11382001	NO						
NB13132001	NO						
NB13264001	NO						
NB14534001	NO						
NB14634001	NO						
NB14932001	NO						
NB15944001	NO						
NB16352001	NO						
NB16502001	NO						
NB18784001	NO						
NB18792001	NO						
NB18932001	NO						
NB19144001	NO						
NB19242001	NO						
NB20024001	NO						
NB20134001	NO						
NB20164001	NO						
NB20384001	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
NB20424001	NO						
NB25842001	NO						