

## **Product Change Notification (PCN)**

| PCN Number   | 510263  |   | Date Issued  | April 29, 2021 |
|--|---|---|--|----------------|
| Reason for Change  | Supplier Change   |   |  |                |
| Change Type Description  | This letter is to inform you that Molex is adding a new supplier or<br>the supplier is making a change affecting the part(s) identified in<br>this notice. There will be no negative impact to product<br>performance as a result of this change. |   |  |                |
| Reason for Short Notice  | Update Previously Issued Change Notice  |   |  |                |
| Assessment of Change   | No change to parts/components FFF   |   |  |                |
| Internal Molex Qualification Date  | May 28, 2021  |   |  |                |
| Sample Availability Date<br>(Changed Part)   | May 28, 2021  |   |  |                |
| Planned Implementation Date  | May 28, 2021  |   |  |                |
| Method of Identifying Change Product made after planned implementation date can contain the change   |   |   |  |                |
| Before Change  |   | After C   | hange  |                |
| Overview  • Due to increase in product demand and storms that have affected the Southern Region of the United States Molex's Resin Supply capacity to respond within lead time has been greatly impacted.  — Impacting all divisions within Molex — Parts shipments will be impacted |   | <ul> <li>(Overview continued)</li> <li>In 'normal' times, we would complete all necessary steps including notifications and testing per USCAR or GMW BUT we are now being asked to make real time decisions on alternate material supply options, or we could in some cases risk running out of needed material.</li> </ul> |  |                |
| <ul> <li>To keep from line down situations not only for Molex but also our customers, the<br/>ability for Molex Guadalajara Mexico to purchase resin from an additional location of<br/>our current resin suppler is needed.</li> </ul>  |   | Risk of alternate location would be low based on resin coming from same supplier,<br>only different location     Mo impact to Fit, Form or Function   |  |                |
| <ul> <li>Currently resin is only purchased from a qualified supplier in Florence Kentucky location in<br/>the U.S., and they are not able to keep up with demand.</li> <li>Molex is working to onboard and qualify resin from the same supplier in Evansville<br/>Indiana</li> </ul> |   | <ul> <li>Qualifications, PPAPs available after date above.</li> <li>Due to urgent supply demand, deviation approvals may be necessary ahead of PPAP documentation.</li> </ul>   |  |                |
| Part Number Impact   |   | Questions   | /concerns contact your Molex Acc   | ount manager   |
| See Attached List      Isia Confident Information     Olice, LLC - All Ryths Reserved, Unsufforced Reproduction/Distribution is Prohibited.  | molex   |   | terital Information<br>— All Rights Reserved. Unauthorized Reproduction/Distribution is Prohibit | •              |

## molex

**Product Change Notification (PCN)** 

You may address any technical inquiries regarding this PCN by sending E-mail to pcn\_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:510263**" in the e-mail Subject line for faster response.

## RELEASED

Molex, LLC 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com PCN # Molex Part # 510263 345650003