



April 8, 2021

Dear Valued Mersen Customers,

I am writing to update you regarding the Mersen [Class J Time-Delay AJT](#) product family, which utilizes our exclusive SmartSpot® technology. There is a shortage in material availability due to the impact of COVID-19 on the supply chain. To resolve this Mersen has identified alternative sources, but the product will need to undergo additional UL testing not required when the product was initially launched. We estimate additional UL testing will take at least 4 months.

Mersen's non-indicating AJT is readily available to cover the ongoing daily demand for this popular product. Below is a table that shows the products with SmartSpot indication along with their non-indicating equivalent (the "N" suffix notates non-indication). Please add these non-indicating AJT part numbers to your system. If you convert existing orders with Mersen to the non-indicating version, we can readily fulfill customer requirements.

SmartSpot Product #	Non-Indicating Product #	SmartSpot Product #	Non-Indicating Product #	SmartSpot Product #	Non-Indicating Product #	SmartSpot Product #	Non-Indicating Product #
AJT8	AJT8N	AJT30	AJT30N	AJT90	AJT90N	AJT250	AJT250N
AJT9	AJT9N	AJT35	AJT35N	AJT100	AJT100N	AJT300	AJT300N
AJT10	AJT10N	AJT40	AJT40N	AJT110	AJT110N	AJT350	AJT350N
AJT12	AJT12N	AJT45	AJT45N	AJT125	AJT125N	AJT400	AJT400N
AJT15	AJT15N	AJT50	AJT50N	AJT150	AJT150N	AJT450	AJT450N
AJT17-1/2	AJT17-1/2N	AJT60	AJT60N	AJT175	AJT175N	AJT500	AJT500N
AJT20	AJT20N	AJT70	AJT70N	AJT200	AJT200N	AJT600	AJT600N
AJT25	AJT25N	AJT80	AJT80N	AJT225	AJT225N		

At Mersen, we are committed to providing the critical safety products that you and your customers require. Thank you for your continued support.

Regards,

Susan Benson

VP Global Product Management – UL/CSA Fuse & Fuse Gear

MERSEN USA EP Corp.

374 MERRIMAC STREET — NEWBURYPORT, MA 01950

T 978 462 6662 — F 978 462 0181 — info.nby@mersen.com

ep.mersen.com