



# Product Change Notification

Current Date: 12-Jul-2023

## TE Connectivity

**Product Change Notification:** PCN-23-175836

**PCN Date:** 11-JUL-23

**Customer:** Heilind Electronics  
Inc(0002135900)

**Location:** WORLDWIDE

**Agreement:** Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

**General Product Description:**

Package (Carton size) change

**Description of Changes**

Dear Customer, In order to improve customer experience, a unified optimization adjustment will be made to the labels and box specifications on the external packaging box. Mainly changes, 1. Replace some old packaging boxes with unified specification packaging boxes, slightly dimension changes. Before- 759598-000 - 1279\*252\*254 After- CR7224-000 - 1300\*270\*270 759598-000 CR7224-000 Before- 394718-000 - 1280\*256\*130 After- CR7225-000- 1300\*260\*140 394718-000 CR7225-000 Before- 406079-000- 605\*308\*308 After- CR7226-000- 600\*310\*310 406079-000 CR7226-000 2. Modification of label position, which are unified on sealing surface. This PCN will be effective in Sep.10th. For any questions or concerns please contact your local Customer Care Professional.

**Reason for Changes:**
**PCN Attributes:**

<b>Product Category:</b>	<b>Kind of Change:</b>
Heat Shrink Tubing	Packaging Type
<b>Change Feature:</b>	<b>Potential Customer Impact:</b>
Bulk	No Customer Impact
<b>Remarks:</b>	

**Estimated Dates:**

<b>Last Order Date (Obsolete Parts Only):</b>	<b>First Ship Date of Changed Items (Changed Parts Only):</b>
	10-SEP-2023
<b>Last Ship Date of Changed Items (Obsolete Parts Only):</b>	<b>Last Date for Mixed Shipments: (Changed Parts Only):</b>
	No Mixed Shipments
<b>Effectivity Date:</b>	<b>Date of First Samples:</b>

**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">0021032009</a>	NO			"9-1190015-4", "RBK-ILS-125-NR3-0-STK"			
<a href="#">035377P004</a>	NO			"4-1190273-8", "ES1000-NO.3-B8-X-STK"			
<a href="#">063725P011</a>	NO			"5-1190481-1", "ES2000-NO.2-B9-0-50MM"			
<a href="#">063725P022</a>	NO			"6-1190481-1", "ES2000-NO.2-B9-0-STK", "ES2000-2-4FOOT"			
<a href="#">063725P028</a>	NO			"6-1190481-5", "ES2000-NO.2-B9-0-25MM"			
<a href="#">085193P003</a>	NO			"9-1190628-5", "ES1000-NO.4-B7-X-STK"			
<a href="#">121397P015</a>	NO			"3-1190883-5", "ES2000-NO.3-B8-0-75MM"			
<a href="#">121397P018</a>	NO			"3-1190883-8", "ES2000-NO.3-B8-0-50MM"			
<a href="#">121397P024</a>	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
<a href="#">121397P043</a>	NO			"5-1190883-3", "ES2000-NO.3-B8-0-40MM"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">130599P003</a>	NO			"6-1190948-1", "ES2000-NO.4-B7-0-75MM"			
<a href="#">130599P006</a>	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			
<a href="#">130599P010</a>	NO			"6-1190948-7", "ES2000-NO.4-B7-0-40MM"			
<a href="#">130599P011</a>	NO			"6-1190948-8", "ES2000-NO.4-B7-0-50MM"			
<a href="#">193197P004</a>	NO			"4-1191401-7", "ES1000-NO.1-C1-X-STK"			
<a href="#">206247P038</a>	NO			"2-1191495-7", "SCT-NO.4-E2-0-STK"			
<a href="#">2525596002</a>	NO			"5-1191848-0", "RBK-ILS-125-NR1-0-50MM"			
<a href="#">4367790003</a>	NO			"1-1193283-5", "ES-CAP-NO.2-B9-0-35MM"			
<a href="#">5201946022</a>	NO			"1194087-8", "RT-3-NO.3-0-1IN"			
<a href="#">5201976026</a>	NO			"5-1194087-5", "RT-3-NO.2-0-1IN"			
<a href="#">520197P055</a>	NO			"1194088-2", "RT-3-NO.2-0-0.81IN"			
<a href="#">537637P035</a>	NO			"7-1194219-9", "SCT-NO.3-E3-0-65MM"			
<a href="#">537637P041</a>	NO			"8-1194219-5", "SCT-NO.3-E3-0-STK"			
<a href="#">543633P051</a>	NO			"3-1194264-7", "SCT-NO.1-E6-0-50MM"			
<a href="#">543633P064</a>	NO			"5-1194264-0", "SCT-NO.1-E6-0-STK"			
<a href="#">543633P079</a>	NO			"6-1194264-0", "SCT-NO.1-E6-0-40MM"			
<a href="#">576105P004</a>	NO			"7-1194570-9", "ES1000-NO.2-B9-X-STK"			
<a href="#">576105P009</a>	NO			"8-1194570-4", "ES1000-NO.2-B9-X-50MM"			
<a href="#">607381P046</a>	NO			"5-1194804-3", "SCT-NO.2-E5-0-STK"			
<a href="#">771113P007</a>	NO			"4-1196007-4", "FL2500-NO.2-I9-0-101MM"			
<a href="#">829131P011</a>	NO			"7-1196474-0", "ES2000-NO.1-C1-0-30MM"			
<a href="#">829131P012</a>	NO			"7-1196474-1", "ES2000-NO.1-C1-0-50MM"			
<a href="#">829131P021</a>	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			
<a href="#">829131P079</a>	NO			"2-1196475-9", "ES2000-NO.1-C1-0-15MM"			
<a href="#">829131P081</a>	NO			"3-1196475-0", "ES2000-NO.1-C1-0-100MM"			
<a href="#">CB5626-000</a>	NO			"FL2500-NO.1-I8-0-25MM"			
<a href="#">CP4937-000</a>	NO			"7-1899572-0", "ES2000-NO.4-B7-0-STK-SH"			
<a href="#">E95757-000</a>	NO			"4-1199653-3", "FL2500-NO.4-I2-0-STK"			

Customer: Heilind Electronics Inc ( 264685 )

Location: Hudson

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">829131P021</a>	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			

Customer: Heilind Electronics Brasil Ltda ( 3088064 )

Location: Sao Paulo

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">829131P011</a>	NO			"7-1196474-0", "ES2000-NO.1-C1-0-30MM"			

Customer: Heilind Electronics Inc ( 3181260 )

Location: Mentor

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">035377P004</a>	NO			"4-1190273-8", "ES1000-NO.3-B8-X-STK"			
<a href="#">063725P011</a>	NO			"5-1190481-1", "ES2000-NO.2-B9-0-50MM"			
<a href="#">063725P022</a>	NO			"6-1190481-1", "ES2000-NO.2-B9-0-STK", "ES2000-2-4FOOT"			
<a href="#">063725P028</a>	NO			"6-1190481-5", "ES2000-NO.2-B9-0-25MM"			
<a href="#">085193P003</a>	NO			"9-1190628-5", "ES1000-NO.4-B7-X-STK"			
<a href="#">121397P015</a>	NO			"3-1190883-5", "ES2000-NO.3-B8-0-75MM"			
<a href="#">121397P018</a>	NO			"3-1190883-8", "ES2000-NO.3-B8-0-50MM"			
<a href="#">121397P024</a>	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
<a href="#">121397P043</a>	NO			"5-1190883-3", "ES2000-NO.3-B8-0-40MM"			
<a href="#">130599P003</a>	NO			"6-1190948-1", "ES2000-NO.4-B7-0-75MM"			
<a href="#">130599P006</a>	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			
<a href="#">130599P011</a>	NO			"6-1190948-8", "ES2000-NO.4-B7-0-50MM"			
<a href="#">193197P004</a>	NO			"4-1191401-7", "ES1000-NO.1-C1-X-STK"			
<a href="#">4367790003</a>	NO			"1-1193283-5", "ES-CAP-NO.2-B9-0-35MM"			
<a href="#">5201946022</a>	NO			"1194087-8", "RT-3-NO.3-0-1IN"			
<a href="#">5201976026</a>	NO			"5-1194087-5", "RT-3-NO.2-0-1IN"			
<a href="#">537637P035</a>	NO			"7-1194219-9", "SCT-NO.3-E3-0-65MM"			
<a href="#">537637P041</a>	NO			"8-1194219-5", "SCT-NO.3-E3-0-STK"			
<a href="#">543633P051</a>	NO			"3-1194264-7", "SCT-NO.1-E6-0-50MM"			
<a href="#">543633P064</a>	NO			"5-1194264-0", "SCT-NO.1-E6-0-STK"			
<a href="#">576105P004</a>	NO			"7-1194570-9", "ES1000-NO.2-B9-X-STK"			
<a href="#">829131P012</a>	NO			"7-1196474-1", "ES2000-NO.1-C1-0-50MM"			
<a href="#">829131P021</a>	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			
<a href="#">829131P079</a>	NO			"2-1196475-9", "ES2000-NO.1-C1-0-15MM"			

Customer: Heilind Asia Pacific (SG) Pte Ltd ( 3076161 )

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">829131P081</a>	NO			"3-1196475-0", "ES2000-NO.1-C1-0-100MM"			
<a href="#">CP4937-000</a>	NO			"7-1899572-0", "ES2000-NO.4-B7-0-STK-SH"			

Customer: Heilind Asia Pacific ( 3133470 )

Location: Shanghai

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">063725P022</a>	NO			"6-1190481-1", "ES2000-NO.2-B9-0-STK", "ES2000-2-4FOOT"			
<a href="#">121397P024</a>	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
<a href="#">130599P006</a>	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			
<a href="#">829131P021</a>	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			

Customer: Heilind Electronics Inc ( 1275266 )

Location: Visalia

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">035377P004</a>	NO			"4-1190273-8", "ES1000-NO.3-B8-X-STK"			
<a href="#">063725P011</a>	NO			"5-1190481-1", "ES2000-NO.2-B9-0-50MM"			
<a href="#">063725P022</a>	NO			"6-1190481-1", "ES2000-NO.2-B9-0-STK", "ES2000-2-4FOOT"			
<a href="#">063725P028</a>	NO			"6-1190481-5", "ES2000-NO.2-B9-0-25MM"			
<a href="#">121397P015</a>	NO			"3-1190883-5", "ES2000-NO.3-B8-0-75MM"			
<a href="#">121397P018</a>	NO			"3-1190883-8", "ES2000-NO.3-B8-0-50MM"			
<a href="#">121397P024</a>	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
<a href="#">121397P043</a>	NO			"5-1190883-3", "ES2000-NO.3-B8-0-40MM"			
<a href="#">130599P003</a>	NO			"6-1190948-1", "ES2000-NO.4-B7-0-75MM"			
<a href="#">130599P006</a>	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			
<a href="#">130599P010</a>	NO			"6-1190948-7", "ES2000-NO.4-B7-0-40MM"			
<a href="#">130599P011</a>	NO			"6-1190948-8", "ES2000-NO.4-B7-0-50MM"			
<a href="#">193197P004</a>	NO			"4-1191401-7", "ES1000-NO.1-C1-X-STK"			
<a href="#">206247P038</a>	NO			"2-1191495-7", "SCT-NO.4-E2-0-STK"			
<a href="#">5201976026</a>	NO			"5-1194087-5", "RT-3-NO.2-0-1IN"			
<a href="#">520197P055</a>	NO			"1194088-2", "RT-3-NO.2-0-0.81IN"			
<a href="#">537637P035</a>	NO			"7-1194219-9", "SCT-NO.3-E3-0-65MM"			
<a href="#">543633P051</a>	NO			"3-1194264-7", "SCT-NO.1-E6-0-50MM"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">543633P079</a>	NO			"6-1194264-0", "SCT-NO.1-E6-0-40MM"			
<a href="#">576105P004</a>	NO			"7-1194570-9", "ES1000-NO.2-B9-X-STK"			
<a href="#">576105P009</a>	NO			"8-1194570-4", "ES1000-NO.2-B9-X-50MM"			
<a href="#">607381P046</a>	NO			"5-1194804-3", "SCT-NO.2-E5-0-STK"			
<a href="#">771113P007</a>	NO			"4-1196007-4", "FL2500-NO.2-I9-0-101MM"			
<a href="#">829131P012</a>	NO			"7-1196474-1", "ES2000-NO.1-C1-0-50MM"			
<a href="#">829131P021</a>	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			
<a href="#">CB5626-000</a>	NO			"FL2500-NO.1-I8-0-25MM"			
<a href="#">E95757-000</a>	NO			"4-1199653-3", "FL2500-NO.4-J2-0-STK"			

Customer: Heilind Asia Pacific (Hong Kong) ( 2980376 )

Location: Shatin, N.t.

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">085193P003</a>	NO			"9-1190628-5", "ES1000-NO.4-B7-X-STK"			

Customer: Heilind Electronics GmbH ( 113007 )

Location: Feldkirchen- Westerham

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">2525596002</a>	NO			"5-1191848-0", "RBK-ILS-125-NR1-0-50MM"			

Customer: Heilind Electronics Inc ( 1276409 )

Location: Plano

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">035377P004</a>	NO			"4-1190273-8", "ES1000-NO.3-B8-X-STK"			

Customer: Heilind Electronics Inc ( 167811 )

Location: Wilmington

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">0021032009</a>	NO			"9-1190015-4", "RBK-ILS-125-NR3-0-STK"			
<a href="#">035377P004</a>	NO			"4-1190273-8", "ES1000-NO.3-B8-X-STK"			
<a href="#">063725P011</a>	NO			"5-1190481-1", "ES2000-NO.2-B9-0-50MM"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">063725P022</a>	NO			"6-1190481-1", "ES2000-NO.2-B9-0-STK", "ES2000-2-4FOOT"			
<a href="#">063725P028</a>	NO			"6-1190481-5", "ES2000-NO.2-B9-0-25MM"			
<a href="#">085193P003</a>	NO			"9-1190628-5", "ES1000-NO.4-B7-X-STK"			
<a href="#">121397P015</a>	NO			"3-1190883-5", "ES2000-NO.3-B8-0-75MM"			
<a href="#">121397P018</a>	NO			"3-1190883-8", "ES2000-NO.3-B8-0-50MM"			
<a href="#">121397P024</a>	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
<a href="#">121397P043</a>	NO			"5-1190883-3", "ES2000-NO.3-B8-0-40MM"			
<a href="#">130599P003</a>	NO			"6-1190948-1", "ES2000-NO.4-B7-0-75MM"			
<a href="#">130599P006</a>	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			
<a href="#">130599P010</a>	NO			"6-1190948-7", "ES2000-NO.4-B7-0-40MM"			
<a href="#">130599P011</a>	NO			"6-1190948-8", "ES2000-NO.4-B7-0-50MM"			
<a href="#">193197P004</a>	NO			"4-1191401-7", "ES1000-NO.1-C1-X-STK"			
<a href="#">206247P038</a>	NO			"2-1191495-7", "SCT-NO.4-E2-0-STK"			
<a href="#">2525596002</a>	NO			"5-1191848-0", "RBK-ILS-125-NR1-0-50MM"			
<a href="#">4367790003</a>	NO			"1-1193283-5", "ES-CAP-NO.2-B9-0-35MM"			
<a href="#">5201946022</a>	NO			"1194087-8", "RT-3-NO.3-0-1IN"			
<a href="#">5201976026</a>	NO			"5-1194087-5", "RT-3-NO.2-0-1IN"			
<a href="#">520197P055</a>	NO			"1194088-2", "RT-3-NO.2-0-0.81IN"			
<a href="#">537637P035</a>	NO			"7-1194219-9", "SCT-NO.3-E3-0-65MM"			
<a href="#">537637P041</a>	NO			"8-1194219-5", "SCT-NO.3-E3-0-STK"			
<a href="#">543633P051</a>	NO			"3-1194264-7", "SCT-NO.1-E6-0-50MM"			
<a href="#">543633P064</a>	NO			"5-1194264-0", "SCT-NO.1-E6-0-STK"			
<a href="#">543633P079</a>	NO			"6-1194264-0", "SCT-NO.1-E6-0-40MM"			
<a href="#">576105P004</a>	NO			"7-1194570-9", "ES1000-NO.2-B9-X-STK"			
<a href="#">576105P009</a>	NO			"8-1194570-4", "ES1000-NO.2-B9-X-50MM"			
<a href="#">607381P046</a>	NO			"5-1194804-3", "SCT-NO.2-E5-0-STK"			
<a href="#">771113P007</a>	NO			"4-1196007-4", "FL2500-NO.2-I9-0-101MM"			
<a href="#">829131P012</a>	NO			"7-1196474-1", "ES2000-NO.1-C1-0-50MM"			
<a href="#">829131P021</a>	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			
<a href="#">829131P079</a>	NO			"2-1196475-9", "ES2000-NO.1-C1-0-15MM"			
<a href="#">CB5626-000</a>	NO			"FL2500-NO.1-I8-0-25MM"			
<a href="#">E95757-000</a>	NO			"4-1199653-3", "FL2500-NO.4-J2-0-STK"			

Customer: Heilind Asia Pacific (Hong Kong) ( 2991513 )

Location: Hong Kong

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">085193P003</a>	NO			"9-1190628-5", "ES1000-			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
				NO.4-B7-X-STK"			

Customer: Heilind Electronics GmbH ( 3050932 )

Location: Rosenheim

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">2525596002</a>	NO			"5-1191848-0", "RBK-ILS-125-NR1-0-50MM"			