PRODUCT CHANGE NOTIFICATION
E-Switch Series/ Part No affected: TL3253 series (all P/Ns) Part /Series Description:
Affected Process
Assembly Molding Stamping Plating
Change on:
Drawing Process Material Specification X Packaging Tooling Modification New Tooling Manufacturing Location
Reason for change:
 Improve packaging to prevent switch terminals from damage during shipping. Package 1 piece per cavity instead of 2. New quantity per tray is 126.
Proposed change: BEFORE
S I I I I I I I I
IIIIIIIII
I I I I I I I I I I
3333355
AFTER
and the test that the two the the test that the
1111111111111111
tal tai

