Get Email Version

NOTIFICATION

PRODUCT CHANGE

CURRENT DATE: 8-MAY-2013

TE CONNECTIVITY

PRODUCT CHANGE NOTIFICATION NO: P-13-009103 PCN DATE: 06-MAY-13 AGREEMENT NO:

LOCATION: WILMINGTONPCN DACUSTOMER NO: 167811AGREEITE CONNECTIVITY ENTITY:RMP (1082) - U.S. Operations on SAP

We would like to inform you about the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

GENERAL PRODUCT DESCRIPTION:

CUSTOMER: HEILIND ELECTRONICS

AMPLIMITE Cable Clamp Kits

DESCRIPTION OF CHANGE:

The Product Compliance Tracking database had errors in it regarding the REACH June 2011 SvHCs for the subject part numbers. Each of the following part numbers contains SvHC 1,2 benzenedicarboxylic acid, di-C6-8-branched alkyl esters, C7-rich (DIHP)(CAS No 71888-89-6)in the following percentages by weight: 5748676-2 0.75%, 5748676-3 1.32%, 5748676-4 1.21%, 5748676-5 1.11 %, 5748677-1 7.5%, 5748677-2 7.5%, 5748677-3 12.3%, 5748677-4 10.8%, and 5748677-5 11.2%.

REASON FOR CHANGE:

Document clarification. It should be emphasized that the inclusion of this Substance of very High Concern (SvHC) in these parts does not constitute a ban on their sale or use. However, it must be listed in accordance with REACH regulations.

ESTIMATE DATE: LAST ORDER DATE: (OBSOLETE PARTS ONLY)

LAST SHIP DATE:

(OBSOLETE PARTS ONLY)

FIRST DATE TO SHIP CHANGED PARTS:

(CHANGED PARTS ONLY) LAST DATE FOR MIXED SHIPMENTS: NO MIXED SHIPMENTS (CHANGED PARTS ONLY) CURRENT DATE: 8-MAY-2013

TE CONNECTIVITY

PRODUCT CHANGE NOTIFICATION

CUSTOMER: HEILIND ELECTRONICSPRODUCT CHANGE NOTIFICATION NO: P-13-009103LOCATION: WILMINGTONPCN DATE: 06-MAY-13CUSTOMER NO: 167811AGREEMENT NO:TE CONNECTIVITY ENTITY: RMP (1082) - U.S. Operations on SAP

PARTS BEING MODIFIED CUSTOMER PART NBR

5748676-3

5748676-4

5748677-4

Get Email Version

NOTIFICATION

PRODUCT CHANGE

CURRENT DATE: 8-MAY-2013

TE CONNECTIVITY

PRODUCT CHANGE NOTIFICATION NO: P-13-009103 PCN DATE: 06-MAY-13 AGREEMENT NO:

CUSTOMER NO: 155784 AGREEI TE CONNECTIVITY ENTITY: RMP (1082) - U.S. Operations on SAP

We would like to inform you about the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

GENERAL PRODUCT DESCRIPTION:

CUSTOMER: MAVERICK ELECTRONICS

LOCATION: HIGHLAND HEIGHTS

AMPLIMITE Cable Clamp Kits

DESCRIPTION OF CHANGE:

The Product Compliance Tracking database had errors in it regarding the REACH June 2011 SvHCs for the subject part numbers. Each of the following part numbers contains SvHC 1,2 benzenedicarboxylic acid, di-C6-8-branched alkyl esters, C7-rich (DIHP)(CAS No 71888-89-6)in the following percentages by weight: 5748676-2 0.75%, 5748676-3 1.32%, 5748676-4 1.21%, 5748676-5 1.11 %, 5748677-1 7.5%, 5748677-2 7.5%, 5748677-3 12.3%, 5748677-4 10.8%, and 5748677-5 11.2%.

REASON FOR CHANGE:

Document clarification. It should be emphasized that the inclusion of this Substance of very High Concern (SvHC) in these parts does not constitute a ban on their sale or use. However, it must be listed in accordance with REACH regulations.

ESTIMATE DATE: LAST ORDER DATE: (OBSOLETE PARTS ONLY)

LAST SHIP DATE:

(OBSOLETE PARTS ONLY)

FIRST DATE TO SHIP CHANGED PARTS:

(CHANGED PARTS ONLY) LAST DATE FOR MIXED SHIPMENTS: NO MIXED SHIPMENTS (CHANGED PARTS ONLY) CURRENT DATE: 8-MAY-2013

TE CONNECTIVITY

PRODUCT CHANGE NOTIFICATION

CUSTOMER: MAVERICK ELECTRONICSPRODUCLOCATION: HIGHLAND HEIGHTSPCN DATCUSTOMER NO: 155784AGREENTE CONNECTIVITY ENTITY: RMP (1082) - U.S. Operations on SAP

PRODUCT CHANGE NOTIFICATION NO: P-13-009103 PCN DATE: 06-MAY-13 AGREEMENT NO:

PARTS BEING MODIFIED CUSTOMER PART NBR

5748676-3

CURRENT DATE: 7-MAY-2013

TE CONNECTIVITY

Get Email Version

PRODUCT CHANGE NOTIFICATION

CUSTOMER: HEILIND ASIA PACIFIC (HONG KONG)PRODULOCATION: SHATIN, N.T.PCN DCUSTOMER NO: 2980376AGREETE CONNECTIVITY ENTITY: HK (0451) - TE Connectivity HK Ltd

PRODUCT CHANGE NOTIFICATION NO: P-13-009103 PCN DATE: 06-MAY-13 AGREEMENT NO:

We would like to inform you about the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

GENERAL PRODUCT DESCRIPTION:

AMPLIMITE Cable Clamp Kits

DESCRIPTION OF CHANGE:

The Product Compliance Tracking database had errors in it regarding the REACH June 2011 SvHCs for the subject part numbers. Each of the following part numbers contains SvHC 1,2 benzenedicarboxylic acid, di-C6-8-branched alkyl esters, C7-rich (DIHP)(CAS No 71888-89-6)in the following percentages by weight: 5748676-2 0.75%, 5748676-3 1.32%, 5748676-4 1.21%, 5748676-5 1.11 %, 5748677-1 7.5%, 5748677-2 7.5%, 5748677-3 12.3%, 5748677-4 10.8%, and 5748677-5 11.2%.

REASON FOR CHANGE:

Document clarification. It should be emphasized that the inclusion of this Substance of very High Concern (SvHC) in these parts does not constitute a ban on their sale or use. However, it must be listed in accordance with REACH regulations.

ESTIMATE DATE: LAST ORDER DATE: (OBSOLETE PARTS ONLY)

LAST SHIP DATE:

(OBSOLETE PARTS ONLY)

FIRST DATE TO SHIP CHANGED PARTS:

(CHANGED PARTS ONLY) LAST DATE FOR MIXED SHIPMENTS: NO MIXED SHIPMENTS (CHANGED PARTS ONLY) CURRENT DATE: 7-MAY-2013

TE CONNECTIVITY

PRODUCT CHANGE NOTIFICATION

CUSTOMER:HEILIND ASIA PACIFIC (HONG KONG)PRODULOCATION:SHATIN, N.T.PCN D/CUSTOMER NO:2980376AGREETE CONNECTIVITY ENTITY:HK (0451) - TE Connectivity HK Ltd

PARTS BEING MODIFIED CUSTOMER PART NBR

5748676-3

5748677-1

5748677-2

5748677-3