

**CURRENT DATE:** 9-AUGUST-2013

[Get Email Version](#)

## TE CONNECTIVITY

## PRODUCT CHANGE NOTIFICATION

**CUSTOMER:** HEILIND ELECTRONICS

**PRODUCT CHANGE NOTIFICATION NO:** P-13-009385

**LOCATION:** WILMINGTON

**PCN DATE:** 07-AUG-13

**CUSTOMER NO:** 167811

**AGREEMENT NO:**

**TE CONNECTIVITY ENTITY:** RMP (1082) - U.S. Operations on SAP

We would like to inform you about the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

### GENERAL PRODUCT DESCRIPTION:

Universal MATE-N-LOK

### DESCRIPTION OF CHANGE:

COURTESY PCN - Changes are being made to how the product is held within the cardboard reel. Shrink-warp will no longer be placed around the outside edge of the reel. Instead, tape will be used to hold the front flange to the back flange. Four pieces of tape will be evenly spaced around the outside edge of each reel. Also, a twist-tie will firmly hold the end of the continuous strip of contacts to the cardboard flange.

### REASON FOR CHANGE:

Product improvement. Eliminate potential of loosely wound product and damaged reels during shipment. Improvement will also provide customers with a method to secure partially used reels for storage.

### ESTIMATE DATE:

**LAST ORDER DATE:**

(OBSOLETE PARTS ONLY)

**LAST SHIP DATE:**

(OBSOLETE PARTS ONLY)

**FIRST DATE TO SHIP CHANGED PARTS:**

08-AUG-2013

(CHANGED PARTS ONLY)

**LAST DATE FOR MIXED**

**SHIPMENTS:** 03-AUG-2014

(CHANGED PARTS ONLY)

**CURRENT DATE:** 9-AUGUST-2013

## TE CONNECTIVITY

## PRODUCT CHANGE NOTIFICATION

**CUSTOMER:** HEILIND ELECTRONICS

**PRODUCT CHANGE NOTIFICATION NO:** P-13-009385

**LOCATION:** WILMINGTON

**PCN DATE:** 07-AUG-13

**CUSTOMER NO:** 167811

**AGREEMENT NO:**

**TE CONNECTIVITY ENTITY:** RMP (1082) - U.S. Operations on SAP

---

<b>PARTS BEING MODIFIED</b>	<b>CUSTOMER PART NBR</b>
-----------------------------	--------------------------

1-770004-0

1-770010-0

350218-1

350536-1  
(Alias Part Numbers:  
"403429822" )

350536-3  
(Alias Part Numbers:  
"403311541" )

350536-7

350537-2

350537-3

350537-6

350538-1

(Alias Part Numbers:  
"CU3084-000",  
"AMPS-0-0350538-1" )

350538-2

350538-3

(Alias Part Numbers:  
"090064-000",  
"AMPS-0-0350538-3" )

350538-6

350687-1

350687-7

350700-1

770003-3

(Alias Part Numbers:  
"405903444" )

770004-3

(Alias Part Numbers:  
"1199493" )

770005-1

770006-3

770007-1

770008-3

770009-1

770010-3

770193-1

**CURRENT DATE:** 9-AUGUST-2013

[Get Email Version](#)

## TE CONNECTIVITY

## PRODUCT CHANGE NOTIFICATION

**CUSTOMER:** HEILIND ELECTRONICS

**PRODUCT CHANGE NOTIFICATION NO:** P-13-009385

**LOCATION:** HIGHLAND HEIGHTS

**PCN DATE:** 07-AUG-13

**CUSTOMER NO:** 415410

**AGREEMENT NO:**

**TE CONNECTIVITY ENTITY:** RMP (1082) - U.S. Operations on SAP

We would like to inform you about the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

### GENERAL PRODUCT DESCRIPTION:

Universal MATE-N-LOK

### DESCRIPTION OF CHANGE:

COURTESY PCN - Changes are being made to how the product is held within the cardboard reel. Shrink-warp will no longer be placed around the outside edge of the reel. Instead, tape will be used to hold the front flange to the back flange. Four pieces of tape will be evenly spaced around the outside edge of each reel. Also, a twist-tie will firmly hold the end of the continuous strip of contacts to the cardboard flange.

### REASON FOR CHANGE:

Product improvement. Eliminate potential of loosely wound product and damaged reels during shipment. Improvement will also provide customers with a method to secure partially used reels for storage.

### ESTIMATE DATE:

**LAST ORDER DATE:**

(OBSOLETE PARTS ONLY)

**LAST SHIP DATE:**

(OBSOLETE PARTS ONLY)

**FIRST DATE TO SHIP CHANGED PARTS:**

08-AUG-2013

(CHANGED PARTS ONLY)

**LAST DATE FOR MIXED**

**SHIPMENTS:** 03-AUG-2014

(CHANGED PARTS ONLY)

**CURRENT DATE:** 9-AUGUST-2013

**TE CONNECTIVITY**

**PRODUCT CHANGE  
NOTIFICATION**

**CUSTOMER:** HEILIND ELECTRONICS

**PRODUCT CHANGE NOTIFICATION NO:** P-13-009385

**LOCATION:** HIGHLAND HEIGHTS

**PCN DATE:** 07-AUG-13

**CUSTOMER NO:** 415410

**AGREEMENT NO:**

**TE CONNECTIVITY ENTITY:** RMP (1082) - U.S. Operations on SAP

---

**PARTS BEING MODIFIED**

**CUSTOMER PART NBR**

770004-4

**CURRENT DATE:** 9-AUGUST-2013

[Get Email Version](#)

## TE CONNECTIVITY

## PRODUCT CHANGE NOTIFICATION

**CUSTOMER:** MAVERICK ELECTRONICS

**PRODUCT CHANGE NOTIFICATION NO:** P-13-009385

**LOCATION:** HIGHLAND HEIGHTS

**PCN DATE:** 07-AUG-13

**CUSTOMER NO:** 155784

**AGREEMENT NO:**

**TE CONNECTIVITY ENTITY:** RMP (1082) - U.S. Operations on SAP

We would like to inform you about the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

### GENERAL PRODUCT DESCRIPTION:

Universal MATE-N-LOK

### DESCRIPTION OF CHANGE:

COURTESY PCN - Changes are being made to how the product is held within the cardboard reel. Shrink-warp will not longer placed around the outside edge of the reel. Instead, tape will be used to hold the front flange to the back flange. Four piece of tape will be evenly spaced around the outside edge of each reel. Also, a twist-tie will firmly hold the end of the continuous strip of contacts to the cardboard flange.

### REASON FOR CHANGE:

Product improvement. Eliminate potential of loosely wound product and damaged reels during shipment. Improvement will also provide customers with a method to secure partially used reels for storage.

### ESTIMATE DATE:

**LAST ORDER DATE:**

(OBSOLETE PARTS ONLY)

**LAST SHIP DATE:**

(OBSOLETE PARTS ONLY)

**FIRST DATE TO SHIP CHANGED PARTS:**

08-AUG-2013

(CHANGED PARTS ONLY)

**LAST DATE FOR MIXED**

**SHIPMENTS:** 03-AUG-2014

(CHANGED PARTS ONLY)

**CURRENT DATE:** 9-AUGUST-2013

**TE CONNECTIVITY**

**PRODUCT CHANGE  
NOTIFICATION**

**CUSTOMER:** MAVERICK ELECTRONICS

**PRODUCT CHANGE NOTIFICATION NO:** P-13-009385

**LOCATION:** HIGHLAND HEIGHTS

**PCN DATE:** 07-AUG-13

**CUSTOMER NO:** 155784

**AGREEMENT NO:**

**TE CONNECTIVITY ENTITY:** RMP (1082) - U.S. Operations on SAP

---

**PARTS BEING MODIFIED**

**CUSTOMER PART NBR**

350536-7

350537-7

350538-7