

**CURRENT DATE:** 24-SEPTEMBER-2013

[Get Email Version](#)

## TE CONNECTIVITY

## PRODUCT CHANGE NOTIFICATION

**CUSTOMER:** HEILIND ELECTRONICS

**PRODUCT CHANGE NOTIFICATION NO:** P-13-009504

**LOCATION:** WILMINGTON

**PCN DATE:** 19-SEP-13

**CUSTOMER NO:** 167811

**AGREEMENT NO:** 081213180007

**TE CONNECTIVITY ENTITY:** RMP (1082) - U.S. Operations on SAP

We would like to inform you about the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

### GENERAL PRODUCT DESCRIPTION:

Amplimite Hardware, Cable Clamp Kits, and Connectors

### DESCRIPTION OF CHANGE:

Cancellation of pending change to discontinue Amplimite hardware, cable clamp kits, and connectors with yellow chromate finish as communicated in PCN E-13-008804.

### REASON FOR CHANGE:

Customer Request. All part numbers will remain active at this time due to customer objections to the proposed change to eliminate parts with yellow chromate finish.

### ESTIMATE DATE:

**LAST ORDER DATE:**

(OBSOLETE PARTS ONLY)

**LAST SHIP DATE:**

(OBSOLETE PARTS ONLY)

**FIRST DATE TO SHIP CHANGED PARTS:**

(CHANGED PARTS ONLY)

**LAST DATE FOR MIXED**

**SHIPMENTS: NO MIXED SHIPMENTS**

(CHANGED PARTS ONLY)

**CURRENT DATE:** 24-SEPTEMBER-2013

## TE CONNECTIVITY

## PRODUCT CHANGE NOTIFICATION

**CUSTOMER:** HEILIND ELECTRONICS

**PRODUCT CHANGE NOTIFICATION NO:** P-13-009504

**LOCATION:** WILMINGTON

**PCN DATE:** 19-SEP-13

**CUSTOMER NO:** 167811

**AGREEMENT NO:** 081213180007

**TE CONNECTIVITY ENTITY:** RMP (1082) - U.S. Operations on SAP

---

PARTS BEING MODIFIED	CUSTOMER PART NBR
----------------------	-------------------

1-5207908-3

1658640-2

(Alias Part Numbers:  
"1067998" )

205203-3

(Alias Part Numbers:  
"0-0205203-3",  
"2-42934-5726" )

205203-8

(Alias Part Numbers:  
"2-30124-2009" )

205204-4

(Alias Part Numbers:  
"0-0205204-4" )

205204-8

(Alias Part Numbers:  
"2-42934-5716" )

205204-9

(Alias Part Numbers:  
"2-30124-1009" )

205205-2  
(Alias Part Numbers:  
"2-42934-5727",  
"1186906" )

205206-3  
(Alias Part Numbers:  
"5021905",  
"27-01519-00",  
"1186904" )

205206-8

205206-9

205209-2  
(Alias Part Numbers:  
"010-1145-00",  
"2-42934-5729" )

205210-3

205210-7

205210-8

5205207-1  
(Alias Part Numbers:  
"4-16211-7349" )

5205208-1  
(Alias Part Numbers:  
"2-30124-1025" )

5205817-1

5205817-3  
(Alias Part Numbers:  
"673-1082-01" )

5205818-2

5205818-3

5205980-1  
(Alias Part Numbers:  
"2-30351-0010",  
"1185341" )

5205980-4

5205980-5

5206478-3  
(Alias Part Numbers:  
"4-16211-7350" )

5206514-1

5206514-4

5206514-6

5206514-7

5207719-1  
(Alias Part Numbers:  
"2-42935-9042" )

5207719-3

5207719-4

5207871-1

5207908-1  
(Alias Part Numbers:  
"4-27202-1747" )

5207908-7

5745136-2

5745404-1

5745563-1

5745647-1

5748270-2  
(Alias Part Numbers:  
"1364315",  
"1363997" )

5748271-1

5748271-3

5749626-2

5749914-2

**CURRENT DATE:** 24-SEPTEMBER-2013

[Get Email Version](#)

## TE CONNECTIVITY

## PRODUCT CHANGE NOTIFICATION

**CUSTOMER:** MAVERICK ELECTRONICS

**PRODUCT CHANGE NOTIFICATION NO:** P-13-009504

**LOCATION:** HIGHLAND HEIGHTS

**PCN DATE:** 19-SEP-13

**CUSTOMER NO:** 155784

**AGREEMENT NO:**

**TE CONNECTIVITY ENTITY:** RMP (1082) - U.S. Operations on SAP

We would like to inform you about the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

### GENERAL PRODUCT DESCRIPTION:

Amplimite Hardware, Cable Clamp Kits, and Connectors

### DESCRIPTION OF CHANGE:

Cancellation of pending change to discontinue Amplimite hardware, cable clamp kits, and connectors with yellow chromate finish as communicated in PCN E-13-008804.

### REASON FOR CHANGE:

Customer Request. All part numbers will remain active at this time due to customer objections to the proposed change to eliminate parts with yellow chromate finish.

### ESTIMATE DATE:

**LAST ORDER DATE:**

(OBSOLETE PARTS ONLY)

**LAST SHIP DATE:**

(OBSOLETE PARTS ONLY)

**FIRST DATE TO SHIP CHANGED PARTS:**

(CHANGED PARTS ONLY)

**LAST DATE FOR MIXED**

**SHIPMENTS: NO MIXED SHIPMENTS**

(CHANGED PARTS ONLY)

**CURRENT DATE:** 24-SEPTEMBER-2013

## TE CONNECTIVITY

## PRODUCT CHANGE NOTIFICATION

**CUSTOMER:** MAVERICK ELECTRONICS

**PRODUCT CHANGE NOTIFICATION NO:** P-13-009504

**LOCATION:** HIGHLAND HEIGHTS

**PCN DATE:** 19-SEP-13

**CUSTOMER NO:** 155784

**AGREEMENT NO:**

**TE CONNECTIVITY ENTITY:** RMP (1082) - U.S. Operations on SAP

---

PARTS BEING MODIFIED	CUSTOMER PART NBR
----------------------	-------------------

205203-3 (Alias Part Numbers: "0-0205203-3", "2-42934-5726" )	
--	--

205203-8 (Alias Part Numbers: "2-30124-2009" )	
--	--

205204-4 (Alias Part Numbers: "0-0205204-4" )	
---	--

205204-8 (Alias Part Numbers: "2-42934-5716" )	
--	--

205205-2 (Alias Part Numbers: "2-42934-5727", "1186906" )	
--	--

205206-3 (Alias Part Numbers: "5021905", "27-01519-00", "1186904" )	
---	--

205206-8

5205207-1

(Alias Part Numbers:  
"4-16211-7349" )

5205208-1

(Alias Part Numbers:  
"2-30124-1025" )

5205817-3

(Alias Part Numbers:  
"673-1082-01" )

5205980-1

(Alias Part Numbers:  
"2-30351-0010",  
"1185341" )

5207719-4

5745583-5