

## Global Change Notification (GCN)

Product Family	Mini-Fit	10627223
		GCN Number
Series	5566	February 14, 2014
		Date Issued
Reason For Change	New, Modified, Or Replacement Tooling	
Change Description	The mold used to make housing 5566-14 has reached its end of life and is being replaced by an identical tool.	
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.	
Reason For Short Notice Exception		
Assessment Of Change (How Product Will Be Qualified & Validated)	The new tool will be fully qualified by Molex before it is released to production. The housings produced from the new mold will be identical to the current parts.	
Internal Molex Qualification Date (Planned Date Information Available)	May 16, 2014	
Sample Availability Date (Changed Part)	May 16, 2014	
Date of Implementation	August 15, 2014	
Method of Identifying Change	Parts made after August 1, 2014	
Recommended Replacement Parts	Not Applicable	
Last Time Buy Date for Obsolete Parts		
Last Time Ship Date for Obsolete Parts		

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	QuiNann Lim	QuiNann.Lim@molex.com	+31-40-295-8472
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

**Molex, Inc.**  
 2222 Wellington Court  
 Lisle, IL 60532  
 TEL: 630-969-4747  
[www.molex.com](http://www.molex.com)

Material

39288140  
39293146  
39310140  
39310148  
460151400  
460151402  
39296148  
39341140  
39350148  
98013145  
98265143  
98268149  
98282149  
444721455  
444721456  
444721457  
39310141  
39310147  
469990144  
39306142  
435880021  
39309147  
50361888  
50361889  
460151404  
469990570