

Global Change Notification (GCN)

Product Family	Mini-Fit	10641460
		GCN Number
Series	5566	June 11, 2014
		Date Issued
Reason For Change	New, Modified, Or Replacement Tooling	
Change Description	The Mold used to make housing 5566-04 has reached its end of life and is being replaced by an identical tool.	
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.	
Reason For Short Notice Exception		
Assessment Of Change (How Product Will Be Qualified & Validated)	The new tool will be fully qualified by Molex before it is released to production. The housings produced from the new mold will be identical to the current parts.	
Internal Molex Qualification Date (Planned Date Information Available)	September 09, 2014	
Sample Availability Date (Changed Part)	September 09, 2014	
Date of Implementation	December 15, 2014	
Method of Identifying Change	Product made after	
Recommended Replacement Parts	Not Applicable	
Last Time Buy Date for Obsolete Parts		
Last Time Ship Date for Obsolete Parts		

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	QuiNann Lim	QuiNann.Lim@molex.com	+31-40-295-8472
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc.
 2222 Wellington Court
 Lisle, IL 60532
 TEL: 630-969-4747
www.molex.com

Material

39289068
39299062
39299063
39299064
39299065
39299066
39299067
39299069
39306065
39306067
39306068
39348068
50304449
50348559
50348562
98267062
98267063
98267064
98267065
423820015
434600005
434600006
444720650
444720651
444720652
444720653
444720661
444720682
444720683
444729904
444729905
460150601
460150603
460150605
460150607
460150608
460150609