

Global Change Notification (GCN)

Product Family	1.25 FFC ZIF HSG ASSY	10648927
		GCN Number
Series	5597	December 09, 2014
		Date Issued
Reason For Change	Supplier Changes To Raw Material	
Change Description	This is to inform you of molding resin change for actuator 5571series. The material changes from VALOX420SE0-1001 to DURANEX3216-EF2001. Finished Goods are 5597series (1.25 FFC ZIF HSG ASSY), assembled in our vendor, Aidex. The current resin is being produced at SABIC. This time Molex will purchase new resin from WINTECH POLYMERS as a stable material source for our future manufacturing activities. Mass production starting date is estimated as 30th Jan, 2015 (Can be changeable due to demand and manufacturing situation of 5597series). The affected items are as follows $\cdot \cdot 39532034$, 39532044, 39532045, 39532044, 39532055, 39532064, 39532065, 39532074, 39532075, 39532084, 39532085, 39532094, 39532095, 39532104, 39532105, 39532114, 39532115, 39532117, 39532124, 39532125, 39532164, 39532165, 39532174, 39532175, 39532144, 39532155, 39532194, 39532195, 39532204, 39532205, 39532204, 39532244, 39532245, 39532247, 39532244, 39532255, 39532264, 39532265, 39532274, 39532275, 39532284, 39532284, 39532294, 39532295, 39532344, 39532305, 39532314, 39532315, 39532244, 39532255, 39532244, 39532235, 39532344, 39532305, 39532344, 39532355, 39532244, 39532275, 39532344, 39532355, 39532344, 39532305, 39532344, 39532354, 39532344, 39532354, 39532344, 39532354, 39532344, 39532354, 39532344, 39532354, 39532344, 39532354, 39532344, 39532354, 39532344, 39532354, 39532344, 39532354, 39532344, 39532354, 39532344, 39532354, 39532344, 39532354, 39532344, 39532354, 39532344, 39532354, 39532344, 39532354, 39532344, 39532354, 39532344, 39532345, 39532344, 39532345, 39532344, 39532345, 39532344, 39532354, 39532344, 39532354, 39532354, 39532344, 39532354, 39532354, 39532344, 39532354, 39532354, 39532344, 39532354, 395323	
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-r	nail message.
Reason For Short Notice Exception	Medical Industry	
Assessment Of Change (How Product Will Be Qualified & Validated)	First Article Inspection was conducted to find no que any significant influence on products' performance.	ality issues. There will not be
Internal Molex Qualification Date (Planned Date Information Available)	July 31, 2014	
Sample Availability Date (Changed Part)	December 15, 2014	
Date of Implementation	January 30, 2015	
Method of Identifying Change	Lot Number	
Recommended Replacement Parts	Not Applicable	
Last Time Buy Date for Obsolete Parts		
Last Time Ship Date for Obsolete Parts		

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com

Molex Part Number		
39532034		
39532044		
39532084		
39532105		
39532124		
39532144		
39532185		
39532204		
39532205		
39532265		
39532284		
39532285		
39532064		
39532094		