

Product Family

Global Change Notification (GCN)

10663814

GCN Number

Series 2139, 36753, 68801 & 88469 December 22, 2014 Date Issued Reason For Change New, Modified, Or Replacement Tooling Change Description Molex is removing the last circuit ID on 2139 series housings. The circuit 1 ID will remain on the part. This change only affects parts with 6ckts and up. The smaller circuit sizes do not have a last circuit ID. Current part with last circuit identification New part without last circuit identification Part Numbers Affected Please refer to CustomerPartList.csv attached to e-mail message. Reason For Short Notice Exception Assessment Of Change This change will have no effect on fit form or function of the connector. (How Product Will Be Qualified & Validated) Internal Molex Oualification Date (Planned Date Information Available) Sample Availability Date April 15, 2015 (Changed Part) Date of Implementation May 26, 2015 Method of Identifying Change No last circuit ID on parts 6 circuit or larger. Recommended Replacement Parts Not Applicable Last Time Buy Date for Obsolete Parts Last Time Ship Date for Obsolete Parts

KK 3.96 Crimp Terminal Housing

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com

Molex Part Number

....