



Product Change Notification

Current Date: 02-Mar-2015

TE Connectivity

Product Change Notification: E-15-001877

PCN Date: 11-FEB-15

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Code40 CD 90 deg New TE Dimensional Requirements to Reduce L

Description of Changes

Customer Notification on Raychem Brand Adaptors. TE Connectivity is optimising the supply chain for its Connector Accessories product line to improve manufacturability and customer service. Product feature optimisation will mean that there will be some minor dimensional differences on some adaptor codes, these dimensional changes will remain within the current and existing customer drawing. On some adaptors there will be some dimensional differences outside the current and existing customer drawing. All adaptor designs affected by dimensional changes are documented in the attached spreadsheet All Adaptors affected by dimensional change meet the current performance requirements. TE reserve the right to supply both designs during a 6 month transition period. TE will not mix the two designs within a single line item on any order but may mix the designs on different line items on any order

Reason for Changes:

Product Improvement, Optimise Manufacturing, Product Improvement, Single Design, Better Customer Service

Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

10-APR-2015

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
068866-000	NO		8-1201143-5, TXR40SJ90-0806AI			
139242-000	NO		3-1201060-2, TXR40SJ90-1406AI			
189084-000	NO		5-1201153-7, TXR40SJ90-1406BI			
199268-000	NO		5-1199705-2, TXR40SJ90-2214AI			
266379-000	NO		5-1197910-7, TXR40SJ90-1208AI			
379595-000	NO		2-1192839-5, TXR40SC90-0804AI			
438714-000	NO		1201221-3, TXR40SJ90-2010AI			
513051-000	NO		2-1194031-0, TXR40SJ90-2416BI			
589369-000	NO		2-1194663-8, TXR40BW90-2014AI			
595389-000	NO		4-1194708-6, TXR40SC90-1207AI			
679233-000	NO		8-1195339-5, TXR40BW90-2014BI			
698306-000	NO		4-1199152-2, TXR40SJ90-1206BI			
701445-000	NO		7-1195504-4, TXR40SC90-1208AI			
735675-000	NO		2-1195745-8, TXR40SC90-1408BI			
748446-000	NO		7-1201153-3, TXR40SJ90-1812BI			
821132-000	NO		1-1201221-7, TXR40SJ90-1407BI			
846511-000	NO		1196603-6, TXR40SJ90-2420BI			
868217-000	NO		3-1196759-0, TXR40BW90-2212BI			
973429-000	NO		6-1197871-0, TXR40BW90-2420AI			

982413-000	NO		2-1197590-3, TXR40SJ90-1204AI		
A00273-000	NO		2-1201192-3, TXR40SJ90-1412BI		
A10280-000	NO		3-1201060-6, TXR40SJ90-1612AI		
A21151-000	NO		7-1201256-6, TXR40SJ90-1814BI		
A31781-000	NO		3-1201060-8, TXR40SJ90-1814AI		
A31823-000	NO		5-1201569-1, TXR40SJ90-1405AI		
A32643-000	NO		5-1201058-2, TXR40SJ90-1806BI		
A36735-000	NO		1-1202128-0, TXR40SC90-1410AI		
A43939-000	NO		3-1201147-1, TXR40BW90-2418BI		
A50240-000	NO		8-1201113-4, TXR40SJ90-1610BI		
A52242-000	NO		6-1201743-4, TXR40SJ90-2216AI		
A81722-000	NO		4-1201060-7, TXR40SJ90-2416AI		
C07745-000	NO		5-1201060-2, TXR40SJ90-1410AI		
C11265-000	NO		6-1201058-4, TXR40SJ90-2405BI		
C47355-000	NO		7-1201787-7, TXR40SJ90-1614BI		
C86893-000	NO		2-1201056-6, TXR40SJ90-2210BI		
CA2521-000	NO		TXR40SJ90-1812AI		
CA2920-000	NO		1-1899104-6, TXR40SC90-2416AI		
CA2922-000	NO		1-1899104-7, TXR40SC90-1408AI		
CA2924-000	NO		1-1899104-8, TXR40SC90-2214AI		
CA5286-000	NO		6-1899118-8, TXR40SC90-2414AI		
CC4069-000	NO		TXR40SJ90-1210AI		
CF4656-000	NO		TXR40SJ90-1808AI		
CJ1133-000	NO		TXR40SJ90-1204BI		
CJ3461-000	NO		TXR40SJ90-2406AI		
CJ7342-000	NO		"TXR40SJ90-2407AI"		
CJ7500-000	NO		TXR40SJ90-2218BI		
CJ7662-000	NO		"TXR40SJ90-2410BI"		
CJ7663-000	NO		"TXR40SJ90-2408BI"		
CJ7851-000	NO		"TXR40SJ90-2218AI"		
CL1228-000	NO		"TXR40SJ90-2208AI"		
CL1230-000	NO		"TXR40SJ90-1806AI"		
CL1434-000	NO		"TXR40SJ90-1412AI"		
CL5293-000	NO		7-1899352-3, TXR40BW90-2418AI		
CM0329-000	NO		"TXR40SJ90-2016AI"		
CM1936-000	NO		"TXR40SJ90-1816BI"		
CM5228-000	NO		"TXR40SC90-2218BI"		
CM5232-000	NO		"TXR40SC90-1814BI"		
CN0153-000	NO		6-1899454-7, TXR40SC90-2412AI		
CN0738-000	NO				
CN0739-000	NO				
CN0740-000	NO				
CN4386-000	NO		2-1899479-9, TXR40BW90-2410AI		
CN9660-000	NO		TXR40SJ90-0806BI		
CP0485-000	NO		TXR40SJ90-1808BI		
CP0505-000	NO		TXR40SJ90-2012BI		
CP4762-000	NO		TXR40SC90-1608AI		
CP4764-000	NO		TXR40SC90-2010AI		
CP4768-000	NO		TXR40SC90-1612BI		
CP4770-000	NO		TXR40SC90-1812AI		
CP4774-000	NO		TXR40SC90-2216AI		
CP4782-000	NO		4-1899539-5, TXR40SC90-1412AI		

CP6624-000	NO		TXR40SJ90-1210BI		
CP6826-000	NO		TXR40SJ90-1604BI		
CP6827-000	NO		TXR40SJ90-2010BI		
CP6828-000	NO		TXR40SJ90-2012AI		
CS0068-000	NO				
CS0083-000	NO				
CS0085-000	NO				
CS0143-000	NO				
CS0210-000	NO		TXR40SC90-2212AI		
CS0227-000	NO		TXR40SJ90-2208BI		
CV1093-000	NO		8-1899743-9, TXR40SC90-2210AI		
CW3663-000	NO		TXR40SC90-1810BI		
CW3665-000	NO		TXR40SC90-2010BI		
CW3666-000	NO		TXR40SC90-2214BI		
CZ1348-000	NO		TXR40SC90-2012AI		
CZ1351-000	NO		TXR40SC90-1606AI		
CZ7121-000	NO		TXR40SC90-1406AI		
D00967-000	NO		5-1201060-7, TXR40SJ90-1810BI		
D04850-000	NO		5-1201060-8, TXR40SJ90-1810AI		
D06052-000	NO		2-1201279-1, TXR40SJ90-1214AI		
D25034-000	NO		3-1201461-6, TXR40SJ90-1614AI		
D46694-000	NO		8-1201503-8, TXR40SJ90-2408AI		
D52350-000	NO		6-1201154-2, TXR40SJ90-2212AI		
D57499-000	NO		7-1201115-5, TXR40SJ90-2014BI		
D60911-000	NO		9-1201223-1, TXR40SJ90-1604AI		
D62326-000	NO		1201059-1, TXR40SJ90-1608BI		
D76771-000	NO		1201059-3, TXR40SJ90-2406BI		
D77379-000	NO		6-1201271-3, TXR40SJ90-0805AI		
D94187-000	NO		7-1201232-1, TXR40BW90-2016AI		
E02001-000	NO		3-1200373-8, TXR40SJ90-0804AI		
E37260-000	NO		6-1201056-6, TXR40SJ90-2214BI		
E57261-000	NO		1201225-7, TXR40SJ90-0807AI		
E64643-000	NO		7-1201060-1, TXR40SJ90-2014AI		
E64690-000	NO		7-1201060-2, TXR40SJ90-1206AI		
E71052-000	NO		7-1201060-3, TXR40SJ90-2210AI		
E73623-000	NO		1-1201225-8, TXR40SJ90-1407AI		
E76250-000	NO		7-1201060-4, TXR40SJ90-1408AI		
E77877-000	NO		4-1201258-5, TXR40SJ90-2212BI		
E82054-000	NO		7-1201056-8, TXR40SJ90-1208BI		
E87278-000	NO		1-1201145-2, TXR40SJ90-1608AI		
E97848-000	NO		9-1202074-6, TXR40SC90-1610AI		
F17080-000	NO		7-1201060-7, TXR40SJ90-1610AI		
F21844-000	NO		3-1201059-8, TXR40SJ90-2414BI		
F37162-000	NO		9-1200501-3, TXR40SJ90-0804BI		
F51472-000	NO		9-1200501-7, TXR40SJ90-1606BI		
F54420-000	NO		2-1200514-3, TXR40SJ90-2414AI		

F87128-000	NO		8-1201192-6, TXR405J90-0805BI			
----------------------------	----	--	-------------------------------	--	--	--