

## Global Change Notification (GCN)

Product Family	QSFP+ cable assy	10703355
		GCN Number
Series	Various	July 23, 2015
		Date Issued
Reason For Change	New, Modified, Or Replacement Tooling	
Change Description	This letter is to inform you that supplier will add the additional QSFP back shell 747560102/0103/0124/0126/0130/0226/0230/0202/0203/0224 tool to increase their capacity , the additional tool is the same as original tooling. All the assemblies will be impact by the change. The reason to add this additional tool due to QSFP cable assy demand upside. mfg plant is under new tool FAI qualification , and will use new tool component until FAI completed and accepted.	
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.	
Reason For Short Notice Exception	New Capacity	
Assessment Of Change (How Product Will Be Qualified & Validated)	component FAI report	
Internal Molex Qualification Date (Planned Date Information Available)	July 20, 2015	
Sample Availability Date (Changed Part)	July 08, 2015	
Date of Implementation	August 09, 2015	
Method of Identifying Change	No need do the indentification due to spec it is same and just different with new tool to increase the capacity .	
Recommended Replacement Parts	N/A	
Last Time Buy Date for Obsolete Parts		
Last Time Ship Date for Obsolete Parts		

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

**Molex, Inc.**  
 2222 Wellington Court  
 Lisle, IL 60532  
 TEL: 630-969-4747  
[www.molex.com](http://www.molex.com)