

Global Change Notification (GCN)

Product Family	MX150	10698716
		GCN Number
Series	33472	July 31, 2015
		Date Issued
Reason For Change	New, Modified, Or Replacement Tooling	
Change Description	The purpose of this letter is to inform you that a copied line will be fabricated to the MX150 33472**** Seal Recetacle Connector , the reason of this change is the increasing volumes.This is strictly capacity tooling with no design changes.	
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.	
Reason For Short Notice Exception	New Capacity	
Assessment Of Change (How Product Will Be Qualified & Validated)	DVP&R	
Internal Molex Qualification Date (Planned Date Information Available)	July 30, 2015	
Sample Availability Date (Changed Part)	July 15, 2015	
Date of Implementation	August 30, 2015	
Method of Identifying Change	New tooling will have unique body date code from current	
Recommended Replacement Parts		
Last Time Buy Date for Obsolete Parts		
Last Time Ship Date for Obsolete Parts		

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc.
 2222 Wellington Court
 Lisle, IL 60532
 TEL: 630-969-4747
www.molex.com