



Product Change Notification

Current Date: 04-Feb-2016

TE Connectivity

Product Change Notification: P-16-012579

PCN Date: 02-FEB-16

Customer: Heilind Electronics
Inc(0002135900)

Location: WORLDWIDE

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

AFFECTS CUSTOMER SHIPMENTS WITHIN NORTH AMERICA ONLY Delay of Migration: Southwest DC to New El Paso DC

Description of Changes

UPDATE TO PCN P-16-012527. To ensure a smooth and stable transition from SWDC to EPDC, TE will be delaying the transition from the current Santa Teresa, NM DC (SWDC) to the new El Paso, TX DC (EPDC), originally scheduled to implement February 8th - 15th, is now scheduled to implement April 11th - 15th. This delay will allow extended testing on all SAP systems and procedures to ensure a seamless transition into the new warehouse. As we migrate the product and go-live on the new SAP WM software, it is critical to ensure this testing and training is fully incorporated into the systems and operational processes in the new El Paso warehouse. Based on the revised timing of transition, both Customer Shipments and Supplier Deliveries will continue to process from the Santa Teresa, NM location: Address: 101 Lindbergh, Santa Teresa, NM 88008, DUNS Code: 036967748. See attached Customer Letter.

Other attachments:
[Customer Letter](#)
Reason for Changes:

Customer Request. The team arrived at this decision to delay the migration with a focus on our customers and to provide a seamless transition to the new warehouse in El Paso. Per PCN P-16-012527, as of the end of August 2015, our current distribution center located in Santa Teresa, New Mexico was divested to Commscope. As a result, TE has established a new Distribution Center in El Paso, TX to support our South-West Customers. In conjunction with the relocation, our new El Paso Distribution Center will be operating on SAP Warehouse Management. The transition will be transparent with the exception of the SAP Packing List. Currently with the use of MOVE in our Santa Teresa DC, Packing Lists can only be printed by carton or by pallet. With the use of SAP Warehouse Management in our El Paso DC, the Packing Lists will be printed by shipment and/or by pallet.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	11-APR-2016
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-104479-0	NO						
1-104479-3	NO						
1-104480-7	NO						
1-1123722-5	NO						
1-1123723-2	NO						
1-1123723-3	NO						
1-160759-1	NO						
1-170823-3	NO						
1-176497-1	NO						
1-324227-0	NO						
1-33220-2	NO						
1-35115-0	NO						
1-480270-0	NO			"1-0480270-0"			
1-480271-0	NO						
1-480283-0	NO						
1-480284-0	NO						
1-480318-0	NO			"A77825-000", "AMP-1-0480318-0"			
1-480319-0	NO						
1-480319-9	NO						
1-480350-0	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-480388-0	NO						
1-480416-0	NO						
1-480416-1	NO						
1-480698-0	NO			"834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341"			
1-480699-0	NO			"402376412", "1-0480699-0", "500-060-1982", "4-27202-1755"			
1-480700-0	NO			"AMPS-1-0480700-0", "F47049-000", "1-0480700-0", "2-42932-9342"			
1-480701-0	NO						
1-480705-0	NO			"1-0480705-0"			
1-480706-0	NO			"873818-000", "AMPS-1-0480706-0", "2-42934-0301"			
1-66105-8	NO						
1-770904-0	NO						
1-770968-1	NO						
1-794606-2	NO						
1-794608-0	NO						
1-794617-2	NO						
1-794617-6	NO						
103653-1	NO			"010-0961-00"			
103653-2	NO			"010-0962-00"			
103653-4	NO						
104257-1	NO						
104257-2	NO			"AMP-0-0104257-2", "C75259-000", "030-0095-00"			
104257-3	NO						
104257-5	NO			"030-0096-00"			
104479-2	NO						
104479-9	NO						
104480-2	NO						
106455-3	NO						
106455-4	NO						
1123721-2	NO						
1217138-1	NO						
1375819-3	NO						
142685-3	NO						
1445049-4	NO						
1445389-3	NO						
154717-3	NO						
154717-7	NO						
154718-3	NO						
154719	NO			"154719-0"			
154719-1	NO			"0-0154719-1"			
1601063-2	NO			"131-129-021"			
1601117-1	NO			"150-003-000"			
1601140-1	NO			"153-001-000"			
1601623-1	NO			"L061D16TB"			
160173-2	NO						
160467-2	NO						
160859-2	NO						
163300-6	NO						
170003-4	NO						
170360-3	NO						
170362-3	NO						
171637-1	NO						
172159-1	NO						
1744144-1	NO						
177898-1	NO						
177914-1	NO						
177915-1	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
177916-1	NO						
2-1601140-1	NO			"153-004-000"			
2-31819-1	NO						
2-31894-2	NO			"405223587"			
2-31895-1	NO						
2-31897-2	NO			"F55945-000", "RAYVOSS-22-16/22-18-R3/8"			
2-320563-2	NO						
2-320568-1	NO			"403802838"			
2-32952-1	NO						
2-33457-2	NO			"401771357"			
2-33458-3	NO						
2-34112-2	NO						
2-34113-2	NO						
2-34123-1	NO			"405109166"			
2-34144-1	NO						
2-34161-1	NO						
2-34162-1	NO						
2-34163-1	NO						
2-34164-2	NO						
2-35109-1	NO			"1140297", "1139542"			
2-36153-2	NO						
2-36160-1	NO						
2-36161-2	NO			"402624795"			
2-794617-4	NO						
201692-4	NO						
2029154002	NO			"1-1191471-8", "RNF-150-1/2-0-SP"			
206036-2	NO						
206037-1	NO			"A33294-000", "AMPS-0-0206037-1"			
206037-2	NO						
206070-8	NO		118408-3				
206150-1	NO						
206151-2	NO						
206322-9	NO						
206708-1	NO						
206966-9	NO						
208652-1	NO						
2132781-3	NO						
2132813-2	NO						
2201778-1	NO						
3-640252-1	NO						
3-640311-1	NO						
3-640401-1	NO						
3-641190-5	NO						
3-770060-1	NO						
3-794121-1	NO						
316086-1	NO						
31818	NO			"768360-000", "AMPS-0-0031818-0"			
320619	NO			"AMPS-0-0320619-0", "C41604-000", "4-00520-1990"			
320764	NO						
321201	NO						
321253	NO						
321576	NO						
324047	NO			"A42815-000", "AMP-0-0324047-0"			
33220	NO						
33460	NO			"CS4742-000", "AMPS-0-0033460-0"			
33465	NO			"AMP-0-0033465-0", "F07864-000"			
3371890001	NO			"7-1192545-8", "ES-CAP-NO.1-C1-0-30MM"			
34070	NO			"268412-000", "AMPS-0-0034070-0"			
34072	NO			"611528-000", "AMPS-0-0034072-0"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
34125	NO			"AMP-0-0034125-0", "F03616-000"			
34130	NO		5M392-1				
34137	NO		5M392-2	"F21569-000", "AMPS-0-0034137-0"			
34138	NO		5M392-3	"CM8395-000", "AMP-0-0034138-0"			
34318	NO		5M392-4	"AMPS-0-0034318-0", "C05587-000"			
350210-1	NO			"407072693"			
350218-1	NO						
350536-1	NO			"403429822"			
350537-3	NO						
350558-1	NO						
350561-1	NO			"0-0350561-1", "CU3085-000", "AMPS-0-0350561-1"			
350570-1	NO						
350767-1	NO			"AMP-0-0350767-1", "F84278-000"			
350778-1	NO			"403738545", "AMPS-0-0350778-1", "E83488-000", "500-020-2698", "500-020-0104"			
350851-1	NO			"0-0350851-1", "2021755", "CU3086-000", "AMPS-0-0350851-1"			
350923-3	NO			"403980899"			
35109	NO			"AMPS-0-0035109-0", "F67095-000"			
35110	NO			"AMPS-0-0035110-0", "E36230-000", "2-14492-3100"			
35669	NO						
36946	NO		5M392-8	"CN3419-000", "AMPS-0-0036946-0"			
36951	NO		5M392-11				
36958	NO						
4-794636-2	NO						
41765	NO						
41770	NO						
42776-1	NO						
4367790003	NO			"1-1193283-5", "ES-CAP-NO.2-B9-0-35MM"			
5053094268	NO			"4-1193845-5", "RNF-100-1/4-BK-SP"			
5053194267	NO			"3-1193862-4", "RNF-100-1/2-BK-SP", "RNF-100-1/2-0"			
5053344102	NO			"4-1193882-5", "RNF-100-1-1/2-BK-SP"			
5058724002	NO			"5-1193906-0", "VERSAFIT-3/16-0-SP"			
5058744001	NO			"1193907-8", "VERSAFIT-1/4-0-SP"			
5070064069	NO			"2-1193963-6", "RNF-100-1/4-CL-SP"			
51863	NO			"4-16211-9784"			
51863-1	NO						
51864-3	NO						
52041	NO						
52943-1	NO			"401771464"			
53128-1	NO						
53831-1	NO						
5510320002	NO			"3-1194355-8", "PD-CAP-1/8-0"			
55785-1	NO			"AMP-0-0055785-1", "D10979-000"			
61085-1	NO						
61117-1	NO			"403631302"			
61118-1	NO			"0-0061118-1"			
61314-1	NO			"403334121", "0-0061314-1", "14629", "1101201"			
61622-1	NO						
62000-2	NO						
62001-1	NO						
62001-2	NO						
62002-2	NO						
62305-2	NO						
62306-2	NO						
62310-2	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
62311-2	NO						
62429-1	NO						
62935-1	NO						
640251-7	NO						
640388-2	NO						
640388-3	NO						
640456-2	NO			"403612641", "2-42934-0583"			
640456-5	NO						
640903-2	NO						
640923-2	NO			"1181513"			
647402-2	NO						
647402-3	NO						
66098-8	NO						
66100-8	NO						
66102-8	NO						
66104-8	NO						
66105-4	NO						
66358-9	NO						
66359-9	NO						
7-1393114-8	NO			"KUHP-11D51-24"			
770007-1	NO						
770008-3	NO						
770476-1	NO						
770476-2	NO						
770579-1	NO			"0-0770579-1"			
770580-1	NO			"0-0770580-1"			
770849-4	NO						
770903-1	NO			"E25278-000", "DUL-PIN-22-18AW-S/M-UMNL"			
770904-1	NO			"2-42939-6041"			
794219-1	NO						
794221-1	NO						
794223-1	NO						
794272-1	NO						
794412-1	NO						
794606-1	NO			"AMPS-0-0794606-1", "F30642-000"			
794616-4	NO						
794616-6	NO						
794617-8	NO						
794758-1	NO						
794781-1	NO						
796075-1	NO						
796286-1	NO						
796288-1	NO						
87631-2	NO						
917686-1	NO						
926291-1	NO						

Customer: Heilind Electronic(1341448)

Location: Markham

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
106455-3	NO						
106455-4	NO						
177915-1	NO						
206070-8	NO		118408-3				
34072	NO			"611528-000", "AMPS-0-0034072-0"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
34318	NO		5M392-4	"AMPS-0-0034318-0", "C05587-000"			
5058724002	NO			"5-1193906-0", "VERSAFIT- 3/16-0-SP"			
5058744001	NO			"1193907-8", "VERSAFIT- 1/4-0-SP"			

Customer: Heilind Electronics Inc(2914593)

Location: Camarillo

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
104257-3	NO						
177915-1	NO						
177916-1	NO						

Customer: Maverick Electronics(155785)

Location: McAllen

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-104479-0	NO						
1-104479-3	NO						
1-480416-1	NO						
1-480698-0	NO			"834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341"			
1-480700-0	NO			"AMPS-1-0480700-0", "F47049-000", "1-0480700-0", "2-42932-9342"			
1-480701-0	NO						
1-480706-0	NO			"873818-000", "AMPS-1-0480706-0", "2-42934-0301"			
1-794606-2	NO						
1-794617-2	NO						
1-794617-6	NO						
103653-1	NO			"010-0961-00"			
103653-2	NO			"010-0962-00"			
103653-4	NO						
104257-1	NO						
104257-2	NO			"AMP-0-0104257-2", "C75259-000", "030-0095-00"			
104257-3	NO						
104257-5	NO			"030-0096-00"			
1445049-4	NO						
170360-3	NO						
170362-3	NO						
171637-1	NO						
172159-1	NO						
2-34161-1	NO						
2-35109-1	NO			"1140297", "1139542"			
2-36161-2	NO			"402624795"			
2-794617-4	NO						
3-770060-1	NO						
34070	NO			"268412-000", "AMPS-0-0034070-0"			
34137	NO		5M392-2	"F21569-000", "AMPS-0-0034137-0"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
350218-1	NO						
350536-1	NO			"403429822"			
350767-1	NO			"AMP-0-0350767-1", "F84278-000"			
350778-1	NO			"403738545", "AMPS-0-0350778-1", "E83488-000", "500-020-2698", "500-020-0104"			
5053194267	NO			"3-1193862-4", "RNF-100-1/2-BK-SP", "RNF-100-1/2-0"			
5058724002	NO			"5-1193906-0", "VERSAFIT-3/16-0-SP"			
5058744001	NO			"1193907-8", "VERSAFIT-1/4-0-SP"			
52943-1	NO			"401771464"			
647402-3	NO						
770580-1	NO			"0-0770580-1"			
770903-1	NO			"E25278-000", "DUL-PIN-22-18AW-S/M-UMNL"			
770904-1	NO			"2-42939-6041"			
794617-8	NO						
794758-1	NO						

Customer: Heilind Electronics(1281082)

Location: Highland Heights

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-104479-0	NO						
1-104479-3	NO						
1-104480-7	NO						
1-1123722-5	NO						
1-1123723-3	NO						
1-160759-1	NO						
1-324227-0	NO						
1-35115-0	NO						
1-480270-0	NO			"1-0480270-0"			
1-480271-0	NO						
1-480283-0	NO						
1-480284-0	NO						
1-480318-0	NO			"A77825-000", "AMP-1-0480318-0"			
1-480319-0	NO						
1-480319-9	NO						
1-480350-0	NO						
1-480388-0	NO						
1-480416-0	NO						
1-480698-0	NO			"834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341"			
1-480699-0	NO			"402376412", "1-0480699-0", "500-060-1982", "4-27202-1755"			
1-480700-0	NO			"AMPS-1-0480700-0", "F47049-000", "1-0480700-0", "2-42932-9342"			
1-480701-0	NO						
1-480705-0	NO			"1-0480705-0"			
1-480706-0	NO			"873818-000", "AMPS-1-0480706-0", "2-42934-0301"			
1-66105-8	NO						
1-770904-0	NO						
1-770968-1	NO						
1-794606-2	NO						
1-794608-0	NO						
1-794617-2	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-794617-6	NO						
103653-1	NO			"010-0961-00"			
103653-2	NO			"010-0962-00"			
103653-4	NO						
104257-1	NO						
104257-2	NO			"AMP-0-0104257-2", "C75259-000", "030-0095-00"			
104257-3	NO						
104257-5	NO			"030-0096-00"			
104479-9	NO						
104480-2	NO						
106455-3	NO						
1123721-2	NO						
1217138-1	NO						
1375819-3	NO						
142685-3	NO						
1445049-4	NO						
1445389-3	NO						
154718-3	NO						
154719	NO			"154719-0"			
154719-1	NO			"0-0154719-1"			
1601117-1	NO			"150-003-000"			
1601140-1	NO			"153-001-000"			
1601623-1	NO			"L061D16TB"			
170003-4	NO						
170360-3	NO						
170362-3	NO						
171637-1	NO						
172159-1	NO						
1744144-1	NO						
177898-1	NO						
177915-1	NO						
177916-1	NO						
2-1601140-1	NO			"153-004-000"			
2-31819-1	NO						
2-31894-2	NO			"405223587"			
2-31895-1	NO						
2-31897-2	NO			"F55945-000", "RAYVOSS-22-16/22-18-R3/8"			
2-320563-2	NO						
2-320568-1	NO			"403802838"			
2-32952-1	NO						
2-33457-2	NO			"401771357"			
2-33458-3	NO						
2-34112-2	NO						
2-34113-2	NO						
2-34123-1	NO			"405109166"			
2-34144-1	NO						
2-34161-1	NO						
2-34162-1	NO						
2-34163-1	NO						
2-34164-2	NO						
2-35109-1	NO			"1140297", "1139542"			
2-36153-2	NO						
2-36160-1	NO						
2-36161-2	NO			"402624795"			
2-794617-4	NO						
201692-4	NO						
206036-2	NO						
206037-1	NO			"A33294-000", "AMPS-0-0206037-1"			
206037-2	NO						
206070-8	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
206150-1	NO						
206151-2	NO						
206322-9	NO						
206708-1	NO						
206966-9	NO						
2132781-3	NO						
2132813-2	NO						
3-640252-1	NO						
3-640311-1	NO						
3-640401-1	NO						
3-641190-5	NO						
3-770060-1	NO						
3-794121-1	NO						
31818	NO			"768360-000", "AMPS-0-0031818-0"			
320619	NO			"AMPS-0-0320619-0", "C41604-000", "4-00520-1990"			
320764	NO						
321253	NO						
324047	NO			"A42815-000", "AMP-0-0324047-0"			
33220	NO						
33460	NO			"CS4742-000", "AMPS-0-0033460-0"			
33465	NO			"AMP-0-0033465-0", "F07864-000"			
34070	NO			"268412-000", "AMPS-0-0034070-0"			
34072	NO			"611528-000", "AMPS-0-0034072-0"			
34125	NO			"AMP-0-0034125-0", "F03616-000"			
34130	NO						
34137	NO			"F21569-000", "AMPS-0-0034137-0"			
34138	NO			"CM8395-000", "AMP-0-0034138-0"			
34318	NO			"AMPS-0-0034318-0", "C05587-000"			
350210-1	NO			"407072693"			
350218-1	NO						
350536-1	NO			"403429822"			
350537-3	NO						
350558-1	NO						
350561-1	NO			"0-0350561-1", "CU3085-000", "AMPS-0-0350561-1"			
350570-1	NO						
350767-1	NO			"AMP-0-0350767-1", "F84278-000"			
350778-1	NO			"403738545", "AMPS-0-0350778-1", "E83488-000", "500-020-2698", "500-020-0104"			
350851-1	NO			"0-0350851-1", "2021755", "CU3086-000", "AMPS-0-0350851-1"			
350923-3	NO			"403980899"			
35109	NO			"AMPS-0-0035109-0", "F67095-000"			
35110	NO			"AMPS-0-0035110-0", "E36230-000", "2-14492-3100"			
35669	NO						
36946	NO			"CN3419-000", "AMPS-0-0036946-0"			
36951	NO						
36958	NO						
41770	NO						
4367790003	NO			"1-1193283-5", "ES-CAP-NO.2-B9-0-35MM"			
5053094268	NO			"4-1193845-5", "RNF-100-1/4-BK-SP"			
5053344102	NO			"4-1193882-5", "RNF-100-1-1/2-BK-SP"			
5058724002	NO			"5-1193906-0", "VERSAFIT-3/16-0-SP"			
5058744001	NO			"1193907-8", "VERSAFIT-1/4-0-SP"			
5070064069	NO			"2-1193963-6", "RNF-100-1/4-CL-SP"			
51863	NO			"4-16211-9784"			
51863-1	NO						
51864-3	NO						
52943-1	NO			"401771464"			
5510320002	NO			"3-1194355-8", "PD-CAP-1/8-0"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
55785-1	NO			"AMP-0-0055785-1", "D10979-000"			
61085-1	NO						
61117-1	NO			"403631302"			
61118-1	NO			"0-0061118-1"			
61314-1	NO			"403334121", "0-0061314-1", "14629", "1101201"			
61622-1	NO						
62305-2	NO						
62310-2	NO						
62311-2	NO						
640251-7	NO						
640388-2	NO						
640388-3	NO						
640456-2	NO			"403612641", "2-42934-0583"			
640456-5	NO						
640903-2	NO						
640923-2	NO			"1181513"			
647402-2	NO						
647402-3	NO						
66098-8	NO						
66100-8	NO						
66102-8	NO						
66104-8	NO						
66358-9	NO						
66359-9	NO						
770007-1	NO						
770008-3	NO						
770476-1	NO						
770476-2	NO						
770579-1	NO			"0-0770579-1"			
770580-1	NO			"0-0770580-1"			
770849-4	NO						
770903-1	NO			"E25278-000", "DUL-PIN-22-18AW-S/M-UMNL"			
770904-1	NO			"2-42939-6041"			
794219-1	NO						
794221-1	NO						
794223-1	NO						
794272-1	NO						
794412-1	NO						
794606-1	NO			"AMPS-0-0794606-1", "F30642-000"			
794616-4	NO						
794616-6	NO						
794617-8	NO						
794758-1	NO						
794781-1	NO						
87631-2	NO						

Customer: Heilind Electronics(264685)

Location: Hudson

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-104480-7	NO						
104479-9	NO						
2-34161-1	NO						
2-36153-2	NO						
5058724002	NO			"5-1193906-0", "VERSAFIT-3/16-0-SP"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5058744001	NO			"1193907-8", "VERSAFIT-1/4-0-SP"			
66098-8	NO						
66102-8	NO						
66104-8	NO						
66358-9	NO						
770904-1	NO			"2-42939-6041"			

Customer: Heilind Asia Pacific (Hong Kong)(2991513)

Location: Hong Kong

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-104479-0	NO						
1-104480-7	NO						
1-160759-1	NO						
1-480270-0	NO			"1-0480270-0"			
1-480318-0	NO			"A77825-000", "AMP-1-0480318-0"			
1-480319-0	NO						
1-480350-0	NO						
1-480416-0	NO						
1-480698-0	NO			"834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341"			
1-480700-0	NO			"AMPS-1-0480700-0", "F47049-000", "1-0480700-0", "2-42932-9342"			
1-480701-0	NO						
1-480705-0	NO			"1-0480705-0"			
1-480706-0	NO			"873818-000", "AMPS-1-0480706-0", "2-42934-0301"			
1-770904-0	NO						
1-770968-1	NO						
1-794606-2	NO						
1-794608-0	NO						
1-794617-2	NO						
1-794617-6	NO						
103653-1	NO			"010-0961-00"			
103653-2	NO			"010-0962-00"			
103653-4	NO						
104257-1	NO						
104257-2	NO			"AMP-0-0104257-2", "C75259-000", "030-0095-00"			
104257-3	NO						
104257-5	NO			"030-0096-00"			
104479-9	NO						
104480-2	NO						
1375819-3	NO						
154717-7	NO						
154719-1	NO			"0-0154719-1"			
160173-2	NO						
163300-6	NO						
170360-3	NO						
170362-3	NO						
171637-1	NO						
172159-1	NO						
2-36160-1	NO						
206036-2	NO						
206037-1	NO			"A33294-000", "AMPS-0-0206037-1"			
206037-2	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
206070-8	NO						
206322-9	NO						
206708-1	NO						
3-640252-1	NO						
3-640311-1	NO						
3-640401-1	NO						
3-770060-1	NO						
320619	NO			"AMPS-0-0320619-0", "C41604-000", "4-00520-1990"			
321253	NO						
321576	NO						
324047	NO			"A42815-000", "AMP-0-0324047-0"			
33460	NO			"CS4742-000", "AMPS-0-0033460-0"			
33465	NO			"AMP-0-0033465-0", "F07864-000"			
34138	NO			"CM8395-000", "AMP-0-0034138-0"			
350210-1	NO			"407072693"			
350218-1	NO						
350536-1	NO			"403429822"			
350558-1	NO						
350561-1	NO			"0-0350561-1", "CU3085-000", "AMPS-0-0350561-1"			
350570-1	NO						
350767-1	NO			"AMP-0-0350767-1", "F84278-000"			
350778-1	NO			"403738545", "AMPS-0-0350778-1", "E83488-000", "500-020-2698", "500-020-0104"			
350851-1	NO			"0-0350851-1", "2021755", "CU3086-000", "AMPS-0-0350851-1"			
350923-3	NO			"403980899"			
35109	NO			"AMPS-0-0035109-0", "F67095-000"			
35110	NO			"AMPS-0-0035110-0", "E36230-000", "2-14492-3100"			
5053094268	NO			"4-1193845-5", "RNF-100-1/4-BK-SP"			
5058724002	NO			"5-1193906-0", "VERSAFIT-3/16-0-SP"			
5058744001	NO			"1193907-8", "VERSAFIT-1/4-0-SP"			
51863	NO			"4-16211-9784"			
51864-3	NO						
61117-1	NO			"403631302"			
61118-1	NO			"0-0061118-1"			
61314-1	NO			"403334121", "0-0061314-1", "14629", "1101201"			
640456-5	NO						
66098-8	NO						
66100-8	NO						
66102-8	NO						
66104-8	NO						
66358-9	NO						
66359-9	NO						
770007-1	NO						
770008-3	NO						
770476-2	NO						
770579-1	NO			"0-0770579-1"			
770580-1	NO			"0-0770580-1"			
770849-4	NO						
770903-1	NO			"E25278-000", "DUL-PIN-22-18AW-S/M-UMNL"			
770904-1	NO			"2-42939-6041"			
794219-1	NO						
794221-1	NO						
794223-1	NO						
794606-1	NO			"AMPS-0-0794606-1", "F30642-000"			
794617-8	NO						
794758-1	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
796075-1	NO						
926291-1	NO						

Customer: Heilind Electronics(206835)

Location: Highland Heights

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5058724002	NO			"5-1193906-0", "VERSAFIT-3/16-0-SP"			

Customer: Heilind Electronics(2873183)

Location: Hudson

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-104479-0	NO						
1-104480-7	NO						
1-480318-0	NO			"A77825-000", "AMP-1-0480318-0"			
1-480319-0	NO						
1-480698-0	NO			"834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341"			
1-480699-0	NO			"402376412", "1-0480699-0", "500-060-1982", "4-27202-1755"			
1-480700-0	NO			"AMPS-1-0480700-0", "F47049-000", "1-0480700-0", "2-42932-9342"			
1-480701-0	NO						
1-480706-0	NO			"873818-000", "AMPS-1-0480706-0", "2-42934-0301"			
1-770904-0	NO						
1-794606-2	NO						
1-794608-0	NO						
104257-2	NO			"AMP-0-0104257-2", "C75259-000", "030-0095-00"			
104479-9	NO						
104480-2	NO						
1123721-2	NO						
1375819-3	NO						
170360-3	NO						
170362-3	NO						
171637-1	NO						
172159-1	NO						
2-31894-2	NO			"405223587"			
2-320568-1	NO			"403802838"			
2-33457-2	NO			"401771357"			
2-34144-1	NO						
2-34161-1	NO						
2-36153-2	NO						
2-36160-1	NO						
2-36161-2	NO			"402624795"			
3-640252-1	NO						
3-640311-1	NO						
3-770060-1	NO						
350218-1	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
350536-1	NO			"403429822"			
350537-3	NO						
350558-1	NO						
350561-1	NO			"0-0350561-1", "CU3085-000", "AMPS-0-0350561-1"			
350570-1	NO						
350767-1	NO			"AMP-0-0350767-1", "F84278-000"			
350851-1	NO			"0-0350851-1", "2021755", "CU3086-000", "AMPS-0-0350851-1"			
350923-3	NO			"403980899"			
5053194267	NO			"3-1193862-4", "RNF-100-1/2-BK-SP", "RNF-100-1/2-0"			
5053344102	NO			"4-1193882-5", "RNF-100-1-1/2-BK-SP"			
5058724002	NO			"5-1193906-0", "VERSAFIT-3/16-0-SP"			
5058744001	NO			"1193907-8", "VERSAFIT-1/4-0-SP"			
61117-1	NO			"403631302"			
61118-1	NO			"0-0061118-1"			
61314-1	NO			"403334121", "0-0061314-1", "14629", "1101201"			
640251-7	NO						
640456-5	NO						
640903-2	NO						
640923-2	NO			"1181513"			
66098-8	NO						
66100-8	NO						
66102-8	NO						
66104-8	NO						
66358-9	NO						
66359-9	NO						
770007-1	NO						
770008-3	NO						
770476-1	NO						
770476-2	NO						
770849-4	NO						
770903-1	NO			"E25278-000", "DUL-PIN-22-18AWS/M-UMNL"			
770904-1	NO			"2-42939-6041"			
794219-1	NO						
794223-1	NO						
794606-1	NO			"AMPS-0-0794606-1", "F30642-000"			
794617-8	NO						

Customer: Heilind Asia Pacific (Hong Kong)(2980376)

Location: Hong Kong

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-104479-0	NO						
1-104480-7	NO						
1-1123723-2	NO						
1-160759-1	NO						
1-480270-0	NO			"1-0480270-0"			
1-480318-0	NO			"A77825-000", "AMP-1-0480318-0"			
1-480319-0	NO						
1-480350-0	NO						
1-480416-0	NO						
1-480698-0	NO			"834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-480700-0	NO			"AMPS-1-0480700-0", "F47049-000", "1-0480700-0", "2-42932-9342"			
1-480701-0	NO						
1-480705-0	NO			"1-0480705-0"			
1-480706-0	NO			"873818-000", "AMPS-1-0480706-0", "2-42934-0301"			
1-770904-0	NO						
1-770968-1	NO						
1-794606-2	NO						
1-794608-0	NO						
1-794617-2	NO						
1-794617-6	NO						
103653-1	NO			"010-0961-00"			
103653-2	NO			"010-0962-00"			
103653-4	NO						
104257-1	NO						
104257-2	NO			"AMP-0-0104257-2", "C75259-000", "030-0095-00"			
104257-3	NO						
104257-5	NO			"030-0096-00"			
104479-9	NO						
104480-2	NO						
1375819-3	NO						
154717-7	NO						
154719-1	NO			"0-0154719-1"			
160173-2	NO						
163300-6	NO						
170360-3	NO						
170362-3	NO						
171637-1	NO						
172159-1	NO						
2-36160-1	NO						
206036-2	NO						
206037-1	NO			"A33294-000", "AMPS-0-0206037-1"			
206037-2	NO						
206070-8	NO		118408-3				
206322-9	NO						
206708-1	NO						
3-640252-1	NO						
3-640311-1	NO						
3-640401-1	NO						
3-770060-1	NO						
320619	NO			"AMPS-0-0320619-0", "C41604-000", "4-00520-1990"			
321253	NO						
321576	NO						
324047	NO			"A42815-000", "AMP-0-0324047-0"			
33460	NO			"CS4742-000", "AMPS-0-0033460-0"			
33465	NO			"AMP-0-0033465-0", "F07864-000"			
34138	NO		5M392-3	"CM8395-000", "AMP-0-0034138-0"			
350210-1	NO			"407072693"			
350218-1	NO						
350536-1	NO			"403429822"			
350558-1	NO						
350561-1	NO			"0-0350561-1", "CU3085-000", "AMPS-0-0350561-1"			
350570-1	NO						
350767-1	NO			"AMP-0-0350767-1", "F84278-000"			
350778-1	NO			"403738545", "AMPS-0-0350778-1", "E83488-000", "500-020-2698", "500-020-0104"			
350851-1	NO			"0-0350851-1", "2021755", "CU3086-000", "AMPS-0-0350851-1"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
350923-3	NO			"403980899"			
35109	NO			"AMPS-0-0035109-0", "F67095-000"			
35110	NO			"AMPS-0-0035110-0", "E36230-000", "2-14492-3100"			
5053094268	NO			"4-1193845-5", "RNF-100-1/4-BK-SP"			
5058724002	NO			"5-1193906-0", "VERSAFIT-3/16-0-SP"			
5058744001	NO			"1193907-8", "VERSAFIT-1/4-0-SP"			
51863	NO			"4-16211-9784"			
51863-1	NO						
51864-3	NO						
61117-1	NO			"403631302"			
61118-1	NO			"0-0061118-1"			
61314-1	NO			"403334121", "0-0061314-1", "14629", "1101201"			
640456-5	NO						
66098-8	NO						
66100-8	NO						
66102-8	NO						
66104-8	NO						
66358-9	NO						
66359-9	NO						
770007-1	NO						
770008-3	NO						
770476-2	NO						
770579-1	NO			"0-0770579-1"			
770580-1	NO			"0-0770580-1"			
770849-4	NO						
770903-1	NO			"E25278-000", "DUL-PIN-22-18AW-S/M-UMNL"			
770904-1	NO			"2-42939-6041"			
794219-1	NO						
794221-1	NO						
794223-1	NO						
794606-1	NO			"AMPS-0-0794606-1", "F30642-000"			
794617-8	NO						
794758-1	NO						
796075-1	NO						
926291-1	NO						

Customer: Heilind Asia Pacific (SG) Pte Ltd(2980456)

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-170823-3	NO						
1-480270-0	NO			"1-0480270-0"			
1-480416-0	NO						
1-480698-0	NO			"834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341"			
1-480700-0	NO			"AMPS-1-0480700-0", "F47049-000", "1-0480700-0", "2-42932-9342"			
1-794606-2	NO						
104257-2	NO			"AMP-0-0104257-2", "C75259-000", "030-0095-00"			
104257-5	NO			"030-0096-00"			
1375819-3	NO						
154717-7	NO						
170360-3	NO						
171637-1	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
177914-1	NO						
206037-1	NO			"A33294-000", "AMPS-0-0206037-1"			
206070-8	NO		118408-3				
206322-9	NO						
2201778-1	NO						
3-640252-1	NO						
3-770060-1	NO						
321253	NO						
350218-1	NO						
350561-1	NO			"0-0350561-1", "CU3085-000", "AMPS-0-0350561-1"			
350767-1	NO			"AMP-0-0350767-1", "F84278-000"			
350778-1	NO			"403738545", "AMPS-0-0350778-1", "E83488-000", "500-020-2698", "500-020-0104"			
350851-1	NO			"0-0350851-1", "2021755", "CU3086-000", "AMPS-0-0350851-1"			
35110	NO			"AMPS-0-0035110-0", "E36230-000", "2-14492-3100"			
4-794636-2	NO						
51863	NO			"4-16211-9784"			
61117-1	NO			"403631302"			
61314-1	NO			"403334121", "0-0061314-1", "14629", "1101201"			
640456-2	NO			"403612641", "2-42934-0583"			
66102-8	NO						
770008-3	NO						
770579-1	NO			"0-0770579-1"			
794272-1	NO						
794606-1	NO			"AMPS-0-0794606-1", "F30642-000"			
926291-1	NO						

Customer: Heilind Asia Pacific (HK) Ltd(3087523)

Location: Dongguan

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-794606-2	NO						
3-794121-1	NO						
796075-1	NO						

Customer: Heilind Electronics(1276409)

Location: Plano

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-480699-0	NO			"402376412", "1-0480699-0", "500-060-1982", "4-27202-1755"			
1-480700-0	NO			"AMPS-1-0480700-0", "F47049-000", "1-0480700-0", "2-42932-9342"			
1-480701-0	NO						
177915-1	NO						
2-33457-2	NO			"401771357"			
2-33458-3	NO						
2-34161-1	NO						
2-34162-1	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2-34164-2	NO						
2-35109-1	NO			"1140297", "1139542"			
316086-1	NO						
350218-1	NO						
350536-1	NO			"403429822"			
350767-1	NO			"AMP-0-0350767-1", "F84278-000"			
770007-1	NO						
794616-6	NO						

Customer: Heilind Electronics Inc(2914597)

Location: Brookfield

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1445389-3	NO						
34070	NO			"268412-000", "AMPS-0-0034070-0"			
794781-1	NO						

Customer: Heilind Electronics(2932930)

Location: McAllen

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-794617-6	NO						
350778-1	NO			"403738545", "AMPS-0-0350778-1", "E83488-000", "500-020-2698", "500-020-0104"			
61118-1	NO			"0-0061118-1"			

Customer: Kotek Eletro Eletronica Ltda(2786372)

Location: Sao Paulo

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
160467-2	NO						
170362-3	NO						
172159-1	NO						
177914-1	NO						
177915-1	NO						
2-36160-1	NO						
206037-2	NO						
61118-1	NO			"0-0061118-1"			
770476-1	NO						
794272-1	NO						

Customer: Heilind Electronics Inc(2914594)

Location: San Jose

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2-35109-1	NO			"1140297", "1139542"			

Customer: Heilind Asia Pacific (SG) Pte Ltd(2980456)

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-170823-3	NO						
1-480270-0	NO			"1-0480270-0"			
1-480416-0	NO						
1-480698-0	NO			"834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341"			
1-480700-0	NO			"AMPS-1-0480700-0", "F47049-000", "1-0480700-0", "2-42932-9342"			
1-794606-2	NO						
104257-2	NO			"AMP-0-0104257-2", "C75259-000", "030-0095-00"			
104257-5	NO			"030-0096-00"			
1375819-3	NO						
154717-7	NO						
170360-3	NO						
171637-1	NO						
177914-1	NO						
206037-1	NO			"A33294-000", "AMPS-0-0206037-1"			
206070-8	NO		118408-3				
206322-9	NO						
2201778-1	NO						
3-640252-1	NO						
3-770060-1	NO						
321253	NO						
350218-1	NO						
350561-1	NO			"0-0350561-1", "CU3085-000", "AMPS- 0-0350561-1"			
350767-1	NO			"AMP-0-0350767-1", "F84278-000"			
350778-1	NO			"403738545", "AMPS-0-0350778-1", "E83488-000", "500-020-2698", "500-020-0104"			
350851-1	NO			"0-0350851-1", "2021755", "CU3086-000", "AMPS-0-0350851-1"			
35110	NO			"AMPS-0-0035110-0", "E36230-000", "2-14492-3100"			
4-794636-2	NO						
51863	NO			"4-16211-9784"			
61117-1	NO			"403631302"			
61314-1	NO			"403334121", "0-0061314-1", "14629", "1101201"			
640456-2	NO			"403612641", "2-42934-0583"			
66102-8	NO						
770008-3	NO						
770579-1	NO			"0-0770579-1"			
794272-1	NO						
794606-1	NO			"AMPS-0-0794606-1", "F30642-000"			
926291-1	NO						

Customer: Heilind Asia Pacific (SG) Pte Ltd(2980456)

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-170823-3	NO						
1-480270-0	NO			"1-0480270-0"			
1-480416-0	NO						
1-480698-0	NO			"834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341"			
1-480700-0	NO			"AMPS-1-0480700-0", "F47049-000", "1-0480700-0", "2-42932-9342"			
1-794606-2	NO						
104257-2	NO			"AMP-0-0104257-2", "C75259-000", "030-0095-00"			
104257-5	NO			"030-0096-00"			
1375819-3	NO						
154717-7	NO						
170360-3	NO						
171637-1	NO						
177914-1	NO						
206037-1	NO			"A33294-000", "AMPS-0-0206037-1"			
206070-8	NO		118408-3				
206322-9	NO						
2201778-1	NO						
3-640252-1	NO						
3-770060-1	NO						
321253	NO						
350218-1	NO						
350561-1	NO			"0-0350561-1", "CU3085-000", "AMPS- 0-0350561-1"			
350767-1	NO			"AMP-0-0350767-1", "F84278-000"			
350778-1	NO			"403738545", "AMPS-0-0350778-1", "E83488-000", "500-020-2698", "500-020-0104"			
350851-1	NO			"0-0350851-1", "2021755", "CU3086-000", "AMPS-0-0350851-1"			
35110	NO			"AMPS-0-0035110-0", "E36230-000", "2-14492-3100"			
4-794636-2	NO						
51863	NO			"4-16211-9784"			
61117-1	NO			"403631302"			
61314-1	NO			"403334121", "0-0061314-1", "14629", "1101201"			
640456-2	NO			"403612641", "2-42934-0583"			
66102-8	NO						
770008-3	NO						
770579-1	NO			"0-0770579-1"			
794272-1	NO						
794606-1	NO			"AMPS-0-0794606-1", "F30642-000"			
926291-1	NO						

Customer: Heilind Asia Pacific (SG) Pte Ltd(3076161)

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-480698-0	NO			"834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341"			
1-480700-0	NO			"AMPS-1-0480700-0", "F47049-000", "1-0480700-0", "2-42932-9342"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
170360-3	NO						
171637-1	NO						
206037-1	NO			"A33294-000", "AMPS-0-0206037-1"			
350561-1	NO			"0-0350561-1", "CU3085-000", "AMPS-0-0350561-1"			
794272-1	NO						

Customer: Heilind Electronics(1275266)

Location: Visalia

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-104479-3	NO						
1-104480-7	NO						
1-160759-1	NO						
1-176497-1	NO						
1-33220-2	NO						
1-35115-0	NO						
1-480270-0	NO			"1-0480270-0"			
1-480283-0	NO						
1-480318-0	NO			"A77825-000", "AMP-1-0480318-0"			
1-480319-0	NO						
1-480319-9	NO						
1-480350-0	NO						
1-480416-1	NO						
1-480698-0	NO			"834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341"			
1-480699-0	NO			"402376412", "1-0480699-0", "500-060-1982", "4-27202-1755"			
1-480700-0	NO			"AMPS-1-0480700-0", "F47049-000", "1-0480700-0", "2-42932-9342"			
1-480701-0	NO						
1-480705-0	NO			"1-0480705-0"			
1-480706-0	NO			"873818-000", "AMPS-1-0480706-0", "2-42934-0301"			
1-770904-0	NO						
1-794606-2	NO						
1-794608-0	NO						
1-794617-2	NO						
1-794617-6	NO						
103653-1	NO			"010-0961-00"			
103653-2	NO			"010-0962-00"			
103653-4	NO						
104257-1	NO						
104257-2	NO			"AMP-0-0104257-2", "C75259-000", "030-0095-00"			
104257-3	NO						
104257-5	NO			"030-0096-00"			
104479-2	NO						
104479-9	NO						
106455-4	NO						
1123721-2	NO						
1375819-3	NO						
142685-3	NO						
1445049-4	NO						
1445389-3	NO						
154717-3	NO						
154718-3	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
154719	NO			"154719-0"			
154719-1	NO			"0-0154719-1"			
1601063-2	NO			"131-129-021"			
171637-1	NO						
172159-1	NO						
177898-1	NO						
177914-1	NO						
177915-1	NO						
2-31895-1	NO						
2-320563-2	NO						
2-320568-1	NO			"403802838"			
2-32952-1	NO						
2-33457-2	NO			"401771357"			
2-33458-3	NO						
2-34112-2	NO						
2-34113-2	NO						
2-34123-1	NO			"405109166"			
2-34144-1	NO						
2-34161-1	NO						
2-34162-1	NO						
2-34164-2	NO						
2-35109-1	NO			"1140297", "1139542"			
2-36153-2	NO						
2-36160-1	NO						
2-36161-2	NO			"402624795"			
2-794617-4	NO						
201692-4	NO						
2029154002	NO			"1-1191471-8", "RNF-150-1/2-0-SP"			
206036-2	NO						
206037-1	NO			"A33294-000", "AMPS-0-0206037-1"			
206037-2	NO						
206070-8	NO						
206150-1	NO						
206151-2	NO						
206322-9	NO						
206708-1	NO						
208652-1	NO						
3-640252-1	NO						
3-640311-1	NO						
3-770060-1	NO						
3-794121-1	NO						
316086-1	NO						
31818	NO			"768360-000", "AMPS-0-0031818-0"			
320619	NO			"AMPS-0-0320619-0", "C41604-000", "4-00520-1990"			
321253	NO						
321576	NO						
33460	NO			"CS4742-000", "AMPS-0-0033460-0"			
33465	NO			"AMP-0-0033465-0", "F07864-000"			
34130	NO						
34137	NO			"F21569-000", "AMPS-0-0034137-0"			
34138	NO			"CM8395-000", "AMP-0-0034138-0"			
34318	NO			"AMPS-0-0034318-0", "C05587-000"			
350218-1	NO						
350536-1	NO			"403429822"			
350537-3	NO						
350561-1	NO			"0-0350561-1", "CU3085-000", "AMPS-0-0350561-1"			
350570-1	NO						
350851-1	NO			"0-0350851-1", "2021755", "CU3086-000", "AMPS-0-0350851-1"			
350923-3	NO			"403980899"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
35109	NO			"AMPS-0-0035109-0", "F67095-000"			
35110	NO			"AMPS-0-0035110-0", "E36230-000", "2-14492-3100"			
36946	NO			"CN3419-000", "AMPS-0-0036946-0"			
41765	NO						
42776-1	NO						
5053094268	NO			"4-1193845-5", "RNF-100-1/4-BK-SP"			
5053194267	NO			"3-1193862-4", "RNF-100-1/2-BK-SP", "RNF-100-1/2-0"			
5053344102	NO			"4-1193882-5", "RNF-100-1-1/2-BK-SP"			
5058724002	NO			"5-1193906-0", "VERSAFIT-3/16-0-SP"			
5058744001	NO			"1193907-8", "VERSAFIT-1/4-0-SP"			
5070064069	NO			"2-1193963-6", "RNF-100-1/4-CL-SP"			
51863	NO			"4-16211-9784"			
51863-1	NO						
52041	NO						
53128-1	NO						
53831-1	NO						
5510320002	NO			"3-1194355-8", "PD-CAP-1/8-0"			
61085-1	NO						
61117-1	NO			"403631302"			
61118-1	NO			"0-0061118-1"			
61314-1	NO			"403334121", "0-0061314-1", "14629", "1101201"			
62000-2	NO						
62001-1	NO						
62001-2	NO						
62002-2	NO						
62306-2	NO						
62311-2	NO						
62429-1	NO						
62935-1	NO						
640388-2	NO						
640456-2	NO			"403612641", "2-42934-0583"			
640456-5	NO						
640903-2	NO						
66098-8	NO						
66100-8	NO						
66102-8	NO						
66104-8	NO						
7-1393114-8	NO			"KUHP-11D51-24"			
770007-1	NO						
770008-3	NO						
770476-2	NO						
770579-1	NO			"0-0770579-1"			
770580-1	NO			"0-0770580-1"			
770849-4	NO						
770903-1	NO			"E25278-000", "DUL-PIN-22-18AWS/M-UMNL"			
770904-1	NO			"2-42939-6041"			
794412-1	NO						
794606-1	NO			"AMPS-0-0794606-1", "F30642-000"			
794616-4	NO						
794616-6	NO						
794617-8	NO						
794758-1	NO						
796075-1	NO						
796286-1	NO						
87631-2	NO						
917686-1	NO						

Customer: Heilind Electronics(167811)

Location: Wilmington

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-104479-0	NO						
1-104479-3	NO						
1-104480-7	NO						
1-1123722-5	NO						
1-1123723-3	NO						
1-160759-1	NO						
1-176497-1	NO						
1-324227-0	NO						
1-33220-2	NO						
1-35115-0	NO						
1-480270-0	NO			"1-0480270-0"			
1-480271-0	NO						
1-480283-0	NO						
1-480284-0	NO						
1-480318-0	NO			"A77825-000", "AMP-1-0480318-0"			
1-480319-0	NO						
1-480319-9	NO						
1-480350-0	NO						
1-480388-0	NO						
1-480416-0	NO						
1-480416-1	NO						
1-480698-0	NO			"834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341"			
1-480699-0	NO			"402376412", "1-0480699-0", "500-060-1982", "4-27202-1755"			
1-480700-0	NO			"AMPS-1-0480700-0", "F47049-000", "1-0480700-0", "2-42932-9342"			
1-480701-0	NO						
1-480705-0	NO			"1-0480705-0"			
1-480706-0	NO			"873818-000", "AMPS-1-0480706-0", "2-42934-0301"			
1-66105-8	NO						
1-770904-0	NO						
1-770968-1	NO						
1-794606-2	NO						
1-794608-0	NO						
1-794617-2	NO						
1-794617-6	NO						
103653-1	NO			"010-0961-00"			
103653-2	NO			"010-0962-00"			
103653-4	NO						
104257-1	NO						
104257-2	NO			"AMP-0-0104257-2", "C75259-000", "030-0095-00"			
104257-3	NO						
104257-5	NO			"030-0096-00"			
104479-2	NO						
104479-9	NO						
104480-2	NO						
106455-3	NO						
106455-4	NO						
1123721-2	NO						
1217138-1	NO						
1375819-3	NO						
142685-3	NO						
1445049-4	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1445389-3	NO						
154717-3	NO						
154718-3	NO						
154719	NO			"154719-0"			
154719-1	NO			"0-0154719-1"			
1601063-2	NO			"131-129-021"			
1601117-1	NO			"150-003-000"			
1601140-1	NO			"153-001-000"			
1601623-1	NO			"L061D16TB"			
160859-2	NO						
163306-2	NO						
170003-4	NO						
170360-3	NO						
170362-3	NO						
171637-1	NO						
172159-1	NO						
1744144-1	NO						
177898-1	NO						
177914-1	NO						
177915-1	NO						
177916-1	NO						
2-1601140-1	NO			"153-004-000"			
2-31819-1	NO						
2-31894-2	NO			"405223587"			
2-31895-1	NO						
2-31897-2	NO			"F55945-000", "RAYVOSS-22-16/22-18-R3/8"			
2-320563-2	NO						
2-320568-1	NO			"403802838"			
2-32952-1	NO						
2-33457-2	NO			"401771357"			
2-33458-3	NO						
2-34112-2	NO						
2-34113-2	NO						
2-34123-1	NO			"405109166"			
2-34144-1	NO						
2-34161-1	NO						
2-34162-1	NO						
2-34163-1	NO						
2-34164-2	NO						
2-35109-1	NO			"1140297", "1139542"			
2-36153-2	NO						
2-36160-1	NO						
2-36161-2	NO			"402624795"			
2-794617-4	NO						
201692-4	NO						
2029154002	NO			"1-1191471-8", "RNF-150-1/2-0-SP"			
206036-2	NO						
206037-1	NO			"A33294-000", "AMPS-0-0206037-1"			
206037-2	NO						
206070-8	NO		118408-3				
206150-1	NO						
206151-2	NO						
206322-9	NO						
206708-1	NO						
206966-9	NO						
208652-1	NO						
2132781-3	NO						
2132813-2	NO						
3-640252-1	NO						
3-640311-1	NO						
3-640401-1	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
3-641190-5	NO						
3-770060-1	NO						
3-794121-1	NO						
316086-1	NO						
31818	NO			"768360-000", "AMPS-0-0031818-0"			
320619	NO			"AMPS-0-0320619-0", "C41604-000", "4-00520-1990"			
320764	NO						
321201	NO						
321253	NO						
321576	NO						
324047	NO			"A42815-000", "AMP-0-0324047-0"			
33220	NO						
33460	NO			"CS4742-000", "AMPS-0-0033460-0"			
33465	NO			"AMP-0-0033465-0", "F07864-000"			
34070	NO			"268412-000", "AMPS-0-0034070-0"			
34072	NO			"611528-000", "AMPS-0-0034072-0"			
34125	NO			"AMP-0-0034125-0", "F03616-000"			
34130	NO		5M392-1				
34137	NO		5M392-2	"F21569-000", "AMPS-0-0034137-0"			
34138	NO		5M392-3	"CM8395-000", "AMP-0-0034138-0"			
34318	NO		5M392-4	"AMPS-0-0034318-0", "C05587-000"			
350210-1	NO			"407072693"			
350218-1	NO						
350390-2	NO						
350536-1	NO			"403429822"			
350537-3	NO						
350558-1	NO						
350561-1	NO			"0-0350561-1", "CU3085-000", "AMPS-0-0350561-1"			
350570-1	NO						
350767-1	NO			"AMP-0-0350767-1", "F84278-000"			
350778-1	NO			"403738545", "AMPS-0-0350778-1", "E83488-000", "500-020-2698", "500-020-0104"			
350851-1	NO			"0-0350851-1", "2021755", "CU3086-000", "AMPS-0-0350851-1"			
350923-3	NO			"403980899"			
35109	NO			"AMPS-0-0035109-0", "F67095-000"			
35110	NO			"AMPS-0-0035110-0", "E36230-000", "2-14492-3100"			
35669	NO						
36946	NO		5M392-8	"CN3419-000", "AMPS-0-0036946-0"			
36951	NO		5M392-11				
36958	NO						
41765	NO						
41770	NO						
41904	NO						
42776-1	NO						
4367790003	NO			"1-1193283-5", "ES-CAP-NO.2-B9-0-35MM"			
5053094268	NO			"4-1193845-5", "RNF-100-1/4-BK-SP"			
5053194267	NO			"3-1193862-4", "RNF-100-1/2-BK-SP", "RNF-100-1/2-0"			
5053344102	NO			"4-1193882-5", "RNF-100-1-1/2-BK-SP"			
5058724002	NO			"5-1193906-0", "VERSAFIT-3/16-0-SP"			
5058744001	NO			"1193907-8", "VERSAFIT-1/4-0-SP"			
5070064069	NO			"2-1193963-6", "RNF-100-1/4-CL-SP"			
51863	NO			"4-16211-9784"			
51863-1	NO						
51864-3	NO						
52041	NO						
52943-1	NO			"401771464"			
53128-1	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
53831-1	NO						
5510320002	NO			"3-1194355-8", "PD-CAP-1/8-0"			
55785-1	NO			"AMP-0-0055785-1", "D10979-000"			
61085-1	NO						
61117-1	NO			"403631302"			
61118-1	NO			"0-0061118-1"			
61314-1	NO			"403334121", "0-0061314-1", "14629", "1101201"			
61366-1	NO						
61622-1	NO						
62000-2	NO						
62001-1	NO						
62001-2	NO						
62002-2	NO						
62305-2	NO						
62306-2	NO						
62310-2	NO						
62311-2	NO						
62429-1	NO						
62935-1	NO						
640251-7	NO						
640388-2	NO						
640388-3	NO						
640456-2	NO			"403612641", "2-42934-0583"			
640456-5	NO						
640903-2	NO						
640923-2	NO			"1181513"			
647402-2	NO						
647402-3	NO						
66098-8	NO						
66100-8	NO						
66102-8	NO						
66104-8	NO						
66105-4	NO						
66358-9	NO						
66359-9	NO						
7-1393114-8	NO			"KUHP-11D51-24"			
770007-1	NO						
770008-3	NO						
770476-1	NO						
770476-2	NO						
770579-1	NO			"0-0770579-1"			
770580-1	NO			"0-0770580-1"			
770849-4	NO						
770903-1	NO			"E25278-000", "DUL-PIN-22-18AW-S/M-UMNL"			
770904-1	NO			"2-42939-6041"			
794219-1	NO						
794221-1	NO						
794223-1	NO						
794272-1	NO						
794412-1	NO						
794606-1	NO			"AMPS-0-0794606-1", "F30642-000"			
794616-4	NO						
794616-6	NO						
794617-8	NO						
794758-1	NO						
794781-1	NO						
796075-1	NO						
796286-1	NO						
796288-1	NO						
87631-2	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
917686-1	NO						

Customer: Heilind Electronics(2972714)

Location: Cypress

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
154717-3	NO						

Customer: Heilind Electronics(415410)

Location: Highland Heights

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-480705-0	NO			"1-0480705-0"			
3371890001	NO			"7-1192545-8", "ES-CAP-NO.1-C1-0-30MM"			
5058724002	NO			"5-1193906-0", "VERSAFIT-3/16-0-SP"			

Customer: Heilind Electronics(2873181)

Location: Raleigh

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-480700-0	NO			"AMPS-1-0480700-0", "F47049-000", "1-0480700-0", "2-42932-9342"			

Customer: Heilind Electronics(2880698)

Location: Itasca

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-480699-0	NO			"402376412", "1-0480699-0", "500-060-1982", "4-27202-1755"			
1-480705-0	NO			"1-0480705-0"			
206037-1	NO			"A33294-000", "AMPS-0-0206037-1"			
206708-1	NO						

Customer: Heilind Electronics(1331779)

Location: Peachtree City

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-35115-0	NO						

Customer: Heilind Electronics Inc(2873182)

Location: Plano

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
3-640401-1	NO						
350767-1	NO			"AMP-0-0350767-1", "F84278-000"			
53831-1	NO						

Customer: Maverick Electronics(155785)

Location: McAllen

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-104479-0	NO						
1-104479-3	NO						
1-480416-1	NO						
1-480698-0	NO			"834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341"			
1-480700-0	NO			"AMPS-1-0480700-0", "F47049-000", "1-0480700-0", "2-42932-9342"			
1-480701-0	NO						
1-480706-0	NO			"873818-000", "AMPS-1-0480706-0", "2-42934-0301"			
1-794606-2	NO						
1-794617-2	NO						
1-794617-6	NO						
103653-1	NO			"010-0961-00"			
103653-2	NO			"010-0962-00"			
103653-4	NO						
104257-1	NO						
104257-2	NO			"AMP-0-0104257-2", "C75259-000", "030-0095-00"			
104257-3	NO						
104257-5	NO			"030-0096-00"			
1445049-4	NO						
170360-3	NO						
170362-3	NO						
171637-1	NO						
172159-1	NO						
2-34161-1	NO						
2-35109-1	NO			"1140297", "1139542"			
2-36161-2	NO			"402624795"			
2-794617-4	NO						
3-770060-1	NO						
34070	NO			"268412-000", "AMPS-0-0034070-0"			
34137	NO		5M392-2	"F21569-000", "AMPS-0-0034137-0"			
350218-1	NO						
350536-1	NO			"403429822"			
350767-1	NO			"AMP-0-0350767-1", "F84278-000"			
350778-1	NO			"403738545", "AMPS-0-0350778-1", "E83488-000", "500-020-2698", "500-020-0104"			
5053194267	NO			"3-1193862-4", "RNF-100-1/2-BK-SP", "RNF-100-1/2-0"			
5058724002	NO			"5-1193906-0", "VERSAFIT-3/16-0-SP"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5058744001	NO			"1193907-8", "VERSAFIT-1/4-0-SP"			
52943-1	NO			"401771464"			
647402-3	NO						
770580-1	NO			"0-0770580-1"			
770903-1	NO			"E25278-000", "DUL-PIN-22-18AW-S/M-UMNL"			
770904-1	NO			"2-42939-6041"			
794617-8	NO						
794758-1	NO						

Customer: Heilind Asia Pacific HK Ltd(3107423)

Location: Shatin

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
177915-1	NO						
33460	NO			"CS4742-000", "AMPS-0-0033460-0"			