

# Product Change Notification (PCN)

PCN Number	501257	Date Issued	September 28, 2016
Reason for Change	Capacity change or tool replacement		
Change Type Description	This letter is to inform you that another set of tooling is being added to meet the current and future demands of this product. There will be no changes in the fit, form or function from the additional tooling when compared to the current tooling.		
Reason for Short Notice	New Capacity		
Assessment of Change	Test report/Specification Test Report		
Internal Molex Qualification Date	December 31, 2016		
Sample Availability Date (Changed Part)	December 31, 2016		
Planned Implementation Date	January 22, 2017		
Method of Identifying Change	Date code		

RELEASED

After Change

### Overview

- Molex will be adding a MX150 2x8 Receptacle Grommet Cap capacity tool to support increasing demand
  - No change to fit, form, function
  - PPAP will be available upon request
- Assembly Part Numbers Affected
  - 33472-16xx, -17xx, -18xx, -19xx



Molex Confidential Information  
© 2016 Molex - All Rights Reserved. Unauthorized Reproduction/Distribution is Prohibited.



## Product Change Notification (PCN)

---

You may address any technical inquiries regarding this PCN by sending E-mail to [pcn\\_coordinator@molex.com](mailto:pcn_coordinator@molex.com) or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:501257**" in the e-mail Subject line for faster response.

RELEASED

**Molex, LLC**  
2222 Wellington Court  
Lisle, IL 60532  
TEL: 630-969-4747  
[www.molex.com](http://www.molex.com)