

Product Change Notification (PCN)

PCN Number

502580

Date Issued

May 17, 2017

Reason for Change

Change to Product

Change Type Description

This letter is to inform you that changes are being made to the part(s) identified in this Notice. The change may affect the fit, form, function or appearance of the parts, or it may result in a change to the specification. The pictures below show an example of the possible differences.

Assessment of Change

No change to parts/components FFF

Internal Molex Qualification Date

June 01, 2017

Sample Availability Date (Changed Part)

June 01, 2017

Planned Implementation Date

November 17, 2017

Method of Identifying Change

Lot information on label

Before Change

After Change

Overview

- All Phase 3 Modjack parts (series 44050/44150/44560/44661/44170/44520) will have a new terminal plating process. The new plating will have gold flash in the initial contact area with a nickel under plating, and 50u gold in the contact area with nickel under plating vs the current process which has nickel in the initial contact area, and 50u gold with nickel under plating in the contact resting area. The only impact is a slight visual difference to the terminal plating, otherwise form, fit, and function are unchanged.
- Product Impact
 - There are not impacts to form, fit or function



All parts in series 44050/44150/44560/44661/44170/44520

PPAP and samples available upon request





Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "PCN Notification:502580" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com