



Product Change Notification (PCN)


PCN Number	502594	Date Issued	May 17, 2017
Reason for Change	Change to Product		
Change Type Description	This letter is to inform you that changes are being made to the part(s) identified in this Notice. The change may affect the fit, form, function or appearance of the parts, or it may result in a change to the specification. The pictures below show an example of the possible differences.		
Assessment of Change	Product will be fully qualified before it is shipped. Qualification reports are available upon request.		
Internal Molex Qualification Date	May 10, 2017		
Sample Availability Date (Changed Part)	May 10, 2017		
Planned Implementation Date	November 17, 2017		
Method of Identifying Change	Date code		

RELEASED

Before Change

After Change

Impact™ 4 Pair 100 Ohm Daughtercard Front Housing Improvements.



Overview

- Impact™ 4 Pair 100 Ohm Daughtercard Front Housing Improvements.
 - Continuous Improvement to 1) enhance the internal rib structure in the front housing to better retain contact beams in position and 2) make the front housing endwall in column 1 more robust.
- Product Impact
 - All modifications are internal to the front housing component
- Part Number Impact
 - Series 76160 and 172103
- Samples available upon request

1 Molex Confidential Information © 2016 Molex - All Rights Reserved. Unauthorized Reproduction/Distribution is Prohibited.

2 Molex Confidential Information © 2016 Molex - All Rights Reserved. Unauthorized Reproduction/Distribution is Prohibited.





Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:502594**" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC
2222 Wellington Court
Lisle, IL 60532
TEL: 630-969-4747
www.molex.com