



# Product Change Notification

Current Date: 18-Oct-2017

## TE Connectivity

**Product Change Notification:** E-17-013712

**PCN Date:** 10-OCT-17

**Customer:** Heilind Electronics  
Inc(0002135900)

**Location:** WORLDWIDE

**Agreement:** Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

**General Product Description:**

Univer Mate-N-Lok plug Housing

**Description of Changes**

Material upgrade for better supply chain.

**Reason for Changes:**

Product Improvement. Material upgrade for better supply chain.

**Estimated Dates:**

**Last Order Date** (Obsolete Parts Only):

**First Date To Ship** (Changed Parts Only):

15-JAN-2018

**Last Ship Date** (Obsolete Parts Only):

**Last Date for Mixed Shipments:** (Changed Parts Only):

15-FEB-2019

**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">350715-1</a>	NO			"402723738", "AMP-0-0350715-1", "E04329-000"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">350715-4</a>	NO			"C46515-000", "AMPS-0-0350715-4"			
<a href="#">350720-1</a>	NO			"403049182", "AMPS-0-0350720-1", "D76178-000", "500-020-2570"			
<a href="#">350720-4</a>	NO						
<a href="#">350735-4</a>	NO						
<a href="#">350736-1</a>	NO			"403431885", "AMPS-0-0350736-1", "D26199-000"			
<a href="#">350766-1</a>	NO			"AMP-0-0350766-1", "F98408-000", "2-42939-5671"			
<a href="#">350766-4</a>	NO						
<a href="#">350777-1</a>	NO			"403311533", "AMPS-0-0350777-1", "C55004-000"			
<a href="#">350777-4</a>	NO			"CF8009-000", "SIML-0-0350777-4"			
<a href="#">350779-1</a>	NO			"403426000", "AMP-0-0350779-1", "E78305-000", "651-1084-01"			
<a href="#">350779-4</a>	NO						
<a href="#">350809-1</a>	NO			"AMP-0-0350809-1", "E81588-000"			
<a href="#">350865-1</a>	NO			"CU3087-000", "AMPS-0-0350865-1"			
<a href="#">350866-1</a>	NO			"CU3088-000", "AMPS0-0350866-1"			
<a href="#">640581-1</a>	NO			"405000886"			
<a href="#">640582-1</a>	NO						

Customer: Heilind Electronics( 167811 )

Location: Wilmington

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">350715-1</a>	NO			"402723738", "AMP-0-0350715-1", "E04329-000"			
<a href="#">350720-1</a>	NO			"403049182", "AMPS-0-0350720-1", "D76178-000", "500-020-2570"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">350736-1</a>	NO			"403431885", "AMPS-0-0350736-1", "D26199-000"			
<a href="#">350766-1</a>	NO			"AMP-0-0350766-1", "F98408-000", "2-42939-5671"			
<a href="#">350777-1</a>	NO			"403311533", "AMPS-0-0350777-1", "C55004-000"			
<a href="#">350779-1</a>	NO			"403426000", "AMP-0-0350779-1", "E78305-000", "651-1084-01"			
<a href="#">350779-4</a>	NO						
<a href="#">350809-1</a>	NO			"AMP-0-0350809-1", "E81588-000"			
<a href="#">350865-1</a>	NO			"CU3087-000", "AMPS-0-0350865-1"			
<a href="#">350866-1</a>	NO			"CU3088-000", "AMPS0-0350866-1"			
<a href="#">640581-1</a>	NO			"405000886"			
<a href="#">640582-1</a>	NO						

Customer: Heilind Electronics( 2873183 )

Location: Hudson

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">350766-1</a>	NO			"AMP-0-0350766-1", "F98408-000", "2-42939-5671"			
<a href="#">350777-1</a>	NO			"403311533", "AMPS-0-0350777-1", "C55004-000"			
<a href="#">350809-1</a>	NO			"AMP-0-0350809-1", "E81588-000"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">350865-1</a>	NO			"CU3087-000", "AMPS-0-0350865-1"			

Customer: Heilind Electronics( 2880698 )

Location: Itasca

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">350779-1</a>	NO			"403426000", "AMP-0-0350779-1", "E78305-000", "651-1084-01"			

Customer: Heilind Electronics Brasil Ltda( 3088064 )

Location: Sao Paulo

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">350715-1</a>	NO			"402723738", "AMP-0-0350715-1", "E04329-000"			
<a href="#">350720-1</a>	NO			"403049182", "AMPS-0-0350720-1", "D76178-000", "500-020-2570"			
<a href="#">350766-1</a>	NO			"AMP-0-0350766-1", "F98408-000", "2-42939-5671"			
<a href="#">350777-1</a>	NO			"403311533", "AMPS-0-0350777-1", "C55004-000"			
<a href="#">350779-1</a>	NO			"403426000", "AMP-0-0350779-1", "E78305-000", "651-1084-01"			
<a href="#">350809-1</a>	NO			"AMP-0-0350809-1", "E81588-000"			

**Customer:** Maverick Electronics( 155784 )**Location:** Mayfield Village**Agreement Number:** Agreement Unknown**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">350865-1</a>	NO			"CU3087-000", "AMPS-0-0350865-1"			

**Customer:** Heilind Electronics GmbH( 113007 )**Location:** Feldkirchen- Westerham**Agreement Number:** Agreement Unknown**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">350715-1</a>	NO		1550606	"402723738", "AMP-0-0350715-1", "E04329-000"			
<a href="#">350715-4</a>	NO		1550086	"C46515-000", "AMPS-0-0350715-4"			
<a href="#">350720-4</a>	NO		1550010				
<a href="#">350735-4</a>	NO						
<a href="#">350736-1</a>	NO			"403431885", "AMPS-0-0350736-1", "D26199-000"			
<a href="#">350766-1</a>	NO			"AMP-0-0350766-1", "F98408-000", "2-42939-5671"			
<a href="#">350766-4</a>	NO		1550099				
<a href="#">350777-1</a>	NO		1550207	"403311533", "AMPS-0-0350777-1", "C55004-000"			
<a href="#">350779-4</a>	NO		1550080				

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">350809-1</a>	NO			"AMP-0-0350809-1", "E81588-000"			
<a href="#">350866-1</a>	NO		1550094	"CU3088-000", "AMPS0-0350866-1"			

Customer: Heilind Electronics( 1275266 )

Location: Visalia

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">350715-1</a>	NO			"402723738", "AMP-0-0350715-1", "E04329-000"			
<a href="#">350720-1</a>	NO			"403049182", "AMPS-0-0350720-1", "D76178-000", "500-020-2570"			
<a href="#">350736-1</a>	NO			"403431885", "AMPS-0-0350736-1", "D26199-000"			
<a href="#">350766-1</a>	NO			"AMP-0-0350766-1", "F98408-000", "2-42939-5671"			
<a href="#">350777-1</a>	NO			"403311533", "AMPS-0-0350777-1", "C55004-000"			
<a href="#">350809-1</a>	NO			"AMP-0-0350809-1", "E81588-000"			
<a href="#">350865-1</a>	NO			"CU3087-000", "AMPS-0-0350865-1"			
<a href="#">350866-1</a>	NO			"CU3088-000", "AMPS0-0350866-1"			
<a href="#">640581-1</a>	NO			"405000886"			
<a href="#">640582-1</a>	NO						

Customer: Heilind Electronics( 1276409 )

Location: Plano

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">350736-1</a>	NO			"403431885", "AMPS-0-0350736-1", "D26199-000"			
<a href="#">350766-1</a>	NO			"AMP-0-0350766-1", "F98408-000", "2-42939-5671"			
<a href="#">350777-1</a>	NO			"403311533", "AMPS-0-0350777-1", "C55004-000"			

Customer: Heilind Asia Pacific (Hong Kong)( 2991513 )

Location: Hong Kong

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">350715-1</a>	NO			"402723738", "AMP-0-0350715-1", "E04329-000"			
<a href="#">350720-1</a>	NO			"403049182", "AMPS-0-0350720-1", "D76178-000", "500-020-2570"			
<a href="#">350736-1</a>	NO			"403431885", "AMPS-0-0350736-1", "D26199-000"			
<a href="#">350766-1</a>	NO			"AMP-0-0350766-1", "F98408-000", "2-42939-5671"			
<a href="#">350777-1</a>	NO			"403311533", "AMPS-0-0350777-1", "C55004-000"			
<a href="#">350777-4</a>	NO			"CF8009-000", "SIML-0-0350777-4"			
<a href="#">350779-1</a>	NO			"403426000", "AMP-0-0350779-1", "E78305-000", "651-1084-01"			
<a href="#">350809-1</a>	NO			"AMP-0-0350809-1", "E81588-000"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">350865-1</a>	NO			"CU3087-000", "AMPS-0-0350865-1"			
<a href="#">350866-1</a>	NO			"CU3088-000", "AMPS0-0350866-1"			
<a href="#">640581-1</a>	NO			"405000886"			
<a href="#">640582-1</a>	NO						

**Customer:** Heilind Asia Pacific (SG) Pte Ltd( 2980456 )

**Location:** Singapore

**Agreement Number:** Agreement Unknown

**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">350715-1</a>	NO			"402723738", "AMP-0-0350715-1", "E04329-000"			
<a href="#">350720-4</a>	NO						
<a href="#">350766-1</a>	NO			"AMP-0-0350766-1", "F98408-000", "2-42939-5671"			
<a href="#">350777-1</a>	NO			"403311533", "AMPS-0-0350777-1", "C55004-000"			
<a href="#">350779-1</a>	NO			"403426000", "AMP-0-0350779-1", "E78305-000", "651-1084-01"			
<a href="#">640581-1</a>	NO			"405000886"			



Customer: Maverick Electronics( 155785 )

Location: Mcallen

Agreement Number: Agreement Unknown

## Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">350715-1</a>	NO			"402723738", "AMP-0-0350715-1", "E04329-000"			
<a href="#">350736-1</a>	NO			"403431885", "AMPS-0-0350736-1", "D26199-000"			
<a href="#">350736-1</a>	NO			"403431885", "AMPS-0-0350736-1", "D26199-000"			
<a href="#">350766-1</a>	NO			"AMP-0-0350766-1", "F98408-000", "2-42939-5671"			
<a href="#">350766-1</a>	NO			"AMP-0-0350766-1", "F98408-000", "2-42939-5671"			
<a href="#">350777-1</a>	NO			"403311533", "AMPS-0-0350777-1", "C55004-000"			
<a href="#">350777-1</a>	NO			"403311533", "AMPS-0-0350777-1", "C55004-000"			
<a href="#">350779-1</a>	NO			"403426000", "AMP-0-0350779-1", "E78305-000", "651-1084-01"			
<a href="#">350779-1</a>	NO			"403426000", "AMP-0-0350779-1", "E78305-000", "651-1084-01"			
<a href="#">350809-1</a>	NO			"AMP-0-0350809-1", "E81588-000"			
<a href="#">350809-1</a>	NO			"AMP-0-0350809-1", "E81588-000"			
<a href="#">350865-1</a>	NO			"CU3087-000", "AMPS-0-0350865-1"			
<a href="#">350865-1</a>	NO			"CU3087-000", "AMPS-0-0350865-1"			

Customer: Heilind Electronics GmbH( 3050932 )

Location: Rosenheim

Agreement Number: Agreement Unknown

## Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">350715-1</a>	NO		1550606	"402723738", "AMP-0-0350715-1", "E04329-000"			
<a href="#">350715-4</a>	NO		1550086	"C46515-000", "AMPS-0-0350715-4"			
<a href="#">350720-4</a>	NO		1550010				
<a href="#">350735-4</a>	NO						
<a href="#">350736-1</a>	NO			"403431885", "AMPS-0-0350736-1", "D26199-000"			
<a href="#">350766-1</a>	NO			"AMP-0-0350766-1", "F98408-000", "2-42939-5671"			
<a href="#">350766-4</a>	NO		1550099				
<a href="#">350777-1</a>	NO		1550207	"403311533", "AMPS-0-0350777-1", "C55004-000"			
<a href="#">350779-4</a>	NO		1550080				
<a href="#">350809-1</a>	NO			"AMP-0-0350809-1", "E81588-000"			
<a href="#">350866-1</a>	NO		1550094	"CU3088-000", "AMPS0-0350866-1"			

**Customer:** Heilind Asia Pacific (SG) Pte Ltd( 3076161 )

**Location:** Singapore

**Agreement Number:** Agreement Unknown

**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">350715-1</a>	NO			"402723738", "AMP-0-0350715-1", "E04329-000"			

Customer: Heilind Electronics Inc( 3152147 )

Location: San Diego

Agreement Number: Agreement Unknown

## Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">350777-1</a>	NO			"403311533", "AMPS-0-0350777-1", "C55004-000"			

Customer: Maverick Electronics( 155785 )

Location: Mcallen

Agreement Number: Agreement Unknown

## Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">350715-1</a>	NO			"402723738", "AMP-0-0350715-1", "E04329-000"			
<a href="#">350736-1</a>	NO			"403431885", "AMPS-0-0350736-1", "D26199-000"			
<a href="#">350736-1</a>	NO			"403431885", "AMPS-0-0350736-1", "D26199-000"			
<a href="#">350766-1</a>	NO			"AMP-0-0350766-1", "F98408-000", "2-42939-5671"			
<a href="#">350766-1</a>	NO			"AMP-0-0350766-1", "F98408-000", "2-42939-5671"			
<a href="#">350777-1</a>	NO			"403311533", "AMPS-0-0350777-1", "C55004-000"			
<a href="#">350777-1</a>	NO			"403311533", "AMPS-0-0350777-1", "C55004-000"			
<a href="#">350779-1</a>	NO			"403426000", "AMP-0-0350779-1", "E78305-000", "651-1084-01"			
<a href="#">350779-1</a>	NO			"403426000", "AMP-0-0350779-1", "E78305-000", "651-1084-01"			
<a href="#">350809-1</a>	NO			"AMP-0-0350809-1", "E81588-000"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">350809-1</a>	NO			"AMP-0-0350809-1", "E81588-000"			
<a href="#">350865-1</a>	NO			"CU3087-000", "AMPS-0-0350865-1"			
<a href="#">350865-1</a>	NO			"CU3087-000", "AMPS-0-0350865-1"			

**Customer:** Heilind Asia Pacific (SG) Pte Ltd( 2980456 )

**Location:** Singapore

**Agreement Number:** Agreement Unknown

**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">350715-1</a>	NO			"402723738", "AMP-0-0350715-1", "E04329-000"			
<a href="#">350720-4</a>	NO						
<a href="#">350766-1</a>	NO			"AMP-0-0350766-1", "F98408-000", "2-42939-5671"			
<a href="#">350777-1</a>	NO			"403311533", "AMPS-0-0350777-1", "C55004-000"			
<a href="#">350779-1</a>	NO			"403426000", "AMP-0-0350779-1", "E78305-000", "651-1084-01"			
<a href="#">640581-1</a>	NO			"405000886"			

**Customer:** Heilind Asia Pacific (SG) Pte Ltd( 2980456 )

**Location:** Singapore

**Agreement Number:** Agreement Unknown

**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">350715-1</a>	NO			"402723738", "AMP-0-0350715-1", "E04329-000"			
<a href="#">350720-4</a>	NO						
<a href="#">350766-1</a>	NO			"AMP-0-0350766-1", "F98408-000", "2-42939-5671"			
<a href="#">350777-1</a>	NO			"403311533", "AMPS-0-0350777-1", "C55004-000"			
<a href="#">350779-1</a>	NO			"403426000", "AMP-0-0350779-1", "E78305-000", "651-1084-01"			
<a href="#">640581-1</a>	NO			"405000886"			