



# Product Change Notification

Current Date: 09-Apr-2018

## TE Connectivity

**Product Change Notification:** P-18-015325

**PCN Date:** 16-JAN-18

**Customer:** Heilind Electronics Inc(0002135900)

**Location:** WORLDWIDE

**Agreement:** Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

**General Product Description:**  
 Manufacturing Location Change of Menlo Park Appliances Tubing ES2000 Products and UOM change for ES2000 coiled parts

**Description of Changes**  
 Please note - This PCN supersedes PCN P-17-015222. Due to a system error PCN P-17-015222 may not have been distributed to all concerned. Manufacturing location change. This notification is to inform our customers that TE Connectivity is closing our Menlo Park facility in USA and moving the production to our Trutnov facilities in Czech Republic and our Shanghai facility in China. The receiving facility in Shanghai is already an established Heat Shrinkable Tubing ("Tubing" or "Products") manufacturing site manufacturing Tubing since 1996, and the receiving facility in Trutnov is already an established as a Heat Shrinkable Tubing ("Tubing" or "Products") manufacturing site with Trutnov facility manufacturing Tubing since 2008.  
**Other attachments:**  
[ES2000 PCN details](#)  
[ES2000 Packaging details](#)  
[ES2000 PCN details](#)  
[ES2000 Packaging details](#)

**Reason for Changes:**  
 Dear Customer, we hereby inform you about a transfer of processes. The transfer follows a strict procedure, which fully maintains quality, ability to supply and form-fit-function of the concerned products. A TE-internal release test based on the relevant part specifications will be executed before delivery. As part of the production move, we will start to ship ES2000 products from 21st March 2018 from the Trutnov & Shanghai facilities. After this date TE reserves the right to provide qualified products from any of the manufacturing locations during this transfer until the final closure date of Menlo Park location by the end of 2019. As not all part numbers will transfer at the same time customers may still receive products from the Menlo Park location after this transfer date due to the inventory we will carry to allow this transfer to happen and to minimize impact to our tubing customers.  
**Estimated Dates:**

<b>Last Order Date</b> (Obsolete Parts Only):	<b>First Date To Ship</b> (Changed Parts Only):
	21-MAR-2018
<b>Last Ship Date</b> (Obsolete Parts Only):	<b>Last Date for Mixed Shipments:</b> (Changed Parts Only):
	04-JUL-2019

**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">063725P011</a>	NO			"5-1190481-1", "ES2000-NO.2-B9-0-50MM"			
<a href="#">063725P013</a>	NO			"5-1190481-3", "ES2000-NO.2-B9-0-75MM"			
<a href="#">063725P021</a>	NO			"6-1190481-0", "ES2000-NO.2-B9-0-27MM"			
<a href="#">063725P022</a>	NO			"6-1190481-1", "ES2000-NO.2-B9-0-STK", "ES2000-2-4FOOT"			
<a href="#">063725P028</a>	NO			"6-1190481-5", "ES2000-NO.2-B9-0-25MM"			
<a href="#">063725P078</a>	NO			"1190482-7", "ES2000-NO.2-B9-0-38MM"			
<a href="#">063725P080</a>	NO			"1190482-9", "ES2000-NO.2-B9-0-33MM"			
<a href="#">121397P014</a>	NO			"3-1190883-4", "ES2000-NO.3-B8-0-65MM"			
<a href="#">121397P015</a>	NO			"3-1190883-5", "ES2000-NO.3-B8-0-75MM"			
<a href="#">121397P018</a>	NO			"3-1190883-8", "ES2000-NO.3-B8-0-50MM"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">121397P023</a>	NO			"4-1190883-2", "ES2000-NO.3-B8-0-27MM"			
<a href="#">121397P024</a>	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
<a href="#">121397P043</a>	NO			"5-1190883-3", "ES2000-NO.3-B8-0-40MM"			
<a href="#">121397P067</a>	NO			"7-1190883-5", "ES2000-NO.3-B8-0-25MM"			
<a href="#">130599P003</a>	NO			"6-1190948-1", "ES2000-NO.4-B7-0-75MM"			
<a href="#">130599P006</a>	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			
<a href="#">130599P010</a>	NO			"6-1190948-7", "ES2000-NO.4-B7-0-40MM"			
<a href="#">130599P011</a>	NO			"6-1190948-8", "ES2000-NO.4-B7-0-50MM"			
<a href="#">134001-000</a>	NO			"9-1190973-1", "ES2000-NO.2-B9-0-COIL"			
<a href="#">829131P011</a>	NO			"7-1196474-0", "ES2000-NO.1-C1-0-30MM"			
<a href="#">829131P012</a>	NO			"7-1196474-1", "ES2000-NO.1-C1-0-50MM"			
<a href="#">829131P019</a>	NO			"7-1196474-7", "ES2000-NO.1-C1-0-27MM"			
<a href="#">829131P021</a>	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			
<a href="#">829131P079</a>	NO			"2-1196475-9", "ES2000-NO.1-C1-0-15MM"			
<a href="#">829131P081</a>	NO			"3-1196475-0", "ES2000-NO.1-C1-0-100MM"			
<a href="#">CP0507-000</a>	NO			"ES2000-NO.4-B7-0-127MM"			

Customer: Heilind Electronics ( 2873183 )

Location: Hudson

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">063725P022</a>	NO			"6-1190481-1", "ES2000-NO.2-B9-0-STK", "ES2000-2-4FOOT"			
<a href="#">121397P018</a>	NO			"3-1190883-8", "ES2000-NO.3-B8-0-50MM"			
<a href="#">121397P024</a>	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
<a href="#">130599P006</a>	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			
<a href="#">829131P021</a>	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			

Customer: Heilind Electronics Inc ( 1275266 )

Location: Visalia

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">063725P011</a>	NO			"5-1190481-1", "ES2000-NO.2-B9-0-50MM"			
<a href="#">063725P013</a>	NO			"5-1190481-3", "ES2000-NO.2-B9-0-75MM"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">063725P022</a>	NO			"6-1190481-1", "ES2000-NO.2-B9-0-STK", "ES2000-2-4FOOT"			
<a href="#">063725P028</a>	NO			"6-1190481-5", "ES2000-NO.2-B9-0-25MM"			
<a href="#">121397P014</a>	NO			"3-1190883-4", "ES2000-NO.3-B8-0-65MM"			
<a href="#">121397P015</a>	NO			"3-1190883-5", "ES2000-NO.3-B8-0-75MM"			
<a href="#">121397P018</a>	NO			"3-1190883-8", "ES2000-NO.3-B8-0-50MM"			
<a href="#">121397P023</a>	NO			"4-1190883-2", "ES2000-NO.3-B8-0-27MM"			
<a href="#">121397P024</a>	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
<a href="#">121397P043</a>	NO			"5-1190883-3", "ES2000-NO.3-B8-0-40MM"			
<a href="#">130599P003</a>	NO			"6-1190948-1", "ES2000-NO.4-B7-0-75MM"			
<a href="#">130599P006</a>	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			
<a href="#">130599P010</a>	NO			"6-1190948-7", "ES2000-NO.4-B7-0-40MM"			
<a href="#">130599P011</a>	NO			"6-1190948-8", "ES2000-NO.4-B7-0-50MM"			
<a href="#">134001-000</a>	NO			"9-1190973-1", "ES2000-NO.2-B9-0-COIL"			
<a href="#">829131P011</a>	NO			"7-1196474-0", "ES2000-NO.1-C1-0-30MM"			
<a href="#">829131P012</a>	NO			"7-1196474-1", "ES2000-NO.1-C1-0-50MM"			
<a href="#">829131P021</a>	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			
<a href="#">CP0507-000</a>	NO			"ES2000-NO.4-B7-0-127MM"			

Customer: Heilind Asia Pacific (Hong Kong) ( 2980376 )

Location: Hong Kong

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">130599P006</a>	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			

Customer: Heilind Electronics Inc ( 1281082 )

Location: Highland Heights

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">063725P013</a>	NO			"5-1190481-3", "ES2000-NO.2-B9-0-75MM"			
<a href="#">063725P021</a>	NO			"6-1190481-0", "ES2000-NO.2-B9-0-27MM"			
<a href="#">063725P022</a>	NO			"6-1190481-1", "ES2000-NO.2-B9-0-STK", "ES2000-2-4FOOT"			
<a href="#">063725P078</a>	NO			"1190482-7", "ES2000-NO.2-B9-0-38MM"			
<a href="#">063725P080</a>	NO			"1190482-9", "ES2000-NO.2-B9-0-33MM"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">121397P024</a>	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
<a href="#">130599P006</a>	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			
<a href="#">829131P021</a>	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			
<a href="#">829131P079</a>	NO			"2-1196475-9", "ES2000-NO.1-C1-0-15MM"			

Customer: Heilind Electronics Inc ( 264685 )

Location: Hudson

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">121397P023</a>	NO			"4-1190883-2", "ES2000-NO.3-B8-0-27MM"			

Customer: Heilind Asia Pacific (Hong Kong) ( 2991513 )

Location: Hong Kong

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">130599P006</a>	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			

Customer: Heilind Asia Pacific (SG) Pte Ltd ( 2980456 )

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">829131P012</a>	NO			"7-1196474-1", "ES2000-NO.1-C1-0-50MM"			
<a href="#">829131P081</a>	NO			"3-1196475-0", "ES2000-NO.1-C1-0-100MM"			

Customer: Heilind Electronics Inc ( 1276409 )

Location: Plano

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">063725P021</a>	NO			"6-1190481-0", "ES2000-NO.2-B9-0-27MM"			

Customer: Heilind Electronics Inc ( 3152147 )

Location: San Diego

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">121397P024</a>	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
<a href="#">829131P021</a>	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			

Customer: Heilind Electronics Inc ( 167811 )

Location: Wilmington

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">063725P011</a>	NO			"5-1190481-1", "ES2000-NO.2-B9-0-50MM"			
<a href="#">063725P013</a>	NO			"5-1190481-3", "ES2000-NO.2-B9-0-75MM"			
<a href="#">063725P021</a>	NO			"6-1190481-0", "ES2000-NO.2-B9-0-27MM"			
<a href="#">063725P022</a>	NO			"6-1190481-1", "ES2000-NO.2-B9-0-STK", "ES2000-2-4FOOT"			
<a href="#">063725P028</a>	NO			"6-1190481-5", "ES2000-NO.2-B9-0-25MM"			
<a href="#">063725P078</a>	NO			"1190482-7", "ES2000-NO.2-B9-0-38MM"			
<a href="#">063725P080</a>	NO			"1190482-9", "ES2000-NO.2-B9-0-33MM"			
<a href="#">121397P014</a>	NO			"3-1190883-4", "ES2000-NO.3-B8-0-65MM"			
<a href="#">121397P015</a>	NO			"3-1190883-5", "ES2000-NO.3-B8-0-75MM"			
<a href="#">121397P018</a>	NO			"3-1190883-8", "ES2000-NO.3-B8-0-50MM"			
<a href="#">121397P023</a>	NO			"4-1190883-2", "ES2000-NO.3-B8-0-27MM"			
<a href="#">121397P024</a>	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
<a href="#">121397P043</a>	NO			"5-1190883-3", "ES2000-NO.3-B8-0-40MM"			
<a href="#">121397P067</a>	NO			"7-1190883-5", "ES2000-NO.3-B8-0-25MM"			
<a href="#">130599P003</a>	NO			"6-1190948-1", "ES2000-NO.4-B7-0-75MM"			
<a href="#">130599P006</a>	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			
<a href="#">130599P010</a>	NO			"6-1190948-7", "ES2000-NO.4-B7-0-40MM"			
<a href="#">130599P011</a>	NO			"6-1190948-8", "ES2000-NO.4-B7-0-50MM"			
<a href="#">134001-000</a>	NO			"9-1190973-1", "ES2000-NO.2-B9-0-COIL"			
<a href="#">829131P011</a>	NO			"7-1196474-0", "ES2000-NO.1-C1-0-30MM"			
<a href="#">829131P012</a>	NO			"7-1196474-1", "ES2000-NO.1-C1-0-50MM"			
<a href="#">829131P019</a>	NO			"7-1196474-7", "ES2000-NO.1-C1-0-27MM"			
<a href="#">829131P021</a>	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			
<a href="#">829131P079</a>	NO			"2-1196475-9", "ES2000-NO.1-C1-0-15MM"			
<a href="#">CP0507-000</a>	NO			"ES2000-NO.4-B7-0-127MM"			