



Product Change Notification

Current Date: 21-Sep-2018

TE Connectivity

Product Change Notification: P-18-016371

PCN Date: 20-SEP-18

Customer: Heilind Electronics
Inc(0002135900)

Location: WORLDWIDE

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Universal MATE-N-LOK

Description of Changes

Manufacturing location change. Following Part Numbers will be dual sourced from USA and China facility.

Reason for Changes:

Dear Customer, as a result of our continuous strive for improving our processes, we hereby inform you about a transfer of tools and/or processes. The transfer is executed by following a strict transfer procedure, which guarantees no negative influence on quality, ability to supply and form-fit-function of the concerned products. The new manufacturing location is under a certified quality management system according the standard industry requirements. An internal release based on our specifications will be executed before any parts will be delivered, which guarantees the performance.

Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

31-OCT-2018

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-480698-0	NO			"834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341"			
1-480698-2	NO						
1-480698-9	NO						
1-480700-2	NO						
350715-1	NO			"402723738", "AMP-0-0350715-1", "E04329-000"			
350782-1	NO			"402723753", "769264-000", "AMPS-0-0350782-1"			
350783-1	NO						
794535-1	NO						
794814-1	NO						

Customer: Heilind Asia Pacific (3133470)

Location: Shanghai

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-480698-0	NO			"834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341"			

Customer: Heilind Electronics (2873183)

Location: Hudson

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-480698-0	NO			"834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341"			
350715-1	NO			"402723738", "AMP-0-0350715-1", "E04329-000"			

Customer: Heilind Electronics (2880698)

Location: Itasca

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-480698-0	NO			"834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341"			

Customer: Heilind Electronics Brasil Ltda (3088064)

Location: Sao Paulo

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-480698-0	NO			"834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341"			
350715-1	NO			"402723738", "AMP-0-0350715-1", "E04329-000"			

Customer: Heilind Electronics Inc (1275266)

Location: Visalia

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-480698-0	NO			"834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341"			
1-480698-9	NO						
350715-1	NO			"402723738", "AMP-0-0350715-1", "E04329-000"			
350782-1	NO			"402723753", "769264-000", "AMPS-0-0350782-1"			
350783-1	NO						
794535-1	NO						
794814-1	NO						

Customer: Heilind Electronics Inc (1331779)

Location: Peachtree City

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
794535-1	NO						

Customer: Heilind Electronics GmbH (113007)

Location: Feldkirchen- Westerham

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
350715-1	NO		1550606	"402723738", "AMP-0-0350715-1", "E04329-000"			
350782-1	NO			"402723753", "769264-000", "AMPS-0-0350782-1"			

Customer: Heilind Asia Pacific (Hong Kong) (2980376)

Location: Hong Kong

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-480698-0	NO			"834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341"			
350715-1	NO			"402723738", "AMP-0-0350715-1", "E04329-000"			
350782-1	NO			"402723753", "769264-000", "AMPS-0-0350782-1"			
350783-1	NO						

Customer: Heilind Electronics Inc (1281082)

Location: Highland Heights

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-480698-0	NO			"834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341"			
1-480698-2	NO						
1-480698-9	NO						
1-480700-2	NO						
350715-1	NO			"402723738", "AMP-0-0350715-1", "E04329-000"			
350782-1	NO			"402723753", "769264-000", "AMPS-0-0350782-1"			
350783-1	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
794535-1	NO						
794814-1	NO						

Customer: Heilind Asia Pacific (Hong Kong) (2991513)

Location: Hong Kong

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-480698-0	NO			"834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341"			
350715-1	NO			"402723738", "AMP-0-0350715-1", "E04329-000"			
350782-1	NO			"402723753", "769264-000", "AMPS-0-0350782-1"			
350783-1	NO						

Customer: Heilind Asia Pacific (SG) Pte Ltd (2980456)

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-480698-2	NO						
350715-1	NO			"402723738", "AMP-0-0350715-1", "E04329-000"			
350783-1	NO						

Customer: Heilind Electronics Inc (1276409)

Location: Plano

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
794535-1	NO						

Customer: Maverick Electronics (155785)

Location: Mcallen

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-480698-0	NO			"834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-480698-0	NO			"834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341"			
350715-1	NO			"402723738", "AMP-0-0350715-1", "E04329-000"			
350715-1	NO			"402723738", "AMP-0-0350715-1", "E04329-000"			

Customer: Heilind Electronics GmbH (3050932)

Location: Rosenheim

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
350715-1	NO		1550606	"402723738", "AMP-0-0350715-1", "E04329-000"			
350782-1	NO			"402723753", "769264-000", "AMPS-0-0350782-1"			

Customer: Heilind Asia Pacific (SG) Pte Ltd (3076161)

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
350715-1	NO			"402723738", "AMP-0-0350715-1", "E04329-000"			

Customer: Maverick Electronics (155785)

Location: Mcallen

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-480698-0	NO			"834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341"			
1-480698-0	NO			"834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341"			
350715-1	NO			"402723738", "AMP-0-0350715-1", "E04329-000"			
350715-1	NO			"402723738", "AMP-0-0350715-1", "E04329-000"			

Customer: Heilind Electronics Inc (167811)

Location: Wilmington

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-480698-0	NO			"834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-480698-2	NO						
1-480698-9	NO						
1-480700-2	NO						
350715-1	NO			"402723738", "AMP-0-0350715-1", "E04329-000"			
350782-1	NO			"402723753", "769264-000", "AMPS-0-0350782-1"			
350783-1	NO						
794535-1	NO						
794814-1	NO						

Customer: Heilind Asia Pacific (SG) Pte Ltd (2980456)

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-480698-2	NO						
350715-1	NO			"402723738", "AMP-0-0350715-1", "E04329-000"			
350783-1	NO						

Customer: Heilind Electronics Inc (3144575)

Location: Mcallen

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
794535-1	NO						