Worldwide Account Form



Product Change Notification

Current Date: 28-Jun-2021

TE Connectivity

Product Change Notification: E-21-005720

Customer: Heilind Electronics Lo

Inc(0002135900)

PCN Date: 24-JUN-21

Location: WORLDWIDE **Agreement:** Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

AMPMODU MTE HEADER ASSEMBLIES

Description of Changes

ADDENDUM TO PCN E-20-000624 (ATTACHED). ONE OF THE CHANGES NOTED IN PCN E-20-000624 IS NOT BEING IMPLEMENTED DUE TO FINANCIAL IMPLICATIONS. THE TOOLING CHANGE SHOWN IN THE ATTACHED MTE SHROUDED HEADER TOOLING CHANGE FILE IS BEING MADE TO BE AT THE MOLDER'S DISCRETION. SOME PARTS MAY HAVE THIS RECESSED AREA, SOME MIGHT NOT. THERE IS NO PERFORMANCE DIFFERENCE BETWEEN THE PARTS WITH THE RECESSION AND THE PARTS WITHOUT THE RECESSION.

Other attachments:

MTE Shrouded header tooling change

PCN E-20-000624

| Reason for Changes: | | | | | | |
|--|--|--|--|--|--|--|
| Product Improvement. | | | | | | |
| Estimated Dates: | | | | | | |
| Last Order Date (Obsolete Parts Only): | First Date To Ship (Changed Parts Only): | | | | | |
| | 30-JUN-2021 | | | | | |
| Last Ship Date (Obsolete Parts Only): | Last Date for Mixed Shipments: (Changed Parts Only): | | | | | |
| | 31-DEC-2022 | | | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-------------------|---------------------------|---------------------|-------------------------|-----------------------------------|---------------------------|------------------------------------|------------------------------|
| 103638-3 | NO | | | | | | |
| 103670-2 | NO | | | | | | |
| 103670-3 | NO | | | "4-40001-6591" | | | |
| 103670-5 | NO | | | | | | |
| 103908-1 | NO | | | "406746073" | | | |
| <u>5-103634-3</u> | NO | | | | | | |
| <u>5-103635-2</u> | NO | | | | | | |
| <u>5-103639-1</u> | NO | | | | | | |
| <u>5-103639-5</u> | NO | | | | | | |
| <u>5-103672-9</u> | NO | | | | | | |
| <u>5-103673-2</u> | NO | | | | | | |
| <u>5-103673-3</u> | NO | | | | | | |
| <u>5-103673-4</u> | NO | | | | | | |
| <u>5-103673-7</u> | NO | | | "CW5998-000", "PER-5-103673-7" | | | |
| <u>5-103735-3</u> | NO | | | | | | |
| 5-103735-4 | NO | | | | | | |
| <u>5-103735-5</u> | NO | | | | | | |
| <u>5-103904-1</u> | NO | | | | | | |
| <u>5-103904-4</u> | NO | | | | | | |
| 5-103908-2 | NO | | | | | | |
| <u>5-103908-3</u> | NO | | | | | | |
| <u>5-103908-7</u> | NO | | | | | | |
| <u>5-104361-2</u> | NO | | | | | | |
| <u>5-104361-3</u> | NO | | | | | | |
| <u>5-104361-4</u> | NO | | | | | | |
| <u>6-103669-0</u> | NO | | | | | | |
| <u>6-103672-5</u> | NO | | | | | | |
| <u>6-103673-0</u> | NO | | | | | | |

The documents listed below are being modified. Related parts that are not explicitly listed on this PCN are not being modified or discontinued as per the PCN. The Last Order Date, Last Ship Date, First Date to Ship Changed Parts and last date for Mixed Shipments apply only to parts explicitly listed on this PCN.

Customer Drawing(s) Being Modified:

| Drawing Number | Related Part Number | Customer Part Number | Current Revision New Revision |
|----------------|------------------------------------|----------------------|-------------------------------|
| 103634 | 5-103634-3 | | W |
| <u>103635</u> | 5-103635-2 | | U |
| 103638 | 103638-3 | | Т |
| <u>103639</u> | 5-103639-1, 5-103639-5 | | AA |
| <u>103670</u> | 103670-2 | | U |
| 103672 | 5-103672-9 | | AE |
| 103673 | 5-103673-2, 5-103673-4, 5-103673-3 | | V |
| <u>103735</u> | 5-103735-3, 5-103735-4 | | W |
| 103904 | 5-103904-4 | | S |
| 103908 | 5-103908-2, 103908-1 | | S |
| <u>104361</u> | 5-104361-4, 5-104361-3 | | S |

Customer: Heilind Electronics Inc (3181260) Location: Mentor Agreement Number: Agreement Unknown

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-------------------|---------------------------|---------------------|-------------------------|-----------------------------------|---------------------------|------------------------------------|---------------------------|
| 103638-3 | NO | | | | | | |
| 103670-2 | NO | | | | | | |
| 103670-3 | NO | | | "4-40001-6591" | | | |
| 5-103635-2 | NO | | | | | | |
| 5-103639-1 | NO | | | | | | |
| 5-103639-5 | NO | | | | | | |
| <u>5-103672-9</u> | NO | | | | | | |
| <u>5-103673-4</u> | NO | | | | | | |
| 5-103673-7 | NO | | | "CW5998-000", "PER-5-103673-7" | | | |
| 5-103735-3 | NO | | | | | | |
| 5-103735-4 | NO | | | | | | |
| <u>5-103735-5</u> | NO | | | | | | |
| <u>5-103904-4</u> | NO | | | | | | |
| <u>5-103908-2</u> | NO | | | | | | |
| <u>5-103908-3</u> | NO | | | | | | |
| <u>5-103908-7</u> | NO | | | | | | |
| <u>5-104361-4</u> | NO | | | | | | |
| <u>6-103672-5</u> | NO | | | | | | |

The documents listed below are being modified. Related parts that are not explicitly listed on this PCN are not being modified or discontinued as per the PCN. The Last Order Date, Last Ship Date, First Date to Ship Changed Parts and last date for Mixed Shipments apply only to parts explicitly listed on this PCN.

Customer Drawing(s) Being Modified:

| Drawing Number | Related Part Number | Customer Part Number | Current Revision | New Revision |
|----------------|---------------------|----------------------|-------------------------|--------------|
| <u>103635</u> | 5-103635-2 | | U | |
| 103638 | 103638-3 | | Т | |
| 103639 | 5-103639-1 | | AA | |
| <u>103670</u> | 103670-2 | | U | |
| 103672 | 5-103672-9 | | AE | |
| <u>103673</u> | 5-103673-4 | | V | |
| <u>103735</u> | 5-103735-3 | | W | |
| <u>103904</u> | 5-103904-4 | | S | |
| <u>103908</u> | 5-103908-2 | | S | |
| <u>104361</u> | 5-104361-4 | | S | |

Customer: Heilind Asia Pacific (SG) Pte Ltd (3076161) Location: Singapore Agreement Number: Agreement Unknown

Part Number(s) being Modified:

| Part | Part Discontinued per | Customer | Customer Part | Alias Part | Substitute Part | Substitute Alias Part | Description Of | |
|------------|-----------------------|----------|---------------|------------|-----------------|-----------------------|----------------|---|
| Number | PCN | Drawing | Number | Number(s) | Number | Number(s) | Difference | |
| 5-103735-3 | NO | | | | | | |] |

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------|---------------------------|---------------------|-------------------------|-------------------------|---------------------------|------------------------------------|---------------------------|
| 5-103904-1 | | 2.0 | | | | | 2 |
| 5-103908-2 | NO | | | | | | |
| 5-104361-2 | NO | | | | | | |
| 6-103673-0 | NO | | | | | | |

Customer: Heilind Asia Pacific (SG) Pte Ltd (3076161) Location: Singapore Agreement Number: Agreement Unknown

Part Number(s) being Modified:

| Part | Part Discontinued per | Customer | Customer Part | Alias Part | Substitute Part | Substitute Alias Part | Description Of |
|------------|-----------------------|----------|---------------|------------|-----------------|-----------------------|----------------|
| Number | PCN | Drawing | Number | Number(s) | Number | Number(s) | Difference |
| 5-103735-3 | NO | | | | | | |
| 5-103904-1 | NO | | | | | | |
| 5-103908-2 | NO | | | | | | |
| 5-104361-2 | NO | | | | | | |
| 6-103673-0 | NO | | | | | | |

Customer: Heilind Electronics GmbH (113007) Location: Feldkirchen-Westerham Agreement Number: Agreement Unknown

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-------------------|---------------------------|---------------------|-------------------------|-------------------------|---------------------------|------------------------------------|------------------------------|
| 5-103673-3 | NO | | | | | | |
| <u>5-104361-3</u> | NO | | | | | | |

The documents listed below are being modified. Related parts that are not explicitly listed on this PCN are not being modified or discontinued as per the PCN. The Last Order Date, Last Ship Date, First Date to Ship Changed Parts and last date for Mixed Shipments apply only to parts explicitly listed on this PCN.

Customer Drawing(s) Being Modified:

| Di | rawing Number | Related Part Number | Customer Part Number | Current Revision | New Revision |
|----|---------------|---------------------|----------------------|-------------------------|---------------------|
| 10 | <u>)3673</u> | 5-103673-3 | | V | |
| 10 | 04361 | 5-104361-3 | | S | |

 Customer:
 Heilind Asia Pacific (SG) Pte Ltd (2980456)
 Location:
 Singapore

 Agreement Number:
 Agreement Unknown

Part Number(s) being Modified:

| Part | Part Discontinued per | Customer | Customer Part | Alias Part | Substitute Part | Substitute Alias Part | Description Of | | |
|------------|-----------------------|----------|---------------|------------|-----------------|-----------------------|----------------|--|--|
| Number | PCN | Drawing | Number | Number(s) | Number | Number(s) | Difference | | |
| 5-103669-3 | NO | | | | | | | | |
| 5-103673-2 | NO | | | | | | | | |
| 5-103735-3 | NO | | | | | | | | |
| 5-103735-4 | NO | | | | | | | | |
| 5-103904-1 | NO | | | | | | | | |
| 5-103908-2 | NO | | | | | | | | |
| 5-104361-2 | NO | | | | | | | | |
| 6-103673-0 | NO | | | | | | | | |

The documents listed below are being modified. Related parts that are not explicitly listed on this PCN are not being modified or discontinued as per the PCN. The Last Order Date, Last Ship Date, First Date to Ship Changed Parts and last date for Mixed Shipments apply only to parts explicitly listed on this PCN.

Customer Drawing(s) Being Modified:

| Drawing Number | Related Part Number | Customer Part Number | Current Revision | New Revision |
|-----------------------|------------------------|----------------------|-------------------------|---------------------|
| <u>103669</u> | 5-103669-3 | | AC | |
| <u>103673</u> | 6-103673-0, 5-103673-2 | | V | |
| 103735 | 5-103735-3, 5-103735-4 | | W | |
| 103904 | 5-103904-1 | | S | |
| 103908 | 5-103908-2 | | S | |

| Drawing Number | Related Part Number | Customer Part Number | Current Revision | New Revision |
|----------------|---------------------|-----------------------------|-------------------------|---------------------|
| 104361 | 5-104361-2 | | S | |

Customer: Heilind Electronics Inc (167811) Location: Wilmington Agreement Number: Agreement Unknown

Part Number(s) being Modified:

| Part | Part Discontinued | Customer | Customer Part | Alias Part Number(s) | Substitute Part | Substitute Alias Part | Description Of |
|-------------------|-------------------|----------|----------------------|-----------------------------------|-----------------|-----------------------|----------------|
| Number | per PCN | Drawing | Number | Allas Fart Hulliber(3) | Number | Number(s) | Difference |
| <u>103638-3</u> | NO | | | | | | |
| <u>103670-2</u> | NO | | | | | | |
| <u>103670-3</u> | NO | | | "4-40001-6591" | | | |
| <u>103670-5</u> | NO | | | | | | |
| 103908-1 | NO | | | "406746073" | | | |
| 5-103634-3 | NO | | | | | | |
| 5-103635-2 | NO | | | | | | |
| 5-103639-1 | NO | | | | | | |
| 5-103639-5 | NO | | | | | | |
| 5-103672-9 | NO | | | | | | |
| 5-103673-3 | NO | | | | | | |
| <u>5-103673-4</u> | NO | | | | | | |
| 5-103673-7 | NO | | | "CW5998-000", "PER-5-103673-7" | | | |
| 5-103735-3 | NO | | | | | | |
| 5-103735-4 | NO | | | | | | |
| 5-103735-5 | NO | | | | | | |
| 5-103904-4 | NO | | | | | | |
| 5-103908-2 | NO | | | | | | |
| 5-103908-3 | NO | | | | | | |
| 5-103908-7 | NO | | | | | | |
| 5-104361-4 | NO | | | | | | |
| 6-103672-5 | NO | | | | | | |

The documents listed below are being modified. Related parts that are not explicitly listed on this PCN are not being modified or discontinued as per the PCN. The Last Order Date, Last Ship Date, First Date to Ship Changed Parts and last date for Mixed Shipments apply only to parts explicitly listed on this PCN.

Customer Drawing(s) Being Modified:

| Drawing Numbe | Related Part Number | Customer Part Number | Current Revision | New Revision |
|----------------------|---------------------|----------------------|-------------------------|---------------------|
| 103634 | 5-103634-3 | | W | |
| <u>103639</u> | 5-103639-5 | | AA | |
| 103673 | 5-103673-3 | | V | |
| 103908 | 103908-1 | | S | |

Customer: Heilind Asia Pacific (Hong Kong) (2991513) Location: Hong Kong Agreement Number: Agreement Unknown

Part Number(s) being Modified:

| Part | Part Discontinued per | Customer | Customer Part | Alias Part | Substitute Part | Substitute Alias Part | Description Of |
|------------|-----------------------|----------|---------------|------------|-----------------|-----------------------|----------------|
| Number | PCN | Drawing | Number | Number(s) | Number | Number(s) | Difference |
| 5-103908-3 | NO | | | | | | |
| 6-103669-0 | NO | | | | | | |

Customer: Heilind Electronics GmbH (3050932) Location: Rosenheim Agreement Number: Agreement Unknown

Part Number(s) being Modified:

| Part | Part Discontinued per | Customer | Customer Part | Alias Part | Substitute Part | Substitute Alias Part | Description Of |
|------------|-----------------------|----------|----------------------|------------|-----------------|-----------------------|-----------------------|
| Number | PCN | Drawing | Number | Number(s) | Number | Number(s) | Difference |
| 5-103673-3 | NO | | | | | | |