



Product Change No

TE Connectivity

Product Change Notification: PCN-21-112667

Customer: Heilind Electronics
Inc(0002135900)

Location: WORLDWIDE

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

AMPSEAL, AS16 Manufacturing Move within the same plant.

Description of Changes

The Industrial and Commercial Transportation business unit of TE Connectivity is Moving the following part number(s) within the same facility at Empalme Mx TE proprietary designs, therefore considered catalog/general market product. TE reserves the right to move tool back to prior location/supplier based on business request must be submitted within 14 days of PCN submission via ict-ppap-request@te.com or ePPAP system, only PSW will be provided. Submission will not occur. If PPAP requested, disposition response is required within 14 days of submit date or it will be considered approved.

Reason for Changes:

Dear Customer, we hereby inform you of this change. This change is necessary to expand capacity in the same facility. No product, process, or equipment has been changed. The change will not impact connector performance. IMPORTANT: The current and previous revisions of these parts can be used interchangeably in the field. They are being phased in gradually and previous revision can remain stocked until use. Shipments of both configurations may be mixed.

Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

01-OCT-2021

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

31-OCT-2021

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) |
|----------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|
| 1-776087-1 | NO | | | | | |
| 1-776087-4 | NO | | | | | |
| 1-776163-1 | NO | | | | | |
| 1-776163-5 | NO | | | | | |
| 1-776228-1 | NO | | | | | |
| 1-776228-2 | NO | | | | | |
| 1-776231-1 | NO | | | | | |
| 1-776231-2 | NO | | | | | |
| 1-776231-4 | NO | | | | | |
| 1-776276-1 | NO | | | | | |
| 1-776276-2 | NO | | | | | |

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substi Number(s) |
|--------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|------------------|
| 776275-1 | NO | | | | | |
| 776276-1 | NO | | | | | |
| 776280-1 | NO | | | | | |

Customer: Heilind Electronics Brasil Ltda (3088064)

Location: Sao Paulo

Agreement Number:

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substi Number(s) |
|--------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|------------------|
| 776231-1 | NO | | | | | |

Customer: Heilind Electronics Inc (3181260)

Location: Mentor

Agreement Number:

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substi Number(s) |
|----------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|------------------|
| 1-776087-1 | NO | | | | | |
| 1-776087-4 | NO | | | | | |
| 1-776228-1 | NO | | | | | |
| 1-776228-2 | NO | | | | | |
| 1-776231-1 | NO | | | | | |
| 1-776276-1 | NO | | | | | |
| 1-776276-2 | NO | | | | | |
| 776087-1 | NO | | | | | |
| 776163-4 | NO | | | | | |
| 776231-1 | NO | | | | | |
| 776231-2 | NO | | | | | |
| 776231-5 | NO | | | | | |
| 776276-1 | NO | | | | | |

Customer: Heilind Asia Pacific (SG) Pte Ltd (3076161)

Location: Singapore

Agreement Number:

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substi Number(s) |
|----------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|------------------|
| 1-776163-1 | NO | | | | | |
| 770669-1 | NO | | | | | |

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substi Number(s) |
|----------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|------------------|
| 1-776163-5 | NO | | | | | |
| 770669-4 | NO | | | | | |
| 776087-1 | NO | | | | | |
| 776087-2 | NO | | | | | |
| 776087-4 | NO | | | | | |
| 776228-1 | NO | | | | | |
| 776228-2 | NO | | | | | |
| 776228-5 | NO | | | | | |
| 776231-1 | NO | | | | | |
| 776231-5 | NO | | | | | |
| 776261-5 | NO | | | | | |
| 776262-1 | NO | | | | | |
| 776267-1 | NO | | | | | |
| 776276-1 | NO | | | | | |
| 776280-1 | NO | | | | | |

Customer: Heilind Electronics Inc (1276409)

Location: Plano

Agreement Number:

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substi Number(s) |
|--------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|------------------|
| 776200-1 | NO | | | | | |
| 776261-1 | NO | | | | | |

Customer: Heilind Asia Pacific (SG) Pte Ltd (2980456)

Location: Singapore

Agreement Number:

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substi Number(s) |
|----------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|------------------|
| 1-776163-1 | NO | | | | | |
| 1-776231-2 | NO | | | | | |
| 770669-1 | NO | | | | | |

Customer: Heilind Electronics Inc (167811)

Location: Wilmington

Agreement Number:

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substi Number(s) |
|-------------|---------------------------|------------------|----------------------|----------------------|------------------------|------------------|
|-------------|---------------------------|------------------|----------------------|----------------------|------------------------|------------------|

Customer: Heilind Asia Pacific (Hong Kong) (2991513)

Location: Hong Kong

Agreement Number:

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substi Number(s) |
|----------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|------------------|
| 1-776163-5 | NO | | | | | |
| 1-776231-4 | NO | | | | | |
| 770669-4 | NO | | | | | |
| 776087-1 | NO | | | | | |
| 776087-2 | NO | | | | | |
| 776087-4 | NO | | | | | |
| 776228-1 | NO | | | | | |
| 776228-2 | NO | | | | | |
| 776228-5 | NO | | | | | |
| 776231-1 | NO | | | | | |
| 776231-5 | NO | | | | | |
| 776261-5 | NO | | | | | |
| 776262-1 | NO | | | | | |
| 776267-1 | NO | | | | | |
| 776276-1 | NO | | | | | |
| 776280-1 | NO | | | | | |



Product Change Notification

Current Date: 09-Sep-2021

TE Connectivity

Product Change Notification: PCN-21-112667

PCN Date: 08-SEP-21

Customer: Waldom Electronics Corp (167882)

Location: Rockford

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

AMPSEAL, AS16 Manufacturing Move within the same plant.

Description of Changes

The Industrial and Commercial Transportation business unit of TE Connectivity is Moving the following part number(s) within the same facility at Empalme Mx. These PNs are TE proprietary designs, therefore considered catalog/general market product. TE reserves the right to move tool back to prior location/supplier based on business need. PPAP request must be submitted within 14 days of PCN submission via ict-ppap-request@te.com or ePPAP system, only PSW will be provided. Submission will not occur without request. If PPAP requested, disposition response is required within 14 days of submit date or it will be considered approved.

Reason for Changes:

Dear Customer, we hereby inform you of this change. This change is necessary to expand capacity in the same facility. No product, process, or equipment has been changed. The change will not impact connector performance. IMPORTANT: The current and previous revisions of these parts can be used interchangeably in the field. The change(s) are being phased in gradually and previous revision can remain stocked until use. Shipments of both configurations may be mixed.

Estimated Dates:

| | |
|---|---|
| Last Order Date (Obsolete Parts Only): | First Date To Ship (Changed Parts Only): |
| | 01-OCT-2021 |
| Last Ship Date (Obsolete Parts Only): | Last Date for Mixed Shipments: (Changed Parts Only): |
| | 31-OCT-2021 |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| 1-776087-1 | NO | | | | | | |
| 1-776163-1 | NO | | | | | | |
| 1-776180-1 | NO | | | | | | |
| 1-776180-6 | NO | | | | | | |
| 1-776200-4 | NO | | | | | | |
| 1-776231-2 | NO | | | | | | |
| 1-776266-1 | NO | | | | | | |
| 1-776267-2 | NO | | | | | | |
| 1-776276-1 | NO | | | | | | |
| 1-776276-2 | NO | | | | | | |
| 1-776280-1 | NO | | | | | | |
| 1-776280-2 | NO | | | | | | |
| 770669-4 | NO | | | | | | |
| 776163-5 | NO | | | | | | |
| 776200-1 | NO | | | | | | |
| 776228-1 | NO | | | | | | |
| 776262-1 | NO | | | | | | |
| 776275-1 | NO | | | | | | |
| 776275-2 | NO | | | | | | |