



Product Change Notification

Current Date: 09-Jun-2022

TE Connectivity

Product Change Notification: P-22-022863

PCN Date: 07-JUN-22

Customer: Waldom Electronics Corp (167882)

Location: Rockford

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

SAE AS7928 CLASS 2 PART NUMBERS

Description of Changes

TE has removed all Class 2 MIL-SPEC references from product labels and literature for the products listed in this PCN(affected products).Any affected products shipped on or after April 13th,2022 must not be used for applications that specifically require NAVAIR Class 2 qualified product until further notice.The affected products still meet the performance specifications of AS7928 and can continue to be used in commercial applications that do not require NAVAIR Class 2 qualified product.TE Class 1 products remain active on the NAVAIR Class 1 QPL and can continue being used for applications requiring NAVAIR Class 1 qualified product.TE AS7928 Class 2 products were removed from QPL-7928(Class 2) Supplemental Information Sheets for Qualified Products Lists(QPLs), effective April 13, 2022.Since Class 2 parts must be ordered by the manufacturer s standard part number, TE standard package labels indicated both the commercial(standard TE) part number and the applicable MIL-SPEC reference(s).

Other attachments:

[TE TO MILITARY PART NUMBER CROSS REFERENCE](#)

Reason for Changes:

New specification.This action required TE remove all references to Class 2 qualification from product labels in order to continue supplying the affected parts for commercial or(where applicable)Class 1 application.Government standard SAE AS7928,Sec6.2 lists items that should be on procurement documents.In line with the requirements and for all future orders TE will require the class of lug terminal or splice connector and applicable AS detail specification part number.Class 1 part numbers must be ordered by the AS detail specification part number and Class 1 designation must appear in the text/note field.ie: Order M7928/1-13 part number, with a note stating AS7928 Class 1. Once TE is re-qualified to supply Class 2 parts,Class 2 part numbers must be ordered by the TE part number.Also for Class 2 orders,the AS detail specification part number and Class 2 designator must appear in the text/note field as a reference.ie: Order 51863-5 part number,along with a note stating M7928/1-13 Class 2

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	24-JUN-2022
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-51864-0	NO			"AMPS-1-0051864-0", "E21090-000"			
1-51864-1	NO						
2-31880-1	NO						
2-31894-2	NO			"405223587"			
2-320559-4	NO			"405455973"			
2-320561-4	NO						
2-320569-3	NO						
2-320569-6	NO						
2-320571-3	NO						
2-320572-2	NO			"EF5711-000", "AMP-0-2-0320572-2"			
2-321684-1	NO						
2-323914-1	NO						
2-323916-1	NO			"1181451"			
2-327946-4	NO						
2-327952-2	NO						
2-327958-4	NO						
2-327968-1	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2-328975-3	NO						
2-33457-2	NO			"401771357"			
2-34115-2	NO						
2-35110-1	NO			"403665755"			
2-35111-1	NO						
2-36149-4	NO						
2-36149-5	NO						
2-36153-3	NO						
2-36153-4	NO			"8202607913"			
2-36153-5	NO						
2-36153-6	NO						
2-36154-2	NO			"405853706"			
2-36161-2	NO			"402624795"			
2-36161-4	NO						
2-36161-6	NO						
31807	NO			"CN5247-000", "AMP-0-0031807-0"			
31811	NO			"AMPS-0-0031811-0", "C66450-000"			
31812	NO						
31880	NO			"157-0033-M"			
31890	NO			"A28230-000", "AMPS-0-0031890-0", "6089315700", "6089 3 157-00"			
31894	NO			"679058-000", "AMPS-0-0031894-0", "6089315703"			
31895	NO			"C58079-000", "AMPS-0-0031895-0"			
31897	NO			"A84499-000", "AMPS-0-0031897-0"			
320344	NO						
320383	NO			"876388-000", "AMPS-0-0320383-0"			
320551	NO			"F14692-001", "AMP-0-0320551-0", "500-095- 0002", "2-14492-8160"			
320553	NO			"CN5244-000", "AMP-0-0320553-0", "668-1003- 01", "2-14492-4160"			
320559	NO			"A82772-000", "AMPS-0-0320559-0"			
320561	NO			"CF0318-000", "AMP-0-0320561-0", "500-095- 0000", "2-14492-6140", "45-0111"			
320562	NO			"402244693", "AMPS-0-0320562-0", "D26765- 000"			
320563	NO			"D12388-000", "AMPS-0-0320563-0"			
320564	NO			"A69728-000", "AMPS-0-0320564-0"			
320567	NO			"500-095-1042", "2-14492-6100"			
320568	NO			"F51639-001"			
320569	NO			"A22724-000", "AMPS-0-0320569-0"			
320570	NO			"402601611", "939678-000", "AMPS-0- 0320570-0"			
320571	NO			"CN5242-000", "AMP-0-0320571-0", "2-14492- 3160"			
320573	NO						
320575	NO						
320741	NO						
321271	NO						
321298	NO						
321598	NO			"A33970-000", "AMPS-0-0321598-0", "4-26454- 0080"			
321868	NO						
321870	NO						
321873	NO						
321874	NO						
321877	NO						
321878	NO						
321879	NO						
321880	NO						
322870	NO			"834896-000", "AMPS-0-0322870-0"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
323914	NO			"2-14492-4220"			
323994	NO			"1149602"			
324043	NO						
324044	NO						
324045	NO						
324046	NO						
324047	NO			"A42815-000", "AMP-0-0324047-0"			
324048	NO			"AMP-0-0324048-0", "E42038-000"			
324051	NO						
324052	NO						
324056	NO						
324057	NO						
324061	NO			"CN5237-000", "AMP-0-0324061-0", "45-0132"			
324075	NO			"1134503"			
324082	NO						
324159	NO			"D97987-000", "AMPS-0-0324159-0"			
327175	NO			"AMPS-0-0327175-0", "C43841-000"			
328307	NO						
328308	NO						
328309	NO						
328975	NO						
328976	NO						
330301	NO						
33114	NO			"CH2501-000", "AMP-0-0033114-0"			
33220	NO						
33457	NO			"A27999-000", "AMP-0-0033457-0", "45-0110"			
33459	NO			"070086-000", "AMPS-0-0033459-0", "1262492"			
33461	NO			"CN5232-000", "AMP-0-0033461-0", "BAH-1030"			
33463	NO						
33466	NO			"495972-000", "AMPS-0-0033466-0", "1262493", "320000100242"			
33467	NO			"AMPS-0-0033467-0", "C97755-000"			
34103	NO						
34104	NO						
34112	NO						
34114	NO			"1106888"			
34115	NO						
34119	NO			"A65474-000", "AMPS-0-0034119-0"			
34125	NO			"AMP-0-0034125-0", "F03616-000"			
35107	NO						
35108	NO			"AMPS-0-0035108-0", "C57639-000", "500-060-1422", "2-14492-8100"			
35109	NO			"AMPS-0-0035109-0", "F67095-000"			
35110	NO			"AMPS-0-0035110-0", "E36230-000", "2-14492-3100"			
35111	NO			"211624-000", "AMPS-0-0035111-0"			
35112	NO			"D94238-000", "AMPS-0-0035112-0"			
36149	NO			"2-42937-0285"			
36150	NO			"C24355-000", "AMPS-0-0036150-0"			
36153	NO			"E15470-000", "AMP-0-0036153-0", "2-14492-1160"			
36154	NO			"AMPS-0-0036154-0", "D27582-000", "110209", "4-00520-2110", "1-14647-0030"			
36161	NO			"E87226-000"			
51863-1	NO						
51863-2	NO						
51864	NO						
51864-1	NO			"45-0128"			
51864-2	NO						
51864-4	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
51864-5	NO						
51864-6	NO						
51864-7	NO						
51864-9	NO						
52077-2	NO						
52273	NO						
53056	NO						
53073	NO						
53406-1	NO						
53408-1	NO			"CA9730-000", "AMPS-0-0053408-1"			
53409-1	NO						
53417-1	NO			"C91797-000", "AMPS-0-0053417-1"			
53549-1	NO						
53550-1	NO						
54311-1	NO						
696423-5	NO						
696426-1	NO						