



Product Change Notification

Current Date: 19-Jul-2022

TE Connectivity

Product Change Notification: PCN-22-143739

PCN Date: 14-JUL-22

Customer: Heilind Electronics Inc(0002135900)

Location: WORLDWIDE

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Terminal Contacts

Description of Changes

Please be aware that the packaging reel is being changed for the following mentioned part numbers. Please refer to attached document for details.

Other attachments:

[Reference Document](#)

Reason for Changes:

PCN Attributes:

Product Category:	Kind of Change:
Terminals	Packaging Type
Change Feature:	Potential Customer Impact:
Reel	No Customer Impact
Remarks:	

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Ship Date of Changed Items (Changed Parts Only):
	03-OCT-2022
Last Ship Date of Changed Items (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments
Effectivity Date:	Date of First Samples:

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
41202	NO						
41274	NO						
41330	NO			"668-1036-02"			
41332	NO						
41333	NO						
41559	NO						
42100-2	NO						
42400-1	NO						
42801-1	NO						
60197-1	NO						
61283-1	NO			"0-0061283-1"			
61436-1	NO						
63306-1	NO						
63477-2	NO						
640051-1	NO						
640253-2	NO						

Customer: Heilind Electronics Inc (1275266)

Location: Visalia

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
41274	NO						
41332	NO						
41333	NO						
42100-2	NO						
60197-1	NO						
61283-1	NO			"0-0061283-1"			
63306-1	NO						
640051-1	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
640253-2	NO						

Customer: Heilind Asia Pacific (Hong Kong) (2980376)

Location: Shatin, N.t.

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
42100-2	NO						

Customer: Heilind Electronics Inc (167811)

Location: Wilmington

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
41202	NO						
41274	NO						
41330	NO			"668-1036-02"			
41332	NO						
41333	NO						
41559	NO						
42100-2	NO						
42400-1	NO						
42801-1	NO						
60197-1	NO						
61283-1	NO			"0-0061283-1"			
61436-1	NO						
63306-1	NO						
63477-2	NO						
640051-1	NO						
640253-2	NO						

Customer: Heilind Asia Pacific (Hong Kong) (2991513)

Location: Hong Kong

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
42100-2	NO						



Paper reel change from 999225-1 to 2400473-1






EVERY CONNECTION COUNTS



Paper reel appearance status 999225-1 & 2400473-1




Before

Reel part	Reel status	Fixed method	Different
995225-1	 		<ol style="list-style-type: none"> 1. No hole 2. Fixed of FIBER TAPE

Note:

1. Paper core status is different
2. Fixed method is different
3. Flag have small change, two side the circular hole change to the rectangle hole

After

Reel part	Reel status	Fixed method	Different
2400473-1	 		<ol style="list-style-type: none"> 1. Hole on the core 2. Fixed of core hole



Thanks

